

Intracompany
CorrespondenceA-59
50-348/364-010P
2/20/92

0064077

A4.02

MAR 13 P4:44

Alabama Power

NS 87-0351

Gen. 1193

Justification For Continued Operation
(JCO) Unit 1-Terminal Blocks Used In
Instrument Circuit

Subject

Date

NOV 24 1987

To Mr. J. D. Woodard

From
AtW. G. Hairston, III
Vice President,
Nuclear Generation

Enclosed is a justification to allow continued operation of Farley Unit 1 with terminal blocks installed in various instrument loops. A copy of this JCO should be placed in the EQ Central File under States, GE and Foxboro terminal blocks.

If you have any questions, please advise.

W. G. Hairston, III
W. G. Hairston, III

WGH,III/BHW:dst-D72

cc. File: A-3026-JCO
A-5001 1E6 74-018ALABAMA POWER COMPANY
RECEIVED

NOV 20 1987

Gen Mgr	1	Mgr Pk Mod	—	—
Asst Gen Mgr Ops	2	Mgr Syst & Plan	—	—
Asst Gen Mgr S'port	3	Mgr Trng	—	—
Mgr Ops	—	Mgr Admin	—	—
Mgr Maint	—	Staff Asst	—	—
Mgr Tech	4	SSAER	—	—
	—		—	—

PRODUCTION DOCUMENT
CONTROL DEPARTMENT

NUCLEAR REGULATORY COMMISSION

Docket No. 50-348/364-CIVP Official Exh. No. 59
 in the matter of Alabama Power Company

Staff IDENTIFIED 2:34 p.m. 2/20/92
 Applicant ✓ RECEIVED 2/20/92

Intervenor REJECTED

Cont'g Off'r

Contractor DATE

Other Witness

Reporter L. Estep

Justification for Continued Operation
J. M. Farley - Unit 1
Terminal Blocks Used In Instrument Circuits

0064078

I. BACKGROUND

The qualification of the Farley Nuclear Plant Terminal Blocks used in instrument circuits was based on type test information for the States ZWM Terminal Blocks, the GE CR 151B Terminal Blocks, and the Foxboro Terminal Blocks. Each terminal block tested was identical to that installed in the Farley Nuclear Plants. The terminal blocks were tested under simulated LOCA conditions in a configuration similar to that installed at FNP. Each test resulted in the terminal block successfully performing the intended function. However, although these tests substantiate the acceptability of using terminal blocks under LOCA conditions, the performance parameters that would additionally support their acceptability for use in FNP instrument circuits were not measured. On the basis of the 10CFR50.49 provision that permits type test plus analysis for establishing qualification, an analysis was performed to demonstrate that the FNP terminal blocks could have performed as intended for the instrument application. The analysis demonstrated similarity by size, shape, and function to a terminal block that was type tested under similar FNP LOCA conditions where insulation resistance (IR) was measured to determine leakage current. The analysis further assumed, based on review of the Sandia NUREG/CR-3814 report that the input or change in insulation resistance was attributable to a surface film mechanism and not material dependant. The corresponding values recorded during the test of the similar terminal block (Conax Test report irs-107, Connection Terminal Block) provided a worst case IR value of 3×10^7 ohms. Allowance of further margin was provided by accepting a lower value of insulation resistance (i.e., 1×10^7 ohms) for use and input into the FNP setpoint analysis for loop accuracy. (Reference WCAP-11658, Evaluation of the Impact of Cable and Terminal block Leakage on RPS/ESFAS and ERG Setpoints, November 13, 1987). The 1×10^7 ohms insulation resistance was provided to Westinghouse for all terminal blocks used in FNP instrument circuits.

A review conducted by the NRC during the week of November 16 through 20th indicated that the technical analysis approach used to justify the 1×10^7 ohms insulation resistance value was not acceptable to the NRC Staff. APCo believes that the methodology employed for the analysis along with the resulting values are technically sound and justified. However, to further exemplify the amount of conservatism built into the setpoint analysis, additional reviews and studies were performed.

II. EVALUATION

A thorough review of the Sandia NUREG report was performed which resulted in confirmation of basic assumptions such as the insensitivity of the terminal blocks to chemical spray, the lack of surface film dependency on roughness, and the recovery of IR's as temperature is diminished. Additional discussion is provided in Attachment 1 to this report. As explained in Attachment 1, correlation of the Sandia test results to the post accident performance of terminal blocks at FNP can not be made in a quantitative manner.

The previous evaluation of the impact of cable and terminal block leakage on RPS/ESFAS and ERP setpoints (Ref. WCAP-11658, November 13, 1987) considered a conservative value of 1×10^7 ohms for terminal block IR and, combined with other contributors to channel inaccuracy, confirmed that the RPS/ESFAS functions will occur as required in the plant safety analysis. Furthermore, the use of existing ERP setpoints (without revision) was confirmed to not impact plant safety. At the time of reactor trip and during post accident monitoring, there were no uncertainty increases which could cause the operator to be misled into performing inappropriate actions. In view of the continuing concerns raised by the NRC regarding the terminal block insulation resistance values currently demonstrated in the FNP EQ documentation and used in instrument inaccuracy studies, an evaluation has been performed to assess the impact of reduced IR values on the ability to achieve and maintain safe shutdown following design-basis events. The results of this evaluation are described in Attachment 2.

The evaluation described in Attachment 2 considered the postulated design basis events of large and small break LOCA and secondary pipe breaks. A minimum set of safe shutdown instruments and their functions, potentially exposed to a harsh environment were identified. The evaluation determined that if a terminal block IR value of 5×10^5 ohms were conservatively assumed as the worst case value for that minimum set of instruments, the resulting instrument inaccuracy will allow the current ERP values to be used without change.

Terminal block testing performed by Sandia National Laboratories (SNL) is documented in NUREG/CR-3416. As discussed in Attachment 1, correlation of the Sandia test results to the post accident performance of terminal blocks at FNP can not be directly made. However, in recognition of the concerns that the Sandia tests have introduced, an evaluation was made of design basis LOCA and secondary pipe break using IR values derived from the Sandia results. Figure 1 presents a correlation between temperature and IR conservatively assuming a logarithmic relationship between temperature and IR. This data is based on IR values for GE EB25 terminal blocks measured at 175°C and 95°C. Additional discussion on the relationship of IR to temperature is contained in Attachment 3. The methodology employed by Attachment 2 was to determine the containment temperature at which the IR value would decrease below the value of 5×10^5 ohms. At values of 5×10^5 ohms and above the operator can use his instruments with confidence under the existing ERP's and setpoints. Having determined this containment temperature, the FNP temperature profile is used to define the periods of time when IR is below this threshold value, thereby defining the periods during DBE's when inaccuracy would be postulated to be greater than that accounted for in the ERP's. The results are shown in Figure 3.0-1 of Attachment 2. This period of interest occurs at a time when no operator action is required based on instruments exposed to the postulated harsh

environment. For large and small LOCA, no mitigative or recovery operator actions are required using instrumentation in a harsh environment. For secondary breaks, safety injection termination (the required manual operator recovery action) will occur after the instrument accuracy returns to an acceptable value. The onset of excessive instrument inaccuracies as shown in Figure 3.0-1 is not expected during a DBA since the following conservative assumptions were considered:

1. The test profile shown in Figure 1 of Attachment 3, used to obtain the IR values assumed in Figure 1 greatly exceed the maximum calculated design basis LOCA/MSLB temperature profile for FNP.
2. The physical configuration of Phase I specimens in the Sandia test produced more severe conditions than would occur at FNP. The conduit was routed up the exterior of the enclosure and terminated in the test chamber approximately 12 inches below the steam inlet port and the spray header. Neither end of the conduit was sealed. (See Attachment 1.)
3. Sufficient test data exists to indicate that #12 AWG conductors will exhibit lower IR values than smaller #16 AWG conductors with the same insulation system. The Sandia testing used #12 AWG cables whereas #16 AWG is used in FNP field cables for RTD and transmitter applications. (See Attachment 1.)
4. The containment temperature profile assumed is derived from worst case assumptions described in FSAR Chapter 6.2 including 102% power, minimum ESF, and only one containment cooler. The profile which would result from more realistic assumptions would be significantly lower.


5. The minimum values of IR and corresponding high leakage currents recorded in the referenced SNL test results are conservative, and are not representative of values that would be expected at FNP during LOCA/MSLB design basis events. Minimum values of terminal block IR values higher than those recorded in the SNL report are supported by CONAX Text Report IPS-107, and Wyle Report Nos. 17775-1 and 17733-1 for MSLB/LOCA temperatures relevant to FNP. (See Attachment 3.)

III. CONCLUSION

Based on the above, Alabama Power Company concludes that there is reasonable assurance that the instrument loops will perform their safety function when called upon to mitigate the accident for which they are needed. However, to further remove the point of contention regarding terminal block performance and thereby increase the margin of the Westinghouse setpoint analysis, APCo will replace the terminal blocks of concern in Unit 2, during the fifth refueling outage, with qualified splices not relying on terminal blocks and APCo will take the same measure for Unit 1 prior to startup from the eighth refueling outage, currently scheduled for March 1988.

FIGURE 1

0064083



ATTACHMENT 1

Additional Clarifications Regarding the
Qualification of States NT/ZWM and B.E.
CR151B Terminal Blocks at
Farley Nuclear Plant (FNP) Units 1 and 2
in Low Voltage RPS/ESFAS and ERP
Transmitter and RTD Circuits

QUALIFICATION REQUIREMENTS AND STATUS

States terminal blocks mounted in NEMA 4 enclosures, and B.E. CR151B terminal blocks provided with the B.E. Series 100 electrical penetration assembly terminal boxes were installed in containment safety related instrumentation circuits at FNP during construction. As such these blocks including their performance and installed configuration were required to be and are qualified to the DOR Guidelines for FNP Unit #1 and to NUREG-0568, Cat. 2, for FNP Unit #2. In accordance with 10CFR50.49, Par. K, requalification of this electric equipment is not required.

EFFECTS OF LOCA/MSLB ENVIRONMENT ON TERMINAL BLOCK LEAKAGE CURRENTS AND PERFORMANCE

IE Information Notice No. 84-47 indicated that as a result of testing performed by Sandia National Laboratories (SNL) for the NRC it was shown that a moisture film will form on the surface of terminal blocks during the simulation of LOCA/MSLB events. (ref: NUREG/CR-0153; SAND-1617, Printed August 1984. Note that this reference was not provided in IEN 84-47). This film will result in the reduction of insulation resistance between terminal points and ground, and thus will allow some leakage currents to flow to ground. IEN 84-47 further states that the NRC staff recognizes that leakage currents do exist during LOCA/MSLB simulations and that the leakage currents may be of significance in some applications.

No written response to the notice was required, and it was suggested that licensees:

1. Review their facilities to determine if terminal blocks are used in low-voltage applications, such as transmitters and RTD circuits, and
2. Review terminal block qualification documents to ensure that the functional requirements and associated loop accuracy of circuits utilizing terminal blocks will not degrade to an unacceptable level due to the flow of leakage currents that might occur during design basis events.

The notice further stated that the NRC staff considers this review to be part of the on-going activities that licensees

0064085

are currently undertaking to resolve other environmental deficiencies per 10CFR50.49 deadlines and requirements.

IEH 84-47 indicated that where existing terminal block qualification testing does not provide supporting data for instrumentation leakage currents, the following possible corrective action could be considered:

Obtain documentation from valid qualification tests already performed with substantiated data for leakage currents, and perform appropriate analysis to demonstrate that acceptable loop accuracy and associated response times for instrument circuits utilizing terminal blocks are being maintained throughout various operating conditions.

Two other possible corrective actions were also stated which involved either additional qualification testing of installed terminal blocks with provisions for continuous monitoring of leakage currents throughout the test with analysis of loop accuracies, or replacement of installed terminal blocks with qualified splices.

END EVALUATION OF TERMINAL BLOCK LEAKAGE CURRENTS

States terminal blocks in IDIA 4 enclosure were qualified for instrumentation and control circuits inside containment by Wyle Report No. 44354-1. Post LOCA simulation of Insulation Resistance (IR) values were recorded, but no leakage current or IR values were recorded during the LOCA test phase to permit quantification of the surface moisture film leakage currents discussed in IDH

0064086

B4-47. CR151 and States NT terminal blocks installed in B. E. Series 100 Low-Voltage Instrumentation and Control Penetration NEMA 4 terminal boxes inside containment were qualified for FNP by G.E. as stated in G.E. Qualification Test Summary Report 994-75-011, dated March 27, 1975. This report provides one minimum value for IR associated with LOCA simulation testing of the CR151 and States blocks, but insufficient leakage current or IR values recorded during the LOCA test phase exist to permit quantification of the surface moisture film leakage currents discussed in IEN B4-47.

Due to the lack of data recorded in the DOR Guideline and NUREG-0586 Cat. 2 qualification reports for the FNP States and CR151B terminal blocks installed in NEMA 4 enclosures, a documentation search was conducted to obtain documentation from already performed valid qualification tests of identical or similar terminal blocks which could provide leakage current or IR data recorded during the simulated LOCA steam conditions. Of the test report documents evaluated, including the SNL test documentation upon which IEN B4-47 was based, the most representative test of FNP in containment terminal block and enclosure configurations which provided IR readings during simulated LOCA/MSLB steam conditions was Conex Report No. IPS-107, dated 10/5/73. Minimum IR values contained in this report which were obtained during LOCA simulated steam conditions were reviewed and a conservatively low IR value was provided to Westinghouse for determination of the resulting leakage currents and their effects on RPS/ESFAS and ERP setpoint accuracies.

WCAP-11658 addresses the results of this evaluation, and response to APCo E. G. Action Items 018 and 067, addresses the methodology used for the selection of the terminal block IR value used in the Westinghouse evaluation.

BASIS FOR NOT USING SNL IR OR LEAKAGE CURRENT VALUE FOR
WCAP-11658 EVALUATION

All the following comments are based on a review of NUREG/CR-3418, SAND83-1617 entitled "Screening Tests of Terminal Block Performance in a Simulated LOCA Environment" printed August 1984 and are in reference to sections of that document (Attachment 61A to this clarification report). It is important to note that only Phase I testing was performed on G.E. CR151B (Manufacturer I, Model B) and States ZHM (Manufacturer III, Model D) terminal blocks as shown in Table 1, Pg. 12.

- o Environmental Test Temperature and Pressure Profiles - As shown in Figure 1, Pg. 8, the test temperature and pressure peaks as well as profile durations greatly exceeded the maximum calculated

0064087

DBE LOCA/MSLB surface temperature conditions for FNP in containment terminal block applications. As stated in the last paragraph on Pg. 52 of Sect. 4.3.4, "Terminal blocks 6, 11, and 12 (States IWM) experienced a temperature effect. Their inter-terminal barrier softened almost to the liquid melt point, and flowed from between the terminals. The melted material covered some of the lower posts of the terminals, encasing the wires and drooping below the terminal block in large globules. Surprisingly, as Figure 20 shows, the terminal-to-terminal insulation resistances for terminal blocks 6, 11, and 12 were among the highest measured. We have no reasonable hypothesis to explain this behavior. We can speculate that the phase change of the inter-terminal barrier material prevented in some way the formation of a continuous film between terminals, or that changing geometry somehow affected the process of conduction between adjacent terminals". Geometrical changes of the inter-terminal barrier occurred in Kyle Test 44354-1, but complete melting did not occur.

- o No chemical spray was introduced in Phase I LOCA Testing. (However, Section 5.3, Pg. 126 of the conclusion states that little change in the moisture film conductivity may be expected as a result of chemical spray and therefore, chemical spray would appear to not be a significant issue.)
- o Physical Configuration of Phase I Specimens - Three 6-pole CR151B and three 6-pole States IWM terminal blocks were all mounted vertically in the same NEMA 4 enclosure (Enclosure 2) as shown in Figure 4, Pg. 11. Cables were brought into the side of the enclosure through 3/4 inch diameter liquid tight metal hose using elbow conduit terminators to penetrate the NEMA 4 enclosure walls. The conduit was routed up the exterior of the enclosure, and terminated in the test chamber head approximately 12 inches below the steam inlet port and the spray header. Neither end of the conduit was sealed. (See bottom Pg. 16, and top of Pg. 18.)

All cables used to connect the terminal block test circuitry were #12 AWG, either 1-conductor or 3-conductor. The direct steam jetting exposure into the open conduit from the steam inlet port is not representative of installed instrumentation conduit configurations at FNP, and the use of #12 AWG single conductor and multi-conductor cable is not representative of the FNP installed

instrumentation cable. Installed instrumentation cables at FNP for RTD and transmitter applications are #16 AWG.

Sufficient test data exists which appears to indicate that #12 AWG conductors will exhibit lower IR values than smaller #16 AWG conductors with the same insulation system when exposed to LOCA steam conditions. As the #12 AWG cable is a part of the test circuit and its contribution to IR and leakage currents resulting from steam moisture is included in the terminal block measured data, additional error may have been introduced.

- o Electrical Configuration of Phase I Test-(Sect. 3.4, Pg. 10, Figure 10, Sect. 4.1, Pg. 29 and last paragraph Pg. 94).

A serpentine connection of alternate terminal block (TB) poles was used which did not result in the measurement of a unique pole-to-pole resistive path. As stated in Sect. 4.1 "The serpentine connection of the 6-pole terminal blocks actually provided 5 parallel resistive paths. Each of these paths, indicated R_1 through R_5 in Figure 16, is in turn a parallel combination of an infinite number of paths, i.e., a surface." "In measuring the leakage currents the equivalent resistance of these 5 surfaces is actually measured. Without further data or assumption the individual values of the surface equivalent resistances, R_1 through R_5 cannot be determined".

Also as stated in Sect. 3.4 "only one ground return path existed for all 12 phase I terminal blocks, 6 blocks per enclosure. For the majority of the Phase I test, all blocks were powered simultaneously, and hence only pole-to-pole leakage current data is relevant".

As stated in Section 4.4.3, Pg. 94, last paragraph, "If the conduction paths were uniformly distributed over the terminal block surface, the differences in wiring between Phase I (serpentine) and Phase II (straight through), would cause the Phase I IR's to be less than the Phase II IRs. This result is a simple consequence of multiple parallel conducting paths. For our experimental configuration there was approximately five times the pretested conducting surface available on the Phase I terminal blocks as compared to the Phase II terminal blocks. Consequently, the insulation resistance for the Phase I terminal blocks could

0064089

reasonably be expected to be one fifth of the Phase II IR's. Except for the A path of Phase II terminal block 4, the 45Vdc data and the 125 Vdc support the hypothesis of uniformly distributed conduction."

The serpentine test circuitry used to measure the States and CR151B test specimen leakage currents and IR's did not yield direct individual pole-to-pole or pole to ground values of IR during the LOCA steam environment simulation, and are subject to hypothesis in order to arrive at required pole-to-pole values.

- o General Applicability of Phase II Test Data - As stated above, no Phase II testing was performed on CR151B or States terminal blocks. The only block tested in Phase II based on present available information which appears to be similar to the CR151B and States blocks with regard to, block material, pole-to-pole spacing, the presence of a barrier between poles and a one-piece non channel mounted block is the G.E. EB25 (Manufacturer I, Model A). It should be noted that Table, 1 Pg. 12, incorrectly states that the States IWM block is a sectional block. Six EB25 blocks were tested in Phase II. Although, the electrical test circuitry in the Phase II test yields more realistic values of leakage currents and IR's than Phase I test, other electrical test anomalies, and the configuration and environmental test profile are not representative of the installed condition at FNP.

It is interesting to note that the only physical design effects analyzed were related to whether or not the blocks were sectional or one piece as stated in Sect. 4.4.1.3, Pg. 81. No apparent attempt was made to correlate leakage current performance to geometrical considerations such as the presence of barriers and height of blocks with barriers between poles or pole-to-pole spacing. Perhaps the conclusion stated in Sect. 4.4.1.3 that "Figures 34 through 39 show about one to two orders of magnitude difference between the performance of terminal blocks 8, 6, and 12 and the one piece blocks, the one piece blocks being better." is not singularly related to the sectional block design, but to other geometrical considerations. For the Phase II tests, the one piece blocks referenced here are G.E. EB25 blocks which have similar pole spacing to the G.E. CR151B and States IWM one piece blocks and do possess barriers between poles.

0064090

ATTACHMENT 2

Westinghouse
Electric Corporation

Power Systems

Nuclear Technology
Systems Division

Box 355
Pittsburgh, Pennsylvania 15230-0355

ALA-87-882

Ref: ES 87-1000

November 23, 1987

Mr. W. G. Hairton, III, Vice President
Nuclear Generation
Alabama Power Company
600 North Eighth Street
Birmingham, AL 35291-0400

Attn: Mr. J.E. Garlington

Joseph M. Farley Nuclear Plant
Units No. 1 & 2
SEP Information

Dear Mr. Hairton:

Attached is additional information on the report which was generated for Alabama Power Company entitled "Evaluation of the Impact of Cable and Terminal Block Leakage on BPS/TEPAS and EOP Setpoints" dated November 1987. This information was generated as a result of the BPC Equipment Qualification Audit which was held during the week of November 16, 1987.

If you have any additional questions regarding this please contact the project office.

Very truly yours,
WESTINGHOUSE ELECTRIC CORPORATION

99 Knöchel
for C. Eicheldinger, Manager
Alabama Project

AJ/DL/CH

0064091

ATTACHMENT

ALA-87-882

The attached table contains a listing of Farley Unit 1 Emergency Response Procedure (ERP) harsh environment instruments, significant safety related functions of each instrument, and time usage factors and diverse instruments for each function. The purpose of the table is to list the instruments potentially subject to a harsh environment for the Farley design basis events. These instruments have an environmental allowance in their calculated uncertainties used in the ERPs. The design basis events are large and small LOCA and secondary system pipe breaks: i.e., steam line and feed line breaks.

A review of this table results in identification of a minimum set of instruments, and their functions, subject to a harsh environment and also necessary for safe shutdown from design basis events. These are RCS Subcooling, Wide Range Pressure, and Narrow Range Steam Generator Water Level. Backup instruments have been identified where available. Other instruments necessary for safe shutdown are located in a mild environment or are not affected by current leakage. Other instruments used in the ERPs are not used to base any required actions within the Farley design basis events or will not cause any actions to be taken detrimental to plant safety if the instrument uncertainty exceeds the allowance presently in the Farley ERPs.

For RCS Subcooling, Steam Generator Narrow Range Level and Wide Range Pressure, it is recommended that for Farley Unit 1 that a containment temperature criterion be defined that is indicative of current leakage resistance of less than 5×10^5 ohms. A value of greater than 5×10^5 ohms results in an instrument inaccuracy that will allow the current ERP values to be used by the operator to take action as specified in the ERPs. The temperature or a corresponding containment pressure criterion should be used as guidance to the operator using the ERPs on when to consider that additional error above that already accounted for in the ERPs may exist. Under conditions exceeding these criteria no actions which could reduce the margin of safety, specifically termination of safety injection based on RCS Subcooling or stopping of all auxiliary feedwater based on Steam Generator Narrow Range Level or stopping of RHR pumps based on Wide Range Pressure, should be performed since the errors may exceed those accounted for in the ERPs. After containment conditions have returned to below these criteria the operator can safely resume the use of the ERP specified values, provided that the leakage current resistance will increase to above 5×10^5 ohms. The temperature criterion based on 5×10^5 ohms would also apply to Pressurizer Level use in conjunction with RCS Subcooling for Safety Injection termination and reinitiation. If the ERP values for RCS subcooling are changed for Safety Injection termination, then a leakage current resistance of 1×10^5 or greater would be acceptable for use.

Based on a review of Figure 1 and Figure 3.0-1, the instrument inaccuracy that exceeds the value that the operator can utilize with confidence occurs at a time when no operator action based on instrumentation in a harsh environment is required for the design basis events described above. For large and small LOCA, no mitigative or recovery operator actions are required based on instrumentation in a harsh environment. For secondary

0064092

breaks, Safety Injection termination (the required manual operator recovery action) will occur after the instrument accuracy returns to an acceptable value. Therefore, the operator limitation described in the previous paragraph will not prevent any necessary operator actions from being performed.

A review of the Reactor Protection System and Emergency Safeguards Features functions has determined that the significant functions required for harsh environment events (pressurizer pressure - Low SI and steam generator water level - Low-Low) are required only before 5 minutes after the event occurrence for pressurizer pressure - Low SI and 60 seconds for steam generator water level - Low-Low. This early time of use in the event should ensure that the function necessary will be performed before a significant error from leakage current develops.

TABLE

PARAMETER	FUNCTION	TIME	DIVERSE PARAMETER	COMMENTS
1. CTMT Sump <i>Level</i>	A. Identify LOCA B. CTMT Recirculation C. Critical Safety Function	A. Short Term ≤ 20 min B. Long Term C. Long Term	(A-1) CTMT Radiation (RQIist) (A-2) CTMT Pressure (NR or WT) RMST Level None	Only verification - RMST level primary Beyond Design Basis for Flood
2. CTMT Pressure	A. Identify LOCA B. CTMT Integrity CSP C. Adverse CTMT for Instrumentation	A. Short Term ≤ 20 min B. Long Term C. Long Term	(A-1) CTMT Radiation (A-2) CTMT Sump None CTMT Temperature	CTMT Pressure not affected by current leakage
3. Subcooling	A. SI Termination and Re-initiation B. CSP Monitor C. RCP Trip	A. Long Term B. Long Term D. Short Term ≤ 15 min	(A-1) PZR level (A-2) RCS Pressure (WR) (A-3) PZR Pressure None CTMT Pressure	Needed, Needs RCS Pressure + Temperature, margin available Trip on Adverse CTMT as backup
4. WR RCS Pressure	A. SI Termination, <i>trend only</i> B. RCS Subcooling C. CSP Integrity D. <i>ALL Pump Stop</i>	A. Long Term B. Long Term C. Long Term D. Long Term	(A-1) PZR level (A-2) PZR Pressure, backup PZR Pressure PZR Pressure	Needed or backup Not /Dm <i>Not required action</i>
5. WRT (HOT)	A. RCS Subcooling	A. Long Term	(A-1) Core Exit TC (A-2) WRT (Cold) (A-3) SI Pressure	Needed, Unit 1

REV 24 FEB 84:18 MCC-CTMT 4889

0064093

0064094

TABLE (continued)

PARAMETER	FUNCTION	TIME	DIVERSE PARAMETER	COMMENTS
6. WRT (Cold)	A. RCS Subcooling Backup to WRT/(IDT) B. Integrity CSF (PTS)	A. Long Term B. Long Term	(A-1) Core Exit T: (A-2) WRT (lbft) (A-3) SJ Pressure NONE	Backup only NOT IRR, operator information Backup only
7. MR SJ Level	A. Backup to MR level	A. Long Term	(A-1) MR SJ Level (A-2) APW Flow	Backup only
8. MR SJ Level	A. Verify heat sink for CSF, LOCA/STEAM Line Break	A. Long Term	(A-1) APW Flow (A-2) MR SJ Level	Needed, or Backup, one SJ required for heat sink
9. PZR Level	A. SJ Circulation & re-initiation B. CSF Inventory	A. Long Term B. Long Term	(A-2) RCS Subcooling (A-2) MR RCS Pressure (A-3) PZR Pressure NONE	No actions solely on PZR level Above 1700 psig only Only yellow path which is not required
10. CTRC	A. Desuperheate Core Cooling B. RCS Subcooling	A. Long Term B. Long Term	MR T (Hot) (P-1) MR T (THOT) (P-2) MR T (COLD) (I-3) SJ Pressure	Not DRB Unit 2 Only
11. CTRC Radiation	A. Identify LOCA Backup only B. Advise CTRC for Instrumentation C. CTRC Monitor for CSF	A. Short Term < 20 min B. Long Term C. Long Term	(I-1) CTRC Samp (I-2) CTRC Pressure Sample CTRC Atmosphere Sample CTRC Atmosphere	Backup only To unisolate CTRC Backup only
12. CTRC Temp.	A. Backup to CTRC Pressures for Advise CTRC Instrumentation	A. Long Term	CTR Pressure	

not addressed in WCAP 14038, Listed here only as potential backup instrument.

TABLE (continued)

ASSUMPTIONS

- 1) All Rx Trip/ESF in WCAP are HEAVY TRIP. They perform their function before they see a significant adverse CMT. Even 30 level for Rx trip and PER Pressure SI perform their function before they see a significant adverse CMT.
- 2) Short Term: 5 minutes Rx Trip/ESF
 30 minutes other short term
 Long Term covers entire accident
- 3) If instruments are required (column 6) for a DMA to reach Safe Shutdown.
 - 12 are in a hard environment - see pages 1 thru 4
 - 4 are in a mild environment (not listed in Table)
 - APD Flow
 - 30 Pressure
 - BATT Level
 - COT Level
- 4) Any other instruments required for post-accident monitoring (WCAP) are not required for DMA to reach Safe Shutdown.

0064095

TERMINAL BLOCK IR IS TEMPERATURE
FROM SAIL REPORT SAND 03-10-17
FIG. A1-21 A. 110 PHASE 2, 15771000


NOV 24 '87 06:28 JCS-SPT 48391 C2022

20110 42/11 P.0

0064096

Figure 1

Attachment 2




This curve is based on FSAR
Curves Figures 6.2-11, 6.2-13,
and 6.2-40.

FIGURE 3.0-1

COMPOSITE LOC/REL

CONTAINMENT VAPOR TEMPERATURE ENVELOPE



November 24, 1987

TO: JOHN GARLINGTON

FROM: JESSE LOVE

IR vs TEMPERATURE SUPPORTING INFORMATION FOR JCO

As documented in numerous valid test reports, conducted by Wyle, SNL and other industrial test organizations, electrical cable and terminal blocks exhibit generic characteristics with regard to insulation resistance (IR) versus temperature during simulated LOCA/MSLB test conditions. The generic characteristic is that IR values are inversely proportional to temperature i.e. lower temperature yields higher value of IR. Conversely with regard to leakage current, leakage current is directly proportional to temperature. SNL Report SAND 83-1617 provides numerous data representations which demonstrate this accepted phenomenon.

Figure 1 of Westinghouse letter dated 11/23/87 was made from plots of SAND83-1617 (SNL) Phase II test data for exposure of G.E. EB25 terminal blocks to the SNL Phase II simulated LOCA/MSLB profile. (Attached Figure 2, Pg. 9 of SAND83-1617). IR test data for an EB25 block was used from the SNL report as there were no States IWM, or CR151B blocks tested by SNL in Phase II, and the CR151B block is smaller to those FNP installed blocks. Phase I data which did record leakage currents and IR values for States IWM and CR151B blocks was not used due to the inaccuracies associated with the SNL electrical test circuitry that measured leakage current values during Phase I testing.

The minimum values of IR and corresponding high leakage currents recorded in the referenced SNL test results are extremely conservative, and are not representative of values that would be expected at FNP during LOCA/MSLB design basis events. Minimum values of terminal block IR values higher than those recorded in the SNL report are supported by COMAT Text Report IPS-107, and Wyle Report No.s 17775-1 and 17733-1 for MSLB/LOCA temperatures relevant to FNP.




Figure 2

223

0064099

Attachment 3
Figure 1




Figure 2

TOTAL SHIPBOARD TIME

Phase II Development of Shipboard Time

B-11

B-12

