



An EDISON INTERNATIONAL Company

R. W. Krieger
Vice President
Nuclear Generation

March 8, 1996

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Subject: Docket Nos. 50-361 and 50-362
30 Day Report
Licensee Event Report No. 96-002
San Onofre Nuclear Generating Station, Units 2 and 3

This submittal provides a written Licensee Event Report (LER) for a condition that could potentially cause the logarithmic power level indication to become decalibrated. Since this condition is applicable to Units 2 and 3, a single report for Unit 2 is being submitted in accordance with NUREG-1022. Neither the health nor the safety of plant personnel or the public was affected by this occurrence.

Sincerely,

A handwritten signature in cursive script, appearing to read "R. W. Krieger".

Enclosure: LER No. 96-002

cc: L. J. Callan, Regional Administrator, NRC Region IV
J. E. Dyer, Director, Division of Reactor Projects, NRC
Region IV
K. E. Perkins, Jr., Director, Walnut Creek Field Office, NRC
Region IV
J. A. Sloan, NRC Senior Resident Inspector, San Onofre Units
2 & 3
M. B. Fields, NRC Project Manager, San Onofre Units 2 and 3
Institute of Nuclear Power Operations (INPO)

9603120466 960308
PDR ADOCK 05000361
S PDR

P. O. Box 128
San Clemente, CA 92674
714-368-6255
Fax 714-368-6183

JE22

LICENSEE EVENT REPORT (LER)

Facility Name (1) SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 2										Docket Number (2) 0 5 0 0 0 3 6 1				Page (3) 1 of 0 1																																																									
Title (4) Potential Decalibration of Logarithmic Power Level Instrumentation																																																																							
EVENT DATE (5)			LER NUMBER (6)					REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																																																												
Month	Day	Year	Year	///	Sequential Number	///	Revision Number	Month	Day	Year	Facility Names				Docket Number(s)																																																								
0	2	0	9	9	6	9	6	---	0	0	2	---	0	0	0	3	6	2																																																					
OPERATING MODE (9) 1			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)																																																																				
POWER LEVEL (10) 0 9 9			20.402(b)					20.40(c)					50.73(a)(2)(iv)					73.71(b)																																																					
			20.405(a)(1)(i)					50.36(c)(i)					50.73(a)(2)(v)					73.71(c)																																																					
			20.405(a)(1)(ii)					50.36(c)(2)					50.73(a)(2)(vii)					X Other (Specify in																																																					
			20.405(a)(1)(iii)					50.73(a)(2)(i)					50.73(a)(2)(viii)(A)					Abstract below and																																																					
			20.405(a)(1)(iv)					50.73(a)(2)(ii)					50.73(a)(2)(viii)(B)					in text)																																																					
			20.405(a)(1)(v)					50.73(a)(2)(iii)					50.73(a)(2)(x)					10CFR21																																																					
<div style="text-align: center;">LICENSEE CONTACT FOR THIS LER (12)</div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="10">Name R. W. Krieger, Vice President, Nuclear Generation</td> <td colspan="8">TELEPHONE NUMBER</td> </tr> <tr> <td colspan="10"></td> <td colspan="2">AREA CODE</td> <td colspan="6"></td> </tr> <tr> <td colspan="10"></td> <td colspan="2">7 1 4</td> <td colspan="6">3 6 8 - 6 2 5 5</td> </tr> </table>																		Name R. W. Krieger, Vice President, Nuclear Generation										TELEPHONE NUMBER																		AREA CODE																		7 1 4		3 6 8 - 6 2 5 5					
Name R. W. Krieger, Vice President, Nuclear Generation										TELEPHONE NUMBER																																																													
										AREA CODE																																																													
										7 1 4		3 6 8 - 6 2 5 5																																																											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																																																							
CAUSE	SYSTEM	COMPONENT	MANUFAC.-	REPORTABLE	////////	CAUSE	SYSTEM	COMPONENT	MANUFAC.-	REPORTABLE	////////																																																												
			TRUER	TO NPRDS	////////				TRUER	TO NPRDS	////////																																																												
					////////						////////																																																												
					////////						////////																																																												
SUPPLEMENTAL REPORT EXPECTED (14)												Expected Submission Date (15)		Month Day Year																																																									
Yes (If yes, complete EXPECTED SUBMISSION DATE)												X NO																																																											

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 2/9/96, ABB Combustion Engineering (CE) notified Edison that a potential non-conservatism in the calibration of logarithmic (log) power channels [IG] reported by the Waterford Station (Waterford LER 50-382/96-003) may exist at San Onofre Units 2 and 3. At 10:45 PST, Edison determined that the Waterford condition did apply to SONGS 2 and 3, and existed during previous plant startups. Edison provided a 10CFR50.72(b)(2)(iii)(D) report to the NRC at 1427 PST (Log No. 29965).

This condition resulted from calibrating the log power channels at 100% power (chosen to allow correlation to plant power from heat balance methods). While this method is accurate at full power, physics effects may cause the log power indication to vary significantly from actual plant power during low power operation (CEA position, temperature shadowing, boron changes, etc.). CE estimated these effects could cause the log power trip [JC] to be high by a factor of two but less than a factor of 10. Due to the passage of time, it is not known why these effects were not considered in the original CE calculation (circa 1980).

Edison will reduce the trip setpoint by a factor of 10 until the effects have been confirmed by analyses. If either unit is shutdown prior to adjusting the trip setpoint (trip required only during startup), the reactor trip breakers will remain open until the setpoints are adjusted. Edison is working with CE for a long term solution.

Edison believes the setpoint analysis will likely confirm the original trip setpoints were acceptable. There have been no instances in the past which would have required a high log power trip at either unit and the safety significance is believed to be minimal. If the analysis determines otherwise, Edison will revise this LER. Edison has not reported any similar events in the past three years.