

Georgia Power Company  
333 Piedmont Avenue  
Atlanta, Georgia 30308  
Telephone 404 526-6526

Mailing Address:  
Post Office Box 4545  
Atlanta, Georgia 30302

L. T. Gucwa  
Manager Nuclear Engineering  
and Chief Nuclear Engineer

34 NOV 29 AIO: 16



November 21, 1984

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II - Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30323

REFERENCE:  
RII: JPO  
50-321  
I&E Bulletin  
80-13

ATTENTION: Mr. James P. O'Reilly

GENTLEMEN:

Pursuant to the requirements of I&E Bulletin 80-13, "Cracking in Core Spray Spargers", visual inspection of the Hatch Unit 1 core spray spargers and associated piping has been performed during the refueling/maintenance outage currently in progress. A remote, underwater television camera (having the required capability of in situ viewing of 0.001 inch fine wires) was used for the inspection.

A circumferential crack was discovered in the heat-affected zone of the lower sparger to T-box weld (approximately 1/8 inch from the weld). It spans at least 180° of circumference and is approximately 0.010 inch wide.

Evaluation of the cracking has been performed by General Electric Company. The cause is suspected to be stress corrosion cracking resulting from cold work and sensitization during fabrication and installation of the sparger. An analysis was performed to determine the acceptability of continued operation, using the conservative assumptions that the crack spanned 360° of circumference, was through-wall, and that no clamping device was installed on the sparger. The analysis considered structural effects, the possibility of loose parts, and the effect on LOCA analysis. It was demonstrated that operation with the core spray sparger in the conservatively assumed condition would not result in any safety concern. A report documenting the evaluation performed will be transmitted prior to unit startup.

8412210158 841121  
PDR ADOCK 05000321  
Q PDR


1/0 IEN

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II - Suite 2900  
November 21, 1984  
Page 2

Although the analysis shows that it is not necessary, GPC has elected to install a clamping device designed to maintain the structural integrity of the sparger. Installation of this device will provide added assurance that continued operation will result in no safety concern.

Please contact this office if there are any questions.

Very truly yours,



L. T. Gucwa

JH/jh

xc: J. T. Beckham, Jr.  
H. C. Nix, Jr.  
Senior Resident Inspector  
NRC Office of Inspection and Enforcement, Division of Reactor Operations  
Inspection