

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Surry Power Station, Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 2 8 1				PAGE (3) 1 OF 0 3											
TITLE (4) Reactor Trip-Feedwater Isolation																									
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)															
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)												
1	1	2	0	8	4	8	4	0	1	6	0	0	1	2	2	0	8	4	0	5	0	0	0		
OPERATING MODE (9) N		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																							
POWER LEVEL (10) 0 2 1		20.402(b)				20.405(c)				<input checked="" type="checkbox"/> 50.73(a)(2)(iv)				73.71(b)											
		20.405(a)(1)(i)				50.38(c)(1)				<input type="checkbox"/> 50.73(a)(2)(v)				73.71(c)											
		20.405(a)(1)(ii)				50.38(c)(2)				<input type="checkbox"/> 50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)											
		20.405(a)(1)(iii)				50.73(a)(2)(i)				<input type="checkbox"/> 50.73(a)(2)(viii)(A)															
		20.405(a)(1)(iv)				50.73(a)(2)(ii)				<input type="checkbox"/> 50.73(a)(2)(viii)(B)															
		20.405(a)(1)(v)				50.73(a)(2)(iii)				<input type="checkbox"/> 50.73(a)(2)(ix)															
LICENSEE CONTACT FOR THIS LER (12)																									
NAME R. F. Saunders, Station Manager										TELEPHONE NUMBER AREA CODE 8 0 4 3 5 7 - 3 1 8 4															
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC															
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR									
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)												<input checked="" type="checkbox"/> NO													

ABSTRACT (Limit to 1000 characters, i.e., approximately fifteen single space typewritten lines) (16)

With reactor power at 21 percent and increasing, the reactor tripped on low water level in "C" steam generator. The low level in "C" steam generator was caused when a unit startup was commenced with the main feedwater manual isolation valves closed. This was due to both a loss of administrative control and personnel error.

Administrative controls (startup procedures) are being modified to include a verification of feedwater valve position and precautions to personnel to use Control Board mounted tagging notes. Personnel involved were also re-instructed in correct plant practices. In addition, Vepco's Human Performance Evaluation System (HPES) was utilized to investigate and make recommendations on improving personnel performance.

8412310464 841220  
PDR ADOCK 05000281  
S PDR

IE22

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)  Surry Power Station, Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 2 8 1 8 4 - 0 1 6 - 0 0 0 2 OF 0 3	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

1. Description of the Event

On November 20, 1984, a unit two startup was in progress after a maintenance outage with the reactor power at 21% and turbine power at 44 MWe. Feedwater control was in manual and the transition from the bypass to the main feed regulating valves (FRV) (EILS FCV) was commenced on "C" steam generator in response to a low water level. At the same time, the operator had accelerated the turbine ramp rate in an attempt to eliminate an indicated anti-motoring turbine trip alarm. The "C" FRV indicated approximately 80% open demand when the operator noticed no feedwater flow. Upon local inspection, the manual isolation valves for main feedwater to all steam generators were discovered closed.

An attempt was made to unisolate main feedwater flow to increase steam generator water level, but a reactor trip ensued as a result of low water level in "C" steam generator at approximately 0419 hours.

During this event, all control and safety systems functioned properly. Operators followed appropriate plant procedures and stabilized the plant following the reactor trip.

2. Safety Consequences and Implications

The worst case loss of feedwater accident, as analyzed in the UFSAR, assumes a reactor power of 102% with low water level in all steam generators. This analysis does not result in any adverse condition in the core, because it does not result in water relief from the pressurizer reliefs or the safety valves, nor does it result in an uncovering of the tube sheets of the steam generators.

Prior to this reactor trip, reactor power was approximately 21%. Feedwater remained available via the main feed by-pass lines and the auxiliary feedwater system. During this event, all safety related systems remained operable and plant parameters remained within the bounds of the accident analysis. Therefore, this event did not constitute an unreviewed safety question or effect the health and safety of the public.

3. Cause

The cause of the low level in "C" steam generator was due to an increasing power level with the manual feedwater isolation valves closed. These valves were closed by direction of Periodic Test 15.3 (Main and Auxiliary Feedwater Cold Shutdown Check Valve Test) which was completed during the maintenance outage. These valves were not reopened to minimized the possibility of overfilling the steam generator.

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)  Surry Power Station, Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 2 8 1 8 4 - 0 1 6 - 0 0 0 3 OF 0 3	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The manual feedwater isolation valves remained closed during startup due to:

- 1) Failure of operators to convey and track off normal plant status.
- 2) Failure to follow administrative procedures.

4. Immediate Corrective Action

An unsuccessful attempt was made to open the manual isolation valves to increase steam generator level.

5. Additional Corrective Action

Following the reactor trip, the operators performed all appropriate emergency procedures and function restoration procedures to ensure the plant was returned to a stable condition. Also, the STA performed the status tree reviews to ensure specific plant parameters were noted and appropriate procedures were used to maintain those parameters within safe bounds.


6. Action Taken to Prevent Recurrence

The following actions were initiated:

- 1) The plant startup procedures are being modified to include checking feedwater valve positions and stroke testing feedwater valves. Precautions are also being added to remind personnel to use control board mounted tagging notes.
- 2) Personnel involved were re-instructed in correct plant practices, for maintaining administrative control of off normal plant conditions.
- 3) Training for plant operators will include material concerning this event.
- 4) Vepco's implementation of INPO's Human Performance Evaluation System (HPES) was used to investigate and to make recommendations on improving personnel performance.

7. Generic Implications

None.



# Vepco

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station  
P. O. Box 315  
Surry, Virginia 23883

DEC 20 1984

Serial No: 84-041

Docket No: 50-281

License No: DPR-37

U. S. Nuclear Regulatory Commission  
Document Control Desk  
016 Phillips Building  
Washington, D.C. 20555

Gentlemen:

Pursuant to Surry Power Station Technical Specifications, the Virginia Electric and Power Company hereby submits the following Licensee Event Report for Surry Unit 2.

REPORT NUMBER

84-016-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be reviewed by Safety Evaluation and Control.

Very truly yours,

*R. F. Saunders*

R. F. Saunders  
Station Manager

Enclosure

cc: Mr. James P. O'Reilly  
Regional Administrator  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30323

IE 22  
11