

OYSTER CREEK NUCLEAR GENERATING STATION
Forked River, NJ 08731

Licensee Event Report Update
Reportable Occurrence No. 50-219/83-09/01X-2

Report Date

January 22, 1985

Previous Report Date

November 2, 1984

Occurrence Date

February 22, 1983

Identification of Occurrence

The results of local leak rate testing identified ten containment isolation valves and one gasket that failed to meet their acceptance criteria. This constitutes operation of the unit or affected systems when any parameter or operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in Technical Specifications, paragraph 4.5.F.d.

This event is considered to be reportable as defined in Technical Specification, paragraph 6.9.2.a.2.

Conditions Prior to Occurrence

The plant was in cold shutdown with reactor coolant temperature less than 212°F and the reactor vented at the time the occurrence was identified. The reactor was in various operating modes prior to the occurrence.

Description of Occurrence

Local leak rate testing identified the following ten (10) valves and one (1) gasket with leakage in excess of the acceptance criteria of 12.08 SCFH @20 psig. The results of the leak rate test program for these valves and gasket are as follows:

| <u>DESCRIPTION</u> | <u>PENETRATION</u> | <u>DATE TESTED</u> | <u>LEAKAGE @20 PSIG (SCFH)</u> |
|---------------------------------------|--------------------|--------------------|--------------------------------|
| Instrument Air and Nitrogen System | V-6-395 | 3/4/83 | 30.49 |
| MSIV | NS04A | 2/14/83 | 16.34 |
| MSIV | NS04B | 2/14/83 | 17.21 |
| MSIV Drain Valves | V-1-106, 107 | 2/14/83 | 19.44 |
| Drywell Headseal | Gasket | 2/16/83 | 544.68 |
| Drywell Purge | V-27-1 | 2/18/83 | 34.08 |
| Drywell Sump Discharge | V-22-28, 29 | 3/17/83 | 12.4 |
| Drywell Vent | V-27-3, 4 | 2/27/83 | 23.19 |

Apparent Cause of Occurrence

The cause of the leakage is as follows:

- I. V-6-395, V-1-106, V-1-107, V-22-28, V-22-29, V-27-3, V-27-4, NS04A, and NS04B had deterioration of valve internals.
- II. Drywell Headseal - cause unknown, seal appeared to be in good condition.
- III. V-27-1 stem was found to be out of proper alignment.

Analysis of Occurrence

For valves V-27-1, V-6-395, NS04A, NS04B, V-1-106, and V-1-107 at least one redundant valve for each containment penetration met the acceptance criteria.

The purpose of the Containment System is to provide a barrier to limit the release of radioactive material to the environment to less than 10CFR100 limits during design basis accident conditions. The failure of Containment Isolation Valves V-27-3, 4 and the Drywell Head Seal Gasket to meet required acceptance criteria could have resulted in these limits being exceeded. All other individual containment isolation valves which failed leak testing were in series with other redundant isolation valves which did meet the acceptance criteria.

Corrective Action

Valves V-1-106, 107, and V-6-395 have been replaced with new valves. NS04A and NS04B had their seats lapped, stems replaced, and packing changed. V-27-1 stem was adjusted. V-22-28 received a new seat, stem, and plug. V-22-29 had its seat lapped. V-27-3, 4 received new seats and the Drywell Head had a new seal installed.

All penetrations passed their subsequent Local Leak Rate Tests.

NRC FORM 356
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J O C P I 1 2 0 0 1 - 0 0 0 b 1 0 1 - 1 d 0 3 4 1 1 1 1 4 1 5
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

01 REPORT SOURCE 0 1 5 10 10 10 12 1 1 9 7 0 1 2 2 2 8 13 8 0 1 1 2 2 8 5 9
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 02 Local leak rate testing revealed that ten containment isolation valves
 03 and one gasket failed to meet their acceptance criteria. The failure of
 04 Drywell Vent Isolation Valves V-27-3 and 4 and Drywell Head gasket to
 05 meet required acceptance criteria could have resulted in exceeding 10CFR
 06 100 limits during design basis accident conditions. All other contain-
 07 ment isolation valves failing leak testing were in series with redundant
 08 valves which passed. Reportable per Tech Specs, paragraph 6.9.2.a.2.
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

09 SYSTEM CODE 11 CAUSE CODE 12 CAUSE SUBCODE 13 COMPONENT CODE 14 CUMP SUBCODE 15 VALVE SUBCODE 16
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 LE/R/O REPORT NUMBER 18 EVENT YEAR 19 SEQUENTIAL REPORT NO. 20 OCCURRENCE CODE 21 REPORT TYPE 22 REVISION NO.
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTION TAKEN 18 FUTURE ACTION 19 EFFECT ON PLANT 20 SHUTDOWN METHOD 21 HOURS 22 ATTACHMENT SUBMITTED 23 APPROX. FORMS/HR 24 PRIME COMP. SUPPLIER 25 COMPONENT MANUFACTURE
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 10 Drywell Purge valve V-27-1 stem was out of alignment. Other valves had
 11 deterioration of internals. All valves were either repaired or replaced.
 12 Although appearing to be in good condition, the Drywell head gasket was
 13 replaced. All penetrations passed their subsequent local leak rate
 14 tests.
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

15 FACILITY STATUS 16 POWER 17 OTHER STATUS 18 METHOD OF DISCOVERY 19 DISCOVERY DESCRIPTION 20
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

16 ACTIVITY CONTENT 17 RELEASED OF RELEASE 18 AMOUNT OF ACTIVITY 19 LOCATION OF RELEASE 20
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 PERSONNEL EXPOSURES 18 NUMBER 19 TYPE 20 DESCRIPTION 21
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

18 PERSONNEL INJURIES 19 NUMBER 20 DESCRIPTION 21
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100


19 LOSS OF OR DAMAGE TO FACILITY 20 TYPE 21 DESCRIPTION 22
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

20 PUBLICITY 21 DESCRIPTION 22
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

21 ISSUED 22 DESCRIPTION 23
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NRC USE ONLY

NAME OF PREPARED: Kenneth Hutko PHONE: 609-971-4698



GPU Nuclear Corporation
Post Office Box 388
Route 9 South
Forked River, New Jersey 08731-0388
609 971-4000
Writer's Direct Dial Number:

January 22, 1985


U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Dear Sir:

Subject: Oyster Creek Nuclear Generating Station
Docket No. 50-219
Licensee Event Report Update

This letter forwards Reportable Occurrence No. 50-219/83-09/01X-2, a Licensee Event Report (LER) revision, in compliance with paragraph 6.9.2.a.2 of the Technical Specifications. The previous revision of this LER contained incorrect leak rates for three (3) valves (V-27-1, 3 and 4). This occurred due to an administrative error resulting from a procedure revision which had changed the leak rate data sheet number for the above valves.

Very truly yours,


Peter B. Fiedler
Vice President and Director
Oyster Creek

PBF:PC:dam
Enclosures

cc: Dr. Thomas E. Murley, Administrator
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

NRC Resident Inspector
Oyster Creek Nuclear Generating Station
Forked River, NJ 08731

IE22
11