

LICENSEE EVENT REPORT (LER)

Supplement to report dated 9/19/84.

FACILITY NAME (1)
Dresden Nuclear Power Station

DOCKET NUMBER (2)

0 | 5 | 0 | 0 | 0 | 2 | 4 | 9 | 1 | OF | 0 | 2

PAGE (3)

TITLE (4)

Unit 3 Reactor Scram

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)								
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)						
0	8	2	3	8	4	8	4	0	1	2	0	5	0	0	0		
									N/A		0	5	0	0	0		
									N/A		0	5	0	0	0		

OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8: (Check one or more of the following) (11)														
POWER LEVEL (10)	0	0	4	20.402(b)			20.405(e)			<input checked="" type="checkbox"/> 80.73(a)(2)(iv)			73.71(b)			
				20.405(a)(1)(i)			80.36(e)(1)			80.73(a)(2)(v)			73.71(c)			
				20.405(a)(1)(ii)			80.36(e)(2)			80.73(a)(2)(vi)			OTHER (Specify in Abstract below and in Text, NRC Form 305A)			
				20.405(a)(1)(iii)			80.73(a)(2)(i)			80.73(a)(2)(vii)(A)						
				20.405(a)(1)(iv)			80.73(a)(2)(ii)			80.73(a)(2)(vii)(B)						
20.405(a)(1)(v)			80.73(a)(2)(iii)			80.73(a)(2)(iii)			80.73(a)(2)(ix)							

LICENSEE CONTACT FOR THIS LER (12)									
NAME						TELEPHONE NUMBER			
Mark Leahy (X-422)						8 1 5 9 4 2 - 1 2 9 2 0			

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
A				N					

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During a manual power reduction, the unit Operator failed to insert the IRM's in a timely manner. When the IRM's were inserted, the unit scrambled on IRM high-high with companion APRM downscale. Safety significance was minimal, as the reactor protection system worked as designed. This was the first reportable occurrence of this type at Dresden Station.

The event resulted from insufficient familiarity of the unit Operator with the shutdown procedure, caused primarily by his lack of experience as an Operator. In order to prevent a recurrence of this type of event, the Operating Engineer reviewed the event with the Operator. In addition, a letter will be issued to all licensed personnel. This letter will reiterate the need for Operators to be familiar with and to be able to anticipate events in procedures that they are about to perform, and to remind shift management to review procedures with shift personnel, especially those new to their position. This letter will be discussed during six week Operator training.

8502040307 850110
PDR ADOCK 05000249
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1) Dresden Nuclear Power Station	DOCKET NUMBER (2) 0 5 0 0 0 2 4 9 8 4 - 0 1 2 - 0 1	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
					Q 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 386A's) (17)

During a manual power reduction, the unit Operator failed to insert the IRM's prior to the APRM's going downscale. The Operator inserted the IRM's with the IRM range switches on low range, which resulted in a scram due to IRM high-high with companion APRM downscale. Safety significance was minimal as all RPS systems operated properly. This is the first reportable occurrence of this type at Dresden Station.

In lieu of a Professionalism Committee review, an informal review was conducted by the unit Operating Engineer and the following conclusions and corrective actions were determined.

The event resulted from insufficient familiarity of the unit Operator with the shutdown procedure, caused primarily by his lack of experience as an Operator. In order to prevent a recurrence of this type of event, the Operating Engineer reviewed the event with the Operator. In addition, a letter will be issued to all licensed personnel. This letter will reiterate the need for Operators to be familiar with and to be able to anticipate events in procedures that they are about to perform, and to remind shift management to review procedures with shift personnel, especially those new to their position. This letter will be discussed during six week Operator training.

SUPPLEMENTAL REPORT TO DIR/LER

DVR NO.

STA

UNIT

YEAR

NO.

D-12

-

3

-

84

-

34

PART 1 TITLE OF EVENT

OCCURRED

Reactor Scram

8/23/84

1846

DATE

TIME

REASON FOR SUPPLEMENTAL REPORT

To update corrective actions. Supplements report dated 9/19/84.

PART 2

ACCEPTANCE BY STATION REVIEW

DATE

SUPPLEMENTAL REPORT APPROVED
AND AUTHORIZED FOR DISTRIBUTION

J. Brunner *JA Cusla*
11/11/85 1/16/85
Douglas Duro
STATION SUPERINTENDENT

1/22/85
DATE



Commonwealth Edison

Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

January 10, 1985

DJS LTR #85-40

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Revised Licensee Event Report #84-012-1, Docket #050249 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(iv). This revised report is provided to update the corrective actions.

D. G. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III
File/NRC
File/Numerical

IE22
1/1