

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) R.E. Ginna Nuclear Power Plant - Unit #1										DOCKET NUMBER (2) 0 5 0 0 0 2 4 4				PAGE (3) 1 OF 0 2												
TITLE (4) Computer Rod Position Deviation Alarm																										
EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)													
0	1	1	6	8	5	8	5	0	0	1	0	0	0	2	1	5	8	5	0	5	0	0	0	2	4	4
OPERATING MODE (9) N		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8: (Check one or more of the following) (11)																								
POWER LEVEL (10) 1 0 0		20.402(b)				20.406(e)				80.73(a)(2)(iv)				73.71(b)												
		20.406(a)(1)(i)				80.38(a)(1)				80.73(a)(2)(v)				73.71(e)												
		20.406(a)(1)(ii)				80.38(a)(2)				80.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Text, NRC Form 308A)												
		20.406(a)(1)(iii)				X 80.73(a)(2)(i)				80.73(a)(2)(vii)(A)																
		20.406(a)(1)(iv)				80.73(a)(2)(ii)				80.75(a)(2)(vii)(B)																
		20.406(a)(1)(v)				80.73(a)(2)(iii)				80.75(a)(2)(ix)																
LICENSEE CONTACT FOR THIS LER (12)																										
NAME E.J. Beatty, Operations Supervisor										TELEPHONE NUMBER 3 1 5 5 2 4 - 4 4 4 6																
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC																
A	I	D	-	C	P	U	W	1	2	0	N															
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR										
YES (If yes, complete EXPECTED SUBMISSION DATE)												X NO														

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 01/16/85 a series of blown fuses in the computer resulted in actuation of about 90 alarms on the Computer Alarm Typewriter at the time that I&C technicians were removing and restoring Foxboro channels for Periodic Test procedures. The computer technician was swapping trend and log typewriters.

A printout alerting the operator to Control Rod Banks not being updated at 1200 hours went unnoticed due to previous alarm activity. Subsequent printouts for Rods not updated occurred and this printout was detected when the afternoon shift operator attempted to perform the computer program check at 1634 hours. The Rod Banks were updated at 1703 hours. Procedure S-26.2 (Computer Out of Service) and Technical Specification Table 4.1-1 Item #9 dictates that Control Rod Position Indicators should be initiated within 4 hours of the alarm.

8502220405 850215
PDR ADOCK 05000244
S PDR

IE 22
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1) R.E. Ginna Nuclear Power Plant Unit #1	DOCKET NUMBER (2) 0 5 0 0 0 2 4 4				LER NUMBER (6)			PAGE (3)		
					YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
					8 5	- 0 0 1	- 0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 368A's) (17)

On 01/16/85 at 0756 hours the "Computer Rod Deviation" alarm was satisfactorily tested. At 0833 hours I&C Technicians removed Foxboro Channel 4 from scan to complete PT-5.40 (Process Instrumentation Reactor Protection Channel Trip Test). At the same time the Computer Technician was swapping trend and log typewriter devices. At 1000 hours and 1100 hours the rod position monitor was functional. At 1102 hours indication of about 90 alarms came in on the Computer Alarm Typewriter as a result of a blown fuse in the computer. A Foxboro channel was added to scan at about the same time. At 1200 hours a printout (no alarm) was displayed that Control Rod Banks were not updated. The operator failed to detect this printout and subsequent printouts on the typewriter device, alluding to the Control Rod Banks not updated, since they were not audibly alarmed.

At 1253 hours Foxboro Channel 1 was removed from scan and the same series of about 90 alarms reoccurred. Another blown fuse was found to be the cause. Further printouts followed indicating Control Rod Banks were not updated.

The afternoon shift, during the computer program check, identified the problem at 1634 hours and updated the computer at 1703 hours.

According to procedure S-26.2 and Technical Specifications Table 4.1-1 Item #9 Control Rod Position Indicators should be hand logged within 4 hours of the initial printout (or the program updated) by 1600 hours.

Although the event falls into the category of personnel error, it is felt that contributing factors include the unforeseen possibility of the failure of fuses concurrent with a Periodic Test well known for the excessive activity of audible alarms. A possible corrective Action plan should include increasing the frequency of the computer check (since this action identified the problem) to every 4 hours rather than once per shift.



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001

ROGER W. KOBER
VICE PRESIDENT
ELECTRIC & STEAM PRODUCTION

TELEPHONE
AREA CODE 716 546-2700


February 15, 1985

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: LER 85-001, Inoperable Analog Rod Position (Computer
Rod Position Deviation Alarm)
R.E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

In accordance with 10 CFR 50.73, Licensee Event Report
System, item (a)(2)(i)(B) which requests a report of, "any operation
or conditions prohibited by the plant Technical Specification",
the attached Licensee Event Report LER 85-001 is hereby submitted.

Very truly yours,


Roger W. Kober

RWK/eeg

xc: U.S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

IE22
1/1