

M S D inc.  
700 Orange St.  
Darlington, SC 29532  
Engineering Department  
(803) 393-5421 Fax (803) 393-4123

April 19, 1996

FAX TO:  
U.S. Nuclear Regulatory Commission  
Operations Center

SUBJECT: Report of discovered defect

Gentlemen;

It has come to our attention that a quantity of Struthers-Dunn type 236APX135NE time delay relays built in 1983 have incorrect coils in them. Specifically, the affected relays contain 39 gauge coils, they should have 43 gauge. As a result, the coils consume several times the required power which is dissipated as heat, and upon prolonged energization may overheat to the point of self-destruction. We have one such occurrence to date.

We believe the defect was caused by person or persons who relied on memory rather than documentation when building these devices. They were intended for use on 125 volt DC circuits; the coils installed are those normally used on 120 volt AC. Since the relays would function properly for brief periods, the defect was obviously overlooked.

To date we have found nine relays as described, all at Georgia Power's Plant Hatch. All are date coded 8335, which indicates they were built in the 35th week of 1983. We are of the opinion this was the only time this occurred, but there is no way to prove it. All indications are the documentation in effect at the time was, had been, and still is correct.

Fortunately, these relays' coils are clearly marked, and verification of correct coil gauge can be accomplished with a visual inspection. The markings consist of the basic coil part number which may be either 45769 or 45770, followed by a dash, followed by the wire gauge number. Some gauges, such as the 43, may be followed by a letter (43 is usually followed by "C"). On the 45769, the wire code is followed by "X". Thus, the incorrect coils are marked 45769-39X; a correct coil for this relay would be marked either 45769-43CX or 45770-43C. In any case, the coils are also marked beneath the part number with a four-digit date code. We strongly recommend any facility that may have additional affected product inspect their installations immediately, and to replace any relays found to have incorrect coils. Again, we believe Plant Hatch has the only ones, but we cannot be

9604220366 960419  
PDR ADOCK 05000321  
PDR S

IE1911

certain.

Since the assets of Struthers-Dunn were acquired in 1990 by MSD, inc. there really is no recourse to be taken. At MSD, we feel we have sufficient safeguards in place to prevent occurrences as described above. We also stand ready to render whatever advice or assistance you or any user of these products may require. If anyone has any question or problem, they are invited to call. In addition to the numbers above, my direct phone line is (803) 395 8512. Please feel free to distribute copies of this letter as you see fit.

Sincerely,



Thomas R. Mahaffey  
Product Engrng. Mgr.

cc: J. Steinback  
D. Scimeca  
T. Metzler

## GENERAL INFORMATION or OTHER

EVENT NUMBER: 30322

LICENSEE: MSD, INC  
CITY: DARLINGTON  
COUNTY:  
LICENSE#:  
DOCKET:

REGION: 2  
STATE: SC  
AGREEMENT: Y

NOTIFICATION DATE: 04/19/96  
NOTIFICATION TIME: 12:03 [ET]  
EVENT DATE: 04/19/96  
EVENT TIME: 00:00 [EDT]  
LAST UPDATE DATE: 04/19/96

## NOTIFICATIONS

NRC NOTIFIED BY: MAHAFFEY  
HQ OPS OFFICER: BOB STRANSKY

VERN HODGE

NRR

EMERGENCY CLASS: NOT APPLICABLE  
10 CFR SECTION:  
CDEF 21.21(b)(2) DEFECTS/NONCOMPLIANCE

## EVENT TEXT

PART 21 REPORT - INCORRECT COILS INSTALLED IN TIME DELAY RELAYS

THE FOLLOWING IS TEXT EXCERPTED FROM A FACSIMILE SUBMITTED BY THE VENDOR:

"IT HAS COME TO OUR ATTENTION THAT A QUANTITY OF STRUTHERS-DUNN TYPE 236ABX135NE TIME DELAY RELAYS BUILT IN 1983 HAVE INCORRECT COILS IN THEM. SPECIFICALLY, THE AFFECTED RELAYS CONTAIN 39 GAUGE COILS; THEY SHOULD HAVE 43 GAUGE. AS A RESULT, THE COILS CONSUME SEVERAL TIMES THE REQUIRED POWER WHICH IS DISSIPATED AS HEAT, AND UPON PROLONGED ENERGIZATION MAY OVERHEAT TO THE POINT OF SELF-DESTRUCTION. WE HAVE ONE SUCH OCCURRENCE TO DATE.

WE BELIEVE THE DEFECT WAS CAUSED BY PERSON OR PERSONS WHO RELIED ON MEMORY RATHER THAN DOCUMENTATION WHEN BUILDING THESE DEVICES. THEY WERE INTENDED FOR USE ON 125 VOLT DC CIRCUITS; THE COILS INSTALLED ARE THOSE NORMALLY USED ON 120 VOLT AC. SINCE THE RELAYS WOULD FUNCTION PROPERLY FOR BRIEF PERIODS, THE DEFECT WAS OBVIOUSLY OVERLOOKED.

TO DATE, WE HAVE FOUND NINE RELAYS AS DESCRIBED, ALL AT GEORGIA POWER'S PLANT HATCH. ALL ARE DATE CODED 8335 WHICH INDICATES THEY WERE BUILT IN THE 35TH WEEK OF 1983. WE ARE OF THE OPINION THIS WAS THE ONLY TIME THIS OCCURRED, BUT THERE IS NO WAY TO PROVE IT ... FORTUNATELY, THESE RELAYS' COILS ARE CLEARLY MARKED, AND VERIFICATION OF CORRECT COIL GAUGE CAN BE ACCOMPLISHED WITH A VISUAL INSPECTION ... AGAIN, WE BELIEVE PLANT HATCH HAS THE ONLY ONES, BUT WE CANNOT BE CERTAIN."

THE ASSETS OF STRUTHERS-DUNN WERE PURCHASED IN 1990 BY MSD, INC.

220056

IE19