

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Dresden Nuclear Power Station Unit 2

DOCKET NUMBER (2)

0 5 0 0 0 2 3 7 1 OF 0 2

PAGE (3)

TITLE (4)

Inadvertent Group II Isolation

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)					
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)			
0	1	3	0	8	5	8	5	0	0	5	N/A	0 5 0 0 0		
0	1	3	0	8	5	0	0	2	2	8	8	5	N/A	0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8: (Check one or more of the following) (11)

OPERATING MODE (9)	POWER LEVEL (10)	20.402(b)	20.406(a)(1)(i)	20.406(a)(1)(ii)	20.406(a)(1)(iii)	20.406(a)(1)(iv)	20.406(a)(1)(v)	20.406(a)	80.36(a)(1)	80.36(a)(2)	80.73(a)(2)(i)	80.73(a)(2)(ii)	80.73(a)(2)(iii)	80.73(a)(2)(iv)	80.73(a)(2)(v)	80.73(a)(2)(vi)	80.73(a)(2)(vii)(A)	80.73(a)(2)(vii)(B)	80.73(a)(2)(viii)	80.73(a)(2)(ix)	73.71(b)	73.71(a)	OTHER (Specify in Abstract below and in Text, NRC Form 308A)
N	0 10 10										X												

LICENSEE CONTACT FOR THIS LER (12)
NAME
Leslie Turnquest (X-489)

TELEPHONE NUMBER

AREA CODE

8 1 5 9 4 2 - 2 9 2 10

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM
A				N							

SUPPLEMENTAL REPORT EXPECTED (14)
X YES (If yes, complete EXPECTED SUBMISSION DATE) NO
EXPECTED SUBMISSION DATE (15)
0 4 1 5 8 5

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During a normal refueling outage, a Group II isolation occurred while returning level transmitter 2-263-58B to service. The event was of minimal safety significance since the reactor was defueled and all scrams were jumpered. All systems associated with the Group II functioned as designed.

The root cause of this event is still under investigation at this writing. A supplemental report will be issued when the root cause is determined.

8503120138 850228
PDR ADOCK 05000237
S PDRIE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1) Dresden Nuclear Power Station Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 2 3 7 8 5	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 5	0 0 5	0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 386A's) (17)

During a normal refueling outage on 1/30/85 at 1330, level transmitter 2-263-58B was being returned to service following work by Instrument Mechanics. Upon valving the transmitter back in, a Group II isolation occurred. All systems functioned as designed. Since the reactor was defueled and all scrams were jumpered at the time, the event was of minimal safety significance.

The root cause of this event is still under investigation as of this writing. A supplemental report will be issued when the root cause is determined.




Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

February 28, 1985

DJS Ltr #85-225

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Licensee Event Report #85-005-0, Docket #050237 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(iv).


D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III
File/NRC
File/Numerical

IE22
1/1