

S-D-14  
3/12/85

February 5, 1985

USNRC

'85 MAR 14 11:07

OFFICE OF SECRETARY  
DOCKETING & SERVICE  
BRANCH

UNITED STATES OF AMERICA  
NUCLEAR REGULATORY COMMISSION

BEFORE THE ATOMIC SAFETY AND LICENSING BOARD

In the Matter of )

LONG ISLAND LIGHTING COMPANY )

(Shoreham Nuclear Power Station,  
Unit 1) )

Docket No. 50-322-OL

JOINT TESTIMONY

AND of  
SPENCER H. BUSH, ADAM J. HENRIKSEN, ~~AND PROFESSOR ARTHUR SARSTEN~~  
on  
LOAD CONTENTIONS CONCERNING TDI EMERGENCY DIESEL GENERATORS  
at the  
SHOREHAM NUCLEAR POWER STATION

NUCLEAR REGULATORY COMMISSION

Docket No. 50-322-1 Official Ex. No. Disput 14  
In the matter of LILCO  
Staff ✓ IDENTIFIED ✓  
Applicant ✓ RECEIVED ✓  
Intervenor ✓ REJECTED ✓  
Cont'g Off'r ✓ DATE 3-12-85  
Contractor ✓ Witness Bush  
Other ✓ Reporter W. B. Brown

8503180448 850312  
PDR ADDCK 05000322  
PDR  
Q

Staff Disput 14

## CONTENTS

INTRODUCTION OF WITNESSES .....	1
SCOPE OF TESTIMONY .....	2
SUMMARY OF TESTIMONY .....	3
FATIGUE LIFE OF CRANKSHAFTS IN THE SHOREHAM EDGS.....	3
CYLINDER BLOCKS .....	6
TESTIMONY ON CONTENTIONS .....	9
I - CRANKSHAFT .....	9
Conclusions That May Be Drawn From Confirmatory Testing .....	9
Fatigue Life of Crankshafts in the Shoreham EDGs .....	13
II - CYLINDER BLOCKS .....	23
Monitoring of Cam Gallery Cracks in EDGs 101 and 102 .....	26
Comments on Testing Performed by Walter C. McCrone Associates, Inc. ....	27
Assumptions and Conclusions Regarding Origin and Characteristics of Cam Gallery Cracks .....	27
Conclusions Regarding the Need for Monitoring Cam Gallery Cracks .....	28
Stud-to-Stud Cracks in the Cylinder Block Top .....	31

### INTRODUCTION OF WITNESSES

Q. Please state your names, your business addresses, and your professional qualifications.

A. (Bush) My name is Spencer H. Bush. I am self-employed, under the firm name of Review and Synthesis Associates, Richland, Washington. A summary of my professional qualifications and experience was submitted as Attachment 2 to Volume 1 of the joint testimony filed by the NRC staff in August 1984.

A. (Henriksen) My name is Adam J. Henriksen. I am self-employed, under the firm name of Adam J. Henriksen, Inc., Fox Point, Wisconsin. A summary of my professional qualifications and experience was submitted as Attachment 3 of the joint testimony referenced above.

~~A. (Sarsten) My name is Arthur Sarsten. I am a Professor of Internal Combustion Engines at the Norwegian Institute of Technology, Trondheim, Norway. A summary of my professional qualifications and experience was submitted as Attachment 5 of the joint testimony referenced above.~~

## SCOPE OF TESTIMONY

Q. What is the scope of your testimony?

A. (All) Our testimony addresses the following parts of Suffolk County's load contention as admitted by the Atomic Safety and Licensing Board:

Contrary to the requirements of 10 C.F.R. Part 50, Appendix A, General Design Criterion 17 -- Electric Power Systems, the emergency diesel generators at Shoreham ("EDGs") with a maximum "qualified" load of 3300 kW do not provide sufficient capacity and capability to assure that the requirements of clauses (1) and (2) of the first paragraph of GDC 17 will be met, in that

- (a) LILCO's proposed "qualified load" of 3300 kW is the maximum load at which the EDGs may be operated, but is inadequate to handle the maximum load that may be imposed on the EDGs because:
  - (i) intermittent and cyclic loads are excluded;
  - (ii) diesel load meter instrument error was not considered;
  - (iii) operators are permitted to maintain diesel load at 3300 kW  $\pm$ 100 kW; and
  - (iv) operators may erroneously start additional equipment.
- (c) The EDG qualification test run performed by LILCO was inadequate to assure that EDGs are capable of reliable operation at 3300 kW because:
  - (i) DG 103 block was not subjected to the entire 740 hours of testing;
  - (ii) the test results on the DG 103 block are not transferable to the DG 101 and 102 blocks;
  - (iii) operators were permitted to control the diesel generators at 3300 kW  $\pm$ 100 kW during the test; and
  - (iv) instrument accuracy was not considered.

## SUMMARY OF TESTIMONY

Q. Please summarize your testimony on these contentions.

A. (A11) Our summary testimony is provided under the two subheadings that follow.

### FATIGUE LIFE OF CRANKSHAFTS IN THE SHOREHAM EDGs

From our review of LILCO's testimony and data logs, we believe that EDG 103 was, in fact, operated at a nominal, instrument-indicated load of 3300 kW during that portion of the  $1 \times 10^7$ -cycle confirmatory test claimed by LILCO to have been conducted at the 3300-kW load level. We understand that the wattmeter may oscillate approximately  $\pm 100$  kW around the value at which the load is set, presumably because this is as close as the load can be controlled without blocking the governor. Based on wattmeter calibration data, the actual load could have differed from the indicated load by about  $\pm 70$  kW. In the context of the overall test loads included in the  $10^7$  cycles and the order in which they occurred, however, we view these deviations from 3300 kW as of no consequence.

In our opinion, EDGs 101, 102, and 103 are suitable for nuclear standby service at the "qualified" load of 3300 kW. This opinion is subject to the surveillance and maintenance recommendations documented in the following technical evaluation report, which we assisted in preparing: Review and Evaluation of Transamerica Delaval, Inc., Diesel Engine Reliability and Operability - Shoreham Nuclear Power Station Unit 1, PNL-5342, dated December 1984. As noted on pages 4.24 through 4.25 of that report, "...the replacement crankshafts for

EDG 101, EDG 102, and EDG 103 are acceptable for their intended service, provided that they are not operated during engine tests at loads in excess of the qualified load of 3300 kW." We believe that this restriction is necessary to avoid routine operation of the crankshafts at loads in excess of the load at which one crankshaft has been successfully tested.

Accordingly, we recommend that the permissible load for engine tests, including surveillance tests at the qualified load, be no higher than 3300 kW as read on control room instrumentation. We understand that the wattmeter may oscillate approximately  $\pm 100$  kilowatts around the value at which the load is set, as discussed above. In our opinion these oscillations during routine tests will not be detrimental to engine reliability, provided that the indicated mean load is no higher than 3300 kW.

Loads at which EDG 103 was operated as part of the confirmatory test to  $1 \times 10^7$  cycles, and the post-test examination that revealed no evidence of damage to the crankshaft or other key engine components, provide a basis for drawing conclusions about the capability of the EDGs for emergency operation at loads above the qualified load. EDG 103 sustained over 220 hours (approximately  $3 \times 10^6$  cycles) at instrument-indicated loads of 3500 kW and above. With a conservative application of instrument error from calibrations performed by LILCO preceding and following the time the higher-load testing was performed, we estimate that the actual load during this period was at least 3430 kW. If cracks had initiated during this testing, it is likely that they would have propagated during subsequent operation at approximately 3300 kW for the time necessary to bring the total cycles to  $1 \times 10^7$ . But no cracks were found in the post-test inspection of the crankshaft.



In light of these results, and taking into consideration the small but inevitable differences in the properties of the three crankshafts, it is our opinion that it would be within the demonstrated capability of the engines to operate at loads to 3430 kW for an hour or so if the engines were needed to carry such loads under emergency conditions. This comment does not apply for routine operation of the engines, including engine testing, for which we recommend a load limit of 3300 kW as discussed earlier in this summary.

The testing performed on EDG 103 does not provide an adequate basis for drawing conclusions about the effects on the EDGs of loads higher than 3430 kW.

~~However, an additional observation may be made based on other considerations.~~

~~It is generally accepted in the technical literature on fatigue and cumulative damage in metals that momentary overloads, even those approaching the ultimate tensile strength of the metal, can be sustained without failure. This literature provides a basis for confidence that brief excursions (less than 1 minute) of the Shoreham engines to loads as high as 3900 kW under emergency conditions would not compromise engine operability.~~

If an engine were operated at high overload for a longer period during an emergency, its capability to meet the load profile throughout the emergency would depend on whether or not a crack would initiate in the crankshaft during the overload and propagate to failure before the engine was no longer needed. The available information does not provide a basis for us to comment with confidence on this scenario. However, overloads to 3900 kW for up to 1 hour under emergency conditions followed by much lower loads in accordance with LILCO's predicted LOOP/LOCA profile are believed to be sustainable. Any crankshaft

that is subjected to more than a momentary overload approaching this level should receive a thorough nondestructive examination before it is returned to service.

#### CYLINDER BLOCKS

The replacement EDG 103 block was not subjected to the entire qualification test performed on the EDG 103 engine. Nevertheless, the absence of any reportable indications in the block top after more than 500 hours of operation at or above 3300 kW provides significant evidence that the replacement block is suitable for service at the qualified load. If further operation beyond the most recent inspection does not exceed the FaAA-recommended inspection interval before the end of the first fuel cycle, the top of the replacement block need not be reinspected until the first shutdown for refueling. It is also unnecessary, in our opinion, to monitor cam gallery cracks in the replacement block. The known cam gallery cracks in this block have not been repair-welded, and, therefore, residual stress fields that may be associated with repair welds have not been introduced into the block material.

The replacement EDG 103 block was more suitable than either the EDG 101 block or the EDG 102 block for the tests that LILCO conducted to obtain data on compressive and alternating stresses in the camshaft gallery. Use of either of the latter two blocks for the cam gallery tests would have involved the installation of strain gages over repair welds rather than over base metal. However, the test of EDG 103 at qualified load did not contribute to resolution of questions concerning the ligament cracks in the top surfaces of the EDG 101 and 102



blocks, the potential for developing stud-to-stud or stud-to-end cracks in those blocks, or the circumferential cracks reported in the original EDG 103 block.

Our conclusions expressed previously in written testimony regarding the EDG 101 and 102 blocks remain unchanged. In our opinion, the 101 and 102 blocks are adequate for service subject to certain caveats on surveillance of known cracks. Following any period of operation of EDG 101 or EDG 102 at or above 50% of qualified load, visual (with the naked eye) and eddy-current inspections should be performed on those portions of the block top that are accessible between cylinder heads. The purpose of these inspections is to verify the continued absence of detectable cracks between studs of adjacent cylinders. In addition, the behavior of several representative cracks in the camshaft galleries of the EDG 101 and 102 blocks should be monitored. If no changes indicative of crack growth are observed over the first fuel cycle, the need for continued monitoring of the cam gallery cracks should be reconsidered by the NRC staff.

Our opinion expressed in previous testimony is also unchanged regarding circumferential cracks of the type found in a cylinder liner counterbore of the original EDG 103 block. If such cracks were to develop in any of the three blocks currently in service, it is highly unlikely that they would represent a hazard to EDG reliability. They would be expected to propagate only a short distance into a region of compressive stress and stop. At any time a liner is removed from any of the three engines, however, it would be prudent to perform an appropriate nondestructive examination of the landing of the block. If a circumferential indication is found, an attempt should be made to characterize

the depth and length of the indication through appropriate nondestructive tests. However, we do not advocate removal of cylinder liners for the sole purpose of this inspection.

## TESTIMONY ON CONTENTIONS

Q1. How is your testimony organized?

A1. (A11) The testimony is presented in two general parts concerning 1) the crankshaft and 2) the cylinder block.

### I - CRANKSHAFT

Q2. What issues are addressed in this part of your testimony?

A2. (A11) This part of the testimony deals with 1) conclusions that may be drawn from the qualification tests, and 2) the fatigue life of the crankshafts currently installed in the Shoreham TDI diesel engines, designated as EDGs 101, 102, and 103. Item 1 is relevant to the contentions (c)(i) through (iv) and Item 2 is relevant to contentions (a)(i) through (iv).

### Conclusions that May be Drawn From Confirmatory Testing

Q3. Can you comment on the purpose of the confirmatory tests done by LILCO to accumulate  $10^7$  operating cycles on EDG 103?

A3. (A11) It is our understanding that these tests were conducted by LILCO primarily to provide unequivocal evidence that the high-cycle fatigue endurance limit of the crankshaft used in EDGs 101, 102, and 103 is at or above 3300 kW. The tests also included strain gage measurements to determine if the stress field in the cam gallery region of the block is compressive. These cam gallery tests are discussed in a later section of this testimony.

Q4. Have you reviewed the procedures and results pertaining to the confirmatory tests done by LILCO to accumulate  $10^7$  operating cycles on EDG 103?

A4. (All) Yes. Our review of the test results has been provided to the Board in two reports, namely Post-Test Examination of Transamerica Delaval, Inc. Emergency Diesel Generator 103 at Shoreham Nuclear Power Station for U.S. Nuclear Regulatory Commission Staff, by A. J. Henriksen, B. J. Kirkwood, W. W. Laity, P. J. Louzecky, J. F. Nesbitt, and L. G. Van Fleet, dated December 3, 1984, and Post-Test Examination of the Transamerica Delaval, Inc. Emergency Diesel Generator 103 Piston Skirts and Related Components at Shoreham Nuclear Power Station for U.S. Nuclear Regulatory Commission Staff, by A. J. Henriksen, B. J. Kirkwood, W. W. Laity, P. J. Louzecky, J. F. Nesbitt, and L. G. Van Fleet, dated December 14, 1984. Our review of the procedures is based on LILCO's letter to NRC (Harold Denton) dated October 18, 1984, concerning the confirmatory test, and information provided in test data sheets and supporting procedures regarding the calibration of electrical switchboard instruments.

~~Q5. Why was it not possible to draw conclusions regarding the acceptability of the crankshafts from calculations alone?~~

~~A5. (Sarsten) Crankshaft calculations involve uncertainties arising from the complex geometry of crankshafts and the variations in torque, bending loads, and other relevant input data. A large factor of safety must be employed to accommodate these uncertainties. It appears to me that the analytical evidence alone does not provide a sufficient basis for concluding that the crankshafts are adequate for the qualified load of 3300 kW. An unequivocal answer can be supplied only by an engine test for a sufficient time to accumulate  $10^7$  operating cycles.~~

Q6. Regarding the tests conducted by LILCO at a nominal 3300 kW, do you believe that they can be proven to have been at that value?

A6. (A11) No. We noted several points that could affect the certainty of the tested value:

1. There was uncertainty with respect to whether operators had the flexibility during the confirmatory tests to operate at  $3300 \pm 100$  kW.
2. Instrument uncertainties could have introduced an error of up to 2.5% of full-scale power readings.
3. LILCO reported that 20 hours were run at loads in the range of 3250 to 3300 kW and that 81 hours were run at loads between 3300 and 3400 kW.

Q7. Have you resolved these questions?

A7. (Henriksen) <sup>BUSH</sup> I believe so. The points just identified have been addressed. First, based on a review of the testimony and the data logs provided, I believe LILCO operators did operate most of the time with the wattmeter indicating a load of 3300 kW. This is based on my belief that the flexibility provided by NRC in conducting surveillance tests at  $3300 \text{ kW} \pm 100 \text{ kW}$  does not really mean that the load will be set at 100 kW above or below 3300 kW during that test. Rather, as I understand it, when set at 3300 kW, due to the mode of operation described in LILCO's testimony, the wattmeter oscillates between 3200 and 3400 kW. This is probably as close as the load can be controlled unless the governor load limit is blocked.

I have also reviewed the level of possible errors involved in the load measuring system. According to LILCO's testimony, the wattmeter instrument error could be as much as  $\pm 2\%$  of full-scale or  $\pm 112$  kW. An additional error of  $\pm 0.5\%$  or  $\pm 28$  kW in the remainder of the instrument loop could result in a total of  $\pm 2.5\%$  or  $\pm 140$  kW error in measuring the load. However, the calibration data furnished for the wattmeter, dated November 10, 1983, October 1, 1984, and January 4, 1985, indicated that the error in the meter never exceeded 40 kW in the 3000 to 4000 kW load range. Thus, including the possible 28 kW error in the remainder of the loop, the total instrument error appears to not have exceeded  $\pm 1.25\%$  or  $\pm 70$  kW during any period of operation of this particular engine since November 10, 1983.

The 20 hours of operation reported to be below 3300 kW is considered to be sufficiently few that they are of little or no significance to the question of the tested load, especially since there were 81 hours of operation above 3300 kW.

Q8. Does the possibility that due to instrument errors the confirmation test may have been conducted at a load as low as 3230 kW mean that the endurance limits for the crankshafts cannot be confirmed to meet or exceed 3300 kW?

A8. (Bush) No. I believe the crankshaft is qualified for its intended service even though some of the confirmatory test data may have been accumulated at loads slightly below 3300 kW. As I will testify in a later section, I am convinced from my analysis of engine load data that EDG 103 has operated at or above an instrumented-indicated load of 3500 kW for about  $3 \times 10^6$  cycles with no evidence of damage to the crankshaft. This strongly suggests that the endurance limit is at or above 3430 kW, accounting for instrument error.



Additional testing of  $7 \times 10^6$  cycles at engine loads near 3300 kW would have been sufficient to propagate any cracks that may have been present because the crankshaft stresses at 3300 kW are quite close to those at 3500 kW. Therefore, I do not consider it significant that some of the confirmatory testing may have occurred at loads somewhat below 3300 kW.

#### Fatigue Life of Crankshafts in the Shoreham EDGs

Q9. Have you reviewed the testimony of the County and LILCO regarding the load profiles that the Shoreham EDGs will be required to provide?

A9. (Bush, ~~Sarsten~~, Henriksen) Yes. Generally we understand the engines may be subjected to loads in the following categories:

~~1. Load spikes equivalent to 3900 kW due to sequenced starting of large cooling pumps for the first 30 to 60 seconds of a LOOP/LOCA event.~~

2. Short time intermittent and cyclic loads for a few minutes that may exceed by a few percent the "qualified load", taken here as 3300 kW.

3. LOOP/LOCA loads, assumed to be at or below 3300 kW after the first few minutes.

4. Loads that may result from operator error during the first hour of a LOOP/LOCA event, taken as 3800 to 3900 kW for times of 40 to 60 minutes.

5. Periodic testing loads of 3300 kW to meet NRC Regulations.

~~Q10. Do you believe the engines (EDGs 101, 102, and 103) can sustain loads of Category 1 as described above?~~

~~A10. (Bush) Short-term loads as high as 3900 kW for less than a minute under emergency conditions are not considered to be a problem. Almost all texts related to fatigue and to cumulative damage in metals cite the effects of momentary overloads. An example is Collins Failure of Materials in Mechanical Design (1981). Figure 1, taken from Collins (1981, p. 293, Figure 8.27), illustrates the prestressing effect of momentary overloads on existing cracks and their subsequent delay in propagation.~~

~~Short-term high loads, even those approaching the ultimate tensile strength, do not generally produce cracks and may, in fact, provide a plastic zone around any existing crack that retards its growth. The preceding condition markedly exceeds the short-term achievable overloads of these EDGs. It is my conclusion, therefore, that loads such as those identified in Category 1 are not of concern.~~

Q11. Do you believe the Shoreham TDI EDG crankshafts can sustain loads identified in Category 2 as described above?

A11. (Bush) I would like to offer some background information prior to answering this question. I have carefully reviewed the operating history of the Shoreham EDGs, particularly noting the operating time at engine loads at and above 3500 kW. In the case of EDG 103, which has undergone extensive post-test examination showing no damage to the engine (particularly the crankshaft), I note that the engine has sustained over  $3 \times 10^6$  cycles at loads at or exceeding 3430 kW when conservative assumptions regarding instrument error are included as discussed earlier.




FIGURE 1. Delay in Crack Growth Following the Application of Single Overload

Source: J. A. Collins, Failure of Materials in Mechanical Design - Analysis, Prediction, Prevention, 1981, p. 293, Figure 8.27.

The loads and corresponding hours at which EDG 103 is reported to have operated are as follows: (a)

<u>Load</u>	<u>Hours</u>
Approximate hours at 3500 kW	119
Approximate hours at loads greater than 3500 kW	101
Approximate hours at 3900 kW	7

Any of several approaches may be used to predict cumulative fatigue damage from these loads. Miner's rule, more correctly termed the Palmgren-Miner cyclic-ratio summation theory, has been used for many years to predict the fatigue (endurance) limit of materials. An alternative method that provides better correlation with experimental data is the Manson approach, which takes into account the loading sequence. The predicted fatigue limit using the latter approach for the EDG 103 crankshaft would vary markedly depending on the sequence of application of the loads noted in the preceding summary. We are unaware from available information what the actual sequence was.

A conservative view is to assume that the beginning of the high-cycle fatigue limit is less than  $3 \times 10^6$  cycles, and to define the lower bound of the fatigue limit as that associated with the lowest load at which EDG 103 was operated during the first  $3 \times 10^6$  cycles. This would set the lower-bound value from the EDG 103 test at 3430 kW, based on an assumed instrument error of  $\pm 70$  kW applied to the indicated load of 3500 kW.

(a) Pacific Northwest Laboratory, Review and Evaluation of Transamerica Delaval, Inc., Diesel Engine Reliability and Operability - Shoreham Nuclear Power Station Unit 1, PNL-5342, December 1984 (p 4.22).

Table 1 is a summary of data from six references on the high-cycle fatigue limit for several ferrite steels. A significant message from this data is that the onset of the fatigue limit is close to  $1 \times 10^6$  cycles, regardless of the ferritic alloy, heat treatment, or surface hardening treatment. Note that several of the values are for aircraft or automobile crankshafts.

As illustrated in Figure 2, the fatigue limit of ferrite steels is essentially constant as a function of the number of cycles above the onset of high-cycle fatigue. This is unlike nonferrous metals, which have no clearly defined fatigue limit with time.

The steel used in the EDG 103 crankshaft is ABS Grade 4S, which corresponds roughly to an AISI-5050 steel in composition. The tensile strength is about 100 ksi and the yield strength about 60 ksi. The mechanical properties would correspond to some of the 4000 series steels cited in Table 1, and, therefore, one would anticipate similar initiation of the fatigue limit near  $1 \times 10^6$  cycles.

LILCO's nondestructive examinations of the EDG 103 crankshaft following the  $10^7$ -cycle test provide evidence that cracks had not initiated in the crankshaft during the initial  $3 \times 10^6$  cycles at loads at or above 3500 kW as read on the wattmeter. Because crankshaft stresses at 3500 kW are not substantially different from stresses at 3300 kW, ~~as discussed in response to~~ <sup>BASED UPON MY EXTRAPOLATION OF DATA</sup> ~~IN F&AA-84-3-16,~~ subsequent operation at the latter load to bring the total cycles to  $10^7$  would have been sufficient to cause propagation of cracks formed at the higher load. This is further confirmation that the high-cycle fatigue limit is at or above the value corresponding to 3500 kW minus known instrument error, or 3430 kW.

TABLE 1. Location of the Initiation of High-Cycle Fatigue (Endurance) Limit for Several Ferrite Steels

Reference	Beginning of Fatigue Limit $\times 10^6$ Cycles	Material	Comments
(1)	1.0	1047 Steel	
(2)	~3.0	4340	Vacuum melted - longitudinal specimens
	~3.0	4340	Vacuum melted - transverse specimens
	~0.9	4340	Air melted - longitudinal specimens
(3)	~1.5	4340	Completely reverse S-N curve
(4)	~0.3	3130	Temper embrittled
	~0.8	3130	Non-temper embrittled
(5)	2.0	0.78% C	Spheroidized
	2.5	0.78% C	Pearlitic
(5)	1.5	4140	Quenched and tempered
	2.0	4140	Shotpeened
	2.5	4140	Nitrided
(5)	0.7	(4140,x4340, VCM)(a)	Quenched and tempered
	1.0	(4140,x4340, VCM)(a)	Shot-peened
	1.5	(4140,x4340, VCM)(a)	Nitrided, polished nitrided
	~3.0	(4140,x4340, VCM)(a)	Nitrided
(5)	0.8	4340	Automobile crankshaft - normal heat treatment
	0.7	4340	Automobile crankshaft - shot-peened
	~2.0	4340	Automobile crankshaft - nitrided
(5)	1.5	4340	Transverse specimens from crankshaft
	0.2	1.20% C	Quenched and tempered

(a) Above are torsional fatigue results on aircraft engine crankshafts including 4140 series.



TABLE 1. (contd)

Reference	Beginning of Fatigue Limit $\times 10^6$ Cycles	Material	Comments
(6)	0.9	3420	Quenched and tempered
	1.0	1050	Quenched and tempered
	1.0	4130	Normalized
	1.5	Structural steel	-
	1.5	Alloy struc. steel	-
	~2.0	Cast iron	-

- (1) Hayden, H. W., et al. 1965. "Mechanical Behavior". Volume III in The Structure and Properties of Materials. John Wiley & Sons; New York, New York.
- (2) Reed-Hill, R. F. 1964. Physical Metallurgy Principles. Van Nostrand, New York, New York.
- (3) Collins, J. A. 1981. Failure of Materials in Mechanical Design - Analysis Prediction, Prevention. John Wiley & Sons, New York, New York.
- (4) Hollomon, J. H., and L. D. Jaffee. 1974. Ferrous Metallurgical Design. John Wiley & Sons, New York, New York.
- (5) American Society of Metals. 1961. "Properties and Selection of Metals". Volume 1 in ASM Metals Handbook. Novelty, Ohio.
- (6) Marks, L. S. 1941. Mechanical Engineers' Handbook. 4th ed. McGraw-Hill, New York, New York.




FIGURE 2. Typical High-Cycle Fatigue Curve for a Ferritic Steel (1050 AISI)

The point of the background discussion is now clear. In my opinion, the Category 2 engine loads that may result from intermittent and cyclic demands in the vicinity of 3350 to 3400 kW for times up to one hour or so are below the probable high-cycle fatigue limit. Therefore, loads in Category 2 are not of concern.

~~Q12. Can you quantify the relative stresses at 3300 kW and 3500 kW?~~

~~A12. (Sarsten) If one takes the bending stresses as employed and interpreted by Det Norske Veritas for the Shoreham crankshafts in their report 84-0099A of September 17, 1984, and the maximum firing pressures as read from TDI test curves dated March 19, 1976, for a Shoreham engine, then the relative calculated bending stresses are 20,450 psi and 21,120 psi for 3300 kW and 3500 kW, respectively.~~

Q13. Do you believe the EDGs can sustain the loads identified in Category 3 above?

A13. (Bush) As defined in the response to Question 9, all loads in Category 3 are at or below 3300 kW. I believe the endurance limit for these crankshafts is above this value. Hence, the Category 3 loads are not of concern.

Q14. The engine loads that may result from operator error (e.g., Category 4) could exceed the high-cycle fatigue limit. Do you believe the crankshafts will sustain these loads for periods up to an hour and still have the ability to meet the succeeding load challenge of a LOOP/LOCA?

A14. (Bush) I believe the crankshaft can survive up to an hour of overload to about 3900 kW without crack initiation, but the probability of

crack initiation cannot be quantified. It is a function of parameters such as previous load history and metallurgical properties. The question then is, if a crack initiates during a LOOP/LOCA, will it propagate to the point of engine shutdown before the engine is no longer needed? My engineering judgment is that the combination of a Category 4 transient operation followed by time at lower load/time profiles such as the LOOP/LOCA demand profile should not lead to crankshaft failure. The only way to quantify this judgment would be to conduct a three-dimensional finite element analysis combining the LOOP or LOOP/LOCA load histories that were imposed on a crankshaft having an initial crack and determine the final crack size.

I feel that any crankshaft that is subjected to a sustained overload approaching Category 4 should be given careful surface and volumetric non-destructive examination prior to returning it to service.

Q15. What LOOP/LOCA load profile did you consider in evaluating the ability of the crankshaft to sustain the assumed operator error load?

A15. (Bush) I assumed the following LOOP/LOCA load profile based on data provided in LILCO's testimony dated January 15, 1985, and the Shoreham Final Safety Analysis Report (FSAR), Tables 8.3.1-1A and 8.3.1-2:

<u>Time</u>	<u>Load (kW)</u>
Less than 1 minute	3900
1 minute to 3 minutes	3331
3 minute to 12 minutes	3266
12 minutes to 30 minutes	3265
30 minutes to 60 minutes	3253
Longer than 60 minutes	2617

Q16. Do you believe the Shoreham EDGs can sustain the required monthly and refueling-outage testing at the qualified load of 3300 kW, identified in the response to Question 3 as Category 5 loads?

A16. (Bush, ~~Sarsten, Henriksen~~) Yes. These Category 5 testing loads are considered to be below the endurance fatigue limit for these crankshafts. As stated earlier, this limit is believed to be at or above 3430 kW, based on the results of the testing up through the first  $3 \times 10^6$  cycles, and is certainly confirmed to be at or above 3300 kW, based on the confirmatory tests that brought the total testing cycles to over  $1 \times 10^7$ . Detailed comments regarding these confirmatory tests, including our views on the uncertainties with watt-meter readings, are provided earlier in this testimony.

In view of the fact that the endurance limit can be established with certainty as being only at or above 3300 kW, we feel that it would be prudent to limit surveillance testing to this value. The reason for this is that surveillance tests can add over  $3 \times 10^7$  cycles during the assumed 40-year life of the Shoreham Nuclear Power Station.

## II - CYLINDER BLOCKS

Q17. What is the purpose of this testimony?

A17. (Bush) This testimony addresses parts c(i) and c(ii) of the contention concerning testing of the EDG 103 block, and also addresses metallurgical considerations related to my conclusion that existing cracks in the cam gallery region of the EDG 101 and 102 blocks should be monitored.

Q18. Have you reviewed the testimonies filed by the County and by LILCO concerning the test involving the EDG 103 block, the suitability of the cylinder blocks in EDGs 101 and 102 for service at 3300 kW, and whether there is a need to monitor the cam gallery cracks in the EDG 101 and 102 blocks?

A18. (Bush) Yes.

Q19. Please summarize your conclusions on these issues.

A19. (Bush) My conclusions are as follows:

First, as I have stated previously in written testimony (filed on October 12, 1984), the replacement EDG 103 block was more suitable than either the EDG 101 block or the EDG 102 block for the tests that LILCO conducted to obtain data on compressive and alternating stresses in the camshaft gallery. Use of either of the latter two blocks for the cam gallery tests would have involved the installation of strain gages over repair welds rather than over base metal. However, the selection of EDG 103 for the test at qualified load did not contribute to resolution of questions concerning the ligament cracks in the top surfaces of the EDG 101 and 102 blocks, the potential for developing stud-to-stud or stud-to-end cracks in those blocks, or the circumferential cracks reported in the original EDG 103 block.

Second, operation of the replacement EDG 103 block for more than 500 hours at or above 3300 kW based on the meter reading, followed by LILCO's nondestructive examinations that revealed no reportable indications in the block top, provides significant evidence that the replacement block is suitable for service at the qualified load of 3300 kW. Based on the known performance of the block through the qualification test, I concur with the conclusion of



Dr. Rau and Dr. Wachob<sup>(a)</sup> that it would be appropriate to reinspect the replacement block top at intervals determined through FaAA's cumulative damage analysis.<sup>(b)</sup> This means that if further operation beyond the most recent inspection does not exceed the FaAA-recommended interval before the end of the first fuel cycle, the top of the replacement block will not have to be reinspected until the first shutdown for refueling.

Third, the conclusions I expressed in previous written testimony regarding the EDG 101 and 102 blocks are not affected by the qualification test performed with EDG 103. As I previously testified, I believe that the 101 and 102 blocks are adequate for service subject to certain caveats on surveillance of known cracks. Following any period of operation of EDG 101 or EDG 102 at or above 50% of qualified load, visual and eddy current inspections should be performed on those portions of the block top that are accessible between cylinder heads. The purpose of these inspections is to verify the continued absence of detectable cracks between studs of adjacent cylinders. ~~In addition, the behavior of several representative cracks in the camshaft galleries of the EDG 101 and 102 blocks should be monitored. If no changes indicative of crack growth are observed over the first fuel cycle, the need for continued monitoring of the cam gallery cracks could be reconsidered by the NRC.~~

Fourth, I have previously expressed the opinion based on engineering judgment that circumferential cracks of the type found in a cylinder liner

---

(a) Additional Cylinder Block Testimony of Dr. Duane P. Johnson, Dr. Charles A. Rau, Jr., Milford H. Schuster, Dr. Harry F. Wachob and Edward J. Youngling on Behalf of Long Island Lighting Company, January 15, 1985, at 10.

(b) This analysis is presented in the FaAA report Design Review of TDI R-4 and RV-4 Series Emergency Diesel Generator Cylinder Blocks, the most recent revision of which is FaAA-84-9-11.1 dated December 1984.

counterbore of the original EDG 103 block do not represent a hazard to EDG reliability. My opinion on that issue remains unchanged. Similar cracks may also occur in the EDG 101 and 102 blocks because of the high stress concentration associated with the geometry of the cylinder liner landing. They may occur even in the replacement EDG 103 block, although the stress concentration in the replacement block appears to be less severe. At any time a liner is removed from any of the three engines, it would be prudent to perform an appropriate nondestructive examination of the landing in the block. If a circumferential indication is found, an attempt should be made to characterize the depth and length through appropriate nondestructive tests. However, I do not advocate removal of cylinder liners for the sole purpose of this inspection.

~~Monitoring of Cam Gallery Cracks in EDGs 101 and 102~~

~~Q20. How is your testimony organized on this topic?~~

~~A20. (Bush) I first will comment on the examination<sup>(a)</sup> performed by Walter C. McCrone Associates, Inc. of a cam gallery crack specimen removed from the original EDG 103 block. I will next briefly summarize my assumptions and conclusions regarding the origin and characteristics of the cam gallery cracks. Finally, I will present my conclusions regarding the need for monitoring cam gallery cracks in the blocks of EDGs 101 and 102, and my reasons for those conclusions.~~

~~(a) Walter C. McCrone Associates, Inc., Cast Iron Analysis re LILCO vs Suffolk Company (sic), MA number 13747, dated January 11, 1985.~~

Comments on Testing Performed by Walter C. McCrone Associates, Inc.

The test results reported by McCrone provide unequivocal evidence that the predominant oxide in the samples removed from the crack surface was magnetite. The x-ray diffraction patterns are unambiguous and can be readily interpreted by an analyst who is trained in the field of x-ray diffraction. The McCrone laboratories are well known at the Pacific Northwest Laboratory as having competence in conducting quantitative iron-oxide measurements of the type requested by the County.

DELETED

Assumptions and Conclusions Regarding Origin and Characteristics of  
Cam Gallery Cracks

Based on the above-mentioned test results, I have concluded that the crack examined in the sample removed from the original EDG 103 cylinder block was formed during cooling of the casting. There was no evidence of an oxide film formed at low temperatures, which could have been indicative of crack propagation after the block was placed in service. The absence of the latter oxide film tends to confirm that the crack is in a compressive stress field as determined analytically and experimentally by FaAA.

Because the original EDG 103 block exhibited degraded metallurgical properties as confirmed by the morphology of the Widmanstaetten structure, it is reasonable to assume the following:

1. The tensile properties of the typical Grade-40 cast iron in the EDG 101 and 102 blocks are superior to those of the degraded Grade-40 cast iron in the original EDG 103 block. The Grade-45 cast iron in

the replacement EDG 103 block compares even more favorably in this regard. If one reasonably assumes that the hot tensile properties of the EDG 101, 102, and replacement 103 blocks would also be better than those of the original EDG 103 block, the depth of cam gallery cracks in the former would be expected to be shallower than those in the latter.

2. With the evidence that cam gallery cracks in the original EDG 103 block are hot tears that did not propagate, and recognizing the superior materials properties of the EDG 101, 102, and replacement 103 blocks, it is reasonable to assume that the cracks in the latter blocks are also hot tears and that these cracks have not grown in service.

DELETED

#### Conclusions Regarding the Need for Monitoring Cam Gallery Cracks

Based on the information summarized above, I conclude that the existing cam gallery cracks in the EDG 101, 102, and 103 cylinder blocks would not be expected to grow under normal operating conditions. Nevertheless, I believe that monitoring of the cam gallery cracks in EDGs 101 and 102 is necessary for the reasons listed below. I do not believe it is necessary to monitor cam gallery cracks in EDG 103, because the known cracks in the replacement block have not been repair-welded.

1. The inferences and conclusions regarding crack behavior are based on detailed examination of one crack in the original EDG 103 block. This is insufficient data on which to draw conclusions with certainty regarding the other EDG blocks.

2. Associated with the known repair welds in the cam galleries of the EDG 101 and 102 blocks are residual stress fields of an undetermined nature. These stress fields could influence crack propagation.

DELETED

3. Cracks in the cam gallery represent a degraded condition. In my opinion the known data on these cracks where weld repairs have been made is insufficient to establish what will or will not happen to these cracks over time. My concern is related to the possibility of an initial lengthening of the cracks into stress fields of decreasing compression or, possibly, tension.

4. Certain postulated crack growth patterns ultimately could lead to a loss of function of a diesel generator. I recognize this is improbable, particularly when coupled to the low probability of a LOOP/LOCA. However, crack monitoring will provide confirmation as to whether or not the cracks continue to be benign. The action needed to perform the monitoring is straightforward, and I believe that it would be consistent with good practice for safety-related equipment in nuclear service.

In my opinion, the preferred approach for monitoring the cracks would be to install crack-opening displacement gages at the weld overlays on the second camshaft bearing saddle inboard of each end of the engine. These saddles are representative, and they are much more accessible than saddles toward the middle of the engine for any servicing of gages that may be required. The gages should be monitored during monthly engine tests. **DELETED**

Other methods of monitoring may also be acceptable. One alternative approach would be to monitor the depth of representative cracks (e.g., at locations described above) with an appropriate surface probe (e.g., a TSI depth gage), and also monitor crack length (parallel to the longitudinal axis of the engine) using magnetic particle or liquid penetrant examinations. Depth measurements taken in this manner may lack accuracy, but the combination of depth measurements and length measurements would probably be sufficient to show any significant changes in crack size. To obtain the desired information in this manner with minimal disruption of engine availability (due to the need to remove access covers), it would be sufficient to take these measurements every 3 months.

Regardless of the method chosen, it is my opinion that the monitoring should continue through the first fuel cycle. A decision should be made by the NRC staff at the first refueling outage regarding the need to continue with the monitoring.



### Stud-to-Stud Cracks in the Cylinder Block Top

Q21. Do you consider that the qualification test performed on the EDG 103 engine provides an appropriate basis for predicting the behavior of block top cracks in the EDG 101 and 102 engines?

A21. (Bush) No. Differences in the mechanical properties of the cast iron used in the EDG 101 and 102 blocks from the cast iron used in the replacement EDG 103 block and, perhaps more importantly, design changes incorporated into the top of the replacement EDG 103 block do not permit an extrapolation of test results from the latter block to the blocks of EDGs 101 and 102.

Q22. What are your views on the probability that stud-to-stud cracks could initiate in either EDG 101 or EDG 102 during a LOOP/LOCA and propagate to the extent that either engine would be lost from service?

A22. I consider loss of function of EDGs 101 and 102 under these postulated circumstances to be highly improbable for the following reasons:

1. There is no evidence of stud-to-stud cracking in these blocks from previous operation at and above 3500 kW. Such cracks would be more likely to initiate at these higher loads than at the qualified load of 3300 kW.
2. All future surveillance testing is to be accompanied by monitoring of the block tops of EDGs 101 and 102 to verify the continued absence of detectable stud-to-stud cracks.

3. Based on extrapolations from the original EDG 103 block, I would not expect the fatigue crack growth rates in the stud-to-stud area to be so high that there would be a loss of EDG function during a LOOP/LOCA, assuming crack initiation occurred shortly after the start of the LOOP/LOCA. This is particularly true at the low power levels--less than 3000 kW--characteristic of predicted load profiles through most of a LOOP/LOCA, even if one assumes the improbable situation that the engines would be the only source of emergency power for approximately a week. A quantification of crack initiation and growth to the point of loss of function would require a three-dimensional finite element analysis in which crack initiation is assumed. FaAA has conducted such an analysis (FaAA-84-9-11.1, December 1984). My own semi-quantitative assessment is that the cumulative probability of crack initiation and propagation to the point of loss-of-function is quite low.