

# PHILADELPHIA ELECTRIC COMPANY

PEACH BOTTOM ATOMIC POWER STATION

R. D. 1, Box 208

DELTA, PA 17314

(717) 456-7014



KEN POWERS  
PLANT MANAGER

October 9, 1992

Docket Nos. 50-277  
50-278

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

SUBJECT: Licensee Event Report  
Peach Bottom Atomic Power Station - Units 2 and 3

This LER concerns a supervisor inadvertently not ensuring that a firewatch was posted at the High Pressure Service Water Pump Structure.

Reference:	Docket Nos. 50-277 50-278
Report Number:	2-92-018
Revision Number:	00
Event Date:	09/15/92
Report Date:	10/09/92
Facility:	Peach Bottom Atomic Power Station RD1, Box 208, Delta, PA 17314

This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(i)(B).

Sincerely,

cc: J. J. Lyash, US NRC Senior Resident Inspector  
T. T. Martin, US NRC, Region I

16004.

9210190091 921009  
PDR ADDC 15000277  
S PDR

JE22

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (7-600104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

ABSTRACT Limit to 1400 spaces (i.e. approximately fifteen single-space typewritten lines) [15]

NRC Form 386 (6-89)

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Peach Bottom Atomic Power Station Units 2 and 3	DOCKET NUMBER (2)  0 5 0 0 0 2 7 7 9 2	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		— 0	1 8	— 0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 386A's) (17)

Requirements for the Report

This LER is being submitted pursuant to the requirements of 10 CFR 50.73 (a)(2)(i)(B) due to a violation of Technical Specification (Tech Spec) 3.14.D.2 concerning a missed 1 hour roving firewatch at the Unit 2 High Pressure Service Water (HPSW) pump structure (EIS:MK).

Unit Conditions at the time of the Event

Unit 2 was in the REFUEL Mode. Unit 3 was at approximately 100% power. There were no inoperable structures, systems or components that contributed to this event.

Description of the Event

On 9/15/92, at approximately 0625, security personnel discovered that a Technical Specification (Tech Spec) required 1 hour firewatch was performed in excess of the 1 hour interval. This is a violation of Tech Spec 3.14.D.2 which requires a 1 hour firewatch be performed for non-functional fire barriers provided fire detectors are operable on at least one side of the fire barrier. The roving firewatch for the Unit 2 High Pressure Service Water Pump structure was performed at approximately 0630 hours, 47 minutes after the allowed 1 hour interval elapsed. The previous firewatch was performed at 0443 hours. The firewatch was in place as a result of an inoperable Thermo-lag encapsulation as discussed in NRC Bulletin 92-01, Supplement 1. The encapsulation protected cabling (EIS:CBL) for the 'B' Emergency Service Water (ESW) (EIS:BI) pump (EIS:P) in the event of an Appendix R fire in the Unit 2 HPSW pump structure. The 'B' ESW Pump is located in the Unit 3 HPSW Pump Structure while the 'A' ESW Pump is located in the Unit 2 HPSW Pump Structure. Subsequent firewatches were performed on time.

Cause of the Event

The cause of the event is due a security supervisor inadvertently not ensuring that a firewatch was posted for a particular round. A security protection technician had been assigned to perform a roving firewatch to satisfy Tech Spec 3.14.D.2 due to inoperable Thermo-lag fire barriers identified in August, 1992. In early September, because of the large amount of areas in the power block to be looked at, the responsibility for ensuring firewatch rounds for some areas outside the power block was given to protection technician supervision (non-utility, non-licensed) who controlled the issuance of posts. The Supervisor inadvertently did not ensure that the round was posted by 0543 on September 15, 1992. No formal method was used by the supervisor to remember to ensure the round was posted.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)	PAGE (3)						
Peach Bottom Atomic Power Station Units 2 and 3		<table border="1"><tr><th data-bbox="1047 270 1120 291">YEAR</th><th data-bbox="1125 270 1285 291">SEQUENTIAL NUMBER</th><th data-bbox="1290 270 1384 291">REVISION NUMBER</th></tr><tr><td data-bbox="1047 327 1120 355">92</td><td data-bbox="1125 327 1285 355">018</td><td data-bbox="1290 327 1384 355">003</td></tr></table>	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	92	018	003	OF 03
YEAR	SEQUENTIAL NUMBER	REVISION NUMBER							
92	018	003							
05000277									

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Analysis of the Event

There were no actual safety consequences as a result of this event. No fires occurred in this area during the period of non-compliance. The probability of not detecting a fire during the period of non-compliance was extremely low. Had a fire occurred in the Unit 2 HPSW Pump Structure area, operable fire detection equipment would alert fire brigade personnel to promptly extinguish the fire. Because no entries were made in the area during the approximately 47 minute non-compliance, no increase in combustibles or potential for fire existed. Had a design basis Appendix R fire occurred in the Unit 2 HPSW Pump Structure and the A and B ESW Pumps became unavailable, the Emergency Cooling Water (ECW) Pump would be available to cool the emergency diesel generators (EIS:EK) and the core and containment cooling equipment rooms.

Corrective Actions

The methodology for ensuring that the firewatch round is performed has been changed. The round has been put back on the round list for the security protection technician. If an urgent circumstance would arise that the round in the Unit 2 Pump Structure could not be made, technicians would notify appropriate supervision for relief. Other current and future similar rounds will be also be handled in this manner.

The Security supervisor involved has been counselled concerning this event including the need to pay careful attention to ensure that all rounds are promptly posted. Other security personnel have been informed of the significance of this event.

Previous Similar Events

There were 2 previous similar events in which security personnel missed a firewatch round due to inadequate instruction from security supervision. LER 3-86-17 involved a missed firewatch due to security supervision issuance of a wrong instruction sheet to firewatch personnel. LER 2-84-14 involved a missed firewatch due to poorly organized log sheets. Corrective actions for LER 2-84-14 involved revising the log sheet and for 3-86-17 involved discipline. Because these events and corrective actions involved specific cases, the corrective actions could not have prevented this event.