



Nuclear Group  
P.O. Box 4  
Shippingport, PA 15077-0004

Telephone (412) 393-6000

October 8, 1992  
ND3MNO:3361

Beaver Valley Power Station, Unit No. 1  
Docket No. 50-334, License No. DPR-66  
LER 92-008-00

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Gentlemen:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following revised Licensee Event Report is submitted:

LER 92-008-00, 10 CFR 50.73.a.2.i.B, "Incomplete Containment Hydrogen Analyzer Surveillance as a Result of Inadequate Change Implementation".

Very truly yours,

*T. P. Noonan* for,  
T. P. Noonan  
General Manager  
Nuclear Operations

JGT/sl

w/Attachment

000065  
9210260324 921008  
PDR ADOCK 05000334  
S PDR

LED2  
11

October 8, 1992

ND3MNO:3361

Page two

cc: Mr. T. T. Martin, Regional Administrator  
United States Nuclear Regulatory Commission  
Region 1  
475 Allendale Road  
King of Prussia, PA 19406

J. A. Holtz, Ohio Edison  
76 S. Main Street  
Akron, OH 44308

Mr. A. DeAgazio, BVPS Licensing Project Manager  
United States Nuclear Regulatory Commission  
Washington, DC 20555

Larry Roszbach, Nuclear Regulatory Commission,  
BVPS Senior Resident Inspector

Larry Beck  
Centerior Energy  
6200 Oak Tree Blvd.  
Independence, Ohio 44101-4661

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, GA 30339

G. E. Muckle,  
Factory Mutual Engineering  
680 Anderson Drive #BLD10  
Pittsburgh, PA 15220-2773

Mr. Richard Janati  
Department of Environmental Resources  
P. O. Box 2063  
16th Floor, Fulton Building  
Harrisburg, PA 17120

Director, Safety Evaluation & Control  
Virginia Electric & Power Co.  
P.O. Box 26666  
One James River Plaza  
Richmond, VA 23261

W. Hartley  
Virginia Power Company  
5000 Dominion Blvd.  
2SW Glenn Allen, VA 23060

J. M. Riddle  
Halliburton NUS  
Foster Plaza 7  
661 Anderson Drive  
Pittsburgh, PA 15220

October 8, 1992

ND3MNO:3361

Page three

Bill Wegner, Consultant  
23 Woodlawn Terrace  
Fredricksburg, VA 22404

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (PS30), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3160-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

0	5	0	0	0	3	3	4	1	OF	0	5
---	---	---	---	---	---	---	---	---	----	---	---

#### Incomplete Containment Hydrogen Analyzer Surveillance As a Result of Inadequate Change Implementation

LHC生物燃料有限公司 CONTACT 中國 廣州 1121
$$4, 1, 2 \mid 6, 4, 3, -1, 2, 5, 8$$

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

SUPPLEMENTAL REPORT EXPECTED 11A☐ YES (I) YES (DATE EXPECTED SUBMISSION DATE)☐ NO

EXPERIMENT  
SILVER (SILVER)  
DART (18)

MONTH	DAY	YEAR
-------	-----	------

ABSTRACT 14, 1991 pp. 1400-1404. doi: 10.1006/jneuro.1991.0015. Single-blind, placebo-controlled study.

On 9/9/92, a review of the surveillance procedures for the containment wide range hydrogen analyzers revealed that they were not tested as required by Technical Specifications. The surveillance for the hydrogen analyzers requires a channel calibration using sample gasses containing one and four volume percent hydrogen. The calibration procedures required a zero, four, and nine volume percent hydrogen concentration, but did not require one volume percent. When the determination was made that the analyzers were not tested as required by Technical Specifications, both analyzers were declared inoperable at 0800 hrs on 9/9/92. The surveillance procedures were revised to include the one volume percent hydrogen sample gas. At 1839 hrs. on 9/9/92, the A hydrogen analyzer surveillance procedure was completed successfully, and the analyzer was declared operable. The revised B hydrogen analyzer procedure was completed successfully, and the analyzer was declared operable 2227 hrs. on 9/9/92. The cause of the incomplete surveillance was a result of inadequate implementation of a Technical Specification amendment in 1986. The amendment replaced narrow range analyzers with wide range analyzers that were installed in 1982. The existing wide range surveillance procedures, that were based on vendor recommendations, were not verified for compliance with the surveillance requirement.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-30), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (2150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

Beaver Valley Power Station Unit 1

0 5 0 0 0 3 3 4 9 2 - 0 0 8 - 0 0 0 2 OF 0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT

On 9/9/92, the Independent Safety Evaluation Group completed a review of the surveillance requirements for the containment wide range hydrogen analyzers [H2-HY101A and H2-HY101B], and concluded that they were not tested as required by Technical Specifications. Technical Specification 3.6.4.1, requires that two separate and independent wide range containment hydrogen analyzers are to be operable in operational Modes 1 and 2. The surveillance for the hydrogen analyzers requires that once per 92 days the analyzers be demonstrated operable by performing a channel calibration using sample gasses containing one volume percent (1%) and four volume percent (4%) hydrogen, with the balance gas containing nitrogen.

A review of the Maintenance Surveillance Procedures, (MSP 1.46.04A and MSP 1.46.04B, Containment Hydrogen Monitoring Loop H2-HY101A(B) Calibration), determined that the analyzers were not tested with the one volume percent (1%) sample gas. The calibration procedures required a zero (0), four (4), and nine (9) volume percent hydrogen concentration.

When the determination was made that the analyzers were not tested in accordance with Technical Specification 3.6.4.1, both analyzers were declared inoperable at 0800 hrs on 9/9/92. Since the unit was at 90% (Mode 1), the Technical Specification action statement required that one must be restored within 72 hrs., or the unit must be placed in hot standby (Mode 3) within the next 12 hrs.

The surveillance procedures were revised to include the one volume percent (1%) hydrogen sample gas. At 1839 hrs. on 9/9/92, the Train A hydrogen analyzer surveillance procedure was completed satisfactorily, and the analyzer was declared operable. In accordance with the action statement requirement of Technical Specification 3.6.4.1, with one wide range hydrogen analyzer inoperable, the inoperable analyzer must be restored within the next 30 days, or hot standby (Mode 3) must be entered in the next 12 hrs.

The revised surveillance procedure was completed successfully on the Train B analyzer, and the analyzer was declared operable at 2227 hrs. on 9/9/92.



LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (PC-30), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Beaver Valley Power Station Unit 1	DOCKET NUMBER (2)  05000334	LER NUMBER (6)			PAGE (3)	
		YEAR 92	SEQUENTIAL NUMBER 008	REVISION NUMBER 00	03 OF 05	

TEXT (If more space is required, use additional NRC Form 366A's) (17)

CAUSE OF EVENT

The cause of the incomplete surveillance was a result of inadequate implementation of a Technical Specification change in 1986. The original station design included two (2) narrow range hydrogen analyzers, [H2-HY100A and H2-HY100B]. The Technical Specification surveillance for the analyzers required a channel calibration using sample gasses containing one (1) and four (4) volume percent hydrogen, and the balance gas containing nitrogen. The analyzers were tested every 92 days by the performance of MSP 1.46.03A and 1.46.03B, Hydrogen Analyzer H2-HY100A(B) Calibration. These surveillance procedures properly used one (1) and four (4) volume percent hydrogen sample gasses as required by Technical Specifications.

In 1982, two (2) wide range hydrogen analyzers (0 to 10%) were added per the requirements of NUREG 0737, Clarification of TMI Action Plan Requirements. Preoperational testing was based on vendor recommendations (Teledyne Analytical Instruments) which recommended sample gas concentrations of zero volume percent (0%) hydrogen (100% nitrogen was used), and four (4) and nine (9) volume percent hydrogen. Although the new wide range analyzers were not required by Technical Specifications, new Maintenance Surveillance Procedures, MSP 1.46.04A and MSP 1.46.04B were written and issued on 6/25/82. The surveillance procedures were based on the gas concentrations used for the preoperational tests, and were tested once every 92 days on a staggered testing basis.

Technical Specification Amendment 105 went in effect on 8/12/86 which changed Technical Specification 3.6.4.1. The amendment was to fulfill two purposes, one was an administrative change to identify the wide range analyzers installed as a result of NUREG 0737 as the Technical Specification required monitors, and to modify the action statement as recommended by Generic Letter 83-37. The surveillance requirements of one (1) and four (4) volume percent hydrogen were not changed. The existing surveillance procedures for the wide range analyzers, MSP 1.46.04A and 1.46.04B were to be used to prove operability per the Technical Specification surveillance requirements. Following the approval of the amendment, the narrow range analyzers were to be retired, and the narrow range analyzer surveillance procedures were to be cancelled. During the amendment review process, the required gas concentrations in the Technical Specification surveillance requirements were not compared to the concentrations identified the wide range analyzer surveillance procedures, since the surveillance procedures for the wide range analyzers were known to exist, and the Technical Specification amendment did not change the surveillance requirements.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20548, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Beaver Valley Power Station Unit 1	DOCKET NUMBER (2)  0 5 0 0 0 3 3 4	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		9 2	— 0 0 8	— 0 0	0 4	OF 0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

CORRECTIVE ACTIONS

The corrective actions taken as a result of this event are:

- 1). Upon notification of the incomplete surveillance testing of the wide range hydrogen analyzers, both analyzers were immediately declared inoperable.
- 2). The two (2) surveillance procedures were revised to require a test gas concentration of one volume percent (1%) hydrogen, and the balance gas containing nitrogen.
- 3). Both hydrogen analyzers were successfully retested using the revised surveillance procedures and declared operable.
- 4). A review of the surveillance requirements for the Beaver Valley Unit 2 wide range hydrogen analyzers was performed. The Technical Specification surveillance for the hydrogen analyzers also requires a channel calibration using sample gases containing one volume percent (1%) and four volume percent (4%) hydrogen, with the balance gas containing nitrogen. The Beaver Valley Unit 2 surveillance procedures have always required a sample gas concentration of one volume percent (1%) and four volume percent (4%) hydrogen, with the balance gas containing nitrogen.
- 5). Since this event (1986), the administrative controls for the implementation of Technical Specification changes have been strengthened and formalized. The station groups affected by the proposed Technical Specification amendment are now required by an administrative procedure to perform a review to identify all procedures affected by the change. Draft procedure changes are prepared which are reviewed at a meeting which is held before the amendment is submitted to the Nuclear Regulatory Commission. Independent reviewers are also appointed to ensure the proposed change can be adequately implemented.

REPORTABILITY

The failure to perform a required surveillance results in a condition prohibited by Technical Specifications. As such, this event is reportable in accordance with 10 CFR 50.73.a.2.i.B.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Beaver Valley Power Station Unit 1	05000334	92	008	00	05	OF 05

TEXT (If more space is required, use additional NRC Form 360A's. (17)

SAFETY IMPLICATIONS

At no time was the margin of safety to the general public reduced. The hydrogen gas concentration in containment is measured by a thermal conductivity cell in the measurement loop located in the analyzer. The conductivity cell output is an amplified, linearized signal which is supplied to the analyzer meter and alarm circuits, with a range of 0 to 10%. The previous calibration procedure tested the analyzer over a range of 0 to 9%. Since the analyzer output is a linear function, the zero (0), four (4), and nine (9) volume percent calibration concentrations could be interpolated to include the 1 volume percent (1%) Technical Specification requirement.

PREVIOUS SIMILAR EVENTS

There has been one previous event that resulted in a missed surveillance due to inadequate change implementation, and is documented in Licensee Event Report 88-005-01, Containment Isolation Valves Omission from Surveillance Testing. Three containment isolation valves were installed in 1982 as part of an extensive fire protection design change. Due to personnel error on the part of the procedure writer responsible for revising the procedure changes, they were omitted from the surveillance test that verified valve closure following a containment isolation signal.