



GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 225 ST. FRANCISVILLE, LOUISIANA 70779

AREA CODE 504 535-6091 346-8861

November 17, 1992

RBG- 37757

File Nos. G9.5, G9.25.1.3

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Gentlemen:

River Bend Station - Unit 1

Docket No. 50-4-3

Please find enclosed Licensee Event Report No. 92-024 for River Bend Station - Unit 1. This report is submitted pursuant to 10CFR50.73.

Sincerely,

W. H. Odell
Manager - Oversight
River Bend Nuclear Group

921173 Bob RCH
LAEJS / FRC/DCH/RWM/kvm

23001

9211230368 921117
PDR ADGCK 05000458
S PDR

IF22
11

cc: U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

NRC Resident Inspector
P.O. Box 1051
St. Francisville, LA 70775

INPO Records Center
1100 Circle 75 Parkway
Atlanta, GA 30339-3064

Mr. C.R. Oberg
Public Utility Commission of Texas
7800 Shoal Creek Blvd., Suite 400 North
Austin, TX 78757

Department of Environmental Quality
Radiation Protection Division
P.O. Box 82135
Baton Rouge, LA 70884-2135
ATTN: Administrator

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.5 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNRB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545-9001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

RIVER BEND STATION

DOCKET NUMBER (2)

05000458

PAGE (3)

1 OF 3

TITLE (4) EQUIPMENT PROBLEMS IN THE CONTROL BUILDING VENTILATION SYSTEM RESULTS IN ENTRY INTO TECHNICAL SPECIFICATION 3.0.3

EVENT DATE (5)			LER NUMBER (6)			REPORT NUMBER (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
10	18	92	92	024	00	11	17	92		05000
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50.73(a)(2)(i)(b). (Check one or more) (11)							
1			20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)	
POWER LEVEL (10)			20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)	
10%			20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		OTHER	
			20.405(a)(1)(iii)		X 50.73(a)(2)(i)		50.73(a)(2)(viii)(A)		(Specify in Abstract below and in Text, NRC Form 366A)	
			20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)			
			20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(ix)			

LICENSEE CONTACT FOR THIS LER (12)

NAME

L.A. ENGLAND, DIRECTOR - NUCLEAR LICENSING

TELEPHONE NUMBER (Include Area Code)

(504) 381-4145

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
X			12	17	92

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On October 18, 1992 at 0355, equipment problems with the control building ventilation system rendered both Divisions of the system inoperable. Chiller HVK*CHL1D tripped while chiller HVK*CHL1B was inoperable due to an ongoing annual preventive maintenance task. The Division I control building ventilation system chillers, HVK*CHL1A and HVK*CHL1C, were inoperable following a fault on panel SCV*PNL8A1. Technical Specification (TS) 3.0.3 was entered and power reduction began at 0409. In NUREG 1022, Supplement 1 ("Licensee Event Report System"), Section II, the answer to question 2.4 states that when TS 3.0.3 is entered, "the plant is operating with a condition prohibited by the plant's Technical Specifications." Therefore, this report is submitted pursuant to 10CFR50.73(a)(2)(i)(b).

At 0622 on October 18, 1992, HVK*CHL1A was restored. This permitted TS 3.0.3 to be exited, and initiation of power ascension.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB-7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
RIVER BEND STATION	05000 458	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 3
		92	- 024 -	00	

TEXT (If more space is required, use additional copies of NRC Form 366A, (17))

REPORTED CONDITION

On October 18, 1992 at 0355, equipment problems with the control building ventilation system rendered both Divisions of the system inoperable. Chiller HVK*CHL1D tripped while chiller HVK*CHL1B was inoperable due to an ongoing annual preventive maintenance task. The Division I control building ventilation system chillers, HVK*CHL1A and HVK*CHL1C, were inoperable following a fault on panel SCV*PNL8A1. Technical Specification (TS) 3.0.3 was entered and power reduction began at 0409. In NUREG 1022, Supplement 1 ("Licensee Event Report System"), Section II, the answer to question 2.4 states that when TS 3.0.3 is entered, "the plant is operating with a condition prohibited by the plant's Technical Specifications." Therefore, this report is submitted pursuant to 10CFR50.73(a)(2)(i)(b).

INVESTIGATION

Problems with HVK*CHL1D were identified at 0211 on October 18, 1992. Troubleshooting efforts resulted in restarting the chiller, but it tripped again at 0311. At 0349, the chiller was restored a second time; however, a faulty flow switch was suspected in the Division II air handling unit. The Division II control building ventilation system (HVK) was declared inoperable at 0355. At 0409, power reduction began in accordance with TS 3.0.3.

The trip of HVK*CHL1D has tentatively been attributed to a faulty airflow switch on one of the air handling units served by the chiller and is still under investigation. The combination of an inoperable safety related control panel (Division I), a chiller trip, (Division II) and another chiller (Division II) being down for an annual PM, led to the entry into TS 3.0.3.

Due to the failure of panel SCV*PNL8A1 on October 16, 1992, all equipment on circuits fed from the panel was declared inoperable, including the Division I control building chillers, HVK*CHL1A and HVK*CHL1C. Maintenance work orders (MWOs) were written to troubleshoot and restore the affected equipment. At 0622 on October 18, 1992, HVK*CHL1A was restored. This permitted TS 3.0.3 to be exited, and initiation of power ascension. Note that the fault on panel SCV*PNL8A1 was due to a failed ground wire that had become loose.

ROOT CAUSE

The combination of an inoperable safety related control panel (Division I), a chiller trip, (Division II) and another chiller (Division II) being down for an annual PM, led to the entry into TS 3.0.3.

NRC FORM 365A (5-92)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB NO. 3100-0104 EXPIRES 5/31/95	
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MN88 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.	
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)		PAGE (3)	
RIVER BEND STATION	05000 458	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 3
		92	024	(0)	

TEXT (If more space is required, use additional copies of NRC Form 365A) (17)

The root cause of the intermittent failure of HVK*CHL1D is still under investigation. GSU will provide a supplement to this report to provide this information by December 17, 1992.

CORRECTIVE ACTION

The corrective action was to restore chiller HVK*CHL1A, declare Division I operable, and exit TS 3.0.3. Additional corrective action was to complete the PM on the Division II chiller, HVK*CHL1B and return it to service. Troubleshooting on Division II chiller, HVK*CHL1D, continues.

SAFETY ASSESSMENT

The intended function of the control room ventilation system is to provide cooling to maintain ambient control room temperatures at design conditions. Technical Specification bases 3/4.7.2, "MAIN CONTROL ROOM AIR CONDITIONING SYSTEM" states in part "The OPERABILITY of the main control room air conditioning system ensures that (1) the ambient air temperature does not exceed the allowable temperature (less than or equal to 104 degrees F) for continuous duty rating for the equipment and instrumentation cooled by this system and (2) the control room will remain habitable for operations personnel during and following all design basis accident conditions. The control room ventilation system was at all times available, but not operable. A plant shutdown was initiated in accordance with TS 3.0.3 and was terminated when the Division I chiller (HVK*CHL1A) became available.