

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:

| | | | | | | |
|--|--|--|--|--|--|--|
| | | | | | | |
|--|--|--|--|--|--|--|

| | | | | | | |
|---|--|--|--|--|--|---|
| 1 | | | | | | 6 |
|---|--|--|--|--|--|---|

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|---|---|---------------|---|---|---|---|---|----|----------------|---|---|---|---|---|---|---|----|------------|--------------|----|---|---|---|---|-------------|----|----|-----|----|----|----|---|---|---|---|---|---|----|----|----|---|---|---|---|---|---|----|----|
| 10 | 1 | 8 | 9 | A | R | A | N | 0 | 14 | 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 13 | 25 | 26 | 4 | 1 | 1 | 1 | 1 | 1 | 14 | 57 | CAT | 58 | 15 | | | | | | | | | | | | | | | | | | |
| | | | LICENSEE CODE | | | | | | | LICENSE NUMBER | | | | | | | | | | LICENSE TYPE | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10 | 1 | 8 | REPORT SOURCE | | | | | | | | | | | | | | | | 16 | 60 | 61 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 8 | 17 | 68 | 69 | 0 | 9 | 1 | 8 | 8 | 2 | 18 | 74 | 75 | 0 | 4 | 2 | 5 | 8 | 5 | 19 | 80 |
| | | | DOCKET NUMBER | | | | | | | | | | | | | | | | EVENT DATE | | | | | | | REPORT DATE | | | | | | | | | | | | | | | | | | | | | | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

| 7 | 8 | 9 | SYSTEM | CAUSE | CAUSE |
|---|---|---|--------|-------|-------|
| 0 | 2 | | | | |
| 0 | 3 | | | | |
| 0 | 4 | | | | |
| 0 | 5 | | | | |
| 0 | 6 | | | | |
| 0 | 7 | | | | |
| 0 | 8 | | | | |

| SYSTEM CODE | | CAUSE CODE | | CAUSE SUBCODE | | COMPONENT CODE | | | | | | COMP SUBCODE | | VALVE SUBCODE | | REVISION | | | | | |
|-------------|--|------------|--|---------------|--|----------------|--|----------------------------|--|----|--|--------------|--|---------------|--|-------------|--|--------------|--|--|--|
| 0 9 8 | | A B 11 | | A 12 | | C 13 | | Z Z Z Z Z Z 14 | | | | | | Z 15 | | Z 16 | | | | | |
| 7 | | 9 | | 11 | | 12 | | 13 | | 18 | | | | | | 19 | | 20 | | | |
| LER/RO | | EVENT YEAR | | --- | | SEQUENTIAL | | OCCURRENCE | | | | | | REPORT | | | | REVISION | | | |
| 17 | | 1 | | 2 | | 24 | | 28 | | | | | | 30 | | 31 | | 32 | | | |
| REPORT | | 1 | | 2 | | 24 | | 28 | | | | | | 30 | | 31 | | 32 | | | |
| NUMBER | | 21 | | 23 | | 26 | | 29 | | | | | | 30 | | 31 | | 32 | | | |
| ACTION | | FUTURE | | EFFECT | | SHUTDOWN | | ATTACHMENT | | | | | | NPRD-4 | | PRIME COMP. | | COMPONENT | | | |
| TAKEN | | ACTION | | ON PLANT | | METHOD | | SUBMITTED | | | | | | FORM SUB | | SUPPLIER | | MANUFACTURER | | | |
| 1 | | 2 | | 3 | | 4 | | 5 | | | | | | 6 | | 7 | | 8 | | | |
| 33 | | 34 | | 35 | | 36 | | 41 | | | | | | 42 | | 43 | | 47 | | | |
| X | | Z | | Z | | Z | | Y | | | | | | N | | Z | | Z | | | |
| 18 | | 19 | | 20 | | 21 | | 23 | | | | | | 24 | | 25 | | 26 | | | |
| 33 | | 34 | | 35 | | 36 | | 41 | | | | | | 42 | | 43 | | 47 | | | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | 1 The personnel performing the test did not realize that the opening in the wall had a fire curtain. It appeared

1 1 | 1 that the opening was to provide ventilation for the battery room (a similar opening for the other battery room

1 2 | 1 had a grill covering the opening). The cables were left overnight without a fire watch, but the cables were

1 3 | 1 removed the next morning as soon as the error was discovered. Electrical maintenance personnel who performed

1 4 | 1 the battery test received a review of this occurrence and were advised to maintain a fire watch (Continued)

| FACILITY STATUS | | | | | | | | | | % POWER | | OTHER STATUS | | METHOD OF DISCOVERY | | DISCOVERY DESCRIPTION | | |
|-----------------|---|---|---|-----|----|---|---|---|-----|---------|----|--------------|----|---------------------|-----|-----------------------|---------------|-----|
| 1 | 5 | 1 | H | 128 | 10 | 0 | 0 | 0 | 129 | 1 | NA | 130 | 1 | B | 131 | 1 | QC Inspection | 132 |
| 7 | 8 | 9 | | | 10 | | | | 12 | 13 | | 44 | 45 | | 46 | | | 80 |

| ACTIVITY RELEASED | | CONTENT OF RELEASE | | AMOUNT OF ACTIVITY | | LOCATION OF RELEASE | |
|---------------------|----|--------------------|----|--------------------|----|---------------------|----|
| 1 | 6 | 1 | 2 | 1 | 35 | 1 | 36 |
| 8 | 33 | 10 | 34 | 44 | 45 | 80 | |
| PERSONNEL EXPOSURES | | | | | | | |

| PERSONNEL EXPOSURES | | | | | | | | | | | | | 44 | 45 | 80 | |
|---------------------|---|--|------|----|----|-------------|---|----|----|--|--|--|----|----|----|--|
| NUMBER | | | TYPE | | | DESCRIPTION | | | | | | | | | | |
| 1 | 7 | | 0 | 0 | 0 | 37 | 2 | 38 | NA | | | | | | | |
| 8 | 9 | | 11 | 12 | 13 | | | | | | | | | | | |

| PERSONNEL INJURIES | | | | | | | | | | 80 |
|--------------------|---|----|----|---|-------------|----|----|--|--|----|
| NUMBER | | | | | DESCRIPTION | | | | | |
| 1 | 8 | 1 | 0 | 0 | 0 | 40 | NA | | | 41 |
| 8 | 9 | 11 | 12 | | | | | | | 80 |

| LOSS OF OR DAMAGE TO FACILITY | | 80 |
|-------------------------------|-------------|----|
| TYPE | DESCRIPTION | |
| 1 9 | 2 42 NA | 43 |

[illegible]

NAME OF PREPARER: Patrick Rogers

PHONE: (501) 964-3100

IE 22
111

LICENSEE EVENT REPORT

EXHIBIT A

LER NO. 50-368/82-029/03X-1

Cause Description and Corrective Actions (Continued)

when using this opening for cable routing while conducting the battery test. The opening in the wall has been marked to indicate the presence of a fire curtain. To prevent recurrence, the station battery maintenance procedure has been revised to include precautions and guidelines in appropriate steps of the procedure regarding fire dampers and fire doors. This procedure change was effective on 12/22/82. In addition, fire barriers and fire barrier penetrations have been uniquely identified, and supplemental guidance has been issued for maintenance activities affecting fire barriers.



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

April 25, 1985

2CAN048509


U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report
No. 82-029/03X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning four electrical cables used for a station battery capacity test. The cables were pulled through a fire curtain, and a fire watch had not been established as required by the Technical Specifications. This is an update to a previous submittal dated October 15, 1982.

Very truly yours,


J. Ted Enos
Manager, Licensing

JTE:RJS:ds

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, DC 20555

JE22
/1