

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Wolf Creek Generating Station

DOCKET NUMBER (2)
0 5 0 0 0 4 8 2 1 OF 0 2

PAGE (3)
1 OF 0 2

TITLE (4)

Inadvertant ESF Actuation - Fuel Building and Control Room Ventilation Isolation

EVENT DATE (6)			LER NUMBER (8)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	4	0	7	8	5	8	5	0	0	0	0
0	4	0	7	8	5	0	0	0	5	0	3
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)								
5			20.402(b)			20.406(e)			X 50.73(a)(2)(iv)		
POWER LEVEL (10)			20.406(a)(1)(i)			50.38(e)(1)			73.71(b)		
0 0 1 0			20.406(a)(1)(ii)			50.38(e)(2)			73.71(e)		
			20.406(a)(1)(iii)			50.73(a)(2)(i)			OTHER (Specify in Abstract below and in Text, NRC Form 366A)		
			20.406(a)(1)(iv)			50.73(a)(2)(ii)					
			20.406(a)(1)(v)			50.73(a)(2)(iii)					

LICENSEE CONTACT FOR THIS LER (12)

NAME
Merlin G. Williams - Superintendent of Regulatory, Quality and Administrative Services

TELEPHONE NUMBER
AREA CODE 31 1 6 3 1 6 4 1 - 1 8 1 8 1 3 1 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	
A										

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 1038 CST on April 7, 1985, an Engineered Safety Features (ESF) actuation occurred when an I&C Technician inadvertently actuated a Fuel Building Ventilation Isolation Signal (FBVIS). This signal also resulted in a Control Room Ventilation Isolation Signal (CRVIS). All required engineered safety features equipment responded properly.

The plant was in Mode 5 at the time and this event posed no threat to the public health or safety.

8505090619 850503
PDR ADOCK 05000482
S PDR

IE 22
//

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1) Wolf Creek Generating Station	DOCKET NUMBER (2) 0 5 0 0 0 4 8 2 8 5 - 0 0 6 - 0 0 0 2 OF 0 2	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

At 1038 CST on April 7, 1985, a Fuel Building Ventilation Isolation Signal (FBVIS) and a Control Room Ventilation Isolation Signal (CRVIS) occurred on "A" Train as a result of an I&C Technician inadvertently depressing a manual actuation push button on a circuit board in the Engineered Safety Features Actuation System (ESFAS) cabinets. All required engineered safety features equipment responded properly.

At the time of the event, the plant was in mode 5 and the ESFAS cabinets were being restored to normal following minor modifications installed under Work Request 03802-85. Part of the restoration procedure required removal and reinsertion of the decoder boards (6N247) to allow reset of the automatic test insertion function. While reinserting the decoder board in one cabinet, the I&C Technician inadvertently depressed a FBVIS Train "A" manual actuation push button located on the front of an adjacent circuit board.

The channel was reset, and the Fuel Building Ventilation System and the Control Room Ventilation System were returned to normal per plant operating procedures at 1133.

This cognitive personnel error was reviewed with I&C personnel by the I&C Coordinator. During this discussion, the extreme caution necessary to avoid inadvertently actuating or upsetting plant equipment while working in powered cabinets was emphasized. In addition, this Licensee Event Report is included in required reading for I&C personnel.



KANSAS GAS AND ELECTRIC COMPANY

GLENN L. KOESTER
VICE PRESIDENT - NUCLEAR

May 3, 1985

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

COPY FOR

Mr. R.P. Denise, Director
Wolf Creek Task Force
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

KMLNRC 85-104
Re: Docket No. STN 50-482
Subj: Licensee Event Report 85-006-00

Gentlemen:

The enclosed Licensee Event Report is submitted pursuant to 10 CFR 50.73 (a)(2)(iv) concerning an Engineered Safety Feature actuation.

Yours very truly,

Glenn L. Koester

GLK:bb
Enc.
xc:PO'Connor (2), w/a
JCummins, w/a

IE22
1/1