

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Joseph M. Farley - Unit 1DOCKET NUMBER (2)
0 5 0 0 0 3 4 8PAGE (3)
1 OF 0 1TITLE (4)
Inoperable Fire DoorEVENT DATE (5)
MONTH DAY YEAR
0 4 1 1 8 5 8 5LER NUMBER (6)
0 0 7REPORT DATE (7)
MONTH DAY YEAR
0 0 5 1 0 8 5

OTHER FACILITIES INVOLVED (8)

FACILITY NAME
J. M. Farley - Unit 2DOCKET NUMBER (9)
0 5 0 0 0 3 6 4THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 6 (Check one or more of the following) (11)
OPERATING MODE (10) 6
POWER LEVEL (10) 0 0 0
20.402 (b) 20.405 (a) 00.73 (a) (2) (iv) 73.71 (b)
20.405 (a) (1) (i) 00.73 (a) (2) (v) 73.71 (c)
20.405 (a) (1) (ii) 00.73 (a) (2) (vi) X OTHER (Specify in Abstract below and in Test, NRC Form 206A)
20.405 (a) (1) (iii) 00.73 (a) (2) (vii) (A) Special Report per
20.405 (a) (1) (iv) 00.73 (a) (2) (vii) (B) Tech. Spec. 3.7.12
20.405 (a) (1) (v) 00.73 (a) (2) (vii) (C)

LICENSEE CONTACT FOR THIS LER (12)

NAME
J. D. Woodard

TELEPHONE NUMBER

AREA CODE
2 0 5 8 9 9 - 5 1 5 6

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) X NO
EXPECTED SUBMISSION DATE (15)
MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 0005 on 4-11-85, fire door 401 was declared inoperable and could not be repaired within seven days. Therefore, this special report is submitted in accordance with the requirements of Technical Specification 3.7.12. Technical Specification 3.7.12 requirements for verifying the operability of fire detectors on at least one side of the non-functional fire barrier and establishing an hourly fire watch were met.

The fire door was declared inoperable due to a loose auto-closure mechanism and loose astragal. While attempting to repair the door, additional problems were found and it was determined that the door assembly should be replaced. A new door assembly has been ordered and is expected to be received on 6-24-85. Repairs will be completed as soon as practicable after the door has been received. Fire watch requirements continue to be met and a fire watch will be maintained until the door is replaced and determined functional. Health/safety of the public was not affected by this event.

B505170071 B50510
PDR ADDOCK 05000348
PDR

JE22

Mailing Address

Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6090

R. P. McDonald

Senior Vice President
Flintridge Building



Alabama Power

the southern electric system

May 10, 1985

Docket No. 348

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 1, Licensee Event Report No. LER 85-007-00 is forwarded in accordance with 10CFR50.73 to provide 30 day written notification of the occurrence.

If you have any questions, please advise.

Yours very truly,

R. P. McDonald

RPM/DSM:sam

Enclosure

xc: IE, Region II

IE22
11