



Serving The Best Location in the Nation
PERRY NUCLEAR POWER PLANT

May 7, 1985
PY-CEI/OIE-00042LO

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

RE: Perry Nuclear Power Plant
Docket Nos. 50-440; 50-441
Potential Leakage Path in
Electronics Housing Threads
of Transmitters Supplied by
Rosemount [RDC 115(84)]

Dear Mr. Keppler:

This letter serves to update the status of our corrective actions associated with Rosemount Model 1153 Series B Pressure Transmitters as discussed in our Final Report dated January 24, 1985. These transmitters had potential for a leakage path in the seal of the threads between the sensor module and the electronics housing.

All subject Rosemount transmitters have been repaired by the vendor and returned to the site. The corrective actions necessary for resolution of the reported deficiency have now been completed. The reinstallation of Unit 1 transmitters will be completed consistent with the Preoperational Test schedule.

Sincerely,

Murray R. Edelman
Vice President
Nuclear Group

MRE:sab

cc: Mr. J. A. Grobe
USNRC Site Office (SBB50)

Mr. D. E. Keating
USNRC Site Office (SBB50)

Records Center, SEE-IN
Institute of Nuclear Power
Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8505170512 850507
PDR ADOCK 05000440
S PDR

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

MAY 9 1985

IE27
985 1/0