



Tennessee Valley Authority, Post Office Box 10, Soddy-Daisy, Tennessee 37379

J. L. Wilson
Vice President, Sequoyah Nuclear Plant

September 30, 1992


U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - LICENSEE EVENT REPORT
(LER) 50-328/92012

The enclosed LER provides details concerning a manual start of the auxiliary feedwater system resulting from a secondary system perturbation. This event is being reported in accordance with 10 CFR 50.73(a)(2)(iv) as an event that resulted in the manual actuation of engineered safety features.

Sincerely,


J. L. Wilson

Enclosure
cc: See page 2

656129

9210480034 920930
PDR ADDCK 05000328
S PDR

LE22
11

U.S. Nuclear Regulatory Commission

Page 2

September 30, 1992

cc (Enclosure):

INPO Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. D. E. LaBarge, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

NRC Resident Inspector
Sequoyah Nuclear Plant
2600 Igou Ferry Road
Soddy-Daisy, Tennessee 37379

Mr. B. A. Wilson, Project Chief
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Sequoyah Nuclear Plant, Unit 2 DOCKET NUMBER (2) PAGE (3)
10500013 2 8 11 OF 0 5

TITLE (4) Manual Auxiliary Feedwater Start as a Result of a Secondary System Perturbation.

EVENT DAY (5)			LER NUMBER (6)		REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
			SEQUENTIAL	REVISION				FACILITY NAMES	DOCKET NUMBER(S)										
MONTH	DAY	YEAR	NUMBER	NUMBER	MONTH	DAY	YEAR												
0	9	0	4	9	2	0	1	2	0	0	0	9	3	0	9	2		10500013	
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following)(11)																	
1		20.402(b)		20.405(c)		XX 50.73(a)(2)(iv)		73.71(b)											
POWER		20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)											
LEVEL		20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		OTHER (Specify in											
(10) 0 0 8		20.405(a)(1)(iii)		50.73(a)(2)(i)		50.73(a)(2)(viii)(A)		Abstract below and in											
		20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)		Text, NRC Form 366A)											
		20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)													

LICENSEE CONTACT FOR THIS LER (12)

NAME J. W. Proffitt, Compliance Licensing TELEPHONE NUMBER
AREA CODE 6 1 5 8 4 3 - 6 6 5 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) X NO
DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On September 4, 1992, at 0214 Eastern daylight time (EDT), Fire Operations personnel reported a fire at the B-phase main transformer neutral bushing to the main control room. The Unit 1 assistant shift operations supervisor was dispatched to the area as the incident commander. An emergency shutdown was initiated utilizing Abnormal Operating Instructions. Unit load was decreased at a rate of 5 percent per minute, and at 9 percent reactor power, the main turbine was manually tripped. At approximately 0256 EDT, with reactor power at approximately 8 percent, the isolation valves on all three strings of intermediate pressure condensate heaters automatically began to close as a result of high-high heater levels. Operations personnel recognized that suction would be lost to the operating main feedwater (MFW) pump, manually started all auxiliary feedwater (AFW) pumps, and tripped the operating MFW pump. Reactor power was reduced, and the plant was stabilized at 1 percent rated thermal power.

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)			
		YEAR	NUMBER	REVISION	NUMBER				
Sequoyah Nuclear Plant, Unit 2		05	00	03	28	19	12	00	01
		05	00	03	28	19	12	00	01

TEXT (If more space is required, use additional NRC Form 366A's) (17)

I. PLANT CONDITIONS

Unit 2 was in power operation at approximately 8 percent reactor thermal power.

II. DESCRIPTION OF EVENT

A. Event

On September 4, 1992, at 0214 Eastern daylight time (EDT), Fire Operations personnel reported a fire at the B-phase main transformer (EIIIS Code EL) neutral bushing to the main control room. The Unit 1 assistant shift operations supervisor was dispatched to the area as the incident commander. Emergency actions were taken to combat the fire using a dry chemical in suppressing the fire, but due to the heat present at the bushing, the fire reignited. An emergency shutdown was commenced utilizing Abnormal Operating Instructions in order to deenergize the transformer and remove the heat source. Unit load was decreased from 100 percent power at a rate of 5 percent per minute, and at 9 percent reactor power, the main turbine was manually tripped. With the transformer removed from service, the fire was extinguished.

At approximately 0256 EDT, with reactor power at approximately 8 percent, the isolation valves on all three strings of intermediate pressure condensate heaters automatically began to close as a result of high-high heater levels. Operations personnel recognized that suction would be lost to the operating main feedwater (MFW) (EIIIS Code SJ) pump, manually started all auxiliary feedwater (AFW) (EIIIS Code BA) pumps, and tripped the operating MFW pump. Reactor power was reduced, and the plant was stabilized at 1 percent rated thermal power.

B. Inoperable Structures, Components, or Systems That Contributed to the Event

None.

C. Dates and Approximate Times of Major Occurrences

1. September 4, 1992 at 0214 EDT A fire on the 23 main transformer was reported to the main control room.
2. September 4, 1992 at 0220 EDT Load reduction was started in accordance with procedures at a rate of 5 percent per minute.
3. September 4, 1992 at 0241 EDT With the unit at approximately 9 percent power, the turbine was manually tripped off-line.
4. September 4, 1992 at 0256 EDT AFW was manually started, and the MFW pump was tripped after the No. 2 heater string isolated.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)			
		SEQUENTIAL		REVISION							
		YEAR	NUMBER	NUMBER	NUMBER	NUMBER	NUMBER				
Sequoyah Nuclear Plant, Unit 2	05000328	92	012	0	0	0	0	0	3	OF	5

TEXT (if more space is required, use additional NRC Form 366A's) (17)

5. September 4, 1992 The unit entered Mode 2.
at 0257 EDT

6. September 8, 1992 NRC was notified of the AFW start.
at 0526 EDT

D. Other Systems or Secondary Functions Affected

None.

E. Method of Discovery

The No. 2 heater string isolation was discovered during observations of plant parameters by main control room Operations personnel following the rapid runback as a result of the fire on the transformer.

F. Operator Actions

When the fire was reported, Operations personnel were immediately dispatched to the area to determine the extent of the fire and assume the incident commander responsibilities. With the firefighting efforts in progress, Operations performed a rapid power reduction, in accordance with plant procedures, and removed the main generator from service. As a result of the No. 2 heater string isolation, Operations personnel immediately started the AFW pumps and tripped the main feedwater pump (MFP). The plant was subsequently placed in a stable condition.

G. Safety System Responses

The auxiliary feedwater system performed as expected.

III. CAUSE OF EVENT

A. Immediate Cause

Auxiliary feedwater was manually started as a result of a heater string isolation, following a condensate and feedwater transient resulting from the rapid reduction in power.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	NUMBER	REVISION			
Sequoyah Nuclear Plant, Unit 2	050003128912	0	1	2	0	0	4 OF 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

B. Root Cause

The root cause of the feedwater heater isolation was determined to be a normal system response following a rapid power reduction. It was determined that, under the transient condition (i.e., rapid power reduction), the pressure in the No. 2 heater would equalize with that of the No. 3 heater drain tank and then would not drain. Therefore, a high level in the heaters occurred and the subsequent isolation of the heater string.

C. Contributing Factors

None.

IV. ANALYSIS OF EVENT

Plant equipment required to operate after AFW was manually started performed as expected, and plant parameters were within expected ranges. Therefore, the event did not adversely affect the health and safety of plant personnel or the public.

V. CORRECTIVE ACTION

A. Immediate Corrective Actions

When the fire was reported, Operations personnel were immediately dispatched to the area to determine the extent of the fire and assume the incident commander responsibilities. With the firefighting efforts in progress, Operations performed a rapid power reduction, in accordance with plant procedures, and removed the main generator from service. As a result of the No. 2 heater string isolation, Operations personnel immediately started the AFW pumps and tripped the MFP. The plant was subsequently placed in a stable condition.

The 2B main transformer was repaired, tested, and returned to service.

B. Corrective Actions to Prevent Recurrence

None.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	NUMBER	REVISION			
Sequoyah Nuclear Plant, Unit 2	050003 28 9 2	--	0 1 2	--	0 0	0 5	0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

VI. ADDITIONAL INFORMATION

A. Failed Components

None.

B. Previous Similar Events

A review of previously reported events identified several events associated with condensate and feedwater heater isolations. Although these events involved heater string isolations, the problems were not similar (i.e., involved failure of components) to the problem discussed in this LER. Therefore, the corrective action could not have prevented this event.