

# LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 N C B E P 1 2 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 1 5

1 1 L 6 0 5 0 - 0 3 2 5 1 0 7 1 6 7 9 8 0 8 1 4 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 The surveillance time limit requirement for PT 1.1i, Core Performance Parameter Check,  
 3 was exceeded by 2 hours due to a failure of the transverse incore probe machine ID.  
 4 Core parameters per OD-1 could not be determined during this time. The surveillance  
 5 requirements exceeded were 4.2.1a, 4.2.2a, 4.2.3a, 4.2.4a. Power was reduced  
 6 25 MWe to increase margin to core limits.  
 7 (Technical Specifications 3.2.1, 3.2.2, 3.2.3, 3.2.4, 6.9.1.9b)

8

3 R B 11 E 12 X 13 M E C F U N 14 Z 15 Z 16  
 7 9 0 4 6 0 3 L 0  
 E 17 Z 18 Z 19 Z 20 0 0 0 0 0 N 21 Y 22 N 23 G 24 O 25 8 26 0 27

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

9 The spring tension holding the probe to the counter had loosened allowing the probe to  
 10 slip while the counter continued to count. When "Full In" was reached by counter indi-  
 11 cation, the probe was determined to still be below the bottom of the core. The spring  
 12 tension was adjusted and its operation was satisfactory. The PT was completed and all  
 13 core data was normal. This is considered an isolated event and no further action is requir

1 E 2 0 7 2 NA 3 B 31 Periodic Test  
 4 Z 5 Z NA 6 NA  
 7 0 0 0 8 Z NA  
 9 0 0 0 10 NA  
 11 Z 12 NA  
 13 N 14 NA  
 15 7908200299