

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: ①

LICENSE CODE LICENSE NUMBER LICENSE TYPE AND CLASS

REPORT SOURCE 1 6 0 1 5 10 10 10 13 16 16 7 0 2 8 1 0 1 2 1 7 1 9 1 5 10 18 11 10 17 19 1

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

12	While performing calibration procedure HRP-2-5279 as part of routine
13	surveillance; the 2E41-N012C setpoint was found to exceed the Tech. Spec.
14	limit. There have been no similar occurrences of this type. The 2E41-N012C
15	is the HPCI Turbine exhaust diaphragm pressure switch. There were no effects
16	on the environs.

SYSTEM CODE S F 11		CAUSE CODE E 12		CAUSE SUBCODE E 13		COMPONENT CODE I N I S T R U 14		COMP SUBCODE S 15		VALVE SUBCODE Z 16	
EVENT YEAR 7 1 9 22		SEQUENTIAL REPORT NO. 0 9 1 0 24		OCCURRENCE CODE 0 1 3 25		REPORT TYPE L 30		REVISION NO. C 32		COMPONENT MANUFACTURER B I O L O G 37	
ACTION FUTURE TAKEN ACTION 16 18 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 37		ATTACHMENT SUBMITTED N 23		NVRD-4 PCAM SUB. N 24	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (37)		WRITE COMP SUPPLIER N 25		NVRD-4 PCAM SUB. N 24		WRITE COMP SUPPLIER N 25		NVRD-4 PCAM SUB. N 24		WRITE COMP SUPPLIER N 25	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1. Instrument drift was determined to be the cause of the incorrect setpoint. The instrument was recalibrated per procedure HNP-2-5279 and surveillance procedure HNP-2-3309 was performed successfully. The instrument drift was from 9 psig to 12 psig with a Tech. Spec. limit of less than or equal to 10 psig.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1.5	5	11010		NA		B		Surveillance testing	
ACTIVITY CONTENT RELEASED OR RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE					
1.6	7	2		NA					

PERSONNEL EXPOSURES		DESCRIPTION	NA
NUMBER	TYPE		
101010	(1) (7) (2)		

PERSONNEL INQUIRIES
DATE: 12-16-10
DESCRIPTION: (41)

7908200352

RA

[illegible]