

POOR ORIGINAL

This L.E.R refers to main steam sample line inboard isolation valve inoperable. The applicable Technical Specifications are 6.9.2.b (2) and 3.7.D.2.

LICENSEE EVENT REPORT

1. 0 6 3 0 7 9 0 1 0 4 8 0

During surveillance testing, main steam sample line inboard isolation valve, AO-3-2-316, failed close. In accordance with Technical Specification 3.7.D.2, the redundant outboard isolation valve was operable and closed. The daily surveillance requirements for the redundant isolation valve were performed until the failed valve could be checked during the recent Unit 3 refueling outage.

S D X Z V A L V O P D Z
7 9 0 2 1 0 3 X 1
A Z Z Z 0 0 0 0 N Y N B 2 9 5

The valve was inspected during the refueling outage. It operated (stroked) satisfactorily. Most probable cause of valve failure to close was valve packing binding or solenoid valve sticking when the valve was at high temperature. As precautionary measure, packing and solenoid were replaced. A local leak rate test was performed and valve satisfactorily operated.

E 1 0 0 NA B Surveillance Testing

Z Z NA NA

0 0 0 Z NA

0 0 0 NA

Z NA

N NA

90012504

M. J. Cooney
M. J. Cooney

(215) 841-5020

S 8001100 453