

LICENSEE EVENT REPORT

Revision August 5, 1976

CONTROL BLOCK:

| | | | | | |
|--|--|--|--|--|--|
| | | | | | |
|--|--|--|--|--|--|

(PLEASE PRINT ALL REQUIRED INFORMATION)

| LICENSEE NAME | | | | | | LICENSE NUMBER | | | | | | | | | | LICENSE TYPE | | | | | EVENT TYPE | | | |
|---------------|---|---|---|---|---|----------------|----|---|---|---|---|---|---|---|---|--------------|----|----|---|---|------------|----|----|----|
| 01 | N | J | O | C | P | 1 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 0 | 3 |
| 7 | 8 | 9 | | | | 14 | 15 | | | | | | | | | | 25 | 26 | | | | 30 | 31 | 32 |

| CATEGORY | | REPORT TYPE | REPORT SOURCE | DOCKET NUMBER | | | | | | EVENT DATE | | | | | REPORT DATE | | | | | | | | |
|----------|------|-------------|---------------|---------------|----|----|---|---|---|------------|---|----|----|---|-------------|---|----|----|---|---|---|---|---|
| 01 | CONT | L | L | | 0 | 5 | 0 | - | 0 | 2 | 1 | 9 | 0 | 7 | 0 | 1 | 7 | 6 | 0 | 8 | 0 | 5 | 7 |
| 7 | 8 | 57 | 58 | 59 | 60 | 61 | | | | | | 68 | 69 | | | | 74 | 75 | | | | | |

EVENT DESCRIPTION

02 While performing the emergency condenser automatic actuation test, it was found
 03 that the RE15C trip point was less conservative than specified in the Technical
 04 Specifications. The pressure switch was immediately reset to trip at 1064 psig
 05 which is more conservative than the 1066 psig specification. (50-219/76-18-3L)
 06

| SYSTEM CODE | CAUSE CODE | COMPONENT | | | | | PRIME COMPONENT SUPPLIER | COMPONENT MANUFACTURER | | | VIOLATION | | | | |
|-------------|------------|-----------|----|----|----|---|--------------------------|------------------------|----|----|-----------|---|---|----|----|
| 07 | S | D | E | C | K | T | E | R | K | N | 8 | 0 | 7 | 0 | Y |
| 7 | 8 | 9 | 10 | 11 | 12 | | | | 17 | 43 | 44 | | | 47 | 48 |

CAUSE DESCRIPTION

08 The cause was a lack of accuracy within the device. The instrument was operating
 09 within its design accuracy.
 10

| FACILITY STATUS | % POWER | OTHER STATUS | | | METHOD OF DISCOVERY | | DISCOVERY DESCRIPTION | |
|-----------------|---------|--------------|----|----|---------------------|----|-----------------------|----|
| 11 | E | 0 | 9 | 2 | NA | B | | NA |
| 7 | 8 | 9 | 10 | 12 | 13 | 44 | 45 | 46 |

| FORM OF ACTIVITY RELEASED | CONTENT OF RELEASE | AMOUNT OF ACTIVITY | | | LOCATION OF RELEASE | |
|---------------------------|--------------------|--------------------|----|----|---------------------|----|
| 12 | Z | | | NA | | NA |
| 7 | 8 | 9 | 10 | 11 | 44 | 45 |

PERSONNEL EXPOSURES

| NUMBER | TYPE | DESCRIPTION | | | |
|--------|------|-------------|----|----|----|
| 13 | 0 | 0 | 0 | 2 | NA |
| 7 | 8 | 9 | 11 | 12 | 13 |

PERSONNEL INJURIES

| NUMBER | DESCRIPTION | | | |
|--------|-------------|---|----|----|
| 14 | 0 | 0 | 0 | NA |
| 7 | 8 | 9 | 11 | 12 |

Probable Consequences

| | | |
|----|----|---|
| 15 | NA | |
| 7 | 8 | 9 |

LOSS OR DAMAGE TO FACILITY

| TYPE | DESCRIPTION | | |
|------|-------------|---|----|
| 16 | NA | | |
| 7 | 8 | 9 | 10 |

PUBLICITY

| | | |
|----|----|---|
| 17 | NA | |
| 7 | 8 | 9 |

ADDITIONAL FACTORS

| | | |
|----|----|---|
| 18 | NA | |
| 7 | 8 | 9 |

| | | |
|----|---|---|
| 19 | | |
| 7 | 8 | 9 |

Donald A. Ross, Manager

Generating Stations-Nuclear

PHONE 201-539-6111

8/03020459