

LICENSEE EVENT REPORT

CONTROL BLOCK: _____

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME [01] N J O C P 1										LICENSE NUMBER [00] 0 - 0 0 0 0 0 - 0 0										LICENSE TYPE [4] 1 1 1 1					EVENT TYPE [0] 1		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		
[01] CONT		CATEGORY [] []		REPORT TYPE [T]		REPORT SOURCE [L]		DOCKET NUMBER [0] 5 0 - 0 2 1 9										EVENT DATE [7] 6 0 4 0 1					REPORT DATE [7] 6 0 4 1 3				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		

EVENT DESCRIPTION

[02] During routine quarterly automatic actuation test for containment spray system II, the trip point for drywell high pressure switches 1P15B and 1P15D was found to be less conservative than the Technical Specification limit. The loss of sensor redundancy occurred. Corrective action was taken by resetting switches 1P15B and 1P15D to trip within Technical Specification limits.

[03] (Reportable Occurrence No. 50-219/76-9-3L)

[04]

[05]

[06]

SYSTEM CODE [07] S B		CAUSE CODE [F]		COMPONENT CODE [S] W I T C H				FUEL COMPONENT SUPPLIER [N]		COMPONENT MANUFACTURER [8] 0 8 0				VIOLATION [Y]	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

CAUSE DESCRIPTION

[08] Two (2) Barton Instrument Co., Division of ITT, Model 278 pressure switches failed to have trip points within the 2.0 psig Technical Specification limit for drywell high pressure sensors. The cause is attributed to instrument setpoint drift.

[09] The switches were reset.

[10]

FACILITY STATUS [11] F		% POWER [0] 8 6		OTHER STATUS NA		METHOD OF DISCOVERY [B]		DISCOVERY DESCRIPTION NA							
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
FORM OF ACTIVITY RELEASED [12] Z		CONTENT OF RELEASE [Z]		AMOUNT OF ACTIVITY NA				LOCATION OF RELEASE NA							
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

PERSONNEL EXPOSURES

NUMBER [13] 2 2 2		TYPE [Z]		DESCRIPTION NA											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

PERSONNEL INJURIES

NUMBER [14] 2 2 2		DESCRIPTION NA													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

Probable Consequences

[15] NA															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

LOSS OR DAMAGE TO FACILITY

TYPE [16] Z		DESCRIPTION NA													
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

PUBLICITY

[17] NA															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

ADDITIONAL FACTORS

[18] Cause Code - Instrument Repeatability															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

[19]															
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

NAME Donald A. Ross

PHONE 201-539-6111

OFF. MAIL ROOM

8103020490