

CONTROL BLOCK

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: N J O C P I  
 LICENSE NUMBER: 00-000000-000  
 LICENSE TYPE: 41110  
 EVENT TYPE: 01

REPORT TYPE: M I  
 REPORT SOURCE: T L  
 DOCKET NUMBER: 050-0219  
 EVENT DATE: 010676  
 REPORT DATE: 011476

EVENT DESCRIPTION

Local leak rate tests revealed that reactor building to torus vacuum breakers V-26-16 and V-26-18 had a combined leakage rate in excess of the limits specified in Technical Specification 4.5.F.1.C and 10 CFR 50 Appendix J.

SYSTEM CODE: S D  
 CAUSE CODE: F  
 COMPONENT CODE: V A L V E X  
 PRIME COMPONENT SUPPLIER: L  
 COMPONENT MANUFACTURER: F 1 3 0  
 VIOLATION: Y

CAUSE DESCRIPTION

Cause is unknown at this time. Valves V-26-16 and V-26-18 will be adjusted and/or repaired and retested to assure their ability to satisfy leakage requirements.

FACILITY STATUS: H  
 POWER: 000  
 OTHER STATUS: NA  
 METHOD OF DISCOVERY: B  
 DISCOVERY DESCRIPTION: Local Leak Rate Tests

FORM OF ACTIVITY RELEASED: Z  
 CONTENT OF RELEASE: Z  
 AMOUNT OF ACTIVITY: NA  
 LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER: 000  
 TYPE: Z  
 DESCRIPTION: NA

PERSONNEL INJURIES

NUMBER: 000  
 DESCRIPTION: NA

OFFSITE CONSEQUENCES

NA

LOSS OR DAMAGE TO FACILITY

TYPE: Z  
 DESCRIPTION: NA

PUBLICITY

NA

ADDITIONAL FACTORS

Valves V-26-16 and V-26-18 are replacement valves which were installed during the 1975 Refueling Outage because the original valves would not meet the leakage requirements (Abnormal Occurrence 75-10).

NAME: Donald A. Ross  
 PHONE: 201-539-6111  
 Donald A. Ross, Manager-Generating Stations-Nuclear