



P.O. BOX 270
HARTFORD, CONNECTICUT 06101
(203) 548-6811

February 10, 1981

HP-1-1711

Mr. Boyce H. Grier
Director, Region I
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

REFERENCE: Provisional license DPR-21
Docket Number 50-245
Reportable Occurrence RO-81-01/1P



Dear Mr. Grier:

This letter is forwarded to provide prompt notification of Reportable Occurrence RO-81-01/1P as required by the Millstone Unit 1 Technical Specifications.

On February 9, 1981 at 1120 hours, Class I Inservice Inspection of Low Pressure Coolant Injection System (LPCI), subsystem B, revealed a flaw in a pipe weld between the primary containment penetration and the Inboard Isolation Check Valve. The cause of failure is not known at the present time; an investigation is in progress.

Additional information including the cause of failure and corrective action will be included in a 14 day follow-up report.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

E. J. Mroczka
Station Superintendent
Millstone Nuclear Power Station

HJB/EJM:rmw

cc: Director, Office of Management Enforcement and Program Control,
Washington, D.C. (2)

Director, Office of Management Information and Program Control,
Washington, D.C.

U.S. Nuclear Regulatory Commission, c/o Document Management
Branch, Washington, D.C. 20555

BO/9
S
1/0

8108050 629