

ABNORMAL OCCURRENCE REPORT

50-213

Report Number: 50-213/75-3
Report Date: September 5, 1975
Occurrence Date: September 4, 1975
Facility: Haddam Neck Plant
Connecticut Yankee Atomic Power Company
Identification of Occurrence: Correspondence CYH-3058; September 5, 1975;
Tech. Spec. B, Section 2.3.3.1; Diss. Oxygen
Conditions Prior to Occurrence: Steady State Power

Description of Occurrence:

A greater than 2 delta dissolved oxygen alarm was received across the plants cooling water on 9/4 at 0930. Grab samples were taken and analyses made to verify conditions. It was not immediately apparent what could be causing this condition and sampling indicated we were back in specifications by 1235 on the same day. The grab samples also identified that the continuous monitors were not functioning properly even though they had alarmed. We switched to our back-up system. Attachment A is a record of our continuous monitoring results and grab samples spanning this period.

Designation of Apparent Cause of Occurrence:

Unusual Service Condition Including Environmental

Analysis of Occurrence:

There was no traceable plant event that paralleled the time span of this occurrence. However, dredging in the canal upstream of the monitor had started on the same day. It is conceivable and believed that reducing material loosened on the start of the dredging operation scavenged oxygen from the canal water. The dissolved oxygen parameters have remained within acceptable limits since this occurrence.

Corrective Action:

This event is not considered remediable by corrective plant operation.

Failure Data:

See Attachment.



Plant Superintendent

8103060841

INTAKE

DISCH.

IN-OUT

DATE	TIME	PACKAGE DISS. 0	GRAB SAMPLE DISS. 02	PACKAGE DISS. 02	GRAB SAMPLE DISS. 02	A DISS 02
9-4-75	0920	4.4		9.0		> +2.0 Package
9-4-75	1030	5.0	8.5	8.8	4.5	- 4.0 Grab
9-4-75	1100	6.4		9.0		> +2.0 Package
9-4-75	1205	6.2	8.7	9.2		
9-4-75	1220	6.3		9.3	6.5	- 2.2 Grab
9-4-75	1235	7.2		9.2	7.6	- 1.1 Grab
9-4-75	1245	7.2		9.15	8.1	- 0.6 Grab
9-4-75	1300	7.2	9.1	9.2		
9-4-75	1315	7.2		9.4		
9-4-75	1400	7.6		9.1	8.4	- 0.7 Grab
9-4-75	1600	8.0		8.8		+ 1.1 Package



CONNECTICUT YANKEE ATOMIC POWER COMPANY
HADDAM NECK PLANT

RR - 1, BOX 127E, EAST HAMPTON, CONN. 06424

January 23, 1976
CYH - 3160

U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19106

Attention: Mr. James P. O'Reilly,
Director

Dear Mr. O'Reilly:

In accordance with the reporting requirements of Connecticut Yankee Technical Specifications, Section 6.9.2.a, the following preliminary report (75-1/P) concerning the malfunction of two main steam excess flow differential pressure transmitters is hereby submitted.

During severe sub-zero weather conditions, sensing lines to two high steam flow differential pressure transmitters froze. The coincidence of the two high steam flow signals satisfied the tripping logic and a reactor/turbine trip occurred from full power (~593 MWe). The instrument sensing lines were thawed and the instrumentation returned to normal.

The instruments in question are housed in an enclosure attached to the outside of the Reactor Containment. Sub-zero temperatures and strong winds coupled with some openings inadvertently left in the wall as a result of a recent (high energy pipe break) modification to the enclosure overcame the enclosure heating system and caused local freezing of the sensing lines.

The enclosure building openings were plugged and additional freeze protection was applied to the sensing lines.

Very truly yours,

R. H. Graves
Richard H. Graves,
Plant Superintendent

RHS/vad

D-12
8103050136

D
102

NAME	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
REPORT ON	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

EVENT DESCRIPTION

During plant startup, both channels of off-gas radiation monitors were discovered to be reading abnormally low due to purge valve being stuck in the open position. A bypass line restored representative sampling and instrument response. Briefly during removal of valve and installation of bypass line, both channels of off-gas system isolation instrumentation were incapable of sensing trip level required.

SYSTEM CODE	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
CAUSE DESCRIPTION	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

A 3-way moleculoid purge valve associated with the off-gas system was stuck in the purge position, which resulted in a nonrepresentative sample as seen by the off-radiation monitors. Failure of moleculoid purge valve is under investigation.

SAFETY STATUS	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
PERSONNEL EXPOSURES	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

LOSS OR DAMAGE TO FACILITY	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
PURCHASE	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

ADDITIONAL FACTORS	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
02 Cont - by Tech. Spec. Table 3.2.4. AOC System, with its monitors, was in	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

NAME: B.W. Filly

DATE: 25-7-71

Reg. Files