

PRIORITY ROUTING	
First	Second
CIA	HAS
NSA	HIS
DIA	JCS
ORS	SEC
AFSS	MOL
ORNA	WFO
	PAGE

FILE HAS

DEC 7 1992

A. Bert Davis - NRC
December 3, 1992
Page 2

(2) Drinking Water Analysis, Aquifer Performance:


It is not clear what concern is being addressed in the first part of paragraph 2 of Ref (1). If the concern is whether basin or vault leakage from their respective leak detection systems could/would be detected by drinking water analyses, the answer is yes. If the concern is whether MO personnel are protected from ingesting water potentially contaminated by basin or vault leakage, the answer is still yes.

Historical basin and vault leak detection data indicate no leakage to the environs from these sources has ever occurred. If a leak did occur, we believe the presence and magnitude of a leak would be best characterized by radiocesium migration. Attachment (1) provides information on major vault, basin, and drinking water constituents.

(3) Description of Vault and Basin Leak Detection Systems:

Contained in Attachments (2) and (3).

Sincerely,



J. E. Ellis
Manager, Morris Operation

JEE:tlt

cc:
L. L. Denio
J. D. Kesman
G. R. France (NRC)

WATER ANALYSES

	LAW Vault ⁽¹⁾ (11/23/92)	Basin ⁽²⁾ (11/23/92)	Well ⁽³⁾ (10/92)
Alpha	N/A	N/A	$<7 \times 10^{-7}$ $\mu\text{Ci/ml}$ ⁽⁴⁾
Cs-137	1.2 $\mu\text{Ci/ml}$	2×10^{-4} $\mu\text{Ci/ml}$	$<4.4 \times 10^{-6}$ $\mu\text{Ci/ml}$ ⁽⁴⁾
H-3	N/A	1.6×10^{-4} $\mu\text{Ci/ml}$	$<1 \times 10^{-6}$ $\mu\text{Ci/ml}$ ⁽⁴⁾
Cl ⁻	100 ppm	<0.1 ppm	N/A
NO ₃ ⁻	13,000 ppm	<0.8 ppm	1.1 ppm
pH	13.1	5.1	8.3

- (1) LAW Vault sample analyzed quarterly.
- (2) Basin water analysis performed weekly.
- (3) Well water analysis for NO₃⁻ and pH performed monthly. Radiochemical analysis performed quarterly.
- (4) Lower limit of detection.



Est. 1965

ARRO Laboratory, Inc.

P.O. Box 686 Caton Farm Road
Joliet, Illinois 60434

Phone: 815-727-5436

FAX 815-740-3238

Attention of: MR. JOHN E. McGRATH
Company: GENERAL ELECTRIC COMPANY
Address: MORRIS OPER. 7555 E COLLINS RD
City/State/Zip: MORRIS, IL, 60450

P.O. Number 284-91L474X
Date Received 03/30/92
Date Completed 05/20/92

ARRO NO.	SAMPLE DESCRIPTION	DATE
146830	JANITOR'S ROOM - MORRIS OPERATION	03/30/92
146831	TRAINING CENTER - MEN'S ROOM	03/30/92

ANALYSIS	146830	146831
LEAD	<0.010	<0.010
NITRATE AS N	0.47	0.61
SULFIDE (AS S)	<0.02	<0.02
RADIUM 226 PCI/LITER	1.7	1.3
RADIUM 228 PCI/LITER	2.	8.
POTASSIUM ALPHA PCI/LITER	4.2	5.6
CESIUM BETA PCI/LITER	14.8	17.2
VOC	ATTACHED	ATTACHED

RESULTS IN ppm UNLESS OTHERWISE INDICATED

* SEE ATTACHMENT FOR COMMENTS

I CERTIFY THAT I AM FAMILIAR WITH THE INFORMATION CONTAINED IN THIS REPORT AND THAT TO THE BEST OF MY KNOWLEDGE AND BELIEF SUCH INFORMATION IS TRUE, COMPLETE AND ACCURATE.

APPROVED BY: Joan Ralsh DATE: 05/20/92
Joan Ralsh, Director
Environmental Services

TESTING IS IN ACCORDANCE WITH PROCEDURES OUTLINED IN THE NEWEST EDITIONS OF:
STANDARD METHODS FOR THE EXAMINATION OF WATER AND WASTEWATER
ASTM STANDARDS, PART 31, 'WATER, ATMOSPHERIC ANALYSIS'
METHODS FOR CHEMICAL ANALYSIS OF WATER WASTES, EPA WATER QUALITY OFFICE



Est. 1965

ARRO Laboratory, Inc.

P.O. Box 686 Caton Farm Road
Joliet, Illinois 60434

Phone: 815-727-5436
FAX 815-740-3238

VOLATILE ORGANIC COMPOUND (524.2)

GENERAL ELECTRIC COMPANY
JANITOR'S ROOM - MORRIS OPERATION
146830

ALL RESULTS EXPRESSED IN PPB UNLESS OTHERWISE INDICATED.

REGULATED VOC'S

BENZENE	<0.5
CARBON TETRACHLORIDE	<0.5
1,2-DICHLOROETHANE	<0.5
1,1-DICHLOROETHENE	<0.5
1,1,1-TRICHLOROETHANE	<0.5
TRICHLOROETHENE	<0.5
VINYL CHLORIDE	<0.5
p-DICHLOROBENZENE	<0.5

REGULATED VOC'S

BROMOFORM	<1.0
CHLOROBENZENE	<1.0
DIBROMOCHLOROMETHANE	<0.5
CHLOROETHANE	<1.0
CHLOROFORM	<0.5
BROMODICHLOROMETHANE	<0.5
DICHLORODIFLUOROMETHANE	<1.0
1,1-DICHLOROETHANE	<0.5
1,2-DICHLOROPROPANE	<0.5
ETHYL BENZENE	<1.0
1,1,2,2-TETRACHLOROETHANE	<1.0
TOLUENE	<0.5
trans-1,2-DICHLOROETHENE	<0.5
1,1,2-TRICHLOROETHANE	<0.5
TRICHLOROFLUOROMETHANE	<1.0
m-DICHLOROBENZENE	<1.0
METHYLENE CHLORIDE	<1.0
cis-1,2-DICHLOROETHYLENE	<0.5
o-DICHLOROBENZENE	<1.0
1,2,4-TRICHLOROBENZENE	<2.0
DIBROMOMETHANE	<1.0
1,2-DIBROMOETHANE (EDB)	<0.1
1,2-DIBROMO-3-CHLOROPROPANE	<0.1
p-XYLENE	<1.0
XYLENE	<1.0

1,3-DICHLOROPROPANE	<1.0
STYRENE	<1.0
CHLOROMETHANE	<1.0
BROMOMETHANE	<1.0
BROMOCHLOROMETHANE	<0.5
1,2,3-TRICHLOROPROPANE	<2.0
1,2,3-TRICHLOROBENZENE	<3.0
n-PROPYLBENZENE	<1.0
1,1,1,2-TETRACHLOROETHANE	<0.5
TETRACHLOROETHENE	<0.5
1,3-DICHLOROPROPENE	<1.0
2,2-DICHLOROPROPANE	<1.0
1,2,4-TRIMETHYLBENZENE	<2.0
n-BUTYLBENZENE	<1.0
NAPHTHALENE	<2.0
HEXACHLOROBUTADIENE	<2.0
o-CHLOROTOLUENE	<1.0
p-CHLOROTOLUENE	<1.0
1,3,5-TRIMETHYLBENZENE	<2.0
p-ISOPROPYLTOLUENE	<1.0
1,1-DICHLOROPROPENE	<1.0
iso-PROPYLBENZENE	<1.0
tert-BUTYLBENZENE	<2.0
sec-BUTYLBENZENE	<2.0
BROMOBENZENE	<1.0
m-XYLENE	<1.0



Est. 1965

ARRO Laboratory, Inc.

P.O. Box 686 Caton Farm Road
Joliet, Illinois 60434

Phone: 815-727-5436
FAX 815-740-3238

ANALYSIS OF ORGANIC COMPOUND (524.2)

GENERAL ELECTRIC COMPANY
TRAINING CENTER - MEN'S ROOM
146831

ALL RESULTS EXPRESSED IN PPB UNLESS OTHERWISE INDICATED.

REGULATED VOC'S

BENZENE	<0.5
CARBON TETRACHLORIDE	<0.5
1,2-DICHLOROETHANE	<0.5
1,1-DICHLOROETHENE	<0.5
1,1,1-TRICHLOROETHANE	<0.5
TRICHLOROETHENE	<0.5
VINYL CHLORIDE	<0.5
p-DICHLOROBENZENE	<0.5

UNREGULATED VOC'S

BROMOFORM	<1.0	1,3-DICHLOROPROPANE	<1.0
CHLOROBENZENE	<1.0	STYRENE	<1.0
DIBROMOCHLOROMETHANE	<0.5	CHLOROMETHANE	<1.0
CHLOROETHANE	<1.0	BROMOMETHANE	<1.0
CHLOROFORM	<0.5	BROMOCHLOROMETHANE	<0.5
BROMODICHLOROMETHANE	<0.5	1,2,3-TRICHLOROPROPANE	<2.0
DICHLORODIFLUOROMETHANE	<1.0	1,2,3-TRICHLOROBENZENE	<3.0
1,1-DICHLOROETHANE	<0.5	n-PROPYLBENZENE	<1.0
1,2-DICHLOROPROPANE	<0.5	1,1,1,2-TETRACHLOROETHANE	<0.5
ETHYL BENZENE	<1.0	TETRACHLOROETHENE	<0.5
1,1,2,2-TETRACHLOROETHANE	<1.0	1,3-DICHLOROPROPENE	<1.0
TOLUENE	<0.5	2,2-DICHLOROPROPANE	<1.0
trans-1,2-DICHLOROETHENE	<0.5	1,2,4-TRIMETHYLBENZENE	<2.0
1,1,2-TRICHLOROETHANE	<0.5	n-BUTYLBENZENE	<1.0
TRICHLOROFLUOROMETHANE	<1.0	NAPHTHALENE	<2.0
m-DICHLOROBENZENE	<1.0	HEXACHLOROBUTADIENE	<2.0
METHYLENE CHLORIDE	<1.0	o-CHLOROTOLUENE	<1.0
cis-1,2-DICHLOROETHYLENE	<0.5	p-CHLOROTOLUENE	<1.0
o-DICHLOROBENZENE	<1.0	1,3,5-TRIMETHYLBENZENE	<2.0
1,2,4-TRICHLOROBENZENE	<2.0	p-ISOPROPYLTOLUENE	<1.0
DIBROMOMETHANE	<1.0	1,1-DICHLOROPROPENE	<1.0
1,2-DIBROMOETHANE (75%)	<0.1	iso-PROPYLBENZENE	<1.0
1,2-DIBROMO-3-CHLOROPROPANE	<0.1	tert-BUTYLBENZENE	<2.0
p-XYLENE	<1.0	sec-BUTYLBENZENE	<2.0
m-XYLENE	<1.0	BROMOBENZENE	<1.0
		m-XYLENE	<1.0

LAW VAULT LEAK DETECTION

Separate systems exist for detection of liquid build-up in the annular region surrounding the LAW tank proper, and for groundwater intrusion through the concrete vault structure.

The intrusion system collects liquid seepage into the space between the vault bottom liner and the concrete walls and floor. The intrusion stand-pipe penetrates the vault bottom liner and is seal welded to the liner. Above the bottom liner, the stand-pipe has a hole to prevent intrusion water from getting too high behind the liner in the event of a pump failure.

The level is continuously monitored in the Control Room, and audible/visual alarms alert the operator that the pump-out system has malfunctioned.


Intrusion liquid level is maintained by an automatic sump pump but can be manually controlled. Samples of discharge to sanitary waste treatment ponds are collected monthly.

The system is tested monthly according to Section 4.4 of license SNM-2500 to verify:

- Intrusion water pump-out capability
- Intrusion water high level alarm function
- Positive shutdown of intrusion pump if there is a high level in the annular tank
- Concentrations of radioactivity are $<5.0 \times E-06$ microcuries per milliliter (gross gamma)

The annular tank sump, located between the inner tank wall and the concrete vault liner, collects potential leakage from the inner tank. In addition to level instrumentation and alarms typical of other systems of this type, there are several methods of empty-out, including primary and secondary airlifts used in conjunction with a vacuum air jet and an air operated diaphragm pump.

A sampling station is located in the common line for these empty-out systems. Samples are obtained for any and all empty-outs and all discharges are routed back to the LAW inner tank. Quarterly license compliance tests verify leak detection and pump-out capability.



LAW VAULT AND TANK

FUEL STORAGE BASIN LEAK DETECTION

The basin leak detection system consists of a continuous level monitoring instrument with audible and visual alarm functions in the Control Room, to detect liquid level in the void behind the basin liner and the concrete structural walls/floor of the unloading and storage basins.

Collection channels, formed in the concrete at the concrete and steel liner interface, interconnect with a perimeter channel that slopes to a low point which is the bottom of a six inch diameter stand-pipe. This pipe and perimeter channel are embedded in the reinforced concrete structural walls.


A build-up of liquid, whether by infiltration, condensation, or liner leakage, is sensed by the dip-tube and differential pressure level indication transmitter. The indicating range is from 0 to 200 inches of water.

Empty-out is provided by an airlift and steam jet pump arrangement with a sampling station in-line between airlift output and the jet pump suction. Liquid removed is then discharged to the LAW vault.


Weekly license compliance tests are performed to verify operability of the high level alarm function; monthly to calibrate the level instrument and quarterly to verify operability of the empty-out system and determine by sample analyses that no liner leakage has occurred.

The expansion gate, located in the south wall of Basin-2 also has a sump formed by the inner and outer gates which are sealed to the basin walls. This void has an expanded scale level indication instrument and electric pumpout systems. A divider plate or dam isolates the level instrument and pump to the compartment closest to the basin.

Build-up of liquid in either compartment is identified, based on sample analyses, as originating from the basin, groundwater, or other sources.



BASIN LINER LEAKAGE MONITOR & JETOUT SYSTEM
(BASIN LEAK DETECTION)



EXPANSION GATE PUMP OUT SYSTEM