

APR 28 1981

DISTRIBUTION:

Docket File 40-8693
Mill File
WMUR r/f
WMUR c/f RScarano
WM r/f REBrowning
NMSS r/f JBMartin
PDR
IE-HQ (2)
BFisher

MEMORANDUM FOR: John J. Linehan
Uranium Recovery Licensing Branch

Dan Martin
Uranium Recovery Licensing Branch

FROM: Terry Vandell
Uranium Recovery Licensing Branch

SUBJECT: REVIEW AND CONCLUSIONS REGARDING "SPECIAL REPORT ON
MONITOR WELL ANALYTICAL RESULTS," MARCH 25, 1981, FROM
OGLE PETROLEUM

Summary and Conclusions

- (1) Two "minor" lateral excursions occurred at Ogle Petroleum's R&D well field in wells M-2 and M-4 (see attached Figure 1) where (a) well M-2 exceeded UCL's for Cl and $\text{CO}_3 + \text{H}_2\text{CO}_3$ by a maximum of = 15 ppm and = 118 ppm, respectively, and (b) well M-4 exceeded UCL's for Cl, $\text{CO}_3 + \text{H}_2\text{CO}_3$, and specific conductance by a maximum of = 63 ppm, = 118 ppm, and = 71 mhos/cm, respectively.
- (2) During the past month or two, well M-2 has been experiencing above-normal values for chloride and carbonate plus bicarbonate which were believed by Ogle to be caused by the normal outside sweep of the lixiviant during mining operations. An expanded outside sweep by the lixiviant was expected due to the increased injection capacity resulting from new injection wells being placed into operation in the southeast corner of the R&D well field.

The sudden increase over a two-week period in carbonate plus bicarbonate, chloride, and specific conductivity at well M-4 is believed by Ogle to have resulted from a typical horizontal excursion which was most likely caused by localized over-injection on the south side of the field well.
- (3) Control measures were implemented
 - (a) plant bleed increased,
 - (b) injection stopped and reduced and recovery increased, and
 - (c) fresh water injection into an ore zone control well 50 feet from M-2, to reverse the gradient towards the well field.
- (4) All parameters are below their UCL's for well M-4; and although Cl is still high, only $\text{CO}_3 + \text{H}_2\text{CO}_3$ exceeds its UCL at well M-2.

OFFICE					THIS DOCUMENT CONTAINS POOR QUALITY PAGES
SURNAME	8105120275		C		
DATE					

- 2 - APR 28 1981

- (5) The results of the routine biweekly sampling of R&D monitor wells on February 4, 1981, showed that wells M-2 and M-4 exceeded their respective UCL values for at least two excursion parameters each. The seven-day confirmation sampling period verified that well M-2 was in an excursion status but indicated that well M-4 was not in an excursion status. The data to date from the sampling program indicate that the horizontal excursion at well M-2 is under control, and that technically speaking the well is no longer in excursion status.

Staff Recommendations

I believe that OPI has implemented very effective clean-up and control techniques and that they are and should continue on with their monitoring and reporting to us, as they have done, if another excursion occurs.

Original Signed By:

Terry Vandell
Uranium Recovery Licensing Branch

Enclosures:
as stated

Case Closed 04008693m03E

4/20/81

OFFICE	WMOR						
SURNAME	TVandell:ng						
DATE	4/20/81						


4 of 4

M6

M1

M5


Generalized
Ore Body
Outline



M4



LOCATION GUIDE
NO SCALE



LEGEND

- INJECTION WELL (TOTAL 37)
- PRODUCTION WELL (TOTAL 16)
- ⊕ CONTROL WELL (1)
- ⊗ EXISTING MONITOR WELL (5)
- EXISTING UPPER AQUIFER MONITOR

--- TEST AREA BOUNDARY



*new well
drilled
injected
from H₂C
well (1)
to reverse
excursion*

OGLE PETROLEUM INC.

BISON BASIN MINE
WELLFIELD LAYOUT
(R&D AREA)

SCALE 1"=100'

FIGURE 1

18554

April 16, 1981

To: John G. Anderson

Don Martin

From: T.O. Vandell

Re: Review and Conclusions Regarding "Special Report on
Mud for Well Analysis? Results" March 25, 1981
from Ogle Petroleum

Summary and Conclusions

- (1.) Two "minor" lateral excursions occurred at Ogle Petroleum's R & D wellfield in wells M2 and M4 (see attached Figure 1) where (a) well M2 exceeded UCL's for Cl and $\text{CO}_3 + \text{H}_2\text{CO}_3$ by a maximum of $\approx 15 \text{ ppm}$ and $\approx 115 \text{ ppm}$ respectively, and (b) well M4 exceeded UCL's for Cl, $\text{CO}_3 + \text{H}_2\text{CO}_3$, and Specific Conductance by a maximum of $\approx 163 \text{ ppm}$, $\approx 118 \text{ ppm}$, and $\approx 71 \text{ mhos/cm}$, respectively.

(2.)

During the past month or two, well M 2 has been experiencing above-normal values for chloride and carbonate plus bicarbonate which were believed to be caused by the normal outside sweep of the lixiviant during mining operations. An expanded outside sweep of the lixiviant was expected due to the increased injection capacity resulting from new injection wells being placed into operation in the southeast corner of the R & D wellfield.

The sudden increase over a two-week period in carbonate plus bicarbonate, chloride, and specific conductivity at well M 4 is believed to have resulted from a typical horizontal excursion which was most likely caused by localized over-injection on the south side of the wellfield.

- (3) After control measures had been implemented
 - (a) plant UCL increased.
 - (b) injection stopped and allowed and recovery increased and
 - (c) fresh water injection into an onshore control well 50 ft from M2, to reverse the gradient towards the well field,
- (4) All parameters are below their UCLs for well M4, and although Cl is still high, only $\text{CO}_2 + \text{H}_2\text{CO}_3$ exceeds its UCL at well M2.

(5) The results of the routine biweekly sampling of R & D monitor wells on February 4, 1981 showed that wells M 2 and M 4 exceeded their respective UCL values for at least two excursion parameters each. The seven-day confirmation sampling period verified that well M 2 was in an excursion status but indicated that well M 4 was not in an excursion status. The data to date from the sampling program indicate that the horizontal excursion at well M 2 is under control, and that technically speaking the well is no longer in excursion status.

Staff Recommendations

- (1) I believe that OPI has implemented very effective clean-up and control techniques and that they are and should continue on with their monitoring and reporting to us, as they have done, if another excursion occurs.

And finally, something OPI presented when it believed we need to keep in mind for other application has as well as at other sites.

Due to the positive correlation between a relatively high bleed and drop in excursion parameter values, OPI feels that it can control possible future horizontal excursions if adequate mechanisms are available to dispose of well-field bleed. The present limited pond capacity at our R & D mining operation restricts the amount of bleed that can be routed to the pond. This situation hinders our ability to further reduce the concentrations of chloride and carbonate plus bicarbonate at well M 2 at least until another pond is constructed at the site. Because of this factor, OPI wishes to enter into discussions with DEQ and MRC personnel on the possibility of obtaining a permit to surface discharge water from the pond after it has been treated to meet the applicable discharge standards.


M5

4/24

M1

M3

Generalized
Ore Body
Outline



M4

LEGEND

- INJECTION WELL (TOTAL 37)
- PRODUCTION WELL (TOTAL 16)
- ⊕ CONTROL WELL (1)
- ⊗ EXISTING MONITOR WELL (5)
- ⊙ EXISTING UPPER AQUIFER MONITOR WELL (1)

--- TEST AREA BOUNDARY




*new well
drilled
injected
fresh H₂O
to reverse
excursion*



LOCATION GUIDE

NO SCALE



OGLE PETROLEUM INC.

BISON BASIN MINE
WELLFIELD LAYOUT
(RAD AREA)

SCALE 1"=100'

FIGURE 1

10554