

LICENSEE EVENT REPORT

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

M I P A L 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58CON'T
REPORT SOURCE L 6 0 5 0 0 0 2 5 5 7 0 4 2 1 8 1 8 0 5 2 1 3 1 3
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During normal power operation, both the primary and secondary dataloggers failed. Condition is degraded mode of operation per TS 3.17, and is reportable per TS 6.9.2.b2.

Primary datalogger was restored in approximately 1.3 hours. No threat to public health or safety existed. Refer to LER 81-10.

SYSTEM CODE I D 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE INSTRU 14 COMP SUBCODE X 15 VALVE SUBCODE Z 16
LER NO REPORT NUMBER 8 1 17
EVENT YEAR 8 1 21
SEQUENTIAL REPORT NO. 0 1 6 24
OCCURRENCE CODE 0 3 28
REPORT TYPE L 30
REVISION NO. 0 32
ACTION TAKEN B 18 X 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB N 24 PRIME COMP SUPPLIER N 25 COMPONENT MANUFACTURER F 1 2 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Primary datalogger failed due to faulty circuit board, which was replaced. Secondary datalogger failure was caused by failure of typer. Replacement of plant datalogging system equipment is being evaluated.

FACILITY STATUS E 28 % POWER 0 9 8 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY ISSUED N 44 DESCRIPTION N/A 45 NRC USE ONLY

8106020313