

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) EDWIN I. HATCH, UNIT 1										DOCKET NUMBER (2) 0 5 0 0 0 3 2 1										PAGE (3) 1 OF 0 2																																
TITLE (4) PROCEDURAL ERROR WITH RESPECT TO TECH. SPECS.																																																				
EVENT DATE (5)									LER NUMBER (6)									REPORT DATE (7)									OTHER FACILITIES INVOLVED (8)																									
MONTH			DAY			YEAR			YEAR			SEQUENTIAL NUMBER			REVISION NUMBER			MONTH			DAY			YEAR			FACILITY NAMES													DOCKET NUMBER(S)												
0 4			1 5			8 5			8 5			0 2			0 0			0 5			1 4			8 5																0 5 0 0 0												
0 4			1 5			8 5			8 5			0 2			0 0			0 5			1 4			8 5																0 5 0 0 0												
OPERATING MODE (9) 1									THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																																											
POWER LEVEL (10) 1 0 0									20.402(b)									20.405(c)									50.73(a)(2)(iv)									73.71(b)																
									20.406(a)(1)(i)									50.36(c)(1)									50.73(a)(2)(v)									73.71(c)																
									20.406(a)(1)(ii)									50.36(c)(2)									50.73(a)(2)(vii)									OTHER (Specify in Abstract below and in Text, NRC Form 366A)																
									20.406(a)(1)(iii)									X 50.73(a)(2)(i)									50.73(a)(2)(viii)(A)																									
									20.406(a)(1)(iv)									50.73(a)(2)(ii)									50.73(a)(2)(viii)(B)																									
20.406(a)(1)(v)									50.73(a)(2)(iii)									50.73(a)(2)(x)																																		
LICENSEE CONTACT FOR THIS LER (12)																																																				
NAME Steven B. Tipps, Superintendent of Regulatory Compliance																				TELEPHONE NUMBER 9 1 2 3 6 7 1 7 8 5 1																																
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																																				
CAUSE			SYSTEM			COMPONENT			MANUFAC- TURER			REPORTABLE TO NPRDS						CAUSE			SYSTEM			COMPONENT			MANUFAC- TURER			REPORTABLE TO NPRDS																						
SUPPLEMENTAL REPORT EXPECTED (14)																				EXPECTED SUBMISSION DATE (15)										MONTH DAY YEAR																						
YES (If yes, complete EXPECTED SUBMISSION DATE)																				X NO																																

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 04/15/85 with Unit 1 at 2436 Mwt (100% power) and Unit 2 shutdown for refueling, plant personnel determined that a special purpose procedure which had been written to direct the implementation of a DCR on Unit 2's Standby Gas Treatment system (SBGT) would have allowed Unit 1 to operate for a short period of time contrary to the provisions of Tech. Specs. section 3.7.B.1.

The error in the procedure was detected prior to its being used in the field.

The procedure was revised to resolve the error.

8505290575 850514
PDR ADOCK 05000321
S PDR

IE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1) EDWIN I. HATCH, UNIT 1	DOCKET NUMBER (2) 0 5 0 0 0 3 2 1 8 5 - 0 2 0 - 0 0 0 2 OF 0 2	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		

TEXT (If more space is required, use additional NRC Form 365A's) (17)

This 30 day LER is required by 10CFR50.73(a)(2)(vi) because a procedure was written and approved which would have allowed Unit 1 to operate contrary to the provisions of Tech. Specs. section 3.7.B.1.

On 04/15/85 with Unit 1 at 2436 MWt (100% power) and Unit 2 shutdown for refueling, plant personnel determined that a special purpose procedure which had been written to direct the implementation of a DCR on Unit 2's Standby Gas Treatment system (SBGT) would have allowed Unit 1 to operate for a short period of time contrary to the provisions of Tech. Specs. section 3.7.B.1.


The procedure (42SP-T46-001-2), which had been approved for use, would have allowed Unit 1 to operate on a 6 hour LCO with both trains of Unit 2's SBGT system tagged out of service. Tech. Specs. section 3.7.B.1 does not allow Unit 1 operation with both trains of Unit 2's SBGT inoperable.

The error in the procedure was detected prior to its being used in the field. There were no actual safety consequences as a result of this event nor was the health and safety of the public affected.

This event was the result of an inadequate technical review of the procedure prior to approval. The importance of a thorough review of all documents was reemphasized to the personnel involved.

The procedure was revised to resolve the error.

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444




Edwin I. Hatch Nuclear Plant

May 14, 1985
GM-85-428

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-321

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-321/1985-020. This report is required by 10CFR 50.73(a)(2)(vi).



H. C. Nix
General Manager

HCN/SBT/vlz

xc: R. J. Kelly
R. E. Conway
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
D. R. Altman
Superintendent of Regulatory Compliance
R. D. Baker
Control Room
Document Control

IE22
1/1