

LICENSEE EVENT REPORT (LER)

APPROVED OMB NO. 3160-0104
EXPIRES 9/31/93

FACILITY NAME (1) Peach Bottom Atomic Power Station - Unit 2										DOCKET NUMBER (2) 050000277				PAGE (3) 1 OF 3		
TITLE (4) Reactor High Pressure Scram with all Rods Full-In																
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)						
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)				
05	30	85	85	002	00	06	26	85				050000				
OPERATING MODE (9) N		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50. (Check one or more of the following) (11)														
POWER LEVEL (10) 000		20.402(a)				20.408(a)				<input checked="" type="checkbox"/> 60.73(a)(2)(iv)				73.71(a)		
		20.408(a)(1)(i)				60.38(a)(1)				<input type="checkbox"/> 60.73(a)(2)(v)				73.71(a)		
		20.408(a)(1)(iv)				60.38(a)(2)				<input type="checkbox"/> 60.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Test, NRC Form 306A)		
		20.408(a)(1)(iii)				60.73(a)(2)(i)				<input type="checkbox"/> 60.73(a)(2)(vii)(A)						
		20.408(a)(1)(iv)				60.73(a)(2)(iv)				<input type="checkbox"/> 60.73(a)(2)(viii)(B)						
		20.408(a)(1)(v)				60.73(a)(2)(iii)				<input type="checkbox"/> 60.73(a)(2)(a)						
LICENSEE CONTACT FOR THIS LER (12)																
NAME Senior J. C. Nagle, Engineer - Special Projects										TELEPHONE NUMBER AREA CODE 215 841-5184						
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC						
X																
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)												<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1600 words, i.e., approximately fifteen single-space typewritten lines) (16)

Abstract: 2-85-02

During the vessel hydrostatic test, with all control rods in the full-in position and Peach Bottom Unit 2 in cold shutdown, the Reactor Protection System (RPS) initiated a scram signal on reactor high pressure during an excess flow check valve test on May 30, 1985. While performing surveillance test ST 13.8-1, "Excess Flow Check Valve Operability", a leak of approximately five liters per minute was discovered through the excess flow check valve on the recirculation pump seal cavity instrument sensing line. The leak caused reactor pressure to drop below the 1,000 pounds per square inch test pressure required by the surveillance test. The reactor operator responded to the decrease in reactor pressure by increasing control rod drive flow into the vessel to restore pressure. Simultaneously, test personnel isolated the leak by closing the instrument sensing line root valve. The reactor pressure increased rapidly to 1,030 pounds per square inch which resulted in the reactor high pressure scram signal.

8507090215 850626
PDR ADDCK 05000277
S PDRIE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 11/31/86

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Peach Bottom Atomic Power Station - Unit	05000277	85	002	00	02	OF	03

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Description of the Event:

During the vessel hydrostatic test, with all control rods in the full-in position and Peach Bottom Unit 2 in cold shutdown, the Reactor Protection System (RPS) initiated a scram signal on reactor high pressure during an excess flow check valve test on May 30, 1985. While performing surveillance test ST 13.8-1, "Excess Flow Check Valve Operability", a leak of approximately five liters per minute was discovered through the excess flow check valve on the recirculation pump seal cavity instrument sensing line. The leak caused reactor pressure to drop below the 1,000 pounds per square inch test pressure required by the surveillance test. The reactor operator responded to the decrease in reactor pressure by increasing control rod drive (CRD) flow into the vessel to restore pressure. Simultaneously, test personnel isolated the leak by closing the instrument sensing line root valve. The combined effects of increased CRD flow and isolation of the leak resulted in a rapid increase of reactor pressure to 1,030 pounds per square inch which resulted in the reactor high pressure scram signal. This LER is submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(iv). The EIIS code for the reactor protection system is JC.

Consequences of the Event:

At the time of this event, all control rods were fully inserted. The reactor protection system initiated the scram signal in accordance with Technical Specification requirements and the RPS logic functioned properly. Therefore, there were no adverse consequences.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1) Peach Bottom Atomic Power Station - Unit	DOCKET NUMBER (2) 0 5 0 0 0 2 7 7 8 5 -	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 5	0 0 2	0 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Cause of the Event:

This event resulted from the test personnel responding to the leak in the excess flow check valve and the reactor operator attempting to maintain reactor pressure at the required surveillance test pressure of 1,000 pounds per square inch.

The reactor operator responded to the decrease in reactor pressure by increasing control rod drive flow into the vessel to restore pressure. As CRD flow was being increased the test personnel isolated the leak by closing the instrument sensing line root valve. With the reactor vessel hydraulically pressurized, the volume of CRD flow directed to the vessel caused a rapid pressure increase to the reactor high pressure scram setpoint before operator action could be taken.

Corrective Actions:

The scram signal was reset and surveillance testing of excess flow check valves successfully completed following repairs to the recirculation pump seal cavity instrument sensing line excess flow check valve.

Previous Similar Occurrences

None.

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

June 26, 1985

Docket No. 50-277

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

SUBJECT: Licensee Event Report
Peach Bottom Atomic Power Station - Unit 2

This LER concerns an automatic initiation of the reactor protection system with all control rods in the full-in position.

Reference:	Docket No. 50-277
Report Number:	2-85-02
Revision Number:	00
Event Date:	May 30, 1985
Report Date:	June 26, 1985
Facility:	Peach Bottom Atomic Power Station RD #1, Box 208, Delta, PA 17314

This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(iv).

Very truly yours,



W. T. Ullrich
Superintendent
Nuclear Generation Division

cc: Dr. Thomas E. Murley, Administrator
Region I, USNRC

T. P. Johnson, Resident Inspector

LE22
11

cc: Judge Helen F. Hoyt
Judge Jerry Harbour
Judge Richard F. Cole
Troy B. Connor, Jr., Esq.
Ann P. Hogdon, Esq.
Mr. Frank R. Romano
Mr. Robert L. Anthony
Ms. Phyllis Zitzer
Charles W. Elliott, Esq.
Zori G. Ferkin, Esq.
Mr. Thomas Gerusky
Director, Penna. Emergency Management Agency
Angus Love, Esq.
David Wersan, Esq.
Robert J. Sugarman, Esq.
Kathryn S. Lewis, Esq.
Spence W. Perry, Esq.
Jay M. Gutierrez, Esq.
Atomic Safety & Licensing Appeal Board
Atomic Safety & Licensing Appeal Panel
Docket & Service Section
James Wiggins
Timothy R. S. Campbell