

DEPARTMENT OF ENERGY
ALBUQUERQUE OPERATIONS OFFICE
CONTRACT NO. DE-AC04-83AL18796

Draft Radiological and Engineering Assessment

Vicinity Property No. DUR 026

**Remedial Actions
Contractor
for the
Uranium Mill Tailings
Remedial Actions
Project**



MORRISON
KNUDSEN

DRAFT

THE RADIOLOGICAL AND ENGINEERING ASSESSMENT

AND FINAL DESIGN

FOR

DURANGO PROPERTY

DU-026

February 12, 1985

PREPARED FOR

URANIUM MILL TAILINGS REMEDIAL ACTION PROJECT OFFICE

UNITED STATES DEPARTMENT OF ENERGY

PREPARED BY

MORRISON-KNUDSEN COMPANY, INC.

NOTE:

SUPPLEMENTAL STANDARDS

TABLE OF CONTENTS

- 1.0 Executive Summary
 - 1.1 Introduction
 - 1.2 Evaluation and Recommendation
- 2.0 Engineering Field Survey
 - 2.1 Property Description
 - 2.2 Existing Facilities and Structures
- 3.0 Radiological Survey and Assessment
 - 3.1 Gamma Exposure Rate Survey
 - 3.2 Borehole Survey
 - 3.3 Radon/Radon Daughter Survey
 - 3.4 Estimated Extent of Contamination
 - 3.5 Supplemental Standards
- 4.0 Engineering Assessment
 - 4.1 Evaluation of Options
 - 4.2 Recommendation
- 5.0 Technical Specifications
- 6.0 Construction Drawing

DU-026-020 Excavation & Restoration Plan DU-026

FIGURES

- 2.1 Vicinity Map DU-026
- 2.2 Site Plan DU-026
- 2.3 Property Photos
- 3.1 Radiological Survey Data
- 4.1 Excavation & Restoration Plan

TABLES

- 2.1 Property Survey Data
- 3.1 Outdoor Gamma Survey
- 3.2 Borehole Survey
- 3.3 Angle Hole Survey
- 4.1 Costs
- 5.1 Index of Technical Specifications

APPENDIX

- A. Survey Data Logs

1.0 EXECUTIVE SUMMARY

1.1 Introduction

Property DU-026 is a private residence located at 46 Rio Vista Circle, Durango, CO.

1.2 Evaluation and Recommendation

1.2.1 Residual Radioactive Material Involvement

Contaminated material was found in the front yard of the property. No interior contamination was found.

1.2.2 Recommended Remedial Action Option

The recommended option is to remove the contaminated material except that under the sidewalk and street. This material will be left in accordance with the criteria of 40 CFR 192.21(c), "Criteria for Applying Supplemental Standards."

1.2.3 Estimated Costs

The estimated cost for removal of the contaminated material and restoration of the property is \$5,550.00.

1.2.4 Schedule

The estimated duration of the remedial action effort is 3 to 5 days.

2.0 ENGINEERING FIELD SURVEY

2.1 Property Description

2.1.1 Property Use and Occupancy

Property DU-026 is a private residence located at 46 Rio Vista Circle, Durango, Colorado and owned by Carl and Colleen Lundberg. The map in Figure 2.1 illustrates the property's vicinity location.

2.1.2 Legal Description

The legal description as recorded with the La Plata County Recorder's Office on Microfilm No. 464801 follows:

Lot 10, Block 2, RIVERVIEW PARK SECOND RESUBDIVISION in the City of Durango, La Plata County, Colorado.

2.1.3 Bordering Properties

The lot is zoned R-1, residential area. It is located less than 3-1/2 miles northeast of the old Vandium Corporation of America mill tailings site. The property is bounded on the north by a residence; on the east by a residence; on the south by a residence; and on the west by Rio Vista Circle.

2.2 Existing Facilities and Structures

2.2.1 Structures

The residence is a single-story, wood frame structure on a concrete foundation. An attached wood frame single car garage is located on the north side of the structure with a concrete driveway that extends from the garage to the street. Concrete sidewalk extends along the street just outside the west property line, along the driveway from the street to a covered concrete front porch, and along the east side of the house.

Front and side yards are grassed with four large mature conifers and one deciduous tree located in the front yard area. A brick planter extends from the porch to the end of the house on the west side of the house. The rear yard is grassed, fully landscaped, and fenced. Two concrete and one stone retaining wall extends the full width of the rear yard. The lot slopes upward steeply to the east from the first retaining wall to the back fence.

The residence is less than 50 years old and therefore meets the non-historical property requirements of Stipulation I.a. of the Programmatic Memorandum of Agreement between the DOE, the Colorado Historic Preservation Officer, and the Advisory Council on Historic Preservation for which the DOE may proceed with remedial action without additional historical investigations.

2.2.2 Utilities

Utilities are serviced to the property as follows:

Electric power - Overhead to northeast corner of house.

Telephone - Overhead to southeast corner of house.

Water - Underground from Rio Vista Circle.

Gas - Underground from rear (east) of lot.

Sewer -Underground from Rio Vista Circle.

2.2.3 Site Plan and Survey Data

See Figure 2.2 for a site plan of the property. Property survey data and photos are presented in Table 2.1 and Figure 2.3.

Table 2.1

PROPERTY SURVEY DATA

GENERAL:

Site Location: Durango

Property Address: 46 Rio Vista Circle

Owner's Name: Carl and Coleen Lundberg Address: Same

Lot No.: 10 Property Type: Residential

Occupancy Group: Adults: N/A Children: N/A

Survey Completed By: R. Livengood/C. Sanders-Meena Date: 5-16-84

Property Description - Exterior:

Dwelling: Sq. Ft.: N/A

Levels: Single Story With Crawl Space

Construction Type: Wood Frame; Stucco with 3' High Brick Veneer
Exterior Wainscoting in front; Stucco with 3'
High Exterior Wainscoting Sides and Back

Foundation: 38" High Concrete Perimeter Wall with Two Concrete Center
Support Piers

Garage: Single Car Attached on North Side of House

Storage Bldg: Prefab: None

Other: _____

Improvement Additions: None Porches: Covered Concrete on
to Dwellings: Deck: None West Side of House

Other: _____

Driveway: Concrete: From Street to Garage Paved: _____
Gravel: _____ Other: _____

Sidewalks: Concrete/Paved: As Noted on Drawing

Other: _____

Fences/Gates: Wood: 4' Ht on N Side Backyd From 1st Ret Wall & along E Side Lot
Chain Link: 3' Ht of N Side Backyd to 1st Ret Wall & on S Side
Bkyd

PROPERTY SURVEY DATA

Property Description - Interior: No Interior Contamination

Air Cond: Gas: _____ Heat Pump: _____

Radiological and Engineering Assessment: Property DU-026

Table 2.1 (cont'd)

PROPERTY SURVEY DATA

Site Location: Durango

Property Address: 46 Rio Vista Circle

Electric Line Location: Overhead to Northeast Corner of House

Gas Line Location: Underground from Rear (East) of Lot

Water Line Location: Underground from Rio Vista Circle Main (See Drawing)

Sewage Line Location: Underground from Rio Vista Circle Main (See Drawing)

Telephone Line Location: Overhead to Southeast Corner of House

Building Codes and Zoning:

<u>Codes</u>	<u>Local</u>	<u>State</u>	<u>Federal</u>
<u>Building Work</u>	<u>UBC</u>		
<u>Plumbing</u>			
<u>HVAC</u>			
<u>Electrical</u>			
<u>Other</u>			

Zoning District: City of Durango

Present Dwelling Zoning: R-1 Residence District

Setbacks: Front: _____


Rear: _____

Side: _____

Other: _____

Photographs:

<u>Roll Frame</u>	<u>Description</u>	<u>Direction</u>
<u>2-15</u>	<u>Front of House</u>	<u>Looking East</u>
<u>2-13</u>	<u>Rear of House</u>	<u>Looking Northwest</u>



LEGEND

— W —	WATER LINE
— G —	GAS LINE
— GM —	GAS MAIN
— S —	SEWER LINE
— SM —	SEWER MAIN
— STM —	STORM SEWER
— E —	ELECTRICAL LINE
— T —	TELEPHONE LINE
— TV —	CABLE TV
— — —	PROPERTY LINE
— x — x — x —	FENCE LINE
⊙ G, W or E	METER
⊗ G or W	VALVE
⊙	PROPERTY PIN
⊙	POWER POLE

NOTE: OVERHEAD SERVICE DENOTED BY SOLID LINE.
UNDERGROUND SERVICE DENOTED BY DASHED LINE.



Also Available On
Aperture Card

TI
APERTURE
CARD

U. S. DEPARTMENT OF ENERGY ALBUQUERQUE, NEW MEXICO

DESIGNED BY	NR
CHECKED BY	NR
REVIEWED BY	NR
RECOMMENDED BY	NR
APPROVED BY	NR

FIGURE 2.2
SITE PLAN DU-026

DURANGO, COLORADO
URANIUM MILL TAILINGS REMEDIAL ACTION PROJECT

APPROVED	DATE	DOE PROJECT MANAGER	DATE	DOE PROJECT ENGINEER	DATE
NR		NR		NR	

PROJECT NO.
DE-AC04-83AL18796




MORRISON
KNUDSEN

DRAWING NO. DU-026-010 REV. A


8507100094 - 01

DATE	REVISIONS	DESIGNED BY	CHECKED BY	APPROVED BY	DOE PROJECT MANAGER	DOE PROJECT ENGINEER
2/1/1985	FINAL REA SUBMITTAL	GJW	UP	DP	VCD	VCD



OLD VANADIUM CORP
MILL TAILINGS SITE

CITY OF D



Also Available On
Aperture Card

TI APERTURE CARD

DURANGO, COLORADO

8507100094-02

U. S. DEPARTMENT OF ENERGY									
ALBUQUERQUE, NEW MEXICO									
DESIGNED/DRAWN <i>[Signature]</i> GJW		FIGURE 2.1							
CHECKED <i>[Signature]</i>		VICINITY MAP DU-026							
REVIEWED <i>[Signature]</i>		DURANGO, COLORADO							
RECOMMENDED <i>[Signature]</i>		URANIUM MILL TAILINGS REMEDIAL ACTION PROJECT							
APPROVED		DATE	DOE PROJECT MANAGER	DATE	DOE PROJECT ENGINEER	DATE			
NR			NR		NR				
MORRISON KNUDSEN		PROJECT NO. DE-AC04-83AL18796							
		DRAWING NO. DU-026-005							
		REV. A							

3/1 1985	FINAL REA SUBMITTAL	GJW	SP	VP	VAD	VAD	-
DATE	REVISIONS	DRAWN BY	CHECKED BY	APPROVED LDR	APPROVED DR	APPROVED ENR	APPROVED DOE



Front of House Looking East



Rear of House Looking Northwest

Figure 2.3 Property Photos

3.0 RADIOLOGICAL SURVEY AND ASSESSMENT

3.1 Gamma Exposure Rate Survey

3.1.1 Survey Method

The outdoor contaminated areas identified in the inclusion survey (Results of the Radiological Survey at Property DU-026, ORNL, May 1983) were surveyed in accordance with the RAC UMTRA Procedure 019. The survey was made on a 10' x 10' grid. A surface scan was made of the entire gridded yard with a gamma scintillometer to identify the boundary of the contamination.

An indoor gamma survey was not conducted inside the house, since the inclusion survey indicated that contamination is not present in or under the house.

3.1.2 Survey Results

Surface gamma readings on the property range from 14 to 57 micro R/hr (Table 3.1). This may be compared with the background for the Durango site of 14 micro R/hr. Table 3.1 lists surface gamma readings greater than 16 micro R/hr.

3.2 Borehole Survey

3.2.1 Survey Method

A gasoline-powered hand auger was used to drill 4-inch diameter holes in and around the regions identified as contaminated during the gamma survey. The holes were surveyed in compliance with the RAC UMTRA Procedure 018.

Four shovel holes were dug, one at each wall of the house, to determine if contamination was underneath the house. The hole at the west wall was located at the point of entrance into the house of the main water line and very near to the sewer line. Each hole was dug vertically for 6 inches and then augered under the footing as far as possible. These holes were surveyed as closely as possible to the method described in RAC Procedure 018.

3.2.2 Survey Results

Contamination was found in 4 of the 8 outdoor holes augered. The location and depth of the contamination is described in Table 3.2 and is shown in Figure 3.1.

No contamination was found in any of the angle holes. The location and depth of these holes are described in Table 3.3 and are shown in Figure 3.1. The only contamination observed along the utility lines is within Area A, described below.

3.3 Radon/Radon Daughter Survey

No radon/radon daughter surveys were performed inside buildings at the property, since the inclusion survey reported that no contamination is present in or under the structures. The inclusion survey found a "grab sample" radon daughter concentration of 0.001 WL inside the house.

3.4 Estimated Extent of Contamination

Three areas of contamination were identified in the survey.

In Area, A the depth of contamination could not be determined because of the difficulty of drilling, but it is known to be greater than 27 inches. (A depth of 36 inches should be assumed for estimating purposes.) Area A includes the driveway. According to the present owner, the tailings have been removed from under the driveway. However, as shown on Figure 3.1, contamination has been identified to a depth of more than 2 feet on either side of the driveway. The depth at which any materials under the driveway may have been removed is unknown. It is not radiologically necessary to remove the two trees associated with Area A.

The west boundary of Area B is undefined since contamination is known to extend into the street. The depth of contamination is known to be more than 18 inches and is expected to be about 30 inches. (See Section 3.5 below).

Area C is a small area with an estimated depth of contamination of 12 inches. Area C consists only of low-level contamination and its surface area is much less than 100 m². However, since remedial action is indicated for this property anyway, it is prudent to clean up Area C along with Area A.

3.5 Supplemental Standards

Supplemental Standards apply to Area B (Figure 3.1) per 40 CFR 192.21(c), "Criteria for Applying Supplemental Standards," and, therefore, no excavation is required in this area.

Table 3.1
OUTDOOR GAMMA SURVEY
Property DU-026

POINT	uR/hr
0+00,10L	37
0+10	42
0+20	41
0+30	57
0+40	45
0+50	45
0+60	56
0+67.5,10L	39
0+00,00R	19
0+30,00R	21
0+60,00R	17
0+10+10R	17
0+00,20R	17
0+60,20R	17

Table 3.2
BOREHOLE SURVEY
Property DU-026


HOLE	COORDINATES	CONTAMINATION DEPTH
1	0+44,10R	None
2	0+10,02L	None
3	0+57,20R	0-27"+
4	0+47,18R	0-24"+
5	0+21,10L	0-18"+
6	0+46,07R	0-21"+
7	0+30,00R	0-12"*
8	0+34,06R	None

+Vertical extent of contamination not reached.

*Low-level contamination present.

Table 3.3
ANGLE HOLE SURVEY
Property DU-026

HOLE	LOCATION	CONTAMINATION DEPTH
H-1	West Wall Water pipe	None
H-2	East Wall	None
H-3	South Wall	None
H-4	North Wall	None



③ AUGER HOLE DESIGNATION

ESTIMATED DEPTH OF CONTAMINATION



12^a


 30"

Available On
Aperture Card

TI
APERTURE
CARD

8507100094-03

8/7 1985	FINAL REA SUBMITTAL					GJW							
DATE	REVISIONS					DRAWN BY	CHECKED BY	APPROV LDE	APPROV CH	PRIOR ENG	SUPPVA OC		

U. S. DEPARTMENT OF ENERGY									
ALBUQUERQUE, NEW MEXICO									
DESIGNED	DRAWN		FIGURE 3.1						
CHECKED	<i>J. Morrison</i>		RADIOLOGICAL SURVEY DATA DU-026						
REVIEWED									
RECOMMENDED									
APPROVED									
			DURANGO, COLORADO						
			URANIUM MILL TAILINGS REMEDIAL ACTION PROJECT						
NR			DATE	DOE PROJECT MANAGER		DATE	DOE PROJECT ENGINEER		DATE
				NR			NR		
 MORRISON KNUDSEN			PROJECT NO.						
			DE-AC04-83AL18796						
			DRAWING NO. DU-026-015						
			REV A						

4.0 ENGINEERING ASSESSMENT

Engineering options were formulated and evaluated based on the radiological and engineering assessment for this property. Factors forming the basis of the evaluation were: the extent and location of the contamination, construction costs, and required demolition and constructibility for the various options. Results of the evaluation are detailed below.

4.1 Evaluation of Options

4.1.1 Options

Two options were evaluated for property DU-026:

1. No action should be taken.
2. Complete decontamination of the property including retrieval of the contaminated material and restoration of the property.

Area B will not be addressed with this property. It will be excavated at a later date along with Rio Vista Circle.

Option 2 will include the following:

- o Demolish and remove concrete sidewalk adjacent to the driveway.
- o Remove and replace maple tree in contaminated area.
- o Excavate Area A to the depth shown in Figure 4.1, except for the driveway. Resurvey to determine if further excavation is required, including removal of the driveway.
- o Backfill excavated area with common fill and top with structural fill in sidewalk area and with topsoil and sod in lawn area.
- o Excavate Area "C" to the depth shown in Figure 4.1. Backfill with common fill and top with topsoil and sod.

4.1.2 Costs

Estimated costs for the activities associated with Option 2 are detailed in Table 4.1. Costs include labor, insurance, material, equipment, supplies, overhead, profit, and contingency. All costs are listed in 1985 dollars. It is anticipated that the time required for the subcontractor to complete the work will be 3 to 5 days.

4.2 Recommendation

The limited cost and amount of remedial action work precluded evaluating any more than these two options. The results of the radiological assessment concluded that contamination levels on the property exceeded EPA guidelines. Therefore, based on these guidelines, it is recommended that Option 2, decontamination of the property, be pursued. The total estimated cost for Option 2 is \$5,550.00.

Table 4.1
OPTION 2 COSTS

<u>Activity</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Estimated Cost</u>
Demolish and Remove Concrete Driveway and Sidewalk	3.00	364 sf	1,092.00
Remove Tree	200.00	1 ea	200.00
Excavation (Machine)	8.30	46 cy	381.00
Common Backfill	7.20	35 cy	252.00
Structural Fill	26.40	7 cy	184.80
Topsoil	26.40	4 cy	105.60
Sod	3.00	20 sf	60.00
Replace Tree	300.00	1 ea	300.00
Concrete Driveway and Sidewalk	3.50	364 sf	1,274.00

Subtotal	\$3,849.40
5% Subcontractor's Contingency	192.47
20% Overhead and Profit	<u>769.88</u>
Subtotal	\$4,811.75
15% Engineer's Contingency	<u>721.76</u>
Total (Rounded)	\$5,550.00

5.0 TECHNICAL SPECIFICATIONS

Technical specifications applicable to this property are indexed in Table 5.1 . Specifications previously approved by the Department of Energy (DOE) are noted in the table. Also listed are specifications not previously submitted to the DOE which require approval. The text for these additional specifications follow the table.


Table 5.1
INDEX OF TECHNICAL SPECIFICATIONS

Description	Specifications	
	Previously Approved	Specifications Requiring DOE Approval
Division 2 - Site Work		
SECTION 02050	DEMOLITION	X
SECTION 02110	CLEARING AND GRUBBING	X
SECTION 02130	CONTAMINATED MATERIAL REMOVAL	X
SECTION 02200	EXCAVATION AND BACKFILL	X
SECTION 02480	LANDSCAPING	X
SECTION 02500	PAVING AND SURFACING	X
Division 3 - Concrete		
SECTION 03300	CAST-IN-PLACE CONCRETE	X

6.0 CONSTRUCTION DRAWINGS

Listed below is an index of the construction drawings required for remedial action on this property. Copies of the drawings follow this section.

<u>Drawing Number</u>	<u>Drawing Title</u>
DU-026-020	Excavation & Restoration DU-026



LEGEND

— W —	WATER LINE
— G —	GAS LINE
— GM —	GAS MAIN
— S —	SEWER LINE
— SM —	SEWER MAIN
— STM —	STORM SEWER
— E —	ELECTRICAL LINE
— T —	TELEPHONE LINE
— TV —	CABLE TV
— — —	PROPERTY LINE
— X — X — X —	FENCE LINE
⊗ G, W or E	METER
⊗ G or W	VALVE
●	PROPERTY PIN
●	POWER POLE

NOTE: OVERHEAD SERVICE DENOTED BY SOLID LINE.
UNDERGROUND SERVICE DENOTED BY DASHED LINE.

NOTES:

1. THE LATEST REVISION OF THE FOLLOWING TECHNICAL SPECIFICATIONS APPLY TO THE REMEDIAL ACTION WORK REQUIRED FOR PROPERTY NO. DU-026.

SECTION 02110
CLEARING AND GRUBBING

SECTION 02130
CONTAMINATED MATERIAL REMOVAL

SECTION 02200
EXCAVATION AND BACKFILL

SECTION 02480
LANDSCAPING

SECTION 03300
CAST-IN-PLACE CONCRETE

2. UTILITY LOCATIONS ARE FOR REFERENCE ONLY. ACTUAL LOCATIONS SHALL BE DETERMINED BY THE SUBCONTRACTOR PRIOR TO START OF CONSTRUCTION.

3. THE EXCAVATION LIMITS AND DEPTHS ARE BASED ON A LIMITED NUMBER OF BORINGS TAKEN DURING THE RADIOLOGICAL SURVEYS OF THIS PROPERTY. ADDITIONAL RADIOLOGICAL SURVEYS PERFORMED DURING REMEDIAL ACTION MAY REQUIRE MORE OR LESS EXCAVATION TO BE TAKEN FROM THE DESIGNATED AREAS. ALL CHANGES TO THE LIMITS AND DEPTHS OF EXCAVATION AS SHOWN ON THE DESIGN DRAWINGS SHALL BE AS DIRECTED BY THE CONTRACTOR'S REPRESENTATIVE.

SCOPE OF WORK

AREA "A"

- DEMOLISH AND REMOVE CONCRETE SIDEWALK ADJACENT TO THE DRIVEWAY AND REMOVE MAPLE TREE NORTH OF THE DRIVEWAY.
- PROTECT DRIVEWAY DURING EXCAVATION.
- EXCAVATE AREA "A" TO A DEPTH OF 30 INCHES. RESURVEY THE AREA INCLUDING THE DRIVEWAY FOR ADDITIONAL CONTAMINATION. FURTHER EXCAVATION WILL BE APPROVED BY THE CONTRACTOR'S REPRESENTATIVE.
- BACKFILL SIDEWALK AREA WITH 20 INCHES OF COMMON FILL AND TOP WITH 6 INCHES OF STRUCTURAL FILL. BACKFILL LAWN AREA WITH 24 INCHES OF COMMON FILL, 6 INCHES OF TOPSOIL AND SOD.
- CONSTRUCT NEW 4 INCH THICK CONCRETE SIDEWALK TO SAME SIZE AND ELEVATION OF THAT REMOVED.
- REPLACE TREE WITH SIMILAR TYPE AND SIZE AS APPROVED BY THE CONTRACTOR'S REPRESENTATIVE.

AREA "C"

- EXCAVATE AREA "C" TO A DEPTH OF 12 INCHES.
- BACKFILL WITH 6 INCHES OF COMMON FILL AND 6 INCHES OF TOPSOIL AND SOD.



Also Available On
Aperture Card

TI
APERTURE
CARD

8507100094-04

U. S. DEPARTMENT OF ENERGY ALBUQUERQUE, NEW MEXICO

FIGURE 4.1

EXCAVATION & RESTORATION PLAN DU-026

DURANGO, COLORADO
URANIUM MILL TAILINGS REMEDIAL ACTION PROJECT

DESIGNED/DRAWN	DATE
CHECKED	DATE
REVIEWED	DATE
RECOMMENDED	DATE
APPROVED	DATE

NR

NR

NR

PROJECT NO.

DE-AC04-83AL18796

DRAWING NO.

DU-026-020

REV. A



MORRISON
KNUDSEN

2/1
1985 FINAL REA SUBMITTAL

DATE REVISIONS

DRW	CHK	APP	APP	APP	APP
BY	BY	DATE	DATE	DATE	DATE

APPENDIX A
SURVEY DATA LOGS

OUTDOOR GAMMA SCREENING SURVEY DATA SHEET

LOGGING CREW: ERNEST COUCH
EDWARD SCHULTZ
LEON BENALLY

SHEET 1 OF 4 PAGE 1
DATE: 6-21-84
PROPERTY ID: DV-026

INSTRUMENT ID NO.: LUD 2220 #31972 w/4410 #16527

BACKGROUND CALCULATION:

#1 _____ + #2 _____ + #3 _____ = _____ + 3 = 11,500 COUNTS/1MIN

AREA: _____		AREA: _____		AREA: _____		AREA: _____	
POINT ID	READING COUNTS/1MIN	POINT ID	READING COUNTS/1MIN	POINT ID	READING COUNTS/1MIN	POINT ID	READING COUNTS/1MIN
0+00	33570	0+00	20380	0+00	16470	0+00	14140
+10L	54440	+20R	23960	+10R	13980	+10R	13800
0+10	46180	0+10	18650	0+20	14230	0+10	14420
+10L	48610	+20R	18420	+10R	13280	+10R	14420
0+20	93800	0+20	17360	0+20	14160	0+20	15720
+10L	46340	+20R	15890	+10R	14210	+10R	14590
0+30	138670	0+30	16610	0+30	13860	0+30	14520
+10L	64180	+20R	16250	+10R	13240	+10R	13740
0+40	102800	0+40	16300	0+40	12630	0+40	14140
+10L	35010	+20R	17760	+10R	13360	+10R	13450
0+50	102610	0+50	14920	0+50	13980	0+50	13720
+10L	58260	+20R	20750	+10R	13110	+10R	13570
0+60	131250	0+60	19150	0+60	13730	0+60	13010
+10L	65570	+10R	19220	+10R	13560	+10R	13770
0+67.5	90230	0+67.5	16410	0+67.5	14110	0+67.5	13800
+10L	58330	+20R	16450	+10R	14040	+10R	12190
0+00+00	27060	0+00	18690	0+00	14140	0+00	14440
	25630	+30R	18310	+10R	14960	+10R	13770
0+00+00	19340	0+10	17780	0+10	14730	0+10	16610
	24260	+30R	17140	+10R	13510	+10R	13200
0+20+00	16820	0+20	16380	0+20	15170	0+20	15210
	21480	+30R	15740	+10R	13650	+10R	13760
0+30+00	35210	0+30	16740	0+30	14120	0+30	13960
	55910	+30R	14630	+10R	14120	+10R	12640
0+40+00	16860	0+40	16960	0+40	14830	0+40	14270
	21580	+30R	14930	+10R	13880	+10R	12140
0+50+00	16960	0+50	17810	0+50	14000	0+50	14450
	24440	+30R	17380	+10R	13440	+10R	12950
0+60+00	22320	0+60	16430	0+60	13720	0+60	15120
	28340	+30R	14200	+10R	13870	+10R	12460
0+67.5	19040	0+67.5	15790	0+67.5	14220	0+67.5	14110
+00	28910	+30R	15050	+10R	13400	+10R	12450
0+00+	19270	0+00+	17270	0+00	16030	0+00	13330
+10R	21500	+40R	17320	+10R	14670	+10R	13360
0+10+	2210	0+08+	14920	0+10	13950	0+10	13650
+10R	26260	+40R	14440	+10R	14340	+10R	12990
0+20	16040	0+60+	10780	0+20	14050	0+20	13920
+10R	18320	+40R	10930	+10R	14450	+10R	13250
0+30	16310	0+67.5	14350	0+30	14550	0+30	13490
+10R	17700	+40R	14980	+10R	13820	+10R	13480
0+40	16070	0+00+	17020	0+40	13740	0+40	13400
+10R	17310	+50R	15990	+10R	14000	+10R	13030
0+50	15720	0+08	14460	0+50	14000	0+50	13320
+10R	21130	+50R	14980	+10R	13240	+10R	13650
0+60	17620	0+60+	16320	0+60	15250	0+60	13300
+10R	21840	+50R	14390	+10R	13400	+10R	13430
0+67.5	16310			0+67.5	13120	0+67.5	13080
+10R	17140			+10R	13190	+10R	13000

REMARKS: ALL MEASUREMENTS ARE IN COUNTS PER MINUTE (CPM) TOP - CONTACT MEASUREMENT
BOTTOM - ARE MEASUREMENTS TAKEN 1 METER
GROUND LEVEL



BOREHOLE LOG

LOGGING CREW: Schultz
Bernal
Couch
INSTRUMENT ID NO. Kudlum #31982

SHEET 3 OF 4 PAGE 3
DATE: 6-21-84
PROPERTY ID: DU-026
AREA: Durango, Co

- NOTES: 1. ALL HOLES ARE 4" DIA. UNLESS OTHERWISE NOTED.
2. RECORD UNUSUAL CONDITIONS, SUCH AS THE PRESENCE OF WATER IN BOREHOLES AND DEPTH, CASING TYPE AND THICKNESS IF USED, CONCRETE CORES AND THICKNESS, OBSTRUCTIONS, UTILITIES, ETC., IN THE REMARKS SECTION.

①		②		③		④	
HOLE ID: <u>0144+10R</u>		HOLE ID: <u>0110+2L</u>		HOLE ID: <u>0157+20R</u>		HOLE ID: <u>0147+18R</u>	
TIME DRILLED: _____		TIME DRILLED: _____		TIME DRILLED: _____		TIME DRILLED: _____	
TIME LOGGED: _____		TIME LOGGED: _____		TIME LOGGED: _____		TIME LOGGED: _____	
SOIL TYPE: _____		SOIL TYPE: _____		SOIL TYPE: _____		SOIL TYPE: _____	
DEPTH	COUNTS/1MIN	DEPTH	COUNTS/1MIN	DEPTH	COUNTS/1MIN	DEPTH	COUNTS/1MIN
SURFACE	<u>18860</u>	SURFACE	<u>20570</u>	SURFACE	<u>49950</u>	SURFACE	<u>155020</u>
0"	—	0"	—	0"	—	0"	—
6"	<u>26720</u>	6"	<u>22790</u>	6"	<u>216960</u>	6"	<u>394890</u>
12"	<u>27360</u>	12"	<u>21780</u>	12"	<u>310010</u>	12"	<u>446160</u>
18"	<u>28100</u>	18" 15"	<u>18410</u>	18"	<u>122500</u>	18"	<u>128940</u>
24"	<u>27370</u>	24"		24"	<u>59180</u>	24" 23"	<u>64550</u>
30"		30"		30" 27"	<u>51200</u>	30"	
36"		36"		36"		36"	
42"		42"		42"		42"	
48"		48"		48"		48"	
54"		54"		54"		54"	
60"		60"		60"		60"	
66"		66"		66"		66"	
72"		72"		72"		72"	
78"		78"		78"		78"	
84"		84"		84"		84"	
90"		90"		90"		90"	
96"		96"		96"		96"	

REMARKS: All readings in cpm
BKgd Bare Hole are 23000 cpm
All holes drilled to rock

BOREHOLE LOG

LOGGING CREW: Schultz
Benally
Couch
 INSTRUMENT ID NO. Knudsen #31982

SHEET 4 OF 4 PAGE 4
 DATE: 6-21-84
 PROPERTY ID: D4-026
 AREA: Durango, Co.

NOTES: 1. ALL HOLES ARE 4" DIA. UNLESS OTHERWISE NOTED.
 2. RECORD UNUSUAL CONDITIONS, SUCH AS THE PRESENCE OF WATER IN BOREHOLES AND DEPTH, CASING TYPE AND THICKNESS IF USED, CONCRETE CORES AND THICKNESS, OBSTRUCTIONS, UTILITIES, ETC. IN THE REMARKS SECTION.

⑤		⑥		⑦		⑧	
HOLE ID: <u>0+2110L</u>		HOLE ID: <u>0+46+7R</u>		HOLE ID: <u>0+30+0V</u>		HOLE ID: <u>0+34+6R</u>	
TIME DRILLED: <u>Sidewalk</u>		TIME DRILLED: <u>Sidewalk</u>		TIME DRILLED: _____		TIME DRILLED: _____	
TIME LOGGED: <u>1h</u>		TIME LOGGED: <u>40</u>		TIME LOGGED: _____		TIME LOGGED: _____	
SOIL TYPE: <u>Front of house</u>		SOIL TYPE: <u>House</u>		SOIL TYPE: _____		SOIL TYPE: _____	
DEPTH	COUNTS/1MIN	DEPTH	COUNTS/1MIN	DEPTH	COUNTS/1MIN	DEPTH	COUNTS/1MIN
SURFACE	<u>166120</u>	SURFACE	<u>63050</u>	SURFACE	<u>32900</u>	SURFACE	<u>16470</u>
0"	<u>—</u>	0"	<u>—</u>	0"	<u>—</u>	0"	<u>—</u>
6"	<u>522240</u>	6"	<u>188670</u>	6"	<u>37400</u>	6"	<u>19920</u>
12"	<u>399840</u>	12"	<u>135490</u>	12"	<u>33660</u>	12"	<u>20950</u>
18"	<u>174870</u>	18"	<u>59120</u>	18"	<u>23590</u>	18"	<u>21830</u>
24"		24" 21"	<u>43720</u>	24" 20"	<u>22250</u>	24"	<u>21810</u>
30"		30"		30"		30" 26"	<u>22880</u>
36"		36"		36"		36"	
42"		42"		42"		42"	
48"		48"		48"		48"	
54"		54"		54"		54"	
60"		60"		60"		60"	
66"		66"		66"		66"	
72"		72"		72"		72"	
78"		78"		78"		78"	
84"		84"		84"		84"	
90"		90"		90"		90"	
96"		96"		96"		96"	

REMARKS: All Readings in cpm
Bkgd. Bore hole are 23,000 cpm
All holes drilled to rock

BOREHOLE LOG

Supplemental Information


LOGGING CREW: Ernest Canch
Edward Schultz
Julius Buttrick
 INSTRUMENT ID NO. LVD-1320 31982 4410 416578

SHEET 1 OF 1 PAGE 1
 DATE: October 16, 1984
 PROPERTY ID: DU-026
 AREA: Durango, Colorado

- NOTES: 1. ALL HOLES ARE 4" DIA. UNLESS OTHERWISE NOTED.
 2. RECORD UNUSUAL CONDITIONS, SUCH AS THE PRESENCE OF WATER IN BOREHOLES AND DEPTH, CASING TYPE AND THICKNESS IF USED, CONCRETE CORES AND THICKNESS, OBSTRUCTIONS, UTILITIES, ETC., IN THE REMARKS SECTION.

H-1		H-2		H-3		H-4	
HOLE ID: <u>Water pipe</u>		HOLE ID: <u>E. WALL</u>		HOLE ID: <u>S. WALL</u>		HOLE ID: <u>N. WALL</u>	
TIME DRILLED: <u>10 WALL</u>		TIME DRILLED: _____		TIME DRILLED: _____		TIME DRILLED: _____	
TIME LOGGED: _____		TIME LOGGED: _____		TIME LOGGED: _____		TIME LOGGED: _____	
SOIL TYPE: _____		SOIL TYPE: _____		SOIL TYPE: _____		SOIL TYPE: _____	
DEPTH	COUNTS/1MIN	DEPTH	COUNTS/1MIN	DEPTH	COUNTS/1MIN	DEPTH	COUNTS/1MIN
SURFACE	15720	SURFACE	16390	SURFACE	17150	SURFACE	16090
H 6"	18120	0"	15740	0"	18700	0"	18150
H 8"12"	18640	6"	18320	6"	20030	6"	18540
H 12"15"	19870	H 12"4"	18450	H 12"6"	19950	H 12"3"	19510
18"		18"		18"		18"	
24"		24"		24"		24"	
30"		30"		30"		30"	
36"		36"		36"		36"	
42"		42"		42"		42"	
48"		48"		48"		48"	
54"		54"		54"		54"	
60"		60"		60"		60"	
66"		66"		66"		66"	
72"		72"		72"		72"	
78"		78"		78"		78"	
84"		84"		84"		84"	
90"		90"		90"		90"	
96"		96"		96"		96"	

REMARKS: H = Horizontal, H # number equals the
hole and # of inches angled under spread
footing. Background is 23000 cpm, all
counts in CPM. (all crowd space)



MORRISON-KNUDSEN COMPANY, INC.

UMTRA PROJECT OFFICE
P.O. BOX 9136
ALBUQUERQUE, NEW MEXICO 87119