

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)  
EDWIN I. HATCH, UNIT 1DOCKET NUMBER (2)  
0 5 0 0 0 3 2 1 1 OF 0 2

TITLE (4)

STANDBY GAS TREATMENT AUTO INITIATION DUE TO INCORRECT RESTART OF BATTERY CHARGER

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)												
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)											
0	4	2	4	8	5	8	5	0	1	1	0	5	0	0	3	2	1	1	OF	0	2

OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)															
POWER LEVEL (10)	1	0	0	20.402(b)	20.406(c)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	73.71(b)									
				20.406(a)(1)(i)	50.36(c)(1)	<input type="checkbox"/>	50.73(a)(2)(v)	73.71(c)									
				20.406(a)(1)(ii)	50.36(c)(2)	<input type="checkbox"/>	50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)									
				20.406(a)(1)(iii)	50.73(a)(2)(i)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)										
				20.406(a)(1)(iv)	50.73(a)(2)(ii)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)										
				20.406(a)(1)(v)	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(ix)										

LICENSEE CONTACT FOR THIS LER (12)  
NAME  
Steven B. Tipps, Superintendent of Regulatory ComplianceTELEPHONE NUMBER  
AREA CODE  
9 1 2 3 6 7 1 7 8 5 1COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)  

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)  
☐ YES (If yes, complete EXPECTED SUBMISSION DATE) ☒ NO  
EXPECTED SUBMISSION DATE (15)  
MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 04/24/85 at approximately 0500 CST, Unit 1 was in steady-state operation at 2423 MWt (approximately 100% power) and Unit 2 was in refuel with no fuel in the vessel when the "A" train of the Standby Gas Treatment (SBGT) Systems for each unit started. This ESF actuation was not part of a pre-planned sequence, thus, this event is reportable per the requirements of 10CFR 50.73(a)(2)(iv).

Each "A" train of SBGT was returned to normal status immediately. The battery charger was correctly placed in service later the same day.

This actuation was due to inadequate special instructions which failed to give detailed instructions for returning a battery charger to service.

These special instructions were for one time use; hence, corrective action to prevent recurrence is not required.

8506040681 850521  
PDR ADOCK 05003321  
S PDRIE22  
11

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
EDWIN I. HATCH, UNIT 1	0 5 0 0 0 3 2 1 8 5	--	0 1 1	--	0 0 0	2	OF 0 2

TEXT (If more space is required, use additional NRC Form 365A's) (17)

On 04/24/85 at approximately 0500 CST, with Unit 1 in steady-state operation at 2423 MWt (approximately 100% power) and with Unit 2 in refuel with no fuel in the vessel, and following replacement of some cells of the "2A" station service battery (2R42-S001A), non-licensed operations personnel were placing the "2A" station service battery charger (2R42-S026) into service. During this operation, the charger's AC supply breaker tripped when the charger was turned on and immediately connected to its output load.

This attempt to place the charger in service resulted in a low voltage dip on the charger's AC power supply due to the high current drawn when the "2A" battery charger tried to start and assume its output load at the same time. This low voltage dip in the supply power momentarily de-energized the "A" train SGBT relay for each unit (this AC supply power is common to the normally energized relay which de-energizes to start the "A" train of SGBT for each unit, and activates the High Radiation Refueling Floor alarm in the control room). Thus, on 04/24/85 at approximately 0500 CST, the "A" train of the Standby Gas Treatment (SBGT) Systems for each unit started.

There was no effect on plant safety since the trains only initiated, and they were returned to normal status immediately. The battery charger was correctly started later the same day.

This ESF actuation was not part of a pre-planned sequence, thus, this event is reportable per the requirements of 10CFR50.73(a)(2)(iv).

Plant personnel initially thought that the refueling floor Area Radiation Monitors (ARMs) (either 2D11-K609A & B or 2D11-K611A & B) had spiked up-scale and actuated the "A" train of SGBT for each unit by de-energizing the respective normally energized relays. However, investigation showed that the refueling floor ARMs had not actuated.

The root cause of this event was inadequate special instructions. Special instructions were written for "2A" station service battery cell replacement and "2B" station service battery replacement to ensure the Division 1 and Division 2 busses remained energized during battery and cell replacement. However, the instructions did not give specific enough instructions for returning the "2A" charger and batteries to service; the instructions should have referenced the "125/250 VDC STATION SERVICE CHARGER ROTATION AND BREAKER RACKING" procedure (HNP-2-1660).

These special instructions were for one time use; hence, corrective action to prevent recurrence is not required.

Georgia Power Company  
Post Office Box 439  
Baxley, Georgia 31513  
Telephone 912 367-7781  
912 537-9444




Edwin I. Hatch Nuclear Plant

May 21, 1985  
GM-84-492

PLANT E. I. HATCH  
Licensee Event Report  
Docket No. 50-321

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Attached is Licensee Event Report No. 50-321/1985-11. This report is required by 10CFR 50.73(a)(2)(iv).

  
H. C. Nix  
General Manager

HCN/TLE/vlt

xc: R. J. Kelly  
R. E. Conway  
J. T. Beckham, Jr.  
P. D. Rice  
K. M. Gillespie  
D. R. Altman  
Superintendent of Regulatory Compliance  
R. D. Baker  
Control Room  
Document Control

IE22  
11