

SAFETY INSPECTION

Page 1 of 2

1. LICENSEE

STAN A HUBER CONSULTANTS

2. REGIONAL OFFICE

REGION III
U S NUCLEAR REGULATORY COMMISSION
801 WARRENVILLE ROAD
LISLE IL 60532-4351

3. DOCKET NUMBER(S)

99990003/96009

4. LICENSE NUMBER(S)

General License
10 CFR 150.20

5. DATE OF INSPECTION

9-24-96

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☐ 1. Within the scope of this inspection, no violations were observed.
- ☐ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- ☒ 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.11.
- ☐ A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b),(c),(d),(e) or 34.42.
- ☐ B. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ or License Condition Number _____.
- ☐ C. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____.
- ☐ D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
- ☐ E. Reports or notification of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
- ☒ F. 10 CFR 71.5 Requires NRC Licensees Follow 49 CFR Regulations 49 CFR 172.203 lists the description of radioactive material that must be on the shipping paper including name of the radioactive and activity. Contrary to the above, on September 23 and 24, 1996, the licensee transported a nominal Borei Cassium-137 sealed source.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE

DATE

SIGNATURE - NRC INSPECTOR

DATE

SAFETY INSPECTION

Page 2 of 2

1. LICENSEE

STAN A. HUBER CONSULTANTS

2. REGIONAL OFFICE

REGION III
U S NUCLEAR REGULATORY COMMISSION
801 WARRENVILLE ROAD
LISLE IL 60532-4351

3. DOCKET NUMBER(S)

99990003/96009

4. LICENSE NUMBER(S)

General license

5. DATE OF INSPECTION

9-24-96

3. (Continued)

☐ G. AND DID NOT PROPERLY DESCRIBE THE QUANTITY ~~OF~~ (quantity) OF EACH RADIOISOTOPE. SPECIFICALLY, THE SHIPPING PAPERS DESCRIBED A NOMINAL 100 milliwatt source. RATHER THAN 13mCi.

☒ H. 10CFR 20.1502 requires each licensee to monitor occupational exposure to radiation and supply and require the use of individual monitoring devices by adults likely to receive a dose in excess of 10 percent of the limit in 20.1201(a).

☐ I. CONTRARY TO THE ABOVE, ON SEPTEMBER 24, 1996, AN UNMONITORED USER OF THE LICENSEE USED RADIOACTIVE MATERIAL UNDER THE GENERAL LICENSE (13mCi Co-60 source) AND DID NOT HAVE REQUIRED DOSIMETRY. SPECIFICALLY, THE BADGE WAS MISPLACED BETWEEN 9/23 AND 9/24/96.

☐ 4. The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.

☐ A. _____
000000

☐ B. _____

☐ C. _____

06 SA 999