

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Palo Verde Unit 1										DOCKET NUMBER (2) 0 5 0 0 0 5 2 8 1 OF 0 2										PAGE (3) 1 OF 0 2	
TITLE (4) Failure To Inspect Automatic Fire Doors																					
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES					DOCKET NUMBER(S)							
05	26	85	85	029	00	07	10	85						0 5 0 0 0							
OPERATING MODE (9) 2			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																		
POWER LEVEL (10) 0.00			20.402(b)				20.405(c)				50.73(a)(2)(iv)				73.71(b)						
			20.405(a)(1)(i)				50.36(c)(1)				50.73(a)(2)(v)				73.71(c)						
			20.405(a)(1)(ii)				50.36(c)(2)				50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
			20.405(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(viii)(A)										
			20.405(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)										
			20.405(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(x)										
LICENSEE CONTACT FOR THIS LER (12)																					
NAME William F. Quinn, Manager - Nuclear Licensing (Ext. 4087)										TELEPHONE NUMBER 6 0 2 9 4 3 - 7 2 0 0											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs											
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)					MONTH	DAY	YEAR				
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)										<input checked="" type="checkbox"/> NO											

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On May 26, 1985, while Unit 1 was in Mode 2, Surveillance Procedure for Inspection of Automatic Fire Doors (14ST-1ZZL was performed 30 hours and 22 minutes after the previous one. The Surveillance interval is once every 24 hours as required by Technical Specification Surveillance Requirement 4.7.12.2.b.

This event was originally reviewed by the Compliance Section on May 28, 1985, and determined to be reportable. An LER was initiated and a draft was written. On June 14, 1985, after further investigation the Compliance Section reviewed the report and recommended that the event not be reported. All Technical Specifications deviations must be reviewed by the Plant Review Board (PRB). On July 1, 1985, the PRB reviewed the event report and determined that the event was reportable.

The Fire Watch was unable to gain timely access to the Automatic Fire Doors because they were located in a Radiologically Controlled Area (RCA). The Fire Watch had not yet received his dosimetry, because of an administrative delay. The RCA had been established and this was the Fire Watch's first time in the RCA. The Fire Watch also did not know the correct time frame required to complete the procedure.

To correct the problem, the performer has since received his dosimetry and has been reinstructed on the requirements of Technical Specifications.

8507230496 850710
PDR ADOCK 05000528
S PDR

IE22

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Palo Verde Unit 1	0 5 0 0 0 5 2 8	8 5	—	0 2 9	—	0 0	0 2 OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On May 26, 1985, while Unit 1 was in Mode 2, Surveillance Procedure for Inspection of Automatic Fire Doors (14ST-1ZZ25) was performed 30 hours and 22 minutes after the previous one. Surveillance Requirement 4.7.12.2.b for Inspection of Automatic Fire Doors, was exceeded by 6 hours and 22 minutes. Technical Specification 4.0.2 allows a 25% extension (or 6 hours). This allowance was exceeded by 22 minutes.

The event was originally reviewed by the Compliance Section on May 28, 1985, and determined to be reportable. An LER was initiated and a draft was written. On June 14, 1985, after further investigation the Compliance Section reviewed the report and recommended that the event not be reported. All Technical Specification deviations must be reviewed by the Plant Review Board (PRB). On July 1, 1985, the PRB reviewed the event report and determined that the event was reportable.

The Fire Watch was unable to gain timely access to the Automatic Fire Doors because they were located in a Radiologically Controlled Area (RCA). The Fire Watch had not yet received his dosimetry, because of an administrative delay. The RCA had been established and this was the Fire Watch's first time in the RCA. The Fire Watch also did not know the correct time frame required to complete the procedure.

To correct the problem, the performer has since received his dosimetry and has been reinstructed on the requirements of Technical Specifications.



Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

July 10, 1985
ANPP-33000-EEVB/GEC

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 1
Docket No. STN 50-528, License No. NPF-34
Licensee Event Report - Failure to Inspect Automatic Fire Doors
File: 85-056-026; G.1.01.10

Dear Sirs:

Attached please find Licensee Event Report (LER) No. 85-029-00 prepared and submitted pursuant to 10CFR 50.73. This LER addresses the failure to inspect automatic fire doors. In accordance with 10CFR 50.73(d), we are herewith forwarding a copy of the LER to the Regional Administrator of the Region V Office.

If you have any questions or concerns, please contact me.

Very truly yours,

E. E. Van Brunt / ASK

E. E. Van Brunt, Jr.
Executive Vice President
Project Director

EEVB/GEC/slh
Attachments

cc: J. B. Martin (all w/a)
R. P. Zimmerman
A. L. Hon
E. A. Ilicitra
A. C. Gehr
INPO Records Center

LE22