

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) EDWIN I. HATCH, UNIT I										DOCKET NUMBER (2) 0 5 0 0 0 3 2 1										PAGE (3) 1 OF 0 2																													
TITLE (4) FAILURE TO MEET TECH. SPES. CALIBRATION REQUIREMENTS																																																	
EVENT DATE (5) MONTH DAY YEAR 0 6 1 7 8 5										LER NUMBER (6) YEAR SEQUENTIAL NUMBER REVISION NUMBER 8 5 - 0 2 4 - 0 0										REPORT DATE (7) MONTH DAY YEAR										OTHER FACILITIES INVOLVED (8) FACILITY NAMES DOCKET NUMBER(S) 0 5 0 0 0																			
OPERATING MODE (9) 5										THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8 (Check one or more of the following) (11)																																							
POWER LEVEL (10) 9 0 0										20.402(b)										20.406(c)										50.73(a)(2)(iv)										73.71(b)									
										20.406(a)(1)(i)										50.36(c)(1)										50.73(a)(2)(v)										73.71(c)									
										20.406(a)(1)(ii)										50.36(c)(2)										50.73(a)(2)(vi)										OTHER (Specify in Abstract below and in Text, NRC Form 366A)									
										20.406(a)(1)(iii)										X 50.73(a)(2)(i)										50.73(a)(2)(vii)(A)																			
										20.406(a)(1)(iv)										50.73(a)(2)(ii)										50.73(a)(2)(vii)(B)																			
										20.406(a)(1)(v)										50.73(a)(2)(iii)										50.73(a)(2)(x)																			
LICENSEE CONTACT FOR THIS LER (12)																																																	
NAME Steven B. Tipps, Superintendent of Regulatory Compliance																				TELEPHONE NUMBER AREA CODE 9 1 2 3 6 7 1 7 8 5 1																													
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																																	
CAUSE SYSTEM COMPONENT MANUFACTURER REPORTABLE TO NPDs										CAUSE SYSTEM COMPONENT MANUFACTURER REPORTABLE TO NPDs																																							
SUPPLEMENTAL REPORT EXPECTED (14)																				EXPECTED SUBMISSION DATE (15)										MONTH DAY YEAR 1 2 1 7 8 5																			
X YES (If yes, complete EXPECTED SUBMISSION DATE)																				NO																													

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 06/17/85 at approximately 1500 CDT with the reactor mode switch in the shutdown position and the unit in cold shutdown, plant Instrumentation and Control (I and C) personnel determined that the Post LOCA Radiation Monitoring System recorders (1D11-R622A and B) were not being calibrated once every six months as required by Tech. Specs. table 3.2-11(12).

Recorders 1D11-R622A and B were calibrated on 06/17/85 and were incorporated into the plant surveillance database to be calibrated once every six-months as required by Tech. Specs. table 3.2-11(12).

There were no actual or potential safety consequences as a result of this event nor were the health and safety of the public affected.

There have been similar previous events as reported in LER 50-366/1984-030 Rev 3.

8507290355 850712  
PDR ADOCK 05000321  
S PDR

IE22, 11

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
EDWIN I. HATCH, UNIT 1	05000321	85	024	00	2	OF	2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

This 30 day LER is required by 10CFR50.73(a)(2)(i)(b) because the Post LOCA Radiation Monitoring System recorders (1D11-R622 A and B) were not being calibrated once every six months as required by Tech. Specs. table 3.2-11(12).

On 06/17/85 at approximately 1500 CDT with the reactor mode switch in the shutdown position and the unit in cold shutdown, plant Instrumentation and Control (I and C) personnel determined that the Post LOCA Radiation Monitoring System recorders (1D11-R622A and B) were not being calibrated once every six months as required by Tech. Specs. table 3.2-11(12).

The cause of this event was personnel error in that 1D11-R622A and B were never incorporated into the plant surveillance database. The Post LOCA Radiation Monitoring indicating and trip units (1D11-K622A through D) however, were included in the surveillance database and were being calibrated every six months as required by Tech. Specs.

There were no actual or potential safety consequences as a result of this event, nor were the health and safety of the public affected.

Recorders 1D11-R622A and B were calibrated on 06/17/85 and were incorporated into the plant surveillance database to be calibrated once every six months as required by Tech. Specs. table 3.2-11(12).

Similar previous events were reported in LER 50-366/1984-030 Rev 3. At that time, plant personnel conducted an on-site review of the surveillance database, Tech. Specs. and the applicable plant procedures in order to prevent recurrence. That review did not identify all of the existing discrepancies.

Plant personnel are presently investigating the most effective course of action to be taken in order to prevent the recurrence of events of this type.

An update report will be filed relating the results of this investigation.

Georgia Power Company  
Post Office Box 439  
Baxley, Georgia 31513  
Telephone 912 367-7781  
912 537-9444




Edwin I. Hatch Nuclear Plant

July 12, 1985  
LR-MGR-058-0785

PLANT E. I. HATCH  
Licensee Event Report  
Docket No. 50-321

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-321/1985-024. This report is required by 10CFR 50.73(a)(2)(i).

  
\_\_\_\_\_  
H. C. Nix  
General Manager

*SB*  
HCN/SBT/vlz

xc: R. J. Kelly  
R. E. Conway  
J. T. Beckham, Jr.  
P. D. Rice  
K. M. Gillespie  
D. R. Altman  
Superintendent of Regulatory Compliance  
R. D. Baker  
Control Room  
Document Control

*1622*  
*1/1*