

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Fort Calhoun Station, Unit No. 1	DOCKET NUMBER (2) 0 5 0 0 0 2 8 5	PAGE (3) 1 OF 0 2
---	--------------------------------------	----------------------

TITLE (4)  
VIAS Actuation

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)	
0 6	2 0	8 5	8 5	0 0 4	0 0	0 7	2 0	8 5	N	0 5 0 0 0	
										0 5 0 0 0	

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8: (Check one or more of the following) (11)											
	20.402(b)			20.408(a)			<input checked="" type="checkbox"/> 80.73(a)(2)(iv)			73.71(b)		
	20.408(a)(1)(i)			80.36(e)(1)			80.73(a)(2)(v)			73.71(e)		
	20.408(a)(1)(ii)			80.36(e)(2)			80.73(a)(2)(vi)			OTHER (Specify in Abstract below and in Text, NRC Form 365A)		
	20.408(a)(1)(iii)			80.73(a)(2)(i)			80.73(a)(2)(vii)(A)					
	20.408(a)(1)(iv)			80.73(a)(2)(ii)			80.73(a)(2)(vii)(B)					
20.408(a)(1)(v)			80.73(a)(2)(iii)			80.73(a)(2)(ix)						
POWER LEVEL (10) 11 0 1 0												

LICENSEE CONTACT FOR THIS LER (12)		TELEPHONE NUMBER
NAME Lawrence T. Kusek, Supervisor-Operations Fort Calhoun Station, Unit No. 1	AREA CODE 4 0 2	4 2 6 - 4 0 1 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)									
CAUSE	SYSTEM	COMPONENT	MANUFAC. TURER	REPORTABLE TO NPDs	CAUSE	SYSTEM	COMPONENT	MANUFAC. TURER	REPORTABLE TO NPDs

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During normal plant operation at 100% power, an unplanned actuation of the Ventilation Isolation Actuation System (VIAS) occurred at 1121 on June 20, 1985. The actuation of the VIAS signal [an Engineered Safety Feature (ESF)] was not initiated to mitigate an event as described in the USAR. The actuation was caused by operator error. The actuation occurred while the operator was returning RM-062 to "operate" from "calibrate" after the chemist had taken a sample of RM-061 filter paper. The "calibrate" position is higher than the trip setpoint of RM-062. The operator released the "reset" pushbutton before the meter dropped below the trip setpoint. If the "reset" pushbutton had been depressed long enough, the VIAS actuation would not have occurred.

As soon as the VIAS actuation occurred, the monitor was returned to normal and VIAS was reset. All Engineered Safeguards Features involved in this incident functioned as designed. No equipment malfunctions occurred and no radioactive release occurred.

To prevent future unplanned VIAS actuations of this nature, applicable plant procedures will be reviewed and clarified if necessary. The operators will be made aware of this incident and retrained on the proper methods of monitor operation through training.

8507310040 850720  
PDR ADOCK 05000285  
S PDR

IE22  
11

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Fort Calhoun Station, Unit No. 1	0 5 0 0 0 2 8 5	8 5	— 0 0 4	— 0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

During normal plant operation at 100% power, an unplanned actuation of the Ventilation Isolation Actuation System (VIAS) occurred at 1121 on June 20, 1985. The actuation of the VIAS signal [an Engineered Safety Feature (ESF)] was caused by operator error. This VIAS actuation occurred while the operator was placing the ventilation discharge duct monitors, RM-061 and RM-062, back in service following a sample clipping by the shift chemist of RM-061's filter paper. RM-061 and RM-062 share the same sample pump so both monitors had to be placed in "calibrate" to prevent spiking of the RM-061 and RM-062 monitors when the sample pump was restarted. The "calibrate" position on the scale of RM-062 is higher than the trip setpoint. When returning a monitor to service from the "calibrate" mode, the "reset" pushbutton must be held in until the meter indication drops below the trip setpoint; otherwise, the monitor will trip and initiate VIAS. In this case, the operator released the "reset" pushbutton too early and RM-062 tripped into high alarm. This causes the Containment Radiation High Signal (CRHS) relay to actuate due to the 1-out-of-5 logic, causing the VIAS relay to actuate.

VIAS, as described in the USAR, is designed to mitigate a release of significant radioiodine or radiogas from the containment to atmosphere from such sources as reactor coolant leaks. VIAS is initiated by a safety injection actuation signal (SIAS) or a containment spray actuation signal (CSAS) or a containment radiation high signal (CRHS). The CRHS feature employs five radiation monitors taking samples from the containment and/or ventilation stack. These monitors supply a 1-out-of-5 logic network to trip the VIAS lockout relays.

The five ventilation radiation monitors that actuate VIAS are used for an isolation function similar to that performed by other process radiation monitor systems. The ventilation monitors are used as process monitors in order to satisfy the Technical Specification 2.9 objective of controlling the release of radioactive effluents to the environs to as low as practicable.

The VIAS performs the following functions:

1. Closes the containment purge valves.
2. Closes the containment pressure relief valves.
3. Stops the containment purge fans.
4. Closes the containment air sampling valves.
5. Opens the inlet and outlet vents to the safety injection pump rooms and the spent regenerant tank room.
6. Limits the control room air conditioning units to single operation and places the control room ventilation system in a filtered air makeup mode.
7. Closes the waste gas header release valve to the stack.
8. Places the containment cooling and filtering units in the filtered mode.

To prevent future unplanned VIAS actuations of this nature, applicable plant procedures will be reviewed and clarified if necessary. The operators will be made aware of this incident and retrained on the proper methods of monitor operation through training.

Other VIAS actuations that have occurred since the new LER rule went into effect on January 1, 1984, were reported in LER's 84-005, 84-007, 84-006, 84-014, 84-017, 84-018, 84-019, 84-023, 84-024, 84-025, 85-001, 85-002 and 85-003.

**Omaha Public Power District**  
1623 Harney Omaha, Nebraska 68102  
402/536-4000

July 19, 1985  
FC-284-85  
LIC-85-337

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555


Reference: Docket No. 50-285

Gentlemen:

Licensee Event Report for the  
Fort Calhoun Station

Please find attached Licensee Event Report 85-004 dated June 20, 1985. This report is being submitted per requirements of 10 CFR 50.73.

Sincerely,



R. L. Andrews  
Division Manager  
Nuclear Production

RLA/DJM/rh-W

Attachment

cc: Mr. Dorwin R. Hunter, Chief  
Reactor Project Branch 2  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Mr. E. G. Tourigny, Project Manager  
Mr. L. A. Yandell, Senior Resident Inspector  
INPO Records Center  
American Nuclear Insurers  
SARC Chairman  
PRC Chairman  
Fort Calhoun File (2)