

JUN 4 1985

DISTRIBUTION:
 Central Files
 HFEB Files (2)
 DHFS Files (2)
 WHRegan
 HFEB Members

MEMORANDUM FOR: Gus C. Laines, Assistant Director
 for Operating Reactors
 Division of Licensing

FROM: Don H. Beckham, Acting Deputy Director
 Division of Human Factors Safety

SUBJECT: DRAFT SER INPUT FOR THE MAINE YANKEE ATOMIC POWER PLANT
 DETAILED CONTROL ROOM DESIGN REVIEW (DCRDR)

Maine Yankee Atomic Power Company (MYAPCo) submitted a Program Plan to the NRC on August 12, 1982, for conducting a DCRDR of the Maine Yankee control room. MYAPCo submitted their DCRDR Summary Report on February 28, 1985.

The staff conducted an on-site, in-progress audit of the licensee's DCRDR during February 13-17, 1984.

Enclosure 1 provides results of the staff's safety evaluation of MYAPCo's DCRDR for Maine Yankee. The evaluation was based on information provided in the Program Plan, the Summary Report and results of the on-site in-progress audit. The organization, methods and processes, and results of the MYAPCo DCRDR were compared with the requirements of Supplement 1 to NUREG-0737 and guidance contained in NUREG-0700 and Section 18.1, Revision 0 and Appendix A to Section 18.1, Revision 0 of the Standard Review Plan. Consultants from Science Applications International Corporation (SAIC) assisted the staff in the evaluation and provided a Technical Evaluation Report (TER).

The TER, which addresses the strengths and weaknesses of the licensee's DCRDR Summary Report is being transmitted to you as Enclosure 2. The NRC staff agrees with the technical positions and conclusions as presented in the TER. MYAPCo has conducted a DCRDR for Maine Yankee that probably satisfies most of the requirements of a DCRDR as contained in Supplement 1 to NUREG-0737. However, the staff could not fully evaluate the results of the Maine Yankee DCRDR Program because of insufficient information. In addition, it has come to the staff's attention that the System and Function Analyses (that were the

Contacts:
 G. W. Lapinsky
 x29794

J. J. Kramer
 x29853

OFFICE							
SURNAME							
DATE							

6506110155 XA

JUN 4 1985

basis for upgrading the Maine Yankee Emergency Procedures and Control Room) are being redone. The implications of this revision were not discussed in the licensee's submittals. Therefore, the staff recommends that representatives from MYAPCo meet with the staff as soon as possible to discuss:

1. submitting supplemental information so that the staff's review may continue;
2. implementation schedule for control room modifications;
3. scheduling a Pre-Implementation Audit for review of the system function and task analysis, and specific review of selected human engineering discrepancies, their assessed safety significance and priority, and their proposed resolution.

In the meantime, MYAPCo should continue implementing its program and should not delay any scheduled control room upgrades. The enclosed draft SER and TER should be transmitted to MYAPCo and a meeting date scheduled as soon as possible.

The draft SER was prepared by George Lapinsky of the Human Factors Engineering Branch.

15/
Don H. Beckham, Acting Deputy Director
Division of Human Factors Safety

Enclosures:
As stated

cc: J. R. Miller
K. Heitner
C. Miller
S. Bajwa
R. Liner, SAIC
M. Fineberg, SAIC
D. Schultz, COMEX

GWL3/DCRDR SER MAINE YANKEE

OFFICE	HFEB	HFEB	HFEB:SL	HFEB:AC	DHFS:ADD	
SURNAME	GLapinsky:b	RRamirez	Sweiss	WH	DHBeckham	
DATE	5/22/85	5/22/85	5/22/85	5/29/85	6/4/85	

DRAFT

ENCLOSURE 1

HUMAN FACTORS ENGINEERING BRANCH
DETAILED CONTROL ROOM DESIGN REVIEW
DRAFT
SAFETY EVALUATION REPORT
FOR
MAINE YANKEE ATOMIC POWER PLANT

POSITION

Licensees and applicants for operating licenses shall conduct a Detailed Control Room Design Review (DCRDR). The objective is to "improve the ability of nuclear power plant control room operators to prevent accidents or cope with accidents if they occur by improving the information provided to them" (NUREG-0660, Item I.D.). The need to conduct a DCRDR was confirmed in NUREG-0737 and Supplement 1 to NUREG-0737. DCRDR requirements in Supplement 1 to NUREG-0737 replaced those in earlier documents. Supplement 1 to NUREG-0737 requires each applicant or licensee to conduct a DCRDR on a schedule negotiated with the Nuclear Regulatory Commission (NRC).

NUREG-0700 (Ref. 7) describes four phases of the DCRDR to be performed by the applicant and licensee. The phases are:

1. Planning
2. Review
3. Assessment and Implementation, and
4. Reporting.

Criteria for evaluating each phase are contained in Section 18.1, Revision 0 and Appendix A to Section 18.1, Revision 0 of the Standard Review Plan.

As a requirement of Supplement 1 to NUREG-0737, the applicants and licensees are required to submit a program plan that describes how the following elements of the DCRDR will be accomplished:

1. Establishment of a qualified multidisciplinary review team
2. Function and task analyses to identify control room operator tasks and information and control requirements during emergency operations
3. A comparison of display and control requirements with a control room inventory
4. A control room survey to identify deviations from accepted human factors principles
5. Assessment of human engineering discrepancies (HEDs) to determine which HEDs are significant and should be corrected
6. Selection of design improvements

7. Verification that selected design improvements will provide the necessary correction
8. Verification that improvements will not introduce new HEDs
9. Coordination of control room improvements with changes from other programs such as SPDS, operator training, Reg. Guide 1.97 instrumentation, and upgraded emergency operating procedures.

The NRC requires each applicant and licensee to submit a summary report at the end of the DCRDR. The report should describe the proposed control room changes, implementation schedules, and provide justification for leaving safety significant HEDs uncorrected or partially corrected.

The NRC will evaluate the organization, process, and results of each DCRDR. The evaluation of the applicant's and licensee's DCRDR efforts will consist of the following, as described in NUREG-0800 (Ref. 8).

1. An evaluation of the Program Plan report submitted by the licensee/applicant
2. A visit to some of the plant sites to audit the progress of the DCRDR programs
3. An evaluation of the licensee/applicant DCRDR summary report

4. A possible pre-implementation audit
5. The preparation of a Safety Evaluation Report (SER) that will present the results of the NRC evaluation.

Significant HEDs should be corrected. Improvements which can be accomplished with an enhancement program should be done promptly.

DISCUSSION

The Maine Yankee Atomic Power Company (MYAPCo) submitted a Program Plan (Ref. 1) for conducting a DCRDR at the Maine Yankee Atomic Power Plant to the NRC on August 12, 1982. Staff comments on the Program Plan were issued on October 4, 1983 (Ref. 2). MYAPCo submitted a Summary Report on February 28, 1985 (Ref. 4).

The staff conducted an on-site in-progress audit of the MYAPCo DCRDR on February 13-17, 1984 with consultants from Science Applications International Corporation (SAIC). The licensee's DCRDR has been evaluated based on information provided in the Program Plan, Summary Report and during the in-progress audit.

The organization, methods and processes, and results of the Maine Yankee DCRDR were compared with the requirements of Supplement 1 to NUREG-0737 and guidance contained in NUREG-0700 and Section 18.1, Revision 0 and Appendix A to Section 18.1, Revision 0 of the Standard Review Plan. Consultants from

SAIC assisted the staff in the evaluation and prepared the enclosed Technical Evaluation Report (TER). The NRC staff agrees with the technical positions and conclusions as presented in the TER.

The following is a summary of the staff's comments on MYAPCo's compliance with the DCRDR requirements of NUREG-0737, Supplement 1:

1. Establishment of a Qualified Multidisciplinary Team - It is not clear whether the necessary expertise was available at appropriate levels of effort for each of the DCRDR tasks.
2. System Function and Task Analysis (SFTA) To Identify Control Room Operator Tasks and Information and Control Requirements During Emergency Operations - It is not clear whether the staff's audit findings have been resolved; in addition, since MYAPCo plans to redo its EOP upgrade program, it appears that further task analysis and validation may be necessary.
3. Comparison Of Display and Control Requirements With a Control Room Inventory - The licensee has generated an acceptable control room inventory; however, since the acceptability of this requirement is contingent on both the inventory and the task analysis results, and since the task analysis is in question (see above), this remains an open item.

4. Control Room Survey To Identify Deviations From Accepted Human Factors Principles - The control room survey has been conducted satisfactorily, using the guidance and criteria of NUREG-0700.
5. Assessment Of HEDs To Determine Which Are Significant And Should Be Corrected - While the licensee has developed an acceptable assessment process, actual implementation of the process is unclear, i.e., MYAPCo should describe how cut-off levels were determined.
6. Selection Of Design Improvements That Will Correct Discrepancies - The licensee did not provide a description of how this process was addressed.
7. Verification That Improvements Will Provide The Necessary Correction Without Introducing New HEDs - MYAPCo proposed an acceptable verification method during the in-progress audit. Staff could not determine whether that method was actually implemented.
8. Coordination Of Control Room Improvements With Changes Resulting From Other Improvement Programs - Specific coordination mechanisms and processes were not described in the licensee's Summary Report.

DRAFT

CONCLUSIONS

The licensee has provided sufficient evidence for the staff to affirm that one of the requirements of NUREG-0737, Supplement 1 has been satisfied, that is the requirement for a control room survey. However, insufficient information was provided to allow complete evaluation of the other eight requirements. Therefore, the staff recommends that the licensee submit supplemental information, as follows:

1. discussion about the level of involvement of specific team members in various phases and tasks of the DCRDR especially the human factors specialist, training specialist, and nuclear systems engineer;
2. further discussion to clarify how the NRC in-progress audit findings regarding the system function review and task analysis have been resolved;
3. discussion regarding the possible impact of revising the emergency procedure program on the DCRDR, especially the task analysis and validation;
4. discussion addressing the concerns raised in the enclosed TER regarding task analysis;

5. discussion addressing the concerns raised in the enclosed TER regarding the assessment process, e.g., how was the cut-off point for safety significance established?
6. further description of the actual processes used to select design improvements;
7. confirmation that the process for verifying the adequacy of corrections, as described at the in-progress audit, has been implemented;
8. further discussion regarding the coordination of initiatives, especially emergency procedure upgrading, SPDS, and DCRDR.

The staff also recommends that a meeting be held with representatives from MYAPCo in early July, 1985 so that the staff's information needs are clearly understood. In addition, based on the staff's present knowledge of the task analysis effort at Maine Yankee, it appears that a Pre-Implementation Audit may be needed at some later date to confirm that the task analysis has been adequately performed. This matter will be discussed at the meeting and, if necessary, a date scheduled. A final item for discussion at the meeting will be a clarification of the implementation schedule for control room upgrades.

In conclusion, the licensee provided sufficient evidence for the staff to confirm that an acceptable control room survey has been done at Maine Yankee.

DRAFT

- 9 -

However, eight requirements of NUREG-0737, Supplement 1, Section 5 could not be properly evaluated because of insufficient information. The staff recommends that these open items be resolved by requesting supplemental information from the licensee and, possibly, performing an on-site audit.

DRAFT

REFERENCES

1. Letter from J. H. Garrity (MYAPCo) to R. A. Clark (NRC) dated August 12, 1982, with attachment, "Program Plan Report for the Detailed Control Room Design Review."
2. "NUREG-0737, Supplement 1 - DCRDR Program Plan Letter" from J. R. Miller (NRC) to J. H. Garrity (MYAPCo), dated October 4, 1983.
3. NUREG-0737, Supplement 1, "Requirements for Emergency Response Capability," U.S. NRC, Washington, D.C., December 1982, transmitted to reactor licensees via Generic Letter 82-33, December 17, 1982.
4. Letter from G. D. Whittier (MYAPCo) to J. R. Miller (NRC) dated February 28, 1985, with attachment, "A Human Factors Engineering Critical Assessment of the Design of the Control Room at Maine Yankee Atomic Power Company."
5. NUREG-0660, Vol. 1, "NRC Action Plan Developed as a Result of the TMI-2 Accident," May 1980; revision 1, August 1980.
6. NUREG-0700, "Guidelines for Control Room Design Reviews," September 1981.
7. NUREG-0800, "Standard Review Plan," section 18.1, "Control Room," and Appendix A "Evaluation Criteria for Detailed Control Room Design Reviews (DCRDR)," September 1984.

EVALUATION OF THE
DETAILED CONTROL ROOM DESIGN REVIEW
SUMMARY REPORT
FOR MAINE YANKEE ATOMIC POWER STATION

May 8, 1985

Prepared for
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Contract NRC-03-82-096

Prepared by
Science Applications International Corporation
1710 Goodridge Drive
McLean, Virginia 22102

~~8506040512~~

FOREWORD

This Technical Evaluation Report (TER) was prepared by Science Applications International Corporation (SAIC) under Contract NRC-03-82-096, Technical Assistance in Support of NRC Licensing Actions: Program III. The evaluation was performed in support of the Division of Human Factors Safety, Human Factors Engineering Branch (HFEB). SAIC previously evaluated Maine Yankee Atomic Power Company's Program Plan submitted for the Detailed Control Room Design Review (DCRDR) conducted for Maine Yankee Atomic Power Station (Reference 1). Results of that evaluation are described in a memorandum prepared by HFEB and transmitted to the licensee (Reference 2). Subsequent to issuance of the memorandum, an in-progress audit was conducted at the plant (Reference 3).

This report includes the SAIC evaluation of the licensee's Summary Report (Reference 4) and considers DCRDR activity information presented in the Program Plan and findings provided at the audit.

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
BACKGROUND	1
PLANNING PHASE	3
1. Preparation and Submission of a Program Plan	3
2. Qualifications and Structure of the DCRDR Team	3
REVIEW PHASE	5
1. Operating Experience Review	5
2. System Function Review and Task Analysis	6
3. Comparison of Display and Control Requirements With a Control Room Inventory	9
4. Control Room Survey	10
ASSESSMENT AND IMPLEMENTATION PHASE	10
1. Assessment of HEDs	11
2. Selection of Design Improvements	13
3. Proposed Schedules for Implementing HED Corrections	14
4. Verification That Improvements Will Provide the Necessary Corrections Without Introducing New HEDs	14
5. Coordination of the DCRDR With Other Improvement Programs.	15
CONCLUSIONS AND RECOMMENDATIONS	15
REFERENCES	18

EVALUATION OF THE
DETAILED CONTROL ROOM DESIGN REVIEW
SUMMARY REPORT
FOR MAINE YANKEE ATOMIC POWER STATION

This report documents the Science Applications International Corporation (SAIC) evaluation of the Summary Report of the Detailed Control Room Design Review (DCRDR) submitted to the Nuclear Regulatory Commission (NRC) by Maine Yankee Atomic Power Company (MYAPCo) for Maine Yankee Atomic Power Station on February 28, 1985 (Reference 4). This evaluation also considers information obtained from the previously submitted Program Plan (Reference 1). Further information regarding DCRDR activities was acquired at an in-progress audit conducted at the plant on February 13-17, 1984 (Reference 3).

Results of the SAIC evaluation follow a brief overview of the background leading up to preparation and submission of the Summary Report by the licensee.

BACKGROUND

Licensees and applicants for operating licenses are required to conduct a Detailed Control Room Design Review. The objective of the review is to "...improve the ability of nuclear power plant control room operators to prevent accidents or cope with accidents if they occur by improving the information provided to them" NUREG-0660, Item I.D.1 (Reference 5). The need to conduct a DCRDR was confirmed in NUREG-0737 (Reference 6), and the requirements to be met in such a review were contained in Supplement 1 to NUREG-0737 (Reference 7). Guidelines for conducting a DCRDR are provided in NUREG-0700 (Reference 8), while NUREG-0800 (Reference 9) presents the assessment processes for use by the NRC.

The DCRDR requirements as stated in Supplement 1 to NUREG-0737 can be summarized in terms of nine specific issues, a list of which provides a convenient outline of the areas covered in this technical evaluation. The nine issues include:

1. Establishment of a qualified multidisciplinary review team;

2. Use of function and task analyses to identify control room operator tasks and information and control requirements during emergency operations;
3. A comparison of display and control requirements with a control room inventory;
4. A control room survey to identify deviations from accepted human factors principles;
5. Assessment of human engineering discrepancies (HEDs) to determine which HEDs are significant and should be corrected;
6. Selection of design improvements that will correct these discrepancies;
7. Verification that selected design improvements will provide the necessary correction;
8. Verification that improvements can be introduced in the control room without creating any unacceptable human engineering discrepancies; and
9. Coordination of control room improvements with changes resulting from other improvement programs such as SPDS, operator training, new instrumentation (Reg. Guide 1.97, Rev. 2), and upgraded emergency operating procedures.

A DCRDR is to be conducted according to the licensee's own Program Plan (which must be submitted to the NRC). According to NUREG-0700, it should address the previously stated requirements and be conducted in accordance with the following four phases: (1) planning, (2) review, (3) assessment, and (4) reporting. The product of the last phase is a Summary Report which must include an outline of proposed control room changes, their proposed schedules for implementation, and summary justification of human engineering discrepancies with safety significance to be left uncorrected or partially corrected. Upon receipt of the licensee's Summary Report and prior to implementation of proposed changes, the NRC must prepare a Safety Evaluation

Report (SER) indicating the acceptability of the DCRDR (not just the Summary Report). The NRC's evaluation encompasses all documentation as well as briefings, discussions, and audits if any were conducted.

PLANNING PHASE

Maine Yankee's planning phase activities included: (1) preparation and submission of a Program Plan, and (2) establishment of a review team.

1. Preparation and Submission of a Program Plan

The Program Plan submitted for Maine Yankee did not fulfill the requirements of Supplement 1 to NUREG-0737. Although many of the elements of a review were addressed, the Maine Yankee Program Plan only provided brief descriptions of what would be accomplished. Specific areas of the work were not described in sufficient detail to provide assurance that the licensee understood the processes necessary to complete the tasks and therefore meet the requirements. The results of the evaluation of the Maine Yankee Program Plan are detailed in Reference 2.

2. Establishment of a Qualified Multidisciplinary Review Team

The licensee's Program Plan included a brief description of the staff and management organization that was established to conduct the control room design review. From additional information provided by the licensee at the audit and in the Summary Report, it appears that the structure and management of the DCRDR are flexible enough to permit a multidisciplinary effort. Management seemed to be actively interested and involved. Management of the DCRDR was the responsibility of the chairman of a steering committee who supervised the activities of a working group, reported progress to Maine Yankee management concerning activities of the review team, managed resources allocated to the design review, and coordinated review team personnel assignments.

The Maine Yankee DCRDR team itself consisted of two groups: a Steering Committee, and a Working Group. The NRC audit team concluded that most members had suitable qualifications. Some team members attended a formal human factors engineering course at the Maine Yankee Plant conducted by a

senior Human Factors Specialist, Professor John Senders of the University of Maine. It is evident that Maine Yankee is attempting to instigate a long-term commitment to the integration of human factors to the plant operations by establishing an in-house awareness of human factors principles. The DCRDR team was organized with representatives from several levels of management.

The Steering Committee of the DCRDR team included representatives from operator training, control room simulation, and engineering. Human factors and operations management expertise were also included. The Steering Committee was responsible for providing guidance to the Working Group, reviewing and analyzing data outputs, and developing the assessment criteria for HEDs.

The Working Group consisted of a core of two engineers, the human factors consultant, a human factors engineer, and various engineering assistants. Other support staff were available on an as-needed basis.

Other than the information above, the Summary Report provides little new information about the DCRDR team or qualifications of team members. It was pointed out in the review of the Program Plan and at the in-progress audit that Maine Yankee should increase the level of participation by a human factors specialist in conduct of the DCRDR. Nuclear systems engineering and training expertise should also be increased. Based on information provided in the Summary Report, the degree to which the licensee adopted these recommendations is not clear.

In summary, it appears that Maine Yankee has organized a DCRDR team composed of qualified personnel. However, the adequacy of the team and DCRDR task accomplishment cannot be fully evaluated until Maine Yankee provides information relevant to the level of effort expended by specific team members. At a minimum, the licensee should provide information to show team members, their relevant areas of expertise, and degree of participation in the accomplishment of each of the DCRDR tasks.

REVIEW PHASE

Maine Yankee's review phase activities included:

1. Review of operating experience,
2. Control room operator task analysis,
3. Control room inventory,
4. Control room survey, and
5. Validation of control room functions.

For the most part, the above activities are those recommended by NUREG-0700 guidelines as contributing to the review phase objectives. Activities 2, 3, and 4 contribute to the accomplishment of specific DCRDR requirements contained in Supplement 1 to NUREG-0737. Activities 1 and 5 are discussed in this evaluation only to the extent that they impact or augment those tasks required by NUREG-0737, Supplement 1.

1. Review of Operating Experience

A review of operating experience is not explicitly required by NUREG-0737, Supplement 1. However, it is an activity recommended by NUREG-0700 guidelines as contributing to the accomplishment of review phase activities.

As described by the licensee, its review of operating experience included: (1) a review of Maine Yankee License Event Reports and Plant Information Reports; (2) review of the operating history of other power plants; and (3) conduct of interviews with control room operators to identify specific aspects of the control room which have reduced or could reduce operator effectiveness.

It was difficult to assess the adequacy of Maine Yankee's operating experience review due to lack of detail concerning procedures employed. Twelve operators were interviewed on an individual basis to gather information on specific aspects of the control room which have reduced or could

reduce operator effectiveness. To facilitate communication, interviews were conducted by an independent consultant who was familiarized with plant design and terminology although he had little expertise in the area of human factors. The actual survey questionnaire used has not been provided for review. No information has been provided on analyses performed on data collected or on how information acquired was actually utilized by the licensee in its assessment. The degree to which industry-wide reports were reviewed and documented is not clear. Furthermore, it is unclear whether plant documents for the last five years were reviewed to determine how an operator may have erred because the procedures, instruments, and controls did not comply with accepted human factors engineering principles. Such information and examples of checklists or questionnaires employed for data collection would provide greater confidence in the review of operating experience performed by the licensee.

2. System Function Review and Task Analysis

Supplement 1 to NUREG-0737 states that the licensee is required to perform a "function and task analysis (that had been used as the basis for developing emergency operating procedures) to identify control room operator tasks and information and control requirements during emergency operations." In other words, the objective of the task analysis is to establish the input and output requirements of control room operator tasks. These information requirements are then to serve as benchmarks for examination of the adequacy of control room instrumentation, controls, and other equipment.

Maine Yankee conducted its system function and task analysis by: (1) defining the intent or functional objective of existing emergency procedures, generating task objectives, and defining physical tasks needed to be accomplished; and (2) conducting walk-through/talk-throughs to determine whether the control room operator could implement the procedures with the existing instrumentation, controls, and control room design.

At the in-progress audit, Maine Yankee described its task analysis activity which was based on symptomatic emergency operating procedures (EOPs) that had been developed in response to the requirements of Supplement 1 to NUREG-0737. A subset of these EOPs were walked through in order to observe operators' performance of tasks, to generate comments regarding

behavioral elements, and to provide an opportunity to question operators on information and control requirements beyond those implied or prescribed in the EOPs. The procedures which were walked through did not include all the operator-panel interfaces involved in emergency operations.

Because the "task analysis" was based on existing EOPs, the NRC audit team concluded that a system function analysis was not adequately conducted. The EOPs, as written, did not provide a basis for the function analysis necessary to define the associated operator tasks. The audit team further concluded that an a priori, independent analysis of operator tasks was not thoroughly conducted and that Maine Yankee had performed a verification of task performance capabilities and validation of control room functions rather than a task analysis which should be completed, independent of the control room, prior to validation.

In the Summary Report, the licensee provided a written description of its walk-through activity used to "validate control room functions." The validation effort was conducted to analyze selected operating scenarios (procedures). This provided a method to determine whether the control room operator could implement the procedures with the existing instrumentation, controls, and control room design. Eleven EOPs were said to be used in the validation effort (page 16 of the Summary Report), but it is not clear how many procedures were analyzed. This uncertainty is due to the fact that at the time of the in-progress audit Maine Yankee indicated only seven procedures were analyzed. On page 27 of the Summary Report it is indicated that nine procedures were used by the Maine Yankee Review Team and on page 28 of the Summary Report it is indicated that 15 procedures were analyzed. In any case, the full spectrum of operator tasks required for emergency operation was not analyzed. Consistent with audit team findings, this activity, as described, appears to have provided a means to validate a subset of emergency operating procedures and to verify that controls and displays in the control room will allow operators to execute selected EOP tasks. The walkthroughs did not establish, a priori, the information and control requirements against which the existing control room instrumentation should be compared.

The licensee also briefly described an activity entitled, "Control Room Operator Task Analysis" (p. 20), which was conducted to identify operator

tasks required for emergency operations to list information and controls required to perform these tasks, and to identify the characteristics of the needed instruments and controls.

As described in the Summary Report, the analysis was accomplished by table top discussions between multidisciplinary team members to identify the intent or functional objectives of the existing emergency procedures (p. 20). The functional objectives were used to verify the adequacy of the individual steps of the procedures. Functional objectives were then used to generate task objectives, task descriptions, and finally the physical tasks needed to be accomplished. The physical task list was sufficiently detailed so that a list of required information and controls and applicable characteristics could be generated (p. 21). The result of the task was a list of information and control characteristics which should exist in the control room.

No additional information is provided in the Summary Report as to how function and task analyses actually were conducted. No data analysis or collection forms were provided for review. The licensee has described a procedure for verification of Emergency Operating Procedures (EOPs) steps but has not indicated how analyses were conducted to establish these steps. There is no evidence of a procedure for the identification of systems/ subsystems and their associated functions. Furthermore, there is no evidence of an analytical process being implemented to determine operator tasks or information and controls and their required characteristics necessary for the operator to fulfill successfully his assigned tasks. The requirement of Supplement 1 to NUREG-0737 dictates that these classes of information must be established independent of the control room, prior to the development of EOPs. The methodological approach and the depth of the analyses are difficult to assess with the limited information provided.

It appears that the basis of the analyses conducted was the set of symptomatic emergency operating procedures developed by Maine Yankee in response to the requirement of Supplement 1 to NUREG-0737. The licensee has failed, however, to discuss the basis for and development of its EOPs. Based on a memo (Reference 10) from the NRC to CEEOG, the licensee's owners group, the CE EPGs do identify basic parameters and control functions needed to satisfy safety functions. The EPGs did not explicitly identify the

information and control needs beyond the safety function level necessary for preparing EOPs and determining the adequacy of existing instruments and controls. Therefore, further documentation and analysis are required by licensees belonging to the CEOG.

More specifically, a licensee must describe the process used to identify parameters and other information and control needs that are not provided in, or are different from, those specified in the EPGs. They must also describe how the characteristics of needed information and controls are determined. The task analysis should go to the level of actual operator actions that are required to perform the EOP steps such that the information and control needs for each operator action or subtask are identified. This is important in that the EOPs may not encompass all tasks that come into play during emergency operation. However, for each instrument and control used to perform the EOPs, there should be an auditable record that defines the necessary characteristics of the instrument or control and the bases for that determination.

In summary, the information regarding the licensee's System Function Review and Task Analysis is still not sufficient to evaluate whether it satisfied the intent of the requirement of NUREG-0737, Supplement 1. Consistent with audit team recommendations, the licensee needs to: (1) provide assurance that all display and control interfaces involved in the execution of the upgraded, symptom-based procedures were analyzed; and (2) provide assurance that the depth of the analysis is adequate to define sequentially necessary functions, tasks/subtasks, information and control capabilities, and, finally, necessary control and display characteristics. The licensee should provide assurance that all analyses conducted were systematic, unbiased, and independent of the constraints of the existing control room.

3. Control Room Inventory

The licensee has prepared a full-scale mock-up from control room photographs which contains all instruments and controls. In addition, a list of all instruments and controls has been prepared. Information such as instrument ranges, scaling, manufacturer, etc., were obtained, when required, from applicable plant documents.

Supplement 1 to NUREG-0737 requires the comparison of control room control and display requirements and characteristics with those derived from a prescriptive task analysis. Because of potential inadequacies in the performance of the system function and task analysis (mentioned above), it is not clear whether Maine Yankee performed a comparison of information and control requirements based on an in-depth, prescriptive, and systematic task analysis with its control room inventory. Thus, it is impossible to evaluate whether the licensee has satisfied the intent of the inventory requirement of Supplement 1 to NUREG-0737 until further description of its task analysis procedure and results are provided. The inventory by itself, as represented by a full-scale mock-up and equipment list, is complete and satisfactory.

4. Control Room Survey

Maine Yankee conducted a control room survey based on the guidance and checklist format in Chapter 6 of NUREG-0700. Each item in Chapter 6 was addressed to determine conformance by either measurement or observation. Items which were not relevant to the Maine Yankee plant were documented. To the extent possible, the mock-up was used for the review. However, those criteria that could not be evaluated on the mock-up were evaluated in the control room.

It appears from both a review of documentation and discussions with Maine Yankee staff that the control room survey was conducted in accordance with the requirements of Supplement 1 to NUREG-0737 and the guidance of NUREG-0700. The scope of the control room survey was comprehensive and included consideration of all primary control panels. Whether the Remote Shutdown Panel was reviewed is unclear. Although not explicitly identified as a requirement in Supplement 1 to NUREG-0737, the NRC staff has recommended that a human engineering evaluation of the Remote Shutdown Capability be included in the scope of the DCRDR.

ASSESSMENT AND IMPLEMENTATION PHASE

Maine Yankee's assessment and implementation phase is addressed in Sections 5 through 8 of the Summary Report. Sections 5 through 7 relate to

HED assessment and resolution while Section 8 provides schedules for implementing HED resolutions.

1. Assessment of HEDs

In describing the guidelines the NRC will use to evaluate a plant's assessment of HEDs, NUREG-0800 indicates that the ultimate criterion will be whether the plant assessed the HEDs in terms of their effects on the operator's ability to perform the necessary tasks and resulting consequences of an error on plant safety. These criteria are embodied in NUREG-0800's paragraph 2.5 which states: "To evaluate the significance of design discrepancies, the DCRDR team must determine the effect of each HED on operator performance, both alone and in combination with other HEDs;" and "Corrective action of each HED should be based on its significance as it affects the safety of the plant."

NUREG-0800 specifies the criteria NRC will use to evaluate the plant's assessment of HEDs. The guidelines indicate that the following should be considered:

1. The relative degree of degradation of operator performance;
2. The effect on plant safety;
3. The possible interactions of HEDs; and
4. Whether HEDs have resulted in previous crew errors.

The fourth guideline is amplified in a later sentence of the same paragraph. It states that all HEDs that have caused crew error should be considered significant.

As described in the Summary Report, Maine Yankee's HED assessment methodology relied primarily on plant safety as the criterion for determining the need for corrective action of those HEDs identified during the review. Consistent with NUREG-0800, HEDs that were deemed to jeopardize plant safety were scheduled for corrective action. However, the specific means used by Maine Yankee to determine if an HED jeopardized plant safety

were described only briefly in the Summary Report. The methodology relied on questionnaires, interviews, and observational data obtained from operators during previous DCRDR activities. Data from these sources were used to compute a safety and a frequency factor for each HED. A probability of error estimate was also determined for each HED by the human factors engineering consultant and Steering Committee members. Values for these three factors were normalized and combined to produce a single assessment score which was to indicate the HED's relative need for corrective action.

The "nature" of the HED was said to have been the basis for determining a cutoff score. All HEDs with assessment scores above the cutoff were scheduled for corrective action as were all HEDs "which were viewed to have a high consequence." Presumably a high consequence means a high value of the safety factor of an HED's assessment score, regardless of the values for the other factors.

There are a number of problems associated with the HED assessment methodology as described in the Summary Report. There is no discussion of how or by whom the cutoff score was determined. It is not clear how the "nature" of the HEDs was used to determine a cutoff score. Furthermore, how is "nature" of the HEDs defined? There is no indication that those HEDs which previously contributed to crew error were given a high priority.

Some of the data used to compute the frequency factor of the assessment scores were obtained from operator interviews. There is no indication, however, from which interviews these data were obtained. Still other data were gathered during the walk-throughs of an incomplete set of emergency operating procedures. This raises the question of the completeness of the data available for these computations. Finally, the use of some data in computing factors for the assessment scores is based on assumptions that may or may not be correct (e.g., frequency of use of instruments with a given HED is highly correlated with the operator's awareness of the HED).

In summary, of the 856 HEDs which were identified at Maine Yankee, 221 were deemed in need of corrective action. None of the HEDs and their priorities were listed or described in the Summary Report. Without this information and further description of the HED assessment methodology, it is

not possible to make an informed evaluation of Maine Yankee's assessment methodology.

2. Selection of Design Improvements

As described in the Summary Report, each identified HED was placed into one of 17 categories (e.g., labels, procedural, enhancements, scaling, etc.). Each category was analyzed by the Steering Committee and, if necessary, subgroupings in categories were generated. An initial review was performed to determine if similar problems (subgroups) were assessed to the same criterion value. Those groupings or subgroupings for which the majority of HED criterion values exceeded the assessment threshold were recommended for corrections; the others were not.

An additional screening of HEDs not recommended for resolution was conducted by the Steering Committee to ensure that those HEDs with safety significance were correctly taken into account. This is a commendable procedure.

Recommendations for design improvements (HED corrections) were treated in one of two ways. Those requiring design changes, in accordance with the Maine Yankee Operational Quality Assurance Manual, were submitted to Maine Yankee management via the licensee's standard design change procedure (CPA) for approval. Changes (paint, tape, label) which did not require a plant design change were submitted to management in memoranda for approval. All changes were sent to the Emergency Response Capabilities Integration Program (ECRIP) steering committee for integration with remaining NUREG-0737, Supplement 1 programs.

Although it appears that the selection of design improvements was an integral part of the DCRDR performed at Maine Yankee, the licensee's submittal provides limited information describing the actual processes that were used to select improvements for identified HEDs. Although those groups for which the majority of HEDs exceeded the criterion value were recommended for correction, there is no identification of criterion value and no identification of HEDs that are above or below this value.

There is no information provided on the processes that were used to examine various alternative solutions, their integrated effects on operator performance, and the arrival at a final solution. Therefore, it is difficult to determine whether the process to select design improvements was conducted with full consideration of alternative solutions that would provide the optimum human factors design. Furthermore, it is unclear which members of the DCRDR team were involved in this activity and whether both CPA & PTL improvement recommendations were sent to Maine Yankee for final technical review or as a matter of company policy.

The lack of information regarding how design improvements were selected and which HEDs have been designated for improvement renders this section of the Summary Report impossible to evaluate.

3. Proposed Schedules for Implementing HED Corrections

Sections B and C of the main control board (MCB) are scheduled to be upgraded during Maine Yankee's 1985 refueling outage. These sections are the primary operating sections of the control boards and, as such, contain most of the safety-related displays and controls. Upgrading these sections will alleviate the highest priority HEDs.

Section A of the MCB and the Electric Board will be upgraded and their associated HEDs resolved during the 1987 refueling outage.

Any remaining HEDs and the annunciator panels will be addressed during the 1988 refueling outage.

Due to the fact that the Summary Report does not identify or prioritize HEDs, this schedule cannot be evaluated.

4. Verification That Improvements Will Provide the Necessary Corrections Without Introducing New HEDs

This requirement was not discussed in either the licensee's Program Plan or Summary Report per se. However, at the audit, the licensee indicated that verification of correction effectiveness was to be conducted for hardware changes in a three-step fashion including:

- (1) Testing the proposed change on the Control Room mockup using a "cut and paste" technique;
- (2) Testing the proposed change on the Maine Yankee simulator; and
- (3) Installing the final change on the Control Room control board.

During each of the steps a human factors evaluation would occur prior to proceeding. Those items of a nonhardware nature (e.g., procedures, training) would be implemented and then apparently would not be reviewed further.

This process appeared adequate to the audit team. However, it was recommended that those HEDs corrected by nonhardware improvements be subject to periodic verification to ensure the adequacy of the improvement.

As there is no description in the Summary Report, it is unclear whether recommendations of the audit team were heeded. The licensee should provide documentation to show how Maine Yankee implemented these human factor evaluations. Until further information is provided, this task cannot be fully evaluated.

5. Coordination of the DCRDR with Other Programs

Although coordination activities were not addressed in detail in either of the licensee's submittals, Maine Yankee provided the audit team with information relating to the current status of the SPDS, Reg. Guide 1.97 instrumentation, and other improvement programs. The Summary Report does indicate that all changes resulting from DCRDR activities are sent to the steering committee of the Emergency Response Capabilities Integration Program, a larger program which coordinates NUREG-0737, Supplement 1 initiatives. This arrangement may be entirely satisfactory, but greater confidence in its efficacy would have been fostered if details regarding the mechanics and scheduling of the coordination activities had been provided.

CONCLUSIONS AND RECOMMENDATIONS

Maine Yankee's Summary Report for the DCRDR demonstrates an attempt to meet many of the requirements of Supplement 1 to NUREG-0737. However,

limited discussion of most activities has prevented a complete assessment of the licensee's efforts or its understanding of the requirements. Areas which should be expanded include the following: (1) qualifications of the team; (2) conduct of a function and task analysis; (3) assessment of HEDs; (4) selection of design improvements; (5) verification that improvements will correct HEDs without introducing new HEDs; and (7) coordination of HED resolution implementation.

Due to the brevity of discussion in the Summary Report and the lack of information regarding identified HEDs, proposed corrective actions, and justifications for HEDs left uncorrected, we conclude that a more definitive presentation is necessary to establish the degree to which the requirements of Supplement 1 to NUREG-0737 have been met. Therefore, we recommend that a pre-implementation audit be conducted to clarify the points raised in this evaluation report and to provide Maine Yankee with additional feedback. The concerns raised as a result of this evaluation are summarized below and should be addressed by the licensee during the audit and discussed in detail in a supplementary Summary Report.

- Identification of task assignments and levels of effort for DCRDR team members.
- Identification of the scope and depth of the System Function Review and Task Analysis including discussion of the bases of EOPs and assurance that all tasks involved in emergency operations were analyzed. A description of the process used to identify plant-specific information and control needs and to establish the characteristics required of needed instruments and controls. A description of the auditable record that contains the data generated from the function and task analysis.
- A more detailed description of the HED assessment process.
- A more detailed description of the process used to select design improvements and to ensure the integration of design modifications/changes.

- A description of the human factors evaluations which will be an integral part of the verification that improvements will provide the necessary corrections without introducing new HEDs.
- Coordination with other improvement programs.
- A prioritized list of HEDs identified during the review.
- The proposed design changes to evaluate against provided schedules.
- Summary justifications for HEDs with safety significance to be left uncorrected or partially uncorrected.

REFERENCES

1. "Program Plan Report for the Detailed Control Design Review," Maine Yankee Atomic Power Company, April 12, 1982.
2. Memo from William Russell (NRC) to Gus Lainas (NRC), NRC Comments on the Maine Yankee Power Company Detailed Control Room Design Review Program Plan Submittal, September 26, 1983.
3. Memo from Voss Moore (NRC) to James Miller, NRC, Results of In-progress audit of Maine Yankee Detailed Control Room Design Review, May 17, 1984.
4. "A Human Factors Engineering Critical Assessment of the Design of the Control Room at Maine Yankee Atomic Power Company," Maine Yankee Atomic Power Company, February 28, 1985.
5. NUREG-0660, Vol. 1, "NRC Action Plan Developed as a Result of the TMI-2 Accident," U.S. Nuclear Regulatory Commission, May 1980; Revision 1, August 1980.
6. NUREG-0737, "Clarification of TMI Action Plan Requirements," U.S. Nuclear Regulatory Commission, November 1980.
7. NUREG-0737, Supplement 1, "Clarification of TMI Action Plan Requirements," U.S. Nuclear Regulatory Commission, December 1982.
8. NUREG-0700, "Guidelines for Control Room Design Review," U.S. Nuclear Regulatory Commission, September 1981.
9. NUREG-0800, "Evaluation Criteria for Detailed Control Room Design Review," U.S. Nuclear Regulatory Commission, October 1981.
10. Memo from H. Clayton (NRC) to Dennis Ziemann (NRC), Meeting summary - task analysis requirements of Supplement 1 to NUREG-0737, August 29, 1984 meeting with Combustion Engineering Group (CEOG) Operations Subcommittee, September 7, 1984.

TASK ANALYSIS WORKSHEET

SCENARIO: LOSS OF COOLING ACCIDENT

ENTRY CONDITIONS: RCS Leak Rate Exceeds Charging Capability LCOA Identified Through Actions of 2-70-1
Safety Injection

6-2107 2-2-4

A Break in the pressurizer
steam space needs to be
addressed.

Scenario		TASK			DISPLAYS AND CONTROLS			
I.D.								
EDP 2-70-2		Task	Task	Physical	Required			
		Objective	Description	Task	Characteristics of I&Cs			
Step	Task	Goal	Operator Action Per Procedure	What Operator Does	Information Transfer Requirements	Display Requirements	Control Requirements	Comments
	I.D.							
				WPSI Flow Indication	Same as above	Same as above		
				Pressurizer Level Indication	Same as above	Same as above		
				Look/Find:				
17	To prevent voiding in the upper head; and minimize pressurized thermal shock	Maintain RCS subcooling between 50 and 150 degrees Fahrenheit	Margin to Saturation Indication	Quantitative Indication of degrees F. Margin to Saturation	Range 0-200 with 100 marks and an operational zone between 50 and 150			Need control of the WPSI System and the Steam Dump System and for decay heat release valve can be used. CIS/SIAS is reset. Procedure Related -
				Main Steam Valve Position Indication	Qualitative Indication of Main Steam Valve Position	Range 0-100% CLOSED to OPEN		
				Manipulation:				
				Place Main Steam Valve in the OPEN Position			Discrete Function Valve Switch: OPEN/CLOSE	
				Place the Main Steam Valve Switch in the Reset Position			Mode Select Valve Switch for reset switch. This valve must be placed	

TASK ANALYSIS WORKSHEET

SCENARIO: LOSS OF COOLING ACCIDENT

ENTRY CONDITIONS: RCS Leak Rate Exceeds Charging Capability LDCR Identified Through Actions of E-70-1
Safety Injection


A Break in the pressurizer
steam space needs to be
addressed.

Scenario		TASK			DISPLAYS AND CONTROLS		
I.D.		Task	Task	Physical	Required		
EDP E-70-2	Objective	Description	Task	Task	Characteristics of I&Cs		
Step	Task	Goal	Operator	What	Information	Display	Control
I.D.			Action Per	Operator	Transfer	Requirements	Requirements
			Procedure	Does	Requirements		Comments
2.4	8		Control HPSI to:	Look/Find:			
			- restore pres-	Pressurizer Level	Quantitative	Range 0-100%	
			surizer level	Indication	Indication of:	with 20 marks	
					Pressurizer		
					Level		
			HPSI Pump Breaker	Status of the:	Status Indication		
			Position Indication	HPSI Pump	Indication		
				Breaker	OPEN/CLOSED		
			HPSI Flow Indication	Quantitative	Range 0-400		
				Indication of:	gpm with 10		
				HPSI Flow	marks		
			Manipulation:				
			Place HPSI Pump				
			Breaker in the				
			CLOSED Position				
			Throttle the HPSI				
			Valve until the				
			level in the pres-				
			surizer is restored				
			Feedback:				
			HPSI Pump Breaker	Same as above	Same as above		
			Position Indication				

With a small break
pressurizer level can
be restored.
- Procedure Related -

Discrete
Function
Breaker
Switch
OPEN/CLOSE

Continuous
Control
Valve Switch
CLOSE to
OPEN



SUMMARY 1

For the EDP work and the requirement for certain items or instruments and controls to be present on the Main Control Board at Maine Yankee, Westinghouse's SRTA will take precedent. If the comparison of extra Westinghouse required equipment with the actual M.Y. plant inventory finds the instrument missing, then Maine Yankee will evaluate or perform a task analysis on those areas in the Westinghouse EDP's where the instrument is required. This task analysis will result in determining the characteristics required for the instrument in order that the instrument may be purchased.

SUMMARY 2

For the instruments and controls required by the Westinghouse SRTA and compared against M.Y. actual plant inventory and found to be included in the plant, then a task analysis will be performed to enable a comparison of the required I&C characteristics with those present on the actual I&C. Any deficiencies will then be assessed for importance to safety and resolved as necessary.

SUMMARY 3

If Maine Yankee's DCRDR requires more Instruments and Controls than Westinghouse's SRTA, then the extra equipment will still follow the DCRDR program for improvement.

FORM 7
RECOMMENDATION WORKSHEET

H.E.D. _____

Recommendation _____

Equipment Change Attached

C.P.A. No. _____

Procedural Change Attached

P.C.R. No. _____

Paint, Tape and Label (PTL) Change

PTL Description No. _____

Management Recommendation

I.T.N. No. _____

Training Required

I.T.N. No. _____

Estimate Date of Completion _____

Human Factor Program Recommendation Approval

Chairman

Return to Human Factors Committee when Completed.

Completed _____
Responsible Person

Verification
Resolution Worksheet

HED# 1

Cutoff Status based on Assessment Criteria: ABOVE
(Above/Below)

Will the HED be resolved: YES
(Yes/No)

Main Control Room Location Code: -

MEMO Identification Numbers: -

CPA Identification Numbers: -

EDCR Identification Numbers: -

Verification and Validation of HED Resolution

Pre-implementation Verification Complete: -

Post-implementation Verification Complete: -

Other Comments: