

(7-77)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	9		C	F	11	X	12	Z	13	C	K	T	B	R	K	14	A	15	Z	16						
7	8		9	10		11		12		13					18		19		20							
17	LER/RO REPORT NUMBER		EVENT YEAR					SEQUENTIAL REPORT NO.						OCCURRENCE CODE			REPORT TYPE				REVISION NO.					
			8	3		—		0	4	5		/		0	3		L		—		0					
			21	22		23		24		26		27		28	29		30		31		32					
	ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT			SHUTDOWN METHOD			HOURS			22	ATTACHMENT SUBMITTED			NPRO-4 FORM SUB.		PRIME COMP. SUPPLIER			COMPONENT MANUFACTURER					
	X	18	X	19		Z	20	Z	21		0	0	0	0	22	Y	23	N	24	A	25	C	7	7	0	26
	33	34				35		36			37			40		41		42		43		44			47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

BUFILE (804) 357-3184

ATTACHMENT 1
SURRY POWER STATION, UNIT NO. 2
DOCKET NO: 50-281
REPORT NO: 83-045/03L-0
EVENT DATE: 10-08-83

TITLE OF THE EVENT: MOV-2876D FOUND DE-ENERGIZED

1. Description of the Event

With the unit at 100% power, a routine walkdown of the control board revealed the circuit breaker for MOV-2876D (Boron Injection Tank Outlet) to be open. This breaker had been verified closed 8 hours earlier while performing the control board indicating light walk-down. The redundant flow path was checked to ensure it was energized. This event is contrary to T.S. 3.3.A.7 and reportable in accordance with T.S.6.6.2.b.(2).

2. Probable Consequences and Status of Redundant Equipment

Upon receipt of a safety injection signal, the BIT valves are automatically opened and the BIT contents are pumped into the RCS by the High Head Safety Injection Pumps. The redundant BIT flow path, MOV-2867C, was operable throughout this event; therefore, the health and safety of the public were not affected.

3. Cause

The breaker is located near sliding fire door #18. While attempting to open and transit through the fire door, it is likely that the breaker was accidentally bumped, causing it to open.

4. Immediate Corrective Action

The breaker was closed and the valve responded properly.

5. Subsequent Corrective Action

None required.

6. Action Taken to Prevent Recurrence

The feasibility of providing some form of a barrier to prevent recurrence is being evaluated.

7. Generic Implications

Other similar events have occurred during periods of extensive design change activity.