



CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT

RR#1 • BOX 127E • EAST HAMPTON, CONN. 06424

September 16, 1985

Mr. Jaques P. Durr  
Chief, Engineering Branch  
USNRC, Region One  
631 Park Avenue  
King of Prussia, PA 19406

RE: NRC Open Item #50-213/80-14-03

Dear Sir:

During a telephone conversation on April 10, 1985, between Mr. H. Kerch of the NRC and Mr. J. Stankoski of Northeast Utilities, Open Item 50-213/80-14-03 from NRC Inspection 50-213/84-21 was discussed. This item concerns two U.T. calibration blocks used during the 1980 refueling outage.

In their discussion regarding the austenitic calibration blocks, No. 31 and 32 which are referenced in the unresolved item, the following was determined:

- The piping inspected is under  $\frac{1}{2}$ " thick.
- Ultrasonic inspection of pipe under  $\frac{1}{2}$ " thick is not required by the 1980 edition of the ASME B&PV Code.
- Calibration blocks, numbers 31 and 32 will not be used again since Connecticut Yankee has revised its ISI program to comply with the 1980 edition, including the winter 1980 addenda of the ASME B&PV Code.

Please contact us if you need further information to support the closing of this item.

Sincerely,

Richard H. Graves  
Station Superintendent

lac

cc: P. Swetland

8509300280 850916  
PDR ADOCK 05000213  
Q PDR

1E 01  
10