

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Dresden Nuclear Power Station, Unit 3										DOCKET NUMBER (2) 0 5 0 0 0 2 4 9 1					PAGE (3) OF 0 2			
TITLE (4) High Pressure Coolant Injection (HPCI) Room Cooler Inoperative																		
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)								
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)					
									N/A				0 5 0 0 0					
0 8	2	6	8	5	8 5	0 1	6	0 0	0 9	2	3	8	5	N/A				0 5 0 0 0
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																
N		20.402(b)				20.406(e)				50.73(a)(2)(iv)				73.71(b)				
POWER LEVEL (10)		20.406(a)(1)(i)				50.38(c)(1)				50.73(a)(2)(v)				73.71(c)				
0 9		20.406(a)(1)(ii)				50.38(c)(2)				50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)				
5		20.406(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(viii)(A)								
		20.406(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)								
		20.406(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(ix)								
LICENSEE CONTACT FOR THIS LER (12)																		
NAME Tim Wojtulewicz										TELEPHONE NUMBER AREA CODE 8 1 5 9 4 2 - 2 9 2 0								
(X-529)																		
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																		
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPD		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPD								
X	B J	C L	G 0 8 0	Y														
SUPPLEMENTAL REPORT EXPECTED (14)											EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR			
YES (If yes, complete EXPECTED SUBMISSION DATE):											X NO							
ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)																		
<p>During normal unit operation, while conducting routine rounds, the Unit 3 Equipment Attendant (EA) observed the high pressure coolant injection (HPCI) room cooler fan breaker smoking. The EA immediately racked the breaker out and informed the Shift Foreman of this event. Per Technical Specification 3.5.C, HPCI was declared inoperable and a work request initiated. Upon investigation into this event, Electrical Maintenance found a shorted motor contactor coil. The contactor coil and auxiliary contacts were replaced. Dresden Maintenance Procedure (DMP 7300-5), Inspection and Maintenance of 480 Volt MCC Breakers and Contactors, was performed. The room cooler was successfully operated and HPCI declared operable on 8/26/85 at 1440.</p> <p>The safety significance of this event was minimal since the isolation condenser and automatic depressurization system were operable and capable of relieving high reactor pressure.</p> <p>This is the first failure of the HPCI room cooler motor contactor coil at Dresden.</p>																		
8510010208 850923 PDR ADOCK 05000249 S PDR																		
IE 22 11																		

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)  Dresden Nuclear Power Station, Unit 3	DOCKET NUMBER (2)  0 5 0 0 0 2 4 9	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 5	— 0 1 6	— 0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

During normal unit operation, while conducting routine rounds, the Unit 3 Equipment Attendent (EA) observed the high pressure coolant injection (HPCI) room cooler fan breaker (motor control center MCC 39-1, cubical B-1) smoking. The EA immediately racked the breaker out and informed the Shift Foreman of this event. Per Technical Specification 3.5.C, HPCI was declared inoperable. The limiting condition for operation with HPCI inoperable (Technical Specification 4.5.c) requires performing operability tests for the low pressure coolant injection (LPCI), core spray, automatic depressurization system (ADS) and the isolation condenser valves. The monthly operability test for LPCI and core spray had just been completed on 8/26/85 at 0240 and 0250 respectively. The isolation condenser valve operability test was completed at 0530 on 7/26/85. Containment cooling service water (CCSW) samples were requested prior to operating LPCI in the torus cooling mode for ADS system testing. Upon investigation into this event, Electrical Maintenance found a shorted motor contactor coil. The exact cause of the short could not be determined due to the burnt condition of the coil, however, insulation degradation is the suspected cause. The motor contactor coil and breaker auxiliary contacts were replaced. Dresden Maintenance Procedure (DMP 7300-5), Inspection and Maintenance of 480 Volt Motor Control Center Breakers and Contactors was performed. The room cooler was successfully operated and HPCI was declared operable at 1440 on 8/26/85, before the ADS system testing had begun.

The safety significance of this event was minimal since the isolation condenser and automatic depressurization system were operable and capable of relieving high reactor pressure if such a condition occurred.

This is the first failure of the HPCI room cooler motor contactor coil at Dresden.



**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

September 23, 1985

DJS Ltr #85-917

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Licensee Event Report #85-016-0, Docket #050249 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(v).

D.J. Scott  
Station Manager  
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III  
File/NRC  
File/Numerical

IE22  
1/1