

NRC Form 386  
(9-83)

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Grand Gulf Nuclear Station - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 1 6 1	PAGE (3) 1 OF 3
----------------------------------------------------------	----------------------------------------	--------------------

TITLE (4) Liquid Effluent Flow Rate Estimate Exceeded LCO Time Limit									
-------------------------------------------------------------------------	--	--	--	--	--	--	--	--	--

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)									
1	2	1	8	8	4	8	5	0	3	2	0	0	0	9	2	6	8	5	N/A	0 5 0 0 0

OPERATING MODE (9) 4		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) 0 1 0 0		20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)			
		20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)			
		20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)			
		20.405(a)(1)(iii)	X	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)					
		20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)					
		20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(ix)					

LICENSEE CONTACT FOR THIS LER (12)									
NAME Ronald Byrd/Licensing Engineer								TELEPHONE NUMBER	
								AREA CODE 6 1 0 1 4 3 7 - 2 1 4 9	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS

SUPPLEMENTAL REPORT EXPECTED (14)					EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO								

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On August 29, 1985, following a Quality Assurance audit, Plant Staff determined that a reportable condition had occurred on December 1, 1984, and on December 4, 1984, when liquid effluent release flow rate estimates exceeded the 4 hour frequency of Technical Specification 3.3.7.11 Action 111 requirements.

From November 30, 1984 to December 6, 1984, the circulating water system, the normal dilution source for radwaste liquid effluent, was out of service. Whenever the circulating water blowdown or discharge canal monitors are out of service, dilution flow is obtained from sources without flow rate measuring devices. Technical Specification 3.3.7.11 requires the flow rate to be estimated at least once per 4 hours during actual release when the required flow rate monitors are not operable. During the releases on December 1 and December 4, 1984, flow rates were estimated approximately 30 minutes later than allowed.

Procedural controls at the time were inadequate to ensure compliance with the action statement. The Radioactive Discharge Controls procedure was revised to require that compliance with this action be documented on the Discharge Permit Form.

8510020018 850926  
PDR ADOCK 05000416  
S PDR

IE22 y

NRC Form 368A  
(9-83)

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Grand Gulf Nuclear Station - Unit 1	0 5 0 0 0 4 1 6	8 5	- 0 3 2	- 0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 368A's) (17)

Description of Reportable Occurrence

Action 111 of Technical Specification 3.3.7.11 allows radioactive effluent releases to continue for up to 30 days with flow rate measurement devices inoperable, provided the flow rate is estimated at least once per 4 hours during actual releases. On December 1, 1984 and December 4, 1984, the flow rate estimates exceeded the 4 hour time limit by approximately 30 minutes.

Initial Conditions

On December 1 and December 4, 1984, the plant was in Cold Shutdown.

Status of Redundant or Backup Systems

Not Applicable

Nature of Occurrence

A Quality Assurance audit performed in April, 1985, revealed a potential problem in the documentation of the estimated flow rates for a Limiting Condition for Operation (LCO) which was in effect from November 30, 1984 to December 6, 1984. An LCO was entered under Technical Specification 3.3.7.11 when the circulating water system was shutdown, requiring dilution flow for effluent releases to be obtained from sources that have no flow rate measuring devices. Action 111 of Technical Specification 3.3.7.11 requires the flow rate to be estimated at least once per 4 hours during actual releases if flow rate measurement devices are inoperable.

This condition was a result of inadequate controls for documenting the required estimates. This deficiency was identified by a Quality Assurance audit which resulted in extensive revisions to the Daily Operating Log. Resolution of this concern was completed in July, 1985. It was believed, at that time, that no Technical Specification actions had been violated. After further evaluation of the reportability of the findings, it was determined on August 29, 1985 that a reportable condition had existed. Estimates of dilution flow were made approximately 30 minutes later than the required 4 hour interval during releases on December 1 and December 4, 1984.

Immediate Corrective Actions Taken

Not Applicable

Apparent Cause

On both occasions, operators failed to estimate the flow rate within the 4 hour time limit. Procedural controls were inadequate to ensure compliance with the action statement.

NRC Form 366A  
(9-83)

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		OF	
Grand Gulf Nuclear Station - Unit 1	0 5 0 0 0 4 1 6	8 5	- 0 3 2	- 0 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Supplemental Corrective Actions

On June 13, 1985, the Radioactive Discharge Controls procedure, 01-S-08-11, was revised to require the estimated flow rates to be documented on the Liquid Radwaste Discharge Permit Form whenever the required flow rate monitors are inoperable. This also transferred the responsibility for making the estimates from Control Room operators to the Radwaste operators who are more directly involved with the discharge evolution.

Safety Assessment

There was no threat to plant or public safety during the releases. Dilution flow was adequate during each discharge and no environmental release limits were exceeded.



# MISSISSIPPI POWER & LIGHT COMPANY

*Helping Build Mississippi*

P. O. BOX 1640, JACKSON, MISSISSIPPI 39215-1640

September 26, 1985

NUCLEAR LICENSING & SAFETY DEPARTMENT

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Gentlemen:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-29  
File: 0260/L-835.0  
Liquid Effluent Flow Rate  
Estimate Exceeded LCO Time Limit  
LER 85-032-0  
AECM-85/0308

Attached is Licensee Event Report (LER) 85-032-0 which is a final report.

Yours truly,

L. F. Dale  
Director

JRM/EBS/SHH:bms  
Attachment

cc: Mr. J. B. Richard (w/a)  
Mr. O. D. Kingsley, Jr. (w/a)  
Mr. R. B. McGehee (w/a)  
Mr. N. S. Reynolds (w/a)  
Mr. H. L. Thomas (w/o)  
Mr. R. C. Butcher (w/a)

Mr. James M. Taylor, Director (w/a)  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dr. J. Nelson Grace, Regional Administrator (w/a)  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N. W., Suite 2900  
Atlanta, Georgia 30323

IE22  
||