

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)  
RANCHO SECO NUCLEAR GENERATING STATION UNIT NO. 1DOCKET NUMBER (2)  
0 5 0 0 0 3 1 1 2PAGE (3)  
1 OF 0 1 2

TITLE (4)

HEPA FILTER BANK LEAK

EVENT DATE (5)  
MONTH DAY YEAR  
0 9 0 6 8 5 8 5  
LER NUMBER (6)  
YEAR SEQUENTIAL NUMBER REVISION NUMBER  
0 1 7 0 0 0  
REPORT DATE (7)  
MONTH DAY YEAR  
0 9 1 7 8 5  
OTHER FACILITIES INVOLVED (8)  
FACILITY NAMES  
DOCKET NUMBER(S)  
0 5 0 0 0 0 0 0  
NONE 0 5 0 0 0 0 0 0OPERATING MODE (9)  
N  
POWER LEVEL (10)  
0 1 0 0  
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)  
20.402(b) 20.405(c) 50.73(a)(2)(iv) 73.71(b)  
20.405(a)(1)(i) 50.36(c)(1) X 50.73(a)(2)(v) 73.71(c)  
20.405(a)(1)(ii) 50.36(c)(2) 50.73(a)(2)(vii) OTHER (Specify in Abstract below and in Text, NRC Form 366A)  
20.405(a)(1)(iii) 50.73(a)(2)(i) 50.73(a)(2)(viii)(A)  
20.405(a)(1)(iv) 50.73(a)(2)(ii) 50.73(a)(2)(viii)(B)  
20.405(a)(1)(v) 50.73(a)(2)(iii) 50.73(a)(2)(ix)

LICENSEE CONTACT FOR THIS LER (12)

NAME  
Ron W. Colombo, Regulatory Compliance Supervisor  
TELEPHONE NUMBER  
AREA CODE  
9 1 6 4 5 2 1 3 2 1 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs
B	VIF	AHUI	CIOIIO	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) X NO  
EXPECTED SUBMISSION DATE (15)  
MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On September 6, 1985, it was reported via an internal Occurrence Description Report, that a leakage flow path existed in the filtration unit of the auxiliary building "A" ventilation unit (A-542A), thus allowing a small portion of the air flow to bypass the high-efficiency particulate air (HEPA) filters. This constitutes a condition which could have prevented the fulfillment of the safety function of a system that is needed to control the release of radioactive material and is being reported under 10 CFR 50.73(a)(2)(v).

The "bypass" flow path resulted from the omission of a seal plate during the manufacturing of the filtration unit and has existed since its initial installation. The filtration unit on the "B" train was examined and the seal plate was found to be welded in place. The missing seal plate was discovered while performing the refueling outage auxiliary building filter system surveillance procedure.

An investigation of this concern revealed that the flow being bypassed was approximately .1% of the nominal flow rate. It was also determined that the unfiltered bypass flow alone was not sufficient to prevent the system from meeting the Technical Specifications surveillance standards.

To eliminate the bypass flow path, a steel plate was welded over the bypass opening. Upon completion of the work, a dioctyl phthalate (DOP) scan of the repair was performed and the unit was tested in accordance with the surveillance procedure. Corrective action was completed September 16, 1985.

There were no effects on plant or public safety as a result of this event.

IE22 %

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 3/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
RANCHO SECO NUCLEAR GENERATING STATION UNIT NO. 1	05000312	85	017	00	02	OF	02

TEXT (If more space is required, use additional NRC Form 365A's) (17)

On September 6, 1985, it was reported via an internal Occurrence Description Report, that a leakage flow path existed in the filtration unit of the auxiliary building "A" ventilation unit (A-542A), thus allowing a small portion of the air flow to bypass the high-efficiency particulate air (HEPA) filters. This bypass path represents a degradation of a safety system that is needed to control the release of radioactive material and is being reported under the requirements of 10 CFR 50.73(a)(2)(v).

The "bypass" flow path resulted from the omission of a seal plate during the manufacturing of the filtration unit and has existed since its installation (prior to initial plant criticality in 1974). The manufacturer of the unit was CVI, a subsidiary of Pennwalt. The missing seal plate was discovered while performing surveillance procedure SP 211.04A (Auxiliary and Spent Fuel Building Filter System "A") when a small area of discoloration was detected on the filtration unit. The discoloration was thought to be the result of painting activity and subsequent filtration which occurred during the recent fuel outage. The filtration on the "B" train was examined for a similar deficiency and the seal plate was found to be welded in place.

The bypass area was measured to be .012 ft<sup>2</sup> and from a test it was determined that the flow being bypassed was approximately .1% of the nominal 43400 CFM flow rate. A review of past SP.211.04A surveillance test records also indicated that the unfiltered bypass flow alone was not sufficient to prevent the auxiliary building filter system from meeting the surveillance standards established in the Rancho Seco Unit 1 Technical Specifications Section 4.12.

To eliminate the bypass flow path, a steel plate was welded over the bypass opening. Upon completion of the work, a dioctyl phthalate (DOP) scan of the repair was performed and the "A" unit was tested in accordance with the surveillance procedure. This corrective action was completed September 16, 1985. In addition, the District's Incident Analysis Group will perform a root cause evaluation of this event. If the results of the evaluation differ significantly from the conclusions stated in this report, a supplemental report providing the new information will be submitted.

There were no effects on plant or public safety as a result of this event.



**SMUD**

SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, P.O. Box 15830, Sacramento CA 95852-1830, (916) 452-3211  
AN ELECTRIC SYSTEM SERVING THE HEART OF CALIFORNIA

RJR 85-472


September 26, 1985

J B MARTIN REGIONAL ADMINISTRATOR  
REGION V OFFICE OF INSPECTION AND ENFORCEMENT  
ATTN DOCUMENT CONTROL DESK  
U S NUCLEAR REGULATORY COMMISSION  
WASHINGTON DC 20555

DOCKET NO. 50-312  
LICENSE NO. DPR-54  
LICENSEE EVENT REPORT NUMBER 85-17

In accordance with the requirements of 10 C.F.R. 50.73(a)(2)(v), the Sacramento Municipal Utility District hereby submits Licensee Event Report Number 85-17.

If there are any questions concerning this report, please contact Mr. Ron Colombo at the Rancho Seco Nuclear Generating Station Unit No. 1.

  
P. J. RODRIGUEZ  
ASSISTANT GENERAL MANAGER  
NUCLEAR

Attachment

cc: Region V (2)  
INPO

IE22  
1/1