



UNIVERSITY OF ALASKA, FAIRBANKS  
Fairbanks, Alaska 99701

30-7112  
30-1179  
RECEIVED  
NRC

1985 JUL -1 PM 12:26

REGION V IAE

June 27, 1985

ATTN: DAVID D. SKOV

U.S. Nuclear Regulatory Commission  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, CA 94596

Dear Sirs:

The present letter concerns the recent NRC inspection of Licenses 50-02430-09 and 50-02430-07 on June 20 and 21, 1985 and provides corrective measures taken to alleviate non-compliance items found during that inspection.

NRC 50-02430-09 (Co-60 Irradiators)

The item of non-compliance was failure of performing leak test within each 6 month period. A leak test and site survey has been completed and a copy of these records are enclosed. A "Caution Radioactive Materials" sign has been posted next to the "Caution Radiation Area" sign as suggested.

Our misunderstanding concerning the 6 month leak test stems from item 16 of Amendment 04 which refers to the renewal request of January 20, 1983 in which we specifically requested that leak test not be performed during periods of non-use. We realize now that this request was not granted.

NRC 50-02430-07 (University Broad-Scope License)

A recent copy of form NRC-3, an attached document identifying Room 403, Irving Building where all pertinent licenses, regulation etc. can be inspected, and a copy of "Safe Handling - Emergency Procedures" has been posted in all radioisotope use areas.

Temporary labels identifying the source, activity, date, University, emergency contacts and a "Caution Radioactive Materials" label have been placed on the Cesium-137 source (5 mCi - No. NER572). Also a temporary label has been placed on the Am-241 source (110 mCi) identifying source and activity. We are in the process of obtaining permanent metal labels for these sealed sources.


Six month inventory forms have been sent to all authorized users for the period January 1, 1985 through June 30, 1985. A complete internal audit of all authorized users will be completed in early July 1985.

8508050290 850729  
REG5 LIC30  
50-02430-07 PDR

UNIVERSITY OF ALASKA

All areas, including field-sites where radioactive materials are used or stored will be posted with a "Caution Radioactive Materials" sign if quantities exceed the amounts as specified in 10 CFR 20.203(e). This requirement has not been specifically excluded from our license for field-sites.

Sincerely,

A handwritten signature in dark ink, appearing to read "Dan Holliman". The signature is fluid and cursive, with the first name "Dan" being more prominent than the last name "Holliman".

Dan Holliman  
Radiation Safety Officer  
Institute of Arctic Biology  
University of Alaska  
Fairbanks, AK 99701

DH/na

Jan 10, 1985

These Co-60 sources have not been used during this 6 month period therefore no leak test will be conducted. Leak test will be performed Summer 85 although no use is expected in the foreseeable future.

June 21, 1985 - Licence 50-02430-09 Co-60 irradiators was inspected by NRC David Skov. He informed me that ~~the~~ exclusion from the 6-month leak test was not granted to this licence, although the source was not in use. Leak test will be conducted in the immediate future.

June 24, 1985


The Co-60 sources were operated to the "irradiated" and shield position for several cycles. Wipes were taken from the port of each irradiator and counted along with blank wipes and the Co-60 check source (1  $\mu$ Ci Co-60 1960 - present activity 0.036  $\mu$ Ci). Background was 167 cpm. Samples

June 24, 1985 (continued)

were counted on the Nuclear Data Multi-channel Analyzer and Results were

Sample	cpm	net cpm	activity $\mu\text{Ci}$
Bkg	167		
0.036 $\mu\text{Ci}$ Std.	—	66552	0.036 $\mu\text{Ci}$
Wipe 1 irradiators 1	190	23	$< 2 \times 10^{-5} \mu\text{Ci}$
Wipe 2 irradiators 2	170	3	$< 1 \times 10^{-5} \mu\text{Ci}$

A survey was conducted with the irradiators (outside the building) in the irradiate position - readings were as indicated (Survey Meter NC 2560 was used)



1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31

1 2 3 4 5 6 7 8 9

file 24, 1985 (continued)

The sources were returned to the shielded position and plugs replaced. No readings above normal background were recorded outside the building (0.01-0.02 mR/hr). The highest reading possible is by laying the detector on the shield directly above the shield. This reading was 0.7 mR/hr.