

Joseph M. Farley Nuclear Plant Unit 2 Containment Post-Tensioning System Five-Year Inservice Inspection

Volume 1 – Report

Prepared by:

Southern Company Services, Inc.
September 1985

8510030152 850916
PDR ADOCK 05000364
P PDR



Alabama Power

the southern electric system

Table of Contents

VOLUME 1 - REPORT

- 1.0 Introduction
- 2.0 General Test Description
- 3.0 Summary of Data
 - 3.1 Sheathing Filler Appearance and Coverage
 - 3.2 Corrosion of Anchorage Components
 - 3.3 Buttonhead Condition
 - 3.4 Anchorage Assembly and Concrete Condition
 - 3.5 Sheathing Filler Analysis
 - 3.6 Comparison with Previous Surveillances
 - Table 3-1 End Anchorage Examination Summary
 - Table 3-2 Sheathing Filler Summary
 - Table 3-3 Sheathing Filler Analysis Summary:
Surveillance Tendon Samples
 - Table 3-4 New Sheathing Filler Analysis Summary:
Batch Number Analysis
 - Table 3-5 Comparison with Previous Surveillances
- 4.0 Conclusions and Recommendations
- 5.0 References

VOLUME 2 - DATA

- 1.0 Surveillance Test Procedure (FNP-2-STP-609.0, Rev. 3)
- 2.0 Data Sheets
- 3.0 INRYCO Greasing Procedures and Data Sheets
- 4.0 As-Found Sheathing Filler Analysis
- 5.0 New Sheathing Filler Certification

1.0 INTRODUCTION

This report documents the five-year Containment Building tendon surveillance for the Joseph M. Farley Nuclear Plant - Unit 2. This was the third in a series of surveillances required at one, three, and five years and every five years thereafter. The first and second surveillances followed approximately one and three years respectively, after the initial containment Structural Integrity Test. The post-tensioning system was supplied by INRYCO, Inc.

During the containment inspection performed prior to the Integrated Leakage Rate Test of the Containment Building during the Unit 2 third refueling outage, it was discovered that the grease can for the shop end of vertical tendon V17 was deformed. The grease can for the field end was removed and the field anchorhead was observed to be failed allowing the tendon to become fully detensioned. As a result of this discovery, Alabama Power Company initiated an inspection and repair program to determine if other problems existed. Several other cracked or broken vertical field anchorheads were found and replaced. All vertical field anchorheads were removed, inspected and replaced with new or acceptable used anchorheads. Details of the inspection and repair program are discussed in LER 85-005-01 which was submitted to the NRC on August 12, 1985. As discussed in this LER, the inspection and repair program results demonstrated that containment structural integrity was maintained.

The Unit 2 Five-Year Surveillance was performed upon completion of the vertical tendon inspection and repair program and was conducted in accordance with Farley Nuclear Plant Surveillance Test Procedure FNP-2-STP-609.0, Revision 3, and the INRYCO, Inc., procedures for complete refill of tendon voids.⁹ The test procedures incorporate the requirements of the plant Technical Specifications, and the U. S. Nuclear Regulatory Commission Regulatory Guide 1.35, Revision 2 for the second containment of a two-unit site.² The visual inspection of the 170-wire BBRV buttonhead post-tensioning system consisted of a visual examination of the tendon end anchorage, hardware, and surrounding concrete, and a laboratory analysis of the sheathing filler samples.

2.0 VISUAL TEST DESCRIPTION

The objective of the inservice tendon surveillance program is to provide a systematic means of assessing the continued integrity of the prestressed, post-tensioned containment structure.

To implement the Unit 2 five-year visual surveillance program, a tendon sample composed of 21 tendons was chosen. The individual tendons were randomly selected in accordance with the requirements of reference 1. The initial sample tendons were representatively distributed in the containment wall and dome. Due to its location near the main steam safety and atmospheric dump vents, and the resulting danger to personnel during plant operation, sample tendon D202 was replaced by alternate sample tendon D117. The vertical tendons inspected document the as-left conditions of the repair program and serve as the basis for future surveillance activity.

The inspected tendons were vertical tendons V4, V28, V52, V79, and V100; dome tendons D109, D119, D117, D227, D307, and D319; and hoop tendons H1DE, H3EF, H13FD, H17EF, H21DE, H26FD, H28DE, H31EF, H42FD, and H45DE.

Each tendon was inspected in accordance with reference 1, except as noted, and consisted of the following steps:

- The sheathing filler for all vertical tendons and hoop tendons H1DE and H13EF was drained under the repair and inspection program. These tendons were sampled using INRYCO procedures.¹⁰ The sheathing filler for the remaining hoop and dome tendons was drained from the sample tendon and the end caps were removed as required. A general description of the filler, the total amount (gal) of filler removed, and the absence or presence of water was recorded. Two 1-quart grease samples were taken from each end for lab analysis.
- The anchorage assemblies were cleaned with solvent to expose the bare metal surfaces. Anchorhead numbers and shim stack heights were recorded.
- Results of a visual examination of buttonheads for corrosion (as defined in section 3.2), missing buttonheads, and damaged wires were recorded.
- The anchorheads were visually examined in place for cracks and corrosion levels were recorded.
- Shim corrosion levels were recorded. Shims were visually examined for any cracks.
- Results of the bearing plate examinations for corrosion and damage were recorded.
- The anchorage area concrete was checked for significant cracks and any other irregularities.

- Tendon end caps were replaced using new gaskets.
- Tendons were regreased using the INRYCO procedures listed in reference 9.

The acceptance criteria by which the inspection data was evaluated is summarized below.

- Anchorage assembly components may not be pitted by corrosion.
- The number of ineffective wires in a tendon may not exceed eight. An ineffective wire is defined as one that is missing, unseated, or has a buttonhead with splits summing to greater than 0.12 in. A wire is also classified as ineffective if the buttonhead is judged on the basis of shape, size, or general appearance to be marginal in its load-carrying ability. If a tendon has more than eight wires classified as ineffective per the foregoing criteria, adjacent tendons are inspected.
- Sheathing filler samples may not have water contents exceeding 10 percent of dry weight and must have positive reserve alkalinities. The concentrations of chlorides, nitrates, and sulfides may not exceed 10 ppm (5 ppm for new material). Anchorage components and sheathing filler samples not meeting the acceptance criteria must be evaluated by the owner or his authorized representative.

3.0 SUMMARY OF DATA

The results of the inspection are summarized in tables 3-1 through 3-4 and discussed in the following paragraphs. Original data are reproduced in Volume 2.

3.1 SHEATHING FILLER APPEARANCE AND COVERAGE

For all vertical tendons and hoop tendons H1DE and H13FD, the original sheathing filler was drained during the inspection and repair program. Following anchorhead replacement, the end anchorage components were "cold-packed" by hand coating with new sheathing filler. As a part of this inspection and repair program, grease samples were only collected at the field ends of the vertical tendons. No samples were collected for the shop ends. Additionally, no sample was available for the field end of V52. The sheathing filler samples obtained under the inspection and repair program were collected using the INRYCO procedures listed in reference 10.

A visual inspection of the filler material was conducted on the remaining hoop tendons and all dome tendons as each anchorage grease cap was removed. The sheathing filler material varied in color from tan to black; however, the majority of anchorages were covered with dark brown sheathing filler. Various amounts of black preservative were found. This black preservative is known to be Visconorust 1601 Amber, a coating used by the tendon manufacturer to prevent any corrosion prior to installation.⁷ The shop anchorage of tendon H3EF had filler with a frothy appearance. This texture indicates that the grease temperature was greater than 300°F upon pumping into the void. The satisfactory results of the visual inspection indicated that the grease was providing sufficient protection. The consistency of filler material from all anchorages ranged from a highly viscous lubricant to a light lubricating grease. The variety of colors and textures found is consistent with previous surveillances. The presence of the black preservative is considered normal and is compatible with the sheathing filler, Visconorust 2090 P-4, nuclear grade. This same sheathing filler has been used for regreasing operations in all surveillances.

Two ounces of water were found in the shop end cap of vertical tendon V52. This moisture was condensation. The end anchorage was left cold packed from the repair program and had not yet been fully regreased. The water vapor in the void condensed on the interior surface of the grease can and on the cold packed anchorage. The water did not penetrate the filler coverage and was not allowed into the trumplate opening. The shop end of H3EF contained traces of moisture in uncollectable quantities. Moisture was present in the grease can and on the lower portion of the shims. Water was also noted as dripping slowly from the grease hole and shim gap. No moisture was observed on the anchorhead. This moisture is also suspected to be condensation which collected since the original tendon installation. Traces of water were detected when the bolts were loosened on the field end of D227. No moisture was observed on the anchorage or in the grease can. This moisture was probably trapped between the bearing plate and the gasket retainer plate. The water escaped when the bolts were loosened.

The laboratory analysis of the filler material from tendons H3EF and D227 does not show excessive water content. This confirms that it was free moisture and not in solution with the sheathing filler. There was no evidence of abnormal or progressive corrosion due to the water found in the tendon end caps.

Except for the shop end of D307 and the field end of H21DE, all anchorages were fully covered with sheathing filler. The sheathing filler level on these two tendons was below the top of the anchorage. The portions of these anchorages above the filler were coated with a sufficient coating of grease for corrosion protection. This portion of these anchorages exhibited no rust or progressive corrosion. This exposure is not considered detrimental to the anchorages' ability to perform its design function.

Following the visual inspection, all tendons were regreased using approved INRYCO procedures for tendon regreasing.⁹ The vertical tendons were pumped from the field end (gallery). Grease and air were allowed to flow from the shop end (dome) until the exit temperature of the grease reached a minimum of 120°F. Hoop tendons were greased from both ends. Hot grease was pumped into the grease can until a 10°F minimum rise from ambient grease temperature was obtained from the auxiliary vent plug. In all cases the exit temperature was greater than 100°F. Dome tendons were pumped from one end. Hot grease was pumped in until a 10°F minimum rise from ambient grease temperature was achieved and after 20 gallons had exited the void at the opposite end. The exit location was capped and pumping continued until a 50 psi rise in pressure over pumping pressure was achieved. The exit temperature for all surveillance dome tendons was in excess of 110°F.

3.2 CORROSION OF ANCHORAGE COMPONENTS

The levels of anchorage component corrosion fell in the acceptable A, B, and C categories as defined in reference 1 and summarized below.

- A - Bright metal and no visible oxidation
- B - Reddish-brown metal with no pitting
- C - Metal having patches of red oxide with no pitting
- D - Metal having patches of red oxide with pitting
- E - Heavy rusting with substantial pitting
- F - Conditions more severe than E

Buttonheads, shims, and anchorheads were predominantly in the A and/or B category. The B-level corrosion appears to be old, nonprogressive and probably existed at installation. Bearing plates not only had A and B levels of corrosion, but C levels were also visible. The vast majority of levels B and C appeared to be discolored, crusty oxide layers. These layers had bonded to the painted bearing plate surface from the interior side of the gasket retainer plate. Removal of the crust from the bearing plate revealed intact paint beneath. Edges of the bearing plates exposed to the weather were exhibiting C levels of corrosion extending through the paint into the bearing plate. This weathering is consistent on all hoop end anchorages examined. This same type corrosion is also apparent at the bolt hole locations. Vertical and dome tendons generally did not exhibit this weathering.

Upon inspection, it was found that the H13FD (shop) and D109 (shop) bearing plates were not painted. The sheathing filler appears to be providing adequate corrosion protection for the plates since there was no significant corrosion present.

3.3 BUTTONHEAD CONDITION

The examination of the tendon end anchorages covered 7140 buttonheads and vacant positions. The field end of V52 had one missing buttonhead. Records from the repair program show one buttonhead failed after stressing. Missing buttonheads were noted on H3EF, H26FD and D117. The buttonheads were not located in the grease cap. The original stressing cards indicate H26FD and D117 each lost an effective wire during stressing. Since the buttonhead for H3EF was not found in the end cap, it is suspected that the buttonhead failed after stressing but before the installation of the end cap. There were no indications of abnormal degradation of the buttonheads on any anchorage.

There were three buttonheads with splits greater than 0.12 inches in width. The individual splits ranged from 0.125 to 0.15 inches in width. Both splits on the field end of D119 were noted on the original buttonheading card. The remaining split was found on tendon H3EF but was not noted on the original buttonheading card, which documented only a sample inspection required during installation. There were no indications to suggest that the buttonhead splits were progressive in nature nor was there any reason to believe that the splits had not occurred during the buttonheading process. INRYCO previously confirmed that split widths cannot increase while a wire is under tension. The counterbore in the anchorhead puts the surface of the buttonhead into circumferential compression that reduces split width.⁷ These wires remain stressed even though the wires were considered as ineffective.

Three buttonheads were found unseated. They were gripped with pliers and twisted to determine if the wires were broken a short distance from the unseated ends. The buttonheads were gripped with channel-lock pliers and rotated, with increasing torque, and released. All the buttonheads returned to their original positions, indicating that the wires are probably continuous, but have also been considered as ineffective.

Eleven wires were found double buttonheaded. This condition is considered to be a misshaped head; however, all double buttonheads were seated, of an acceptable diameter, and were considered to have adequate load-carrying capacity. These wires were considered effective.

3.4 ANCHORAGE ASSEMBLY AND CONCRETE CONDITION

Anchorage assemblies (anchorheads, shims and bearing plates) were visually examined in place for cracks, deterioration, and any other deleterious condition. No cracks were observed on any anchorage component. All anchorages observed appear to be in a stable condition.

The concrete adjacent to the tendon end anchorages was examined for cracks exceeding 0.01 inches in width and for any other abnormal condition. No cracks greater than 0.01 inches in width were found nor was there any other abnormal condition visible.

3.5 SHEATHING FILLER ANALYSIS

The sheathing filler chemical analysis reports indicate that all filler (as-found and new) is well within the acceptable ranges as outlined in reference 1. Amounts of chloride, nitrates, and sulfides found in the as-found filler are 1 ppm or less, well below the 10 ppm allowed. The maximum water content (1.3 percent) found in the as-found filler is considerably less than a maximum of 10 percent of dry weight. Neutralization numbers ranged from a low of 22.3 to a high of 69.8, with a minimum of zero required. The neutralization numbers were consistent with those of previous surveillances.

Sheathing filler analysis reports for both new and as-found filler are summarized in tables 3-3 and 3-4. Copies of the new sheathing filler certifications and as-found sheathing filler analysis reports may be found in Volume 2.

3.6 COMPARISON WITH PREVIOUS SURVEILLANCES

Tendon D227 was included in the Three-Year Surveillance and the Five-Year Surveillance. Data from the inspections is included in Table 3-5. By comparing the data collected, it can be seen that this tendon shows no signs of progressive corrosion or abnormal degradation. The five-year inspection did not note B level corrosion on the shop end shims; however, the five-year data does indicate that the corrosion present is not progressing. The five-year data also did not note C level corrosion on the bearing plate as the three-year data did. Since the bearing plate corrosion has generally been attributed to corrosion transferred to the bearing plate paint from the gasket retainer plate, the C level corrosion was considered to have been removed during anchorage assembly clean-up. The three-year data noted one split greater than 0.06". The criteria for denoting splits during the five-year inspection was 0.12"; therefore, since the split noted during the three-year inspection was approximately 0.065", it was not required to be reported by the five-year inspection. All other data collected coincides. By comparing the data collected during the three-year inspection and the five-year inspection, it can be seen that tendon D227 is in the same condition as it was left at the three-year inspection and shows no signs of progressive corrosion or abnormal degradation.

TABLE 3-1

END ANCHORAGE EXAMINATION SUMMARY

Tendon	End	Anchorage Corrosion Levels				Buttonheads				Anchorage Assembly Cracks
		Buttonheads	Anchor Heads	Shims	Bearing Plate	Missing	Split ≥ 0.12"	Unseated	Misshaped	
V4	F	A	A	A, B	A, B, C	None	None	None	None	None
	S	A	A	A	A, B, C	None	None	None	None	None
V28	F	A	A, B	A	A, B, C	None	None	None	None	None
	S	A	A	A	A, B	None	None	None	None	None
V52	F	A	A	A	A, B	1	None	None	None	None
	S	A	A	A, B	A, B, C	None	None	None	None	None
V79	F	A	A	A	A, B, C	None	None	None	1	None
	S	A	A	A, B	A, B	None	None	None	None	None
V100	F	A	A	A	A, B	None	None	None	1	None
	S	A, B	A	A, B	A, C	None	None	None	None	None
H1DE	F	A	A, B	A	A	None	None	None	None	None
	S	A	A	A, B	B, C	None	None	None	None	None
H21DE	F	A	A, B	A	A, B	None	None	None	None	None
	S	A	A	A, B	A, B, C	None	None	None	None	None
H28DE	F	A	A	A	A, B, C	None	None	None	2	None
	S	A	A	A, B	A, B, C	None	None	None	None	None

F = Field
S = Shop

TABLE 3-1

TENDON ANCHORAGE EXAMINATION SUMMARY

Tendon	End	Anchorage Corrosion Levels				Buttonheads				Anchorage Assembly Cracks
		Buttonheads	Anchor Heads	Shims	Bearing Plate	Missing	Split ≥0.12"	Unseated	Misshaped	
H45DE	F	A	A, B	A, B	A, B, C	None	None	None	1	None
	S	A	A	A	A, B, C	None	None	None	None	None
H3EF	F	A	A	A	A, B	None	1	None	None	None
	S	A	A	A	A, B	1	None	None	None	None
H17EF	F	A	A	A	A, B, C	None	None	None	None	None
	S	A	A	A, B	A, B, C	None	None	None	None	None
H31EF	F	A	A	A	A, B, C	None	None	None	1	None
	S	A	A, B	A, B	A, B, C	None	None	None	None	None
H13FD	F	A	A	A	A	None	None	None	None	None
	S	A	A	A	A, B	None	None	1	None	None
H26FD	F	A	A	A, B	A, B, C	2	None	None	1	None
	S	A	A	A	A, B, C	None	None	None	None	None
H42FD	F	A	A, B	A, B	A, B, C	None	None	None	2	None
	S	A	A	A, B	A, B, C	None	None	2	None	None
D109	F	A	A, B	A, B	A, B, C	None	None	None	1	None
	S	A	A	A, B	A, B, C	None	None	None	None	None

F = Field
S = Shop

TABLE 3-1

END ANCHORAGE EXAMINATION SUMMARY

Tendon	End	Anchorage Corrosion Levels				Buttonheads				Anchorage Assembly Cracks
		Buttonheads	Anchor Heads	Shims	Bearing Plate	Missing	Split ≥0.12"	Unseated	Misshaped	
D119	F	A	A	A	A, B, C	None	2	None	1	None
	S	A	A	A	A, B	None	None	None	None	None
D117	F	A	A	A	A, B, C	1	None	None	None	None
	S	A	A, B	A	A, B	None	None	None	None	None
D227	F	A	A	A, B	A, B, C	None	None	None	None	None
	S	A	A	A	A, B	None	None	None	None	None
D307	F	A	A, B	A, B	A, B	None	None	None	None	None
	S	A	A	A	A, B	None	None	None	None	None
D319	F	A	A	A, B	A, B	None	None	None	None	None
	S	A	A	A	A, B	None	None	None	None	None

F = Field
S = Shop

TABLE 3-2
SHEATHING FILLER SUMMARY

Inspection			Regreasing		
Tendon	End	Filler Moisture/Color	Container Temp. °F	Exit Temp. °F	Viscosity Batch No.
V4	S	None/New	-	148	5-6202
	F	None/New	171	-	
V28	S	None/New	-	140	5-6202
	F	None/New	171	-	
V52	S	2 Ounces/New	-	142	5-6202
	F	None/New	171	-	
V79	S	None/New	-	145	5-6202
	F	None/New	171	-	
V100	S	None/New	-	120	5-5928
	F	None/New	169	-	
H1DE	S	None/Brown ^A	220	108	5-5526
	F	None/New	180	120	5-5526
H21DE	S	None/Brown	193	130	5-5526
	F	None/Brown	190	120	5-5526
H28DE	S	None/Brown	180	122	5-6359
	F	None/Brown ^A	152	124	5-6359
H45DE	S	None/Brown	220	160	5-6359
	F	None/Brown ^A	190	150	5-6359
H3EF	S	Traces/Brown ^B	210	120	5-5526
	F	None/Tan	220	120	5-5526
H17EF	S	None/Brown ^A	172	120	5-5526
	F	None/Brown ^A	185	150	5-5526

A = Small amount of black preservative

B = Grease surface frothy

C = New "cold pack" grease mixed with black preservative

D = Predominantly black preservative

TABLE 3-2
SHEATHING FILLER SUMMARY

Inspection			Regreasing		
<u>Tendon</u>	<u>End</u>	<u>Filler Moisture/Color</u>	<u>Container Temp. °F</u>	<u>Exit Temp. °F</u>	<u>Viscosity Batch No.</u>
H31EF	S	None/Brown	220	134	5-6359
	F	None/Brown	215	142	5-6359
H13FD	S	None/Brown	185	150	5-5526
	F	None/New	160	120	5-5526
H26FD	S	None/Brown	182	140	5-6359
	F	None/Brown	220	122	5-6359
H42FD	S	None/Brown	160	132	5-6359
	F	None/Brown ^A	190	136	5-6359
D109	S	None/Brown ^A	184	-	5-6359
	F	None/Brown ^C	-	140	
D119	S	None/Brown	210	-	5-6359
	F	None/Black ^D	-	152	
D117	S	None/Brown	184	-	5-6359
	F	None/Brown ^D	-	130	
D227	S	None/Brown	190	-	5-5526/ 5-6359
	F	None/Brown ^A	-	112	
D307	S	None/Brown	184	-	5-6359
	F	None/Brown ^A	-	142	
D319	S	None/Brown	178	-	5-6359
	F	None/Brown ^A	-	124	

TABLE 3-3

SHEATHING FILLER ANALYSIS SUMMARY:
SURVEILLANCE TENDON SAMPLES

<u>Tendon</u>	<u>End</u>	<u>Chloride (PPM)</u>	<u>Nitrate* (PPM)</u>	<u>Sulfide* (PPM)</u>	<u>Water (%)</u>	<u>Neutralization Number</u>
V4	F	1	1	1	0.5	45.8
V28	F	1	1	1	1.2	56.4
V79	F	1	1	1	0.5	60.8
V100	F	1	1	1	0.2	48.5
H1DE	S	1	1	1	0.3	44.1
	F	1	1	1	0.5	44.6
H21DE	S	1	1	1	0.2	45.8
	F	1	1	1	0.1	48.5
H28DE	S	1	1	1	0.2	46.9
	F	1	1	1	0.2	56.4
H45DE	S	1	1	1	0.3	54.7
	F	1	1	1	0.4	48.5
H3EF	S	1	1	1	1.3	46.9
	F	1	1	1	0.2	49.7
H17EF	S	1	1	1	0.5	48.0
	F	1	1	1	0.3	54.7

*An indicated concentration of 1 PPM represents a true concentration of 0 to 1 PPM.

TABLE 3-3

SHEATHING FILLER ANALYSIS SUMMARY:
SURVEILLANCE TENDON SAMPLES

<u>Tendon</u>	<u>End</u>	<u>Chloride (PPM)</u>	<u>Nitrate* (PPM)</u>	<u>Sulfide* (PPM)</u>	<u>Water (%)</u>	<u>Neutralization Number</u>
H31EF	S	1	1	1	0.3	51.3
	F	1	1	1	0.3	48.5
H13FD	S	1	1	1	0.2	43.5
	F	1	1	1	0.4	44.6
H26FD	S	1	1	1	0.3	42.4
	F	1	1	1	0.4	61.4
H42FD	S	1	1	1	0.4	58.6
	F	1	1	1	0.2	67.0
D109	S	1	1	1	0.1	62.5
	F	1	1	1	0.2	45.1
D117	S	1	1	1	0.2	59.2
	F	1	1	1	0.2	59.7
D119	S	1	1	1	0.2	60.8
	F	1	1	1	0.5	22.3
D227	S	1	1	1	0.1	55.2
	F	1	1	1	0.1	63.6
D307	S	1	1	1	0.1	69.8
	F	1	1	1	0.7	65.3
D319	S	1	1	1	0.2	58.0
	F	1	1	1	0.1	59.2

*An indicated concentration of 1 PPM represents a true concentration of 0 to 1 PPM.

TABLE 3-4
NEW SHEATHING FILLER ANALYSIS SUMMARY:
BATCH NUMBER ANALYSIS

<u>Viscosity Batch No.</u>	<u>Chloride (PPM)</u>	<u>Nitrate* (PPM)</u>	<u>Sulfide* (PPM)</u>	<u>Water (%)</u>	<u>Neutralization Number</u>
5-5526	1	2	1	0.6	48.7
5-5928	1	2	1	0.1	52.0
5-6202	1	2	1	0.2	51.0
5-6359	1	2	1	0.2	49.8

*An indicated concentration of 1 PPM represents a true concentration of 0 to 1 PPM.

TABLE 3-5

COMPARISON WITH PREVIOUS SURVEILLANCES

Tendon	End	Anchorage Corrosion Levels					Buttonheads				Anchorage Assembly Cracks
		Surveil- lance #	Buttonheads	Anchor Heads	Shims	Bearing Plate	Missing	Splits	Unseated	Misshaped	
D227	F	3-Year	A	A	A, B	A, B, C	None	1	None	None	None
	S	3-Year	A	A	A, B	A, B, C	None	None	None	None	None
D227	F	5-Year	A	A	A, B	A, B, C	None	None	None	None	None
	S	5-Year	A	A	A	A, B	None	None	None	None	None

4.0 CONCLUSIONS AND RECOMMENDATIONS

The condensation found in the shop grease can of vertical tendon V52 was a result of the repair and replacement program. This moisture was removed and the tendon regreased as quickly as possible to prevent further condensation. The traces of moisture found in hoop tendon H3EF was suspected to be condensation which collected since initial installation. This moisture was also removed and the anchorage regreased as quickly as possible.

Corrosion of the anchorage components within the end caps appeared to be that which existed at initial sheathing filler injection. There was no evidence to suggest that this corrosion was progressive or had affected the integrity of the tendon. The weathered condition of the bearing plates perimeters is confined to the areas where the scalers, used to trim the concrete around the bearing plate, strayed onto the bearing plate. These areas are not considered detrimental to the integrity of the bearing plate. Corrosion of the areas surrounding the bolt holes is not significant; however, it should be considered during future surveillance activity. Also, detailed measures should be established to ensure complete sealing of the grease can.

Areas of the bearing plate outside the end cap circumference had A, B, and C levels of corrosion. The vast majority of this corrosion appeared to have been transferred from the interior side of the gasket retainer plate. The gasket retainer plates, which are not an inspection item, are neither painted nor galvanized. Their function is only to provide a form for the gasket during installation of the grease can. The corrosion of these retainer plates is obviously progressive, particularly on those anchorages exposed to the elements. Gasket retainer plate condition was noted in some of the data. Approximately 17% were found to have C level corrosion.

The acceptance criteria for any one tendon requires that if the number of ineffective wires exceeds eight, then the two adjacent tendons must be inspected. The total number of ineffective wires found in all tendons inspected during this surveillance was 11; 5 missing buttonheads, 3 splits greater than 0.12 inches, 3 unseated buttonheads. The misshaped buttonheads were all double buttonheads, seated and considered effective. No individual tendon had more than eight ineffective wires. Since the test results are within this acceptance criteria all tendons examined are acceptable.

Based upon the results of these inspections, the results of the repair and inspection program, and the laboratory analysis of the sheathing filler it is concluded that the post-tensioning system is performing its intended design function. Within the scope of this surveillance, the system exhibits no signs of abnormal degradation. It is in essentially an as-installed condition. Reduction of the sample population in accordance with the plant Technical Specifications should be evaluated prior to the ten-year surveillance contingent upon the results of the inspection program as outlined in the LER.

5.0 REFERENCES

1. Farley Nuclear Plant Surveillance Test Procedure, FNP-STP-609.0, Revision 3, Containment Tendon Surveillance Test.
2. Nuclear Regulatory Commission (NRC) Regulatory Guide 1.35, Revision 2, Inservice Inspection of UngROUTed Tendons in Prestressed Concrete Containment Structures.
3. INRYCO, Field Installation and Quality Control Manual, U-201851H.
4. Joseph M. Farley Nuclear Plant Unit 2, Vendor Drawings:

U-205865B	U-205874A	U-208051D	U-208144C
205866A	208806A	208053F	208145C
205867	207808B	208136B	208234
205870A	207811A	208138B	208235
205872B	208049D	208140B	208238
5. Joseph M. Farley Nuclear Plant Unit 1 and 2 Final Safety Analysis Report, paragrpah 3.8.1.7.3.
6. Farley Nuclear Plant, Technical Specifications 3/4.6.1.6.1.
7. Containment One-Year Tendon Surveillance Report - Unit 2, Volume 1.
8. Containment Three-Year Tendon Surveillance Report - Unit 2, Volume 1.
9. INRYCO, Inc., Procedure SQ 12.6, Grease Vertical Tendon - Full Refill; Procedure SQ 12.7; Grease Horizontal Tendon - Final Refill; Procedure SQ 12.8, Grease Dome Tendon - Final Refill.
10. INRYCO, Inc., Procedure SQ 7.3, Grease Samples - Acquire and Evaluate; Procedure SQ 7.4, Grease Samples - Acquire and Evaluate Minimum Quantity.

**Joseph M. Farley Nuclear Plant
Unit 2 Containment Post-Tensioning System
Five-Year Inservice Inspection**

Volume 2 – Data

Prepared by:

Southern Company Services, Inc.
September 1985



Alabama Power

the southern electric system

Table of Contents

VOLUME 1 - REPORT

- 1.0 Introduction
- 2.0 General Test Description
- 3.0 Summary of Data
 - 3.1 Sheathing Filler Appearance and Coverage
 - 3.2 Corrosion of Anchorage Components
 - 3.3 Buttonhead Condition
 - 3.4 Anchorage Assembly and Concrete Condition
 - 3.5 Sheathing Filler Analysis
 - 3.6 Comparison with Previous Surveillances
 - Table 3-1 End Anchorage Examination Summary
 - Table 3-2 Sheathing Filler Summary
 - Table 3-3 Sheathing Filler Analysis Summary:
Surveillance Tendon Samples
 - Table 3-4 New Sheathing Filler Analysis Summary:
Batch Number Analysis
 - Table 3-5 Comparison with Previous Surveillances
- 4.0 Conclusions and Recommendations
- 5.0 References

VOLUME 2 - DATA

- 1.0 Surveillance Test Procedure (FNP-2-STP-609.0, Rev. 3)
- 2.0 Data Sheets
- 3.0 INRYCO Greasing Procedures and Data Sheets
- 4.0 As-Found Sheathing Filler Analysis
- 5.0 New Sheathing Filler Certification

WORK AUTHORIZATION

AUTHORIZATION N° 30283

(1) Item No. FNP-2-STP-609.0 TPNS Q 2 T37 (TENDONS)(2) Inoperable Yes ☐ No ☒ LCO Yes ☐ No ☒ Transient Fire Load Analysis Required Yes ☐ No ☒(3) Clearance No.: N/A

RWP No.: _____

Flame Permit No.: N/A(4) Released David M. Cey 5-10-85 0927
RELEASING INDIVIDUAL DATE TIME

(5) Results: (Include Material Issue Number if applicable)

Test Completed Satisfactory. Procedure Completes Requirements
for 5-year Tendon Surveillance on Unit 2.
David Hartline 2/2/85

(6) Post Test(s) Completed N/A

RW Cey 8-8-85 1002
 RELEASING INDIVIDUAL DATE TIME

(7) Functional Accepted RW Cey 8-8-85 1002
 RELEASING INDIVIDUAL DATE TIME

(8) Manhours used: _____ Account No. _____

Reviewed: David Hartline

VOLUME 7

FNP-2-STP-609.0
November 4, 1983
Revision 3

FARLEY NUCLEAR PLANT
SURVEILLANCE TEST PROCEDURE
FNP-2-STP-609.0

CONTAINMENT TENDON SURVEILLANCE TEST

S
A
F
E
T
Y

R
E
L
A
T
E
D

Approved:



Systems Performance & Planning Superintendent

Date Issued: 5-10-85

Diskette #STP-88

FARLEY NUCLEAR PLANT
SURVEILLANCE TEST REVIEW SHEET

SURVEILLANCE TEST NO. FNP-2-STP-609.0	TECHNICAL SPECIFICATION REFERENCE 4.6.1.6.1
TITLE CONTAINMENT TENDON SURVEILLANCE TEST	MODE(S) REQUIRING TEST: 1,2,3,4
TEST RESULTS. (To be completed by test performer)	
PERFORMED BY <u>JOSEPH M. HALL</u> DATE/TIME <u>6/5/85</u> <u>0800</u>	
COMPONENT OR TRAIN TESTED (if applicable) <u>TENDONS</u>	
<input checked="" type="checkbox"/> ENTIRE STP PERFORMED	
<input type="checkbox"/> PARTIAL STP PERFORMED: <div style="display: inline-block; vertical-align: top; margin-left: 20px;"> <input checked="" type="checkbox"/> For Surveillance Credit <input type="checkbox"/> Not for Surveillance Credit </div>	
REASON FOR PARTIAL: _____	
TEST COMPLETED: <div style="display: inline-block; vertical-align: top; margin-left: 20px;"> <input checked="" type="checkbox"/> Satisfactory </div> <div style="display: inline-block; vertical-align: top; margin-left: 20px;"> <input type="checkbox"/> Unsatisfactory </div>	
<input checked="" type="checkbox"/> The following deficiencies occurred:	
<u>Grease sample analysis not available for shop end of tendons V4, V28,</u>	
<u>V79, V106 or for the shop and field end of V52 due to the tendon repair</u>	
<u>program. Tendons were drained of grease prior to surveillance testing.</u>	
<input checked="" type="checkbox"/> Corrective action taken or initiated:	
<u>Grease analysis included for new grease currently in tendons</u>	
<u>listed above.</u>	

PERFORMING GROUP REVIEW	
REVIEWED BY <u>David Hartline</u> DATE <u>8/8/85</u>	
<input checked="" type="checkbox"/> Procedure properly completed and satisfactory	
<input checked="" type="checkbox"/> Comments: <u>Surveillance conducted in accordance with tendon</u>	
<u>insertion and repair program. Additional information available with</u>	
<u>INRYCO procedures.</u>	
SYSTEMS PERFORMANCE GROUP REVIEW	SCREENED BY <u>Jimmy Reed</u> DATE <u>8-8-85</u> REVIEWED BY _____ DATE _____
<input type="checkbox"/> Satisfactory and Approved	
<input type="checkbox"/> Comments: _____	

INSPECTION SUMMARY

VERTICAL TENDONS

IDON #	INSPECTION COMPLETED	DATE TIME	BT	RESULTS / COMMENTS
V-4 SHOP	✓	5-11-85 1530	JMH	NO MOISTURE, GOOD SHIMS, COLD PACKED
V-4 FIELD	✓	5-11-85 0940	SDL	NO MOISTURE, GOOD SHIMS, NEW FILL GREASE
V-28 SHOP	✓	5-11-85 1530	JMH	NO MOISTURE, GOOD SHIMS, COLD PACKED
V-28 FIELD	✓	5-11-85 1215	SDL	NO MOISTURE, GOOD SHIMS, NEW FILL GREASE
V-52 SHOP	✓	5-11-85 1520	SDL	2oz WATER FOUND, GOOD SHIMS, 'D' GASKET R
V-52 FIELD	✓	5-11-85 1115	JMH	NO MOISTURE, 1 B'HEAD MISSING
V-79 SHOP	✓	5-11-85 1500	JMH	NO MOISTURE, GOOD SHIMS, 'D' GASKET R
V-79 FIELD	✓	5-11-85 1100	SDL	1 'DBL' B'HEAD, GOOD SHIMS NO MOISTURE
V-100 SHOP	✓	5-11-85 1440	SDL	NO MOISTURE, GOOD SHIMS COLD PACKED.
V-100 FIELD	✓	5-11-85 1030	JMH	NO MOISTURE, GOOD SHIMS, 1 DBL B'HEAD

HOOP TENDONS

1 DE SHOP	'E'	✓	5-30-85 0900	LNS	NO MOISTURE, $\frac{3}{8}$ " SHIM GAP
1 DE FIELD	'D'	✓	5-29-85 1356	JMH	NO MOISTURE,
21 DE SHOP	'E'	✓	5-30-85 1330	LNS	NO MOISTURE, 80% COVERAGE
21 DE FIELD	'D'	✓	5-29-85 1632	JMH	NO MOISTURE, GOOD SHIMS, GOOD GASKET R
28 DE SHOP	'E'	✓	5-30-85 1450	LNS	NO MOISTURE,
28 DE FIELD	'D'	✓	6-1-85 1030	LNS	NO MOISTURE, $\frac{1}{2}$ " SHIM GAP, 2 DBL B'HEADS
45 DE SHOP	'E'	✓	5-30-85 1630	LNS	NO MOISTURE,
45 DE FIELD	'D'	✓	5-31-85 1330	LNS	NO MOISTURE, $\frac{1}{2}$ " SHIM GAP, 1 DBL B'HEAD
3 EF SHOP	'E'	✓	5-30-85 0914	JMH	MOISTURE FOUND, 1 MISSING B'HEAD, SHOP BUSHING NOT FULLY ENGAGED BY $\frac{3}{16}$ ", PROBLEMS WITH SHIMS ADJACENT BEARING R.
3 EF FIELD	'F'	✓	5-29-85 0915	JMH	NO MOISTURE, $\frac{1}{2}$ " SHIM GAP, 1 SPLIT 7 0.12"

INSPECTION SUMMARY

HOOP TENDONS (CONT.)

1. TENDON #	INSPECTION COMPLETED	DATE / TIME	BT	RESULTS / COMMENTS
17 EF SHOP	'E' ✓	5-30-85 1130	LNS	No Moisture.
17 EF FIELD	'F' ✓	5-29-85 1250	JMH	No Moisture, Good Shims
31 EF SHOP	'E' ✓	5-31-85 0830	LNS	No Moisture.
31 EF FIELD	'F' ✓	6-1-85 1500	LNS	No Moisture, 1 DBL B'HEAD
13 FD SHOP	'F' ✓	5-29-85 1100	JMH	No Moisture, Good Shims, 1 UNSEATED B'HEAD.
13 FD FIELD	'D' ✓	5-29-85 1507	JMH	No Moisture, Good Shims
26 FD FIELD	'D' ✓	6-1-85 0815	LNS	No Moisture, 1/2" SHIM GAP, 2 MISSING WIRES, 1 DBL B'HEAD
26 FD SHOP	'F' ✓	5-31-85 1545	JMH	No Moisture, BURR ON STARTER THREAD
42 FD FIELD	'D' ✓	5-31-85 1530	LNS	No Moisture, 2 DOUBLE BUTTONHEADS
42 FD SHOP	'F' ✓	6-1-85 1315	LNS	No Moisture, 1/16" SHIM GAP, 2 UNSEATED B'HEADS

DOME TENDONS

D-109 FIELD	AZ 345° 25' 39" ✓	6-10-85 0905	SDL	1 DBL B'HEAD, No Moisture, Good Shims, METAL SHAVINGS FOUND
D-109 SHOP	AZ 204° 34' 21" ✓	6-10-85 1546	SDL	No Moisture, 3/8" SHIM GAPS, UNPAINTED BEARING
D-119 SHOP	AZ 176° 40' 38" ✓	6-10-85 0940	JMH	No Moisture, Good Shims, METAL SHAVINGS FOUND
D-119 FIELD	AZ 13° 19' 22" ✓	6-8-85 0915	LNS	No Moisture, BLACK GREASE, 1 DBL B'HEAD, 2 SPLITS 7 0.12
D-117 SHOP	AZ 182° 13' 27" ✓	6-10-85 0845	JMH	No Moisture, 5/8" SHIM GAP, BUSHING NOT FULLY ENGAGE
D-117 FIELD	AZ 07° 46' 13" ✓	6-8-85 1015	LNS	No Moisture, 1 MISSING BUTTONHEAD.
D-227 FIELD	AZ 213° 45' 11" ✓	6-10-85	SDL	POSSIBLE MOISTURE, Good Shims
D-227 SHOP	AZ 96° 14' 49" ✓	6-10-85 1500	JMH	No Moisture, Good Shims, "WATER SPOTS" ON BUSHING
D-307 SHOP	AZ 99° 39' 55" ✓	6-10-85 1630	JMH	No Moisture, Good Shims, BUSHING INDENTATION
D-307 FIELD	AZ 330° 20' 05" ✓	6-10-85 1030	SDL	No Moisture, Good Shims
D-319 SHOP	AZ 133° 19' 22" ✓	6-10-85 1400	JMH	No Moisture, Good Shims
D-319 FIELD	AZ 296° 40' 38" ✓	6-10-85 1306	SDL	No Moisture, Good Shims

LIST OF EFFECTIVE PAGES

FNP-2-STP-609.0

FORM 10-10710

REVISION NO.												
PAGE NO.	0	1	2	3	4	5	6	7	8	9	10	11
1				X								
2			X									
3				X								
4			X									
5				X								
6			X									
7			X									
8			X									
9				X								
10			X									
TABLE 1	X											
DATA SHEET 1												
1				X								
2				X								
DATA SHEET 2	X											
DATA SHEET 3												
3a		X										
3b			X									
DATA SHEET 4												
4a		X										
4b			X									
APPENDIX A												
A-1			X									
A-2			X									
A-3			X									

LIST OF EFFECTIVE PAGES.

FNP-2-STP-609.0

[illegible]

PROCEDURE FOR
CONTAINMENT TENDON SURVEILLANCE TESTING
FOR FARLEY NUCLEAR PLANT - UNIT NO. 2

1.0 PURPOSE

This procedure provides instructions to perform the testing, analysis and data reporting of the containment post-tensioning system.

The containment structure, designed by Bechtel Power Corporation, has a shallow domed roof on cylindrical walls designed with a tendon arrangement of three (3) families of dome tendons 60° apart, three (3) families of hoop tendons encompassing 240° with buttresses 120° apart and vertical tendons equally spaced in two groups on either side of the concrete wall centerline.

2.0 REFERENCES

- 2.1 Nuclear Regulatory Commission (NRC) Regulatory Guide 1.35, Revision 2, "Inservice Inspection of UngROUTed Tendons in Prestressed Concrete Containment Structures".
- 2.2 Prestressing Report Unit 2 Containment Structure of Joseph M. Farley Nuclear Plant.
- 2.3 U-201851H Field Installation and Quality Control Manual, INRYCO No. 00312.
- 2.4 U-202216B Post Tensions Sequence, Inland-Ryerson Dwg. 505-48, Rev. C.
- 2.5 Farley Nuclear Plant Technical Specifications 3/4.6.1.6.1.
- 2.6 Final Safety Analysis Report Section 3.8.
- 2.7 Containment One Year Tendon Surveillance Report - FNP Unit 2, Bechtel Power Corp., August, 1981.
- 2.8 Containment Three Year Tendon Surveillance Report - FNP Unit 2, Southern Company Services, Inc., September, 1983.

3.0 TEST EQUIPMENT

3.1 Mechanical Equipment

- (a) Two temporary access platforms with overhead support structures. This provides access to the tendons being inspected.

- (b) Portable metal scaffolds as required.
- (c) Grease pump, transmission lines, various fittings, etc., mounted on a storage tank or drum equipped with heating system to heat grease.
- (d) Containers, such as 55-gallon drums, to hold bulk filler grease removed from end anchorages during inspection.

3.2 Electrical Equipment

- (a) Electrical cables or heavy duty extension cords as necessary for lights and other miscellaneous power tools.
- (b) Portable lights as necessary for illuminating tendon anchorage assemblies during check for corrosion and defects.
- (c) Communications equipment for crews at each end of the tendon being inspected.

3.3 Measuring Devices

- (a) Feeler gauges or wire gauges.
- (b) Optical comparators for measuring crack widths in concrete.
- (c) Temperature gauge which will cover a range from 140°F to 210°F.

3.4 Portable Tools

- (a) Suitable wrenches to remove hold-down bolts.
- (b) Come-along hoist, or similar device, as required.
- (c) Small portable power tools, e.g., electric drill, saw, etc., as required.
- (d) Bristle brushes as required to clean tendon anchorage area.

3.5 Miscellaneous Material

- (a) Bulk filler grease (Viscono-rust 2090-P4, or latest compatible formulation, by Viscosity Oil Co.) to replace grease as necessary.

- (b) Solvent for removing grease from around tendon anchorage and cleaning any stained concrete (Viscosity #16 solvent by Viscosity Oil Co., or equal as approved).
- (c) New "O" Rings for tendon end caps.
- (d) Clean rags for cleanup.
- (e) Device suitable to scoop out bulk filler grease from around the anchorage assembly.
- (f) Any other miscellaneous material and tools as required.

4.0 PREREQUISITES AND INITIAL CONDITIONS

Check that the following conditions exist:

- 4.1 All applicable equipment listed in Section 3 is available and ready to be used. Verify references listed in Section 2.0 are available for use.
- 4.2 The representative sample of tendons for the surveillance have been selected in accordance with Appendix A and listed on Table 1.
- 4.3 There is adequate access to all tendon end caps that are to be inspected.
- BY DAVCON 4.4 The Preoperational Service and Inspection Checklist and the Load Test Checklist in Appendix B have been completed.
JMH 5-11-85
- 4.5 A testing laboratory has been contracted to perform the filler grease tests and is prepared to receive the grease samples.
- 4.6 Copies of the original stressing cards for the sample tendons are available.
- 4.7 All data sheets are properly completed with the tendon number, location and the last date stressed, anchor head numbers and previous shim thicknesses from the original stressing card.
- BY INRYCO 4.8 All members of work crew are familiar with safety guidelines given in Appendix B.
JMH 5-11-85

5.0 INSTRUCTIONS FOR TENDON INSPECTION

5.1 General

- (a) These instructions are typical for any given hoop, dome or vertical tendon inspection.

- (b) Data results for the tendons inspected shall be documented on the data sheets as applicable.
- (c) If the tendon inspection is not completed during a work shift, the anchorage area and the end caps shall be protected.
- (d) During the testing program, the Test Coordinator shall be immediately notified of any significant defects.

5.2 Prerequisites and Initial Conditions are complete.

gmH / 5-11-85
Initial Date

5.3 Preparation and Inspection

- (a) Position platforms, where required, at each end of the tendon to be inspected.
- (b) Place collector can and/or protective cover under the tendon end cap to protect the adjacent areas from dripping of the sheathing filler.

NOTE: The entire column of grease may drain from a vertical tendon conduit. Sufficient receptacles shall be available to contain the drained grease.

If the grease is to be re-used, take sufficient precaution to prevent contamination.

- (c) Remove the bolts holding the end cap to the bearing plate. End cap must be fully supported as the bolts are being removed. Care should be taken when removing the end cap since the bulk filler may drop off or drip as a medium viscous liquid.
- (d) Remove the end cap and set it down with open end up to help reduce spillage of the bulk filler.
- (e) Visually examine the condition of bulk filler grease. Note any variation in color, signs of moisture, evidence of voids or any other signs of deterioration. Standard of comparison will be fresh

bulk filler grease. Any deterioration of the grease will be noted on Data Sheet 1.

Look for any missing buttonheads in the bulk filler material and document findings.

- (f) Obtain two samples of sheathing filler from each end of the tendon for laboratory examination per section 6.0.
- (g) Remove any remaining bulk filler from tendon anchorage area and clean up by using bristle brushes, solvent and rags as necessary. Care should be taken to neither increase the effects of corrosion nor damage the steel (for instance, scratch it).
- (h) Record the amount of bulk filler grease removed.
- (i) Record the shim thickness and anchor end number as found.
- (j) Inspect the anchorage assembly for any buttonhead problems such as corrosion, missing, broken, damaged or unseated buttonheads, cracks or splits, or improperly formed buttonheads (e.g., double buttonheads). The width of all buttonhead splits shall be measured with a feeler gauge or wire gauge. Document individual buttonheads with splits greater than .12".

Inspect the anchor head, shims and bearing plate for corrosion and cracks.

Document the results on Data Sheets 2, 3a, 3b, 4a - 4b as applicable.

- (k) Visually examine the concrete in the area surrounding the tendon anchorage assembly. Using an optical comparator or feeler gauges, as necessary, measure and record on Data Sheet 2 the width, length and location of any cracks wider than 0.010 inches. Use grid paper as necessary to identify crack patterns and widths.
- (l) Using the criteria in Section 7.3, determine if an inspection of the adjacent tendons is required.

5.4 Tendon Restoration

- (a) Reinstall end caps, using the following steps:
1. Remove the "O" rings from the end caps, clean the end caps and bearing plate surfaces with rags and solvent and wipe dry.
 2. Install new "O" rings and secure them in place to the end cap flanges. Use grease if necessary to hold the "O" rings in the grooves.
 3. Install bolts and tighten. (Use new bolts if required). Exercise caution to minimize or avoid bulk filler spillage. Install washers and nuts, tighten keeping even distribution of pressure on the gaskets.
- (b) The tendon sheathing shall be refilled with sheathing filler. The sheathing filler shall be Viscosity Oil Company Visconorust 2090P-4 or latest compatible formulation.
1. The temperature of the filler in the drum or other heated container shall be between 140°F and 210°F (150°F is recommended). Record actual temperature.
 2. The Test Coordinator shall determine if the filler which has been removed from the tendon may be re-used or if new grease is required. Document which type is used.
 3. If five gallons or more have been removed from each tendon end, filler material shall be replaced by pumping through a hose attached to the grease cap filler plug. All available valves, vents and drains shall be used during this operation to avoid the entrapment of air in the sheath. Pumping shall continue until filler without any air bubbles or visible foreign substances have come out of the outlet or vent farthest from the pump.

4. If less than five gallons of filler have been removed at each tendon end, filler may be replaced by pumping or pouring into each end provided each end is vented to bleed out air.
 5. Record amount of grease replaced.
 6. The elapsed time between removal and replacement of sheathing filler from a tendon shall not exceed three weeks to avoid unnecessary exposure of the anchorage head.
- (c) Move equipment to the next tendon to be inspected.

6.0 SHEATHING FILLER

- (a) The samples of bulk filler taken from the ends of each tendon shall be placed in one-quart, clean containers (care should be taken not to contaminate the sample). Attach an identification tag to each container. One sample from each location will be shipped to the testing laboratory for testing. The samples should be packaged and shipped to prevent physical damage to the container which could result in contamination or loss of identification of the samples.
- (b) Two samples shall also be taken and tested per section 7.1 from each opened drum of fresh bulk filler grease.
- (c) The testing laboratory shall test each sample for chlorides, nitrates, sulphides, moisture content and neutralization number per Section 7.0 and record this information.
- (d) The second sample from each tendon end and drum of fresh bulk filler grease will be kept as a back-up until the test results from the first sample are received and determined by the Test Coordinator to be satisfactory.

7.0 ACCEPTANCE CRITERIA

7.1 Sheathing Filler Testing

Samples of sheathing filler will be taken from each surveillance tendon and each opened drum of fresh bulk filler material for visual and laboratory

examinations. The filler material samples shall be analyzed in accordance with this specification.

If the following criteria are not met, an engineering evaluation shall be conducted to determine if corrective measures are necessary.

- (a) Chlorides (Cl) - 10 ppm max. (5 ppm for new material) when tested in accordance with ASTM D512-67, Procedure for Determination of Water-Soluble Chlorides (Cl).
- (b) Nitrates (NO_3) - 10 ppm max. (5 ppm for new material) when tested in accordance with ASTM D-992 Brucine Method for Determination of Water-Soluble Nitrates (NO_3).
- (c) Sulfides (S) - 10 ppm max. (5 ppm for new material) when tested in accordance with American Public Health Association (APHA) Standard Method 428 for the Determination of Water-Soluble Sulfides (S).
- (d) Water (H_2O) - 10% dry weight max. when tested in accordance with ASTM D-95.
- (e) Neutralization Number - base number greater than zero when tested in accordance with ASTM D-974 modified for Visconnorust 2090 P4. Contact Viscosity Oil Co. for the modified test procedure.

7.2 Corrosion Inspection

- (a) Anchorage assembly components in category a, b or c are acceptable.

Anchorage assembly components in category d, e or f should be further evaluated.

Definitions

1. Pit - a pit is defined as an indentation visible to the naked eye.
2. Degrees of Corrosion
 - a. Bulk filler material intact and bright metal, no visible oxidation.

- b. Metal reddish brown color, no pitting.
- c. Metal having patches of red oxide, removable but ready to start pitting.
- d. Metal having patches of red oxide, not removable and/or leaving noticeable pits.
- e. Metal having heavy rusting, dark red, and about to form an extremely hard crust which, when removed, leaves very noticeable pitting.
- f. Conditions more severe than category (e).

7.3 Missing, Broken and/or Damaged Wires

- (a) Missing, broken and/or damaged wire criteria is based on original quantity of 170 wires per tendon.
- (b) All misshaped (improperly formed) and/or split buttonheads will be evaluated by the Owner or its authorized representative for any possible effect on the wire load-carrying capacity. The misshaped buttonheads and buttonheads with splits greater than .12 inches which are determined to have effect on the load-carrying capacity will be identified as defective buttonheads.
- (c) The discontinuous and missing wires will be treated as ineffective wires for system evaluation. Discontinuous wires will be removed for examination and laboratory testing if conditions are feasible.
- (d) If the total number of discontinuous and missing wires from 7.3.c plus defective buttonheads from 7.3.b exceed 8, the two adjacent tendons will be inspected.

If either adjacent tendon or more than one tendon in the surveillance sample set have more than 8 missing and/or defective buttonheads, an engineering

evaluation shall be conducted to determine if corrective measures are necessary.

8.0 EQUIPMENT REMOVAL AND STORAGE

- 8.1 All equipment will be removed and the area cleaned of any remaining materials.
- 8.2 Equipment will be stored in accordance with the guidelines for storage of equipment given in Appendix B.

9.0 REPORTS

- 9.1 Upon completion of all testing required by this procedure, a final report of the test program shall be prepared. The report shall include, but not be limited to:

- (a) Tendon end anchor inspection results.
- (b) Sheath filler analysis results.

The final report shall be submitted to the Systems Performance Supervisor within 60 days after completion of the testing program.

- 9.2 Failure of a tendon or parts of a tendon to meet the criteria set forth shall be evaluated by the Owner or its authorized representative. If the failure is determined to be an indication of possible abnormal degradation of the containment structure, the tendon shall be reported to the Commission pursuant to Technical Specification 6.9.1. This report shall include a description of the tendon condition, the condition of the concrete (especially at tendon anchorages), the inspection procedure, the tolerances on cracking, and the corrective actions taken.

TABLE 1
 FARLEY NUCLEAR PLANT UNIT 2 CONTAINMENT TENDON SURVEILLANCE
5 YEARS AFTER S.I.T.

TENDON NO.	DATE			ADJACENT TENDON INSPECTION		INITIAL/DATE
	START (5.3.c)	COMPLETE (5.4.a)	GREASE (5.4.b)	YES/NO	TENDON NOS.	
Hoop (Select 10)						
1. 1 DE	5-30-85	5-30-85	5-31-85	No		gmH / 6-13-85
2. 21 DE	5-30-85	5-30-85	6-3-85	No		gmH / 6-13-85
3. 28 DE	5-30-85	5-30-85	6-4-85	No		gmH / 6-13-85
4. 45 DE	5-30-85	5-31-85	6-7-85	No		gmH / 6-13-85
5. 3 EF	5-29-85	5-30-85	5-31-85	No		gmH / 6-13-85
6. 17 EF	5-29-85	5-30-85	5-31-85	No		gmH / 6-13-85
7. 31 EF	5-31-85	6-1-85	6-6-85	No		gmH / 6-13-85
8. 13 FD	5-29-85	5-29-85	5-30-85	No		gmH / 6-13-85
9. 26 FD	5-31-85	6-1-85	6-8-85	No		gmH / 6-13-85
10. 42 FD	5-31-85	5-31-85	6-7-85	No		gmH / 6-13-85
11. 41 EF	ALTERNATE TENDON					
12.						
13.						
14.						
15.						
Dome (Select 6)						
1. D-109 B	6-10-85	6-10-85	6-13-85	No		gmH / 6-13-85
2. D-119 C	6-8-85	6-10-85	6-12-85	No		gmH / 6-13-85
3. D-202 T/B	INACCESSABLE TENDON					
4. D-227 B/T	6-10-85	6-10-85	6-15-85	No		gmH / 6-13-85
5. D-307 T	6-10-85	6-10-85	6-13-85	No		gmH / 6-13-85
6. D-319 C	6-10-85	6-10-85	6-14-85	No		gmH / 6-13-85
7. D-117 C	6-8-85	6-10-85	6-13-85	No		gmH / 6-13-85
Vertical (Select 5)						
1. V-4	5-11-85	5-11-85	5-15-85	No		gmH / 6-13-85
2. V-28	5-11-85	5-11-85	5-11-85	No		gmH / 6-13-85
3. V-52	5-11-85	5-11-85	5-15-85	No		gmH / 6-13-85
4. V-79	5-11-85	5-11-85	5-15-85	No		gmH / 6-13-85
5. V-100	5-11-85	5-11-85	5-13-85	No		gmH / 6-13-85
6. V-124	ALTERNATE TENDON					

DATA SHEET 1

TENDON NO. V-4

SDL 5-11-85

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

SDL 5-11-85
GALLERY DOME

2. Last Date Stressed 3-20-85

3. Anchor End Number from Stressing Card

Field TFH 17

Shop FT 046
KA 062

4. Previous Shim Thickness from Stressing Card

Field 9.0"

Shop 6.9"

5. Remove Tendon End Cap

JMH
3:50 15:30 5/11/85
Initials Time Date

6. Visual Examination of Bulk Filler Grease NEW CLEAN GREASE

COLD PACKED BY INRYCO, GOOD COVERAGE. NO
MOISTURE PRESENT

7. Grease Sample Taken BY INRYCO

JMH 5/11/85
Initial/Date

8. Bulk Filler Removed (Gal). 1/2 GAL ± INRYCO DATA

JMH 5/11/85
Initial/Date

9. Anchor End Number As Found KA 062 / FT 046

JMH 5/11/85
Initial/Date

10. Shim Thickness As Found 6 13/16"

JMH 5/11/85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

JMH 5/11/85
Initial/Date

DATA SHEET 1

TENDON NO. V-4

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

sol 15-11-85
Initial/Date

13. Tendon End Caps Re-installed

JMH 15/11/85
Initial/Date

14. Tendon Re-greasing: BY INRYLO

Date

Data transferred
from procedure SQ 12.6

5/15/85

Temperature of Grease in Bulk Container

171°F

Type Grease (New/Used)

New

If New Grease, Drum No.

Lot No. J-6202

Amount of Grease Replaced (Gal.)

Entire Tendon

JAH 12/7/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. V-4
 FIELD SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

BEARING PLATE

Degree of Corrosion A, B & C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE

ANCHOR HEAD

Number KA062/FT046
 Degree of Corrosion A
 Cracks NONE

SHIMS


Degree of Corrosion A
 Cracks NONE

REMARKS: GOOD TIGHT SHIM

STACK (GAP < 1/4")


GASKET RETAINER PLATE

HAS B & C CORROSION LEVEL.

SKETCH

Date 5/14/85 Signature James M. Hall

ANCHORAGE ASSEMBLY INSPECTION
SHOP END OF TENDON NO. V-4.



TO CONTAINMENT C

Date 5/11/85 Signature James M. Hall

DATA SHEET 40

REV 1

LEGEND FOR BUTTONHEADS

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

JOSEPH M. FARLEY NUCLEAR PLANT UNIT

SHOP END

TENDON


V-4

SIGNATURE

Joseph M. Hall

15/11/85

DATE



COMMENTS:

NO MISSING, UNSEATED OR MISSHAPED BUTTONHEADSNO SPLITS > 0.12"

DATA SHEET 1

TENDON NO. V-4 FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

GALLERY

2. Last Date Stressed 3-20-85

3. Anchor End Number from Stressing Card

Field TFH-17

Shop FT046
KA 062

4. Previous Shim Thickness from Stressing Card

Field 9.0"

Shop 6.9"

5. Remove Tendon End Cap

SDL 1 0940 5-11-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease FILLER HAD GOOD

APPEARANCE (CAN FILLED BY INRYCO ON 3-22-85 UNTIL
FULL GREASING OPERATION) NO MOISTURE, GOOD COVERAGE

SDL 15-11-85
Initial/Date

7. Grease Sample Taken BY INRYCO

SDL 15-11-85
Initial/Date

8. Bulk Filler Removed (Gal). 3 & SEE INRYCO DATA

SDL 15-11-85
Initial/Date

9. Anchor End Number As Found TFH 17

SDL 15-11-85
Initial/Date

10. Shim Thickness As Found

8 15/16"

SDL 15-11-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

SDL 15-11-85
Initial/Date

DATA SHEET 1

TENDON NO. V-4

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SDL / 5-11-85
Initial/Date

13. Tendon End Caps Re-installed

SDL / 5-11-85
Initial/Date

14. Tendon Re-greasing: BY INRYCO

Date

procedure SQ 12.6

(see shop end data)

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

/
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. V-4
 (FIELD/SHOP END (Circle One))

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: 0

Cracks or splits
 Number not
 properly formed: 0

ANCHOR HEAD

Number TFH 17


Degree of Corrosion A

Cracks NONE

SHIMS

Degree of Corrosion "A" WITH SMALL PATCHES OF "B"

Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion "A" WITH "B" & "C"

Cracks NONE

ANCHORAGE AREA CONCRETE


Cracks (width > 0.01 in.)

NONE > 0.01"

REMARKS: ANCHORAGE LOOKS VERY
GOOD, GOOD SHIM GAP, MOST
BEARING PLATE CORROSION ON
OUTSIDE EDGE, NEW RETAINER
PLATE SEEMS TO HAVE BEEN INSTALLED
DURING REPLACEMENT PROGRAM

Date 5-11-95 Signature Steve D. Lowe

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. V-4

Date 5-11-85

Signature

Steven D. Lowe

LEGEND FOR BUTTONHEADS


JOSEPH M. FARLEY NUCLEAR PLANT UNIT

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON

V-4

Steven D. Lowe
SIGNATURE15-11-85
DATE

COMMENTS:

BUTTONHEADS LOOK VERY GOOD

DATA SHEET 1

SOL 5-11-85

TENDON NO. V-28

~~FIELD~~ SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

DOVE

2. Last Date Stressed 3-11-85

3. Anchor End Number from Stressing Card

Field TFF-13

FT-047

Shop KA-149

4. Previous Shim Thickness from Stressing Card

Field 7.35"

Shop 7.9"

5. Remove Tendon End Cap

JMH

Initials

15

13:30

Time

5/11/85

5/11/85

Date

6. Visual Examination of Bulk Filler Grease

CLEAN NEW GREASE

GOOD COVERAGE ON ASSEMBLY, CLEAN GREASE CAN; NO MOISTURE PRESENT

7. Grease Sample Taken BY INRYCO

JMH 5/11/85

Initial/Date

JMH 5/11/85

Initial/Date

8. Bulk Filler Removed (Gal). 1/2 GAL & SEE INRYCO DATA

JMH 5/11/85

Initial/Date

9. Anchor End Number As Found KA 149 / FT 047

JMH 5/11/85

Initial/Date

10. Shim Thickness As Found

7 15/16"

JMH 5/11/85

Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

JMH 5/11/85

Initial/Date

DATA SHEET 1

TENDON NO. V-28

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SDL 15-11-85
Initial/Date

13. Tendon End Caps Re-installed

SMH 15/11/85
Initial/Date

14. Tendon Re-greasing: PER INRYCO

Date Data transferred from
procedure SQ 12.6

5/15/85

Temperature of Grease in Bulk Container

171°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6202

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

SMH 15/7/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. V-28
 FIELD/SHOP END (Circle One)

BUTTONHEAD


Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

ANCHOR HEAD

Number KA149 / FT047
 Degree of Corrosion A / A
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A & B
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE VISABLE - CONCRETE

IS HYPALON COATED.

REMARKS: GREASE SHIMS ADJACENT

TO ANCHORHEAD HAVE BEEN

MACHINED - BRIGHT SHINY METAL

TIGHT SHIM STACK (GAP < 1/4")

TWO GREASE SHIMS

BUSHING FULLY ENGAGED ON

ANCHOR ... GASKET RETAINER


PLATE HAS LEVEL 'B' CORROSION

OVERALL

SOUND; OVERALL, ANCHORAGE

Dates 5/11/85 Signature Wm M. Hall

ANCHORAGE ASSEMBLY INSPECTION
 SHOP END OF TENDON NO. V-28.



↓
 TO G CONTAINMENT

LEGEND FOR BUTTONHEADS


- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

JOSEPH M. FARLEY NUCLEAR PLANT UNIT

SHOP END

TENDON V-28

Joseph M. Hall 15/11/85
 SIGNATURE DATE



COMMENTS:

NO MISSING, UNSEATED OR IMPROPERLY FORMED

BUTTONHEADS : NO SPLITS GREATER THAN 0.12"

DATA SHEET 1

TENDON NO. V-28

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

GALLERY

2. Last Date Stressed 3-11-85

3. Anchor End Number from Stressing Card

Field TFF-13

Shop FT-047
KA-149

4. Previous Shim Thickness from Stressing Card

Field 7.35"

Shop 7.9"

5. Remove Tendon End Cap

SDL 1215 5-11-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease CLEAN, NEW GREASE

IN CAN PER INRYCO 3-15-85 UNTIL FULLY GREASED,
NO MOISTURE, ANCHORAGE WELL COATED

SDL 5-11-85
Initial/Date

7. Grease Sample Taken BY INRYCO

SDL 5-11-85
Initial/Date

8. Bulk Filler Removed (Gal). 1 1/2 & SEE INRYCO DATA

SDL 5-11-85
Initial/Date

9. Anchor End Number As Found

TFF-13

SDL 5-11-85
Initial/Date

10. Shim Thickness As Found

SDL 5-11-85
7.35 7 3/8"

SDL 5-11-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

SDL 5-11-85
Initial/Date

DATA SHEET 1

TENDON NO. V-28

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SDL 15-11-85
Initial/Date

13. Tendon End Caps Re-installed

SDL 15-11-85
Initial/Date

14. Tendon Re-greasing: BY INRYCO
procedure sq 12.6
Date _____

(see shop end data)

Temperature of Grease in Bulk Container _____

Type Grease (New/Used) _____

If New Grease, Drum No. _____

Amount of Grease Replaced (Gal.) _____

/
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. V-28
 (FIELD) SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing
 broken or damaged: 0

Cracks or splits
 Number not
 properly formed: 0

BEARING PLATE

Degree of Corrosion A with B & C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE > 0.01"

ANCHOR HEAD

Number

TFF 13

Degree of Corrosion "A" with very slight "B"

Cracks

NONE

SHIMS

Degree of Corrosion


A

Cracks

NONE


REMARKS: ANCHORAGE LOOKS GOOD,
SHIM GAPS GOOD, "B" CORROSION
ON HEAD IS VERY SLIGHT
AND APPEARS TO HAVE BEEN
PRESENT AT INSTALLATION,
"B" CORROSION IS NOT PROGRESS
GASKET RETAINER PLATE IN
GOOD CONDITION "A" LEVEL
OF CORROSION

SKETCH



Date 5-11-85 Signature Steven D. L...

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. V-28



Date 5-11-85 Signature Steven A. Lowe

LEGEND FOR BUTTONHEADS


JOSEPH M. FARLEY NUCLEAR PLANT UNIT

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON V-28

Steven A. Lane 15-11-89
SIGNATURE DATE



COMMENTS:

FOUND SMALL PIECE OF TAPE - REMOVED ALL
VISIBLE TAPE

DATA SHEET 1

TENDON NO. V-52

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
DOME
2. Last Date Stressed 3-22-85
3. Anchor End Number from Stressing Card
Field HV 042
Shop FL 059
KA 083
4. Previous Shim Thickness from Stressing Card
Field 7.30"
Shop 8.20"
5. Remove Tendon End Cap
SDL 1 1520 1 5-11-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease GOOD NEW GREASE,
ANCHORAGE WELL COATED, CLEAR WATER (X20X) ON BOTTOM
SIDE PUDDLED IN RETAINER PLATE, NO MOISTURE ON ANCHORAGE,
ANCHORAGE HAD BEEN COLD PACKED PER INRYCO
PENDING FULL GREASING, VERY SMALL AMOUNT
OF WATER IN CAN
SDL 1 5-11-85
Initial/Date
7. Grease Sample Taken BY INRYCO
SDL 1 5-11-85
Initial/Date
8. Bulk Filler Removed (Gal). 1/2 & SEE INRYCO DATA
BUSHING KA 083
SDL 1 5-11-85
Initial/Date
9. Anchor End Number As Found ANCHOR FL 059
SDL 5-11-85
BUSHING KA 083
SDL 1 5-11-85
Initial/Date
10. Shim Thickness As Found ANCHOR FL 059 8 1/4"
SDL 1 5-11-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)
Number of Buttonheads: Missing 0
Misshaped 0
Splits > .12" 0
SDL 1 5-11-85
Initial/Date

DATA SHEET 1

TENDON NO. V-52

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SDL 15-11-85
Initial/Date

13. Tendon End Caps Re-installed

SDL 15-11-85
Initial/Date

14. Tendon Re-greasing: BY INRYCO

Date

Data transferred from
procedure SQ 12.65/15/85

Temperature of Grease in Bulk Container

171°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6202

Amount of Grease Replaced (Gal.)

ENTIRE TENDONDBN 15/7/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. V-52
 FIELD SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion
 Number missing,
 broken or damaged:

A

Cracks or splits
 Number not
 properly formed:

00

ANCHOR HEAD

Number

KA 083
 FL 059

Degree of Corrosion

A


Cracks

NONE

SHIMS

Degree of Corrosion "A" WITH SOME "B"

Cracks

NONESKETCH

BEARING PLATE

Degree of Corrosion "A", "B", "C" ^{ONE SPOT} _{OF "C"}

Cracks

NONE

ANCHORAGE AREA CONCRETE


Cracks (width > 0.01 in.)

NONE > 0.01" VISIBLE

REMARKS: ANCHORAGE LOOKS GOOD,
GOOD SHIM GAP, "B" CORROSION
SEEMS TO HAVE BEEN TRANSFERRED
FROM RETAINER PLATE TO THE BEARING
PLATE & CAN BE SCRAPPED OFF
WITH A SCREW DRIVER, "B" CORROSION
HAS NOT PENETRATED PAINT, CORROSION
ON SHIMS DOES NOT APPEAR PRO-
GRESSIVE IN NATURE, CORROSION
ON BOTTOM SIDE OF RETAINER
PLATE IS GENERALLY "D"

Date 5-11-85 signature Steven D. Lowe

ANCHORAGE ASSEMBLY INSPECTION
 SEOP END OF TENDON NO. V-S2.



TOWARDS
 &
 CTMT

Date 5-11-85 Signature Steven A. Lowe

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

● Missing Buttonhead or Wire


○ Unseated Buttonhead

⊗ Improperly Formed/Misshaped
Buttonhead○ Buttonhead with Split
(Document the Split Size)

SHOP END

TENDON

V-52

Steven D. Lowe 15-11-85
SIGNATURE DATE

COMMENTS:

No Splits > 0.12"

DATA SHEET 1

TENDON NO. V-52

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

GALLERY

2. Last Date Stressed 3-22-85

3. Anchor End Number from Stressing Card

Field HV 042

Shop FU 059
KA 083

4. Previous Shim Thickness from Stressing Card

Field 7.30"

Shop FU SOL 5-11-85
8.20"

5. Remove Tendon End Cap

JMH 11:15 15/11/85
Initials Time Date

6. Visual Examination of Bulk Filler Grease NEW, CLEAN

GREASE IN CAN, NO MOISTURE, BROWN GREASE

FLOWING FROM SHIMS ... NO MOISTURE; GOOD CONSISTENCY

JMH 15/11/85
Initial/Date

7. Grease Sample Taken PER INRYCO

JMH 15/11/85
Initial/Date

8. Bulk Filler Removed (Gal). 4 1/2 & SEE INRYCO DATA

JMH 15/11/84
Initial/Date

9. Anchor End Number As Found HV 042

JMH 15/11/85
Initial/Date

10. Shim Thickness As Found 7 3/16

JMH 15/11/85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

1

Misshaped

0

Splits > .12"

0

JMH 15/11/85
Initial/Date

DATA SHEET 1

TENDON NO. V-52

FIELD SHCP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SOL 15-11-85
Initial/Date

13. Tendon End Caps Re-installed

SM 15/11/85
Initial/Date

14. Tendon Re-greasing: PER INRYCO
Date procedure SQ126

(see shop end data)

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. V-52
 (FIELD) SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
~~Number missing,~~
 broken or damaged: 1
 Cracks or splits
 Number not
 properly formed: 0

BEARING PLATE

Degree of Corrosion A & B
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE

ANCHOR HEAD

Number HV 042
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

REMARKS: TWO GREASE SHIMS

BUTTONHEADS IN GOOD SHAPE


(VERY FEW SLIPS OBSERVED... NOT

RECORDABLE) ANCHORHEAD RECENTLY

GLASS BLASTED... SHINY NEW APPEARANCE


GASKET RETAINER PLATE HAS

'A' TYPE CORROSION

SKETCH

Date 5/11/85 Signature Joseph M. Hall

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. V-52



Date 5/11/85 Signature Joseph M. Hall

LEGEND FOR BUTTONHEADS


- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

JOSEPH M. FARLEY NUCLEAR PLANT UNIT

FIELD END

TENDON V-52

Joseph M. Hall 15/11/85
SIGNATURE DATE



COMMENTS:

ONE MISSING BUTTONHEAD ... OVERALL BUTTONHEAD
APPEARANCE IS ABOVE AVERAGE (BRIGHT SHINY METAL)

DATA SHEET 1

TENDON NO. V-79

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

DOME

2. Last Date Stressed 4-8-85

3. Anchor End Number from Stressing Card

Field HP-095

FU 060

Shop HW 116

4. Previous Shim Thickness from Stressing Card

Field 6.4"

Shop 8.4"

5. Remove Tendon End Cap

mmH 1500 15/11/85
Initials Time Date

6. Visual Examination of Bulk Filler Grease NEW, COLD PACIC GREASE

BY INRYCO, GREASE CAN CLEAN WITH NO
MOISTURE PRESENT

7. Grease Sample Taken BY INRYCO

mmH 15/11/85
Initial/Date

8. Bulk Filler Removed (Gal). 1/2 GAL & INRYCO DATA

mmH 15/11/85
Initial/Date

9. Anchor End Number As Found HW116 / FU 060

mmH 15/11/85
Initial/Date

10. Shim Thickness As Found 8 3/8"

mmH 15/11/85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

mmH 15/11/85
Initial/Date

DATA SHEET 1

TENDON NO. V-79

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SD 15-11-85
Initial/Date

13. Tendon End Caps Re-installed

JMH 15/11/85
Initial/Date

14. Tendon Re-greasing:

Date

BY INRYCO
Data transferred from
procedure SQ 12.6

5/15/85

Temperature of Grease in Bulk Container

171°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6202

Amount of Grease Replaced (Gal.)

ENTIRE Tendon

SD 15/12/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. V-79
FIELD/SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
Number missing,
broken or damaged: 0
Cracks or splits
Number not
properly formed: 0


BEARING PLATE

Degree of Corrosion A & B
Cracks NONEANCHORAGE AREA CONCRETE
Cracks (width > 0.01 in.)NONE VISABLE - HYPALONCOATING ON CONCRETE


ANCHOR HEAD

Number HW116/FU060
Degree of Corrosion A
Cracks NONE

SHIMS

Degree of Corrosion A WITH SMALL B
Cracks NONEREMARKS: GOOD SHIM STACK GAP(2 1/4") BUSHING FULLY ENGAGEDGASKET RETAINER PL HASOVERALL 'D' TYPE CORROSIONLEVELSKETCHDate 5/11/85 Signature Carl M. Hall

ANCHORAGE ASSEMBLY INSPECTION
 SHOP END OF TENDON NO. V-79.



LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT


- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

SHOP END

TENDON V-79

SIGNATURE

DATE



COMMENTS:

1 SPLIT \approx 0.11" WIDE $<$ 0.12" \therefore O.K.

DATA SHEET 1

TENDON NO. V-79

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

GALLERY

2. Last Date Stressed 4-8-85

3. Anchor End Number from Stressing Card

Field HP-095

Shop FU-060
HW-116

4. Previous Shim Thickness from Stressing Card

Field 6.4"

Shop 8.4"

5. Remove Tendon End Cap

SDL 1 1100 1 5-11-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease CLEAN, TAN WITH

SOME BLACK GREASE, NO MOISTURE, GREASE CAN FILLED

BY INRYCO UNTIL FULL GREASING PGM. IMPLEMENTED
GOOD COVERAGE

SDL 15-11-85
Initial/Date

7. Grease Sample Taken BY INRYCO

SDL 15-11-85
Initial/Date

8. Bulk Filler Removed (Gal). 1/2 & SEE INRYCO DATA

SDL 15-11-85
Initial/Date

9. Anchor End Number As Found

HP 095

SDL 15-11-85
Initial/Date

10. Shim Thickness As Found

6 7/16"

SDL 15-11-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

1

Splits > .12"

0

SDL 15-11-85
Initial/Date

DATA SHEET 1

TENDON NO. V-79

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SDL 15-11-85
Initial/Date

13. Tendon End Caps Re-installed

SDL 15-11-85
Initial/Date

14. Tendon Re-greasing: BY INRYCO

Date

procedure SQ 12.6

(see shop end data)

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. V-79
 (FIELD/SHOP END (Circle One))

BUTTONHEAD

Degree of Corrosion A
 Number missing
 broken or damaged: 0

Cracks or splits
 Number not
 properly formed: 1

BEARING PLATE

Degree of Corrosion A WITH SMALL
AMOUNTS OF BEC

Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE > 0.01"

ANCHOR HEAD

Number HP 095


Degree of Corrosion A

Cracks NONE

SHIMS

Degree of Corrosion A


Cracks NONE

SKETCH

REMARKS: ANCHORAGE LOOKS
VERY GOOD, GOOD SHIM GAPS.
RETAINER PLATE IN GOOD
CONDITION HAS "A" WITH
SLIGHT "B" CORROSION

Date 5-11-85 Signature Steven A. Lowe

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. V-79



Date 5-11-85 Signature Steven D. Lowe

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT


- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON V-79

SIGNATURE

DATE



COMMENTS:

1 DOUBLE BUTTONHEAD H-4 (SEATED)

DATA SHEET 1

TENDON NO. V-100

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

DOME

2. Last Date Stressed 3-19-85

3. Anchor End Number from Stressing Card

Field TCBC-11

FD-142

Shop KA-069

4. Previous Shim Thickness from Stressing Card

Field 10.85"

Shop 4.3"

5. Remove Tendon End Cap

SDL 1 1440 5-11-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease GOOD NEW GREASE,
ONLY COLD COATING PER INRYCO, NO MOISTURE,
ANCHORAGE WELL COATED

SDL 15-11-85
Initial/Date

7. Grease Sample Taken BY INRYCO

SDL 15-11-85
Initial/Date

8. Bulk Filler Removed (Gal). 1/2 & SEE INRYCO DATA

SDL 15-11-85
Initial/Date

BUSHING KA 069

9. Anchor End Number As Found ANCHOR FD 142

SDL 15-11-85
Initial/Date

10. Shim Thickness As Found

4 5/16"

SDL 15-11-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

SDL 15-11-85
Initial/Date

DATA SHEET 1

TENDON NO. V-100

FIELD (SHOP END) (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SDL / 5-11-85
Initial/Date

13. Tendon End Caps Re-installed

SDL / 5-11-85
Initial/Date

14. Tendon Re-greasing: BY INRYCO

Date

Data transferred from
procedure SQ 12.6

5/13/85

Temperature of Grease in Bulk Container

165°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-5928

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

SDH / 5/17/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. V-100
 FIELD/SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion
 Number missing,
 broken or damaged:

0

Cracks or splits
 Number not
 properly formed:

0

ANCHOR HEAD

Number

KA 069
FD142

Degree of Corrosion

A

Cracks

NONE


SHIMS

Degree of Corrosion

"A" with some
"B"

Cracks

NONE

SKETCH

BEARING PLATE

Degree of Corrosion

"A" with
one "C" AREA

Cracks

NONE

ANCHORAGE AREA CONCRETE


Cracks (width > 0.01 in.)

NONE > 0.01" VISIBLE

REMARKS: ANCHORAGE LOOKS GOOD,
 SHIM GAP GOOD, "B" CORROSION
 ON SHIMS APPEARS TO HAVE
 BEEN PRESENT AT INSTALLATION
 NOT PROGRESSIVE, "C" CORROSION
 ON BEARING PLATE IS UNDER
 GASKET RETAINER PLATE, BEARING
 PLATE LOOK GOOD INSIDE PLATE
 WITH ONLY "A" CORROSION LEVEL
 PRESENT, GASKET RETAINER
 PLATE VERY CORRODED ON
 BOTTOM SIDE, TOP "A" WITH
 SOME "B"

Date 5-11-85 Signature Steven D. Lowe

ANCHORAGE ASSEMBLY INSPECTION
SHOP END OF TENDON NO. V-10.0



TOWARDS

C TMT

Date 5-11-85 Signature Steven D. Lowe
DATA SHEET 4a DEVI 1

LEGEND FOR BUTTONHEADS


JOSEPH M. FARLEY NUCLEAR PLANT UNIT

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

SHOP END

TENDON

V-100

Steven D. Lowe
SIGNATURE15-11-85
DATE

COMMENTS:

Several splits but none > 0.12"

DATA SHEET 1

TENDON NO. V-100

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

GALLERY

2. Last Date Stressed 3-19-85

3. Anchor End Number from Stressing Card

Field TC BC-11

FD-142

Shop KA-069

4. Previous Shim Thickness from Stressing Card

Field 10.85"

Shop 4.3"

5. Remove Tendon End Cap

gmH

10:30

Time

5-11-85

Date

6. Visual Examination of Bulk Filler Grease CLEAN, NEW

GREASE, NO MOISTURE FOUND, GOOD CONSISTENCY

7. Grease Sample Taken PER INRYCO

gmH / 5-11-85
Initial/Date

8. Bulk Filler Removed (Gal). 6 1/2 & INRYCO DATA

gmH / 5-11-85
Initial/Date

9. Anchor End Number As Found

TC-BB 11

gmH 5-11-85

gmH / 5-11-85
Initial/Date

10. Shim Thickness As Found

10 3/4"

gmH / 5-11-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

1

Splits > .12"

0

gmH / 5-11-85
Initial/Date

DATA SHEET 1

TENDON NO. V-100

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SD 15-11-85
Initial/Date

13. Tendon End Caps Re-installed

SD 15-11-85
Initial/Date

14. Tendon Re-greasing: BY INRYCO
Date procedure sq 12.6

(see shop end data)

Temperature of Grease in Bulk Container _____

Type Grease (New/Used) _____

If New Grease, Drum No. _____

Amount of Grease Replaced (Gal.) _____

/
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. V-100
 (FIELD) / SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing
 broken or damaged: 0

Cracks or splits
 Number not
 properly formed: 1

BEARING PLATE

Degree of Corrosion A & B

Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE FOUND

ANCHOR HEAD

Number TC-BC-11

Degree of Corrosion A

Cracks NONE

SHIMS

Degree of Corrosion A

Cracks NONE

REMARKS:

END ANCHORAGE IN GOOD

CONDITION, GASKET RETAINER


PLATE HAS 'A' TYPE CORROSION

LEVEL — 4 GREASE SHIMS

IN SHIM STACK ... SHIM STACK


GAP < 1/4" ON BOTH SIDES ADJACENT

TO ANCHORHEAD.

SKETCH

Date 5-11-85 Signature J. M. Hall

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. V-100



Date 5-11-85 Signature Samuel M. Hall

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT


- Missing Buttonhead or Wire
- ⊘ Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON

V-100

Joseph M. Hall 15-11-85
SIGNATURE DATE



COMMENTS:

1 DOUBLE BUTTONHEAD (SEATED)

DATA SHEET 1

TENDON NO. 1 DE

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "E"

2. Last Date Stressed 11-15-76

3. Anchor End Number from Stressing Card

Field HP 103

Shop KA 028

4. Previous Shim Thickness from Stressing Card

Field 11"

Shop 11 3/4"

5. Remove Tendon End Cap

LNS / 0900 / 5-30-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease NO APPARENT

FREE MOISTURE, BROWN COLOR - SMALL AMT. BLACK

PRESERVATIVE, GOOD CONSISTENCY, GOOD COVERAGE

LNS / 5-30-85
Initial/Date

7. Grease Sample Taken

5-30-85

LNS / 5-30-85
Initial/Date

8. Bulk Filler Removed (Gal).

LNS
46 gal.

LNS / 5-30-85
Initial/Date

9. Anchor End Number As Found

GT 081
KA 028 BUSH.

LNS / 5-30-85
Initial/Date

10. Shim Thickness As Found

11 7/8"

LNS / 5-30-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

NONE

Misshaped

NONE

Splits > .12"

NONE

LNS / 5-30-85
Initial/Date

DATA SHEET 1

TENDON NO. 1 DE

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LNS / 5-30-85
Initial/Date

13. Tendon End Caps Re-installed

LNS / 5-30-85
Initial/Date

14. Tendon Re-greasing: PER INR4LO

Date

*Data transferred from
procedure SQ 12.7*

5/31/85

Temperature of Grease in Bulk Container

220°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-5526

Amount of Grease Replaced (Gal.)

ENTIRE Tendon

LNS / 5-30-85
Initial/Date
DBH 8/7/85

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 1 DE
 FIELD (SHOP END) (Circle One)

BUTTONHEAD


Degree of Corrosion A
 Number missing,
 broken or damaged: NONE
 Cracks or splits
 Number not
 properly formed: NONE

ANCHOR HEAD

Number GT081
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A & B
 Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion B+C
 Cracks NONE
 ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)
NONE


REMARKS:

MUCH OF BEARING PLATE CORROSION
APPEARS TO BE TRANSFERRED
FROM METAL RETAINER GASKET

APPROX. 3/8" GAP BETWEEN
HALVES OF 2 PAIRS 4" SHIMS
ON OUTSIDE

Date 5-10-85 Signature J. T. Shann

ANCHORAGE ASSEMBLY INSPECTION
SEOP END OF TENDON NO. IDE



Date 5.20.85 Signature [Signature]

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT


- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

SHOP END

TENDON 106

SIGNATURE

DATE

J. J. [Signature] 15-30-25

COMMENTS:

TENDON STRESSING CARD

TENDON LOCATION H

JOB NO. 211-505

DATE 11-15-76

DO NOT EXCEED 80% OF ULT

7602 KIPS 7600 PSI

LINES IN PARENTHESES () FOR STAGE STRESSING ONLY

JACK NO. 5

GAUGE NO. 34

END

JACK NO. 22

GAUGE NO. 22

END

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 2000 PSI 500 PSI

1500

6.30

1500

7.00

2. PRIOR TO STRESSING

1000

12.30

1000

10.20

3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION)

4100

4.00

4000

3.20

4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2)

4100

4.30

4000

6.00

5. (NEW LIFT OFF - SAME PSI AS LINE 3)

—

—

—

—

6. (FULL RAM EXTENSION)

—

—

—

—

7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 3)

—

—

—

—

8. (NEW LIFT OFF - SAME PSI AS LINE 6)

—

—

—

—

9. OVERSTRESS 7602 KIPS 7600 PSI

7600

9.00

7600

9.00

10. TOTAL MEASURED ELONGATION (4+7+9)
(LINE 9 MINUS LINE 2 (9-8+7+6))

870

8.10

870

8.10

11. LOCKOFF 7602 KIPS 6970 PSI TO 6970 PSI

6970

6.80

6800

6.80

REMARKS RESTRESSED REPAIR NCR 505-FIR

SHIMS 11 3/4"

SHIMS 11"

FLD. HEAD KA028

BUSHING 10mm

FOREMAN J. M. J. J. J.

BKG. PLATE FC

BKG. PLATE FC

Q.C. INSPECTOR C. J. J.

DATE 11-15-76

TENDON END PROTECTED OK

TENDON END PROTECTED OK

0 5 2 2 4 2 0 5 0

TENDON BUTTON HEADING CARD

TENDON LOCATION: _____

IED

DATE: _____

11-3-76

INSPECTION

ACCEPTABLE
(CHECK)

REJECTABLE

1090
GO; NO-GO

(OK) 17

SPLITS

(OK) 170

ECCENTRICITY

(OK) 170

TOTAL UNACCEPTABLE HEADS

0

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ☒

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK)

NA

COMMENTS

HP103

FOREMAN

[Signature]

C.C. INSPECTOR

[Signature]

DATE 11-3-76

DATA SHEET 1

TENDON NO. 1 DE

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "D"

2. Last Date Stressed 11-15-76

3. Anchor End Number from Stressing Card

Field HP 103

Shop KA 028

4. Previous Shim Thickness from Stressing Card

Field 11"

Shop 11 3/4"

5. Remove Tendon End Cap

MMH
Initials

13:56
Time

5/29/85
Date

6. Visual Examination of Bulk Filler Grease

Clean GREASE

CAN - ANCHORHEAD COLD PACKED PER INRYCO

NO MOISTURE DETECTED

7. Grease Sample Taken

SEE INRYCO DATA
NO SAMPLE AVAILABLE
FROM CAN

MMH 5/29/85
Initial/Date

MMH 5/29/85
Initial/Date

8. Bulk Filler Removed (Gal).

0

MMH 5/29/85
Initial/Date

9. Anchor End Number As Found

HP 103

MMH 5/29/85
Initial/Date

10. Shim Thickness As Found

10.9"

MMH 5/29/85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

MMH 5/29/85
Initial/Date

DATA SHEET 1

TENDON NO. IDE

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

JMH 15/29/85
Initial/Date

13. Tendon End Caps Re-installed

JMH 15/29/85
Initial/Date

14. Tendon Re-greasing: PER INRYCO
Date Data transferred from
procedure SA 12.7

Temperature of Grease in Bulk Container

5/30/85

Type Grease (New/Used)

180°F

If New Grease, Drum No.

NEW

Amount of Grease Replaced (Gal.)

LOT NO. 5-5526

ENTIRE TENDON

JAH 15/27/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 1 DE
 (FIELD/SHOP END (Circle One))

BUTTONHEAD


Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

ANCHOR HEAD

Number HP103
 Degree of Corrosion A & B
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NO CRACKS VISIBLE...

PAINTED SURFACE... NO

CRACKING OR PEELING OF PAINT
IN AREA


REMARKS: ANCHORAGE FOUND "COR"

PACKED" BY INEYCO

LEVEL "A" CORROSION ON GASKET

RETAINER PLATE -

Date 5/29/85 Signature J. M. Hall

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. 1 DE

LEVEL 'B' CORROSION & WATER SPOTS ON ANCHORAGE HEAD
FACE.

Date 5/29/85 Signature Joseph M. Hall

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

● Missing Buttonhead or Wire

Ø Unseated Buttonhead

✗ Improperly Formed/Misshaped
Buttonhead① Buttonhead with Split
(Document the Split Size)


FIELD END

TENDON

1 DE

SIGNATURE

DATE

Joseph M. Hall 12/29/85

COMMENTS:

↓ UP

BUTTONHEADS HAVE SHINY NEW APPEARANCE

No SPLITS > 0.12"

DATA SHEET 1

TENDON NO. 21 DE

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
BUTTRESS "E"
2. Last Date Stressed 11-23-76
3. Anchor End Number from Stressing Card
Field HP 093
Shop KA 049
4. Previous Shim Thickness from Stressing Card
Field 1 3/4"
Shop 13"
5. Remove Tendon End Cap

LNS
5-30-85
1330
Initials

1330
Time

5-30-85
Date
6. Visual Examination of Bulk Filler Grease NO APPARENT FREE WATER,
LIGHT BROWN & GOOD CONSISTENCY
80% COVERAGE
7. Grease Sample Taken

LNS 15-30-85
Initial/Date
8. Bulk Filler Removed (Gal). 7 1/2 Gal.

LNS 15-30-85
Initial/Date
9. Anchor End Number As Found GL 048
Bushing KA 049

LNS 15-30-85
Initial/Date
10. Shim Thickness As Found 1 5/8"

LNS 15-30-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:	Missing	<u>NONE</u>
	Misshaped	<u>NONE</u>
	Splits > .12"	<u>NONE</u>

LNS 15-30-85
Initial/Date

DATA SHEET 1

TENDON NO. 21 DE

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LN3 / 5-30-85
Initial/Date

13. Tendon End Caps Re-installed

LN3 / 5-30-85
Initial/Date

14. Tendon Re-greasing: PER INRYCO

Date

LN3

5-30-85

*Data transferred
from SQ 12.7*

6/3/85

Temperature of Grease in Bulk Container

193 °F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-5526

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

SAH / 8/7/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 21 DE
 FIELD/SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: NONE
 Cracks or splits
 Number not
 properly formed: NONE

ANCHOR HEAD

Number GLO48
 Degree of Corrosion A
 Cracks NONE

SHIMS


Degree of Corrosion A & B
 Cracks NONE

BEARING PLATE

Degree of Corrosion A, B & C
 Cracks NONE


ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)
NONE

REMARKS: SOME OF CORROSION ON
BEARING plate transferred
FROM the RETAINER plate

SKETCH

Date 5-30-85 Signature J. J. Jones

ANCEORAGE ASSEMBLY INSPECTION
 SEOP END OF TENDON NO. 21 DE



LEGEND FOR BUTTONHEADS


- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

JOSEPH M. FARLEY NUCLEAR PLANT UNIT

SHOP END

TENDON 21 DE

J. J. D. [Signature] 15-30-85
SIGNATURE DATE



COMMENTS:

05225 0029
TENDON STRESSING CARD

DATE 11-23-77

TENDON LOCATION H 210E JOB NO. 717-405 JOBS CARLEY UNIT #2

DO NOT EXCEED 80% OF ULT
1602 KIPS 7600 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 5
GAUGE NO. 24
END

JACK NO. 1
GAUGE NO. 22
END

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 2000 PSI 500 PSI	1500	7.5	1500	7.5
2. PRIOR TO STRESSING	1500	6.10	1500	7.30
3. 3600 TO 4000 PSI (OR FULL RAM EXTENSION)	3500	8.90	3500	10.00
4. (MEASURED 1ST STAGE ELONGATION) (LINE 3 MINUS LINE 2)	3500	2.80	3500	2.70
5. (NEW LIFT OFF - SAME PSI AS LINE 3)	3500	7.80	3500	4.30
6. (FULL RAM EXTENSION)				
7. (MEASURED 2ND STAGE ELONGATION) (LINE 6 MINUS LINE 5)				
8. (NEW LIFT OFF - SAME PSI AS LINE 6)				
9. OVERSTRESS 1602 KIPS 7600 PSI	7600	9.00	7600	10.50
10. TOTAL MEASURED ELONGATION (4+7+9) (LINE 9 MINUS LINE 2 (9-6+7+4))		8.00		9.40
11. LOCKOFF 1402 KIPS 6970 PSI	6860		6900	

REMARKS

SHIMS 11 3/4"

SHIMS 13"

F.L.D. HEAD HP 93

BUSHING 59249

FOREMAN DW Hel

BKG. PLATE NONE

BKG. PLATE NONE

O.C. INSPECTOR C. J. Bass

TENDON END PROTECTED OK

TENDON END PROTECTED OK

DATE 11-23-77

FORM 780.67-40 APRIL 1975 REVISED BY INLAND STEEL COMPANY

NOTE: COMPUTE ITEM 10 AS FOLLOWS:

1ST STAGE (11-14-5) 2ND STAGE (14-7+9)

05224 2070

TENDON BUTTON HEADING CARD

JOB NO:

21705

JOB:

HARLEY UNIT 2

TENDON LOCATION:

2150

DATE:

10-28-76

INSPECTION

ACCEPTABLE
(CHECK)

REJECTABLE

1090
GO; NO-GO

(OK) 17

SPLITS

(OK) 170

ECCENTRICITY

(OK) 170

TOTAL UNACCEPTABLE HEADS

0

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ☒

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK)

NA

COMMENTS

HPO 93

FOREMAN

B. J. [Signature]

Q.C. INSPECTOR

Bobby [Signature]

DATE

10-28-76

FORM 780.65-60

APRIL 1975

INRYCO an INLAND STEEL company

DATA SHEET 1

TENDON NO. 21 DEFIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "D"

2. Last Date Stressed
- 11-23-76

3. Anchor End Number from Stressing Card

Field HP093Shop KA 049

4. Previous Shim Thickness from Stressing Card

Field 1 3/4"Shop 13"

5. Remove Tendon End Cap

JMH 14:32 pm 5/29/85
Initials Time Date

6. Visual Examination of Bulk Filler Grease
- DARK BROWN

GOOD CONSISTENCY, NO MOISTURE IN CAN.GOOD FULL COVERAGE ON ASSEMBLY

7. Grease Sample Taken

JMH 5/29/85
Initial/Date

8. Bulk Filler Removed (Gal).
- 4 1/2 GAL

JMH 5/29/85
Initial/Date

9. Anchor End Number As Found
- HP093

JMH 5/29/85
Initial/Date

10. Shim Thickness As Found
- 12.9"

JMH 5/29/85
Initial/DateJMH 5/29/85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0JMH 5/29/85
Initial/Date

DATA SHEET 1

TENDON NO. 21 DE

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

DMH 1 5/29/85
Initial/Date

13. Tendon End Caps Re-installed

DMH 1 5/29/85
Initial/Date

14. Tendon Re-greasing: BY INRYCO

Date

Data transferred from
procedure SQ 12.7

5/30/85

Temperature of Grease in Bulk Container

190°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-5526

Amount of Grease Replaced (Gal.)

Entire Tendon

DBH 1 8/7/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 21 DE
 FIELD/SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion
 Number missing,
 broken or damaged:

A0

Cracks or splits
 Number not
 properly formed:

00

ANCHOR HEAD

Number

HP093

Degree of Corrosion

A w/B

Cracks


NONE

SHIMS

Degree of Corrosion

A

Cracks

NONESKETCH

BEARING PLATE

Degree of Corrosion

A w/B

Cracks


NONE

ANCHORAGE AREA CONCRETE

Cracks (width > 0.01 in.)

NONE VISIBLE - PAINTEDSURFACE WITH NO CRACKINGOR PEELING OF PAINT.REMARKS: SHIM STACK LOOKSGOOD, GAP $\leq \frac{1}{4}$ " ON BOTHSIDES. WATER SPOTS? TURNED TO"B" LEVEL OF CORROSION ON ANCHORHEADGASKET. RETAINER PLATE HASMOSTLY B LEVEL WITH A.Date 5/29/55 Signature Empl M. J. L.

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. 21 DE



SPOTTY PATCHES OF 'B' ON ANCHORHEAD FACE

Date 5/29/85 Signature James M. Hall

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT


- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON

21 DE

SIGNATURE

Joseph M. Farley 5/21/85
DA

COMMENTS:

NO SPLITS OR SLIPS, MISSING OR UNSEATED

BUTTONHEADS OUTSIDE OF ACCEPTANCE LIMITS

BUTTONHEADS ~~WILL~~ HAVE NEW SHINY APPEARANCE

DATA SHEET 1

TENDON NO. 28 DE

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "D" "E" LNS 5-30-85

2. Last Date Stressed 5-12-77

3. Anchor End Number from Stressing Card

Field LS 013

Shop LG 031

4. Previous Shim Thickness from Stressing Card

Field 13"

Shop 11 1/8"

5. Remove Tendon End Cap

LNS 11450 5-30-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease NO APPARENT FREE MOISTURE,

GOOD CONSISTENCY, LIGHT BROWN, GOOD (100%) COVERAGE

LNS 5-30-85
Initial/Date

7. Grease Sample Taken

LNS 5-30-85
Initial/Date

8. Bulk Filler-Removed (Gal). 6 Gal.

LNS 5-30-85
Initial/Date

9. Anchor End Number As Found

GT 066
Buttress LG 031

LNS 5-30-85
Initial/Date

10. Shim Thickness As Found

11 1/8"

LNS 5-30-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

NONE

Misshaped

NONE

Splits > .12"

NONE

LNS 5-30-85
Initial/Date

DATA SHEET 1

TENDON NO. 28 DE

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LN3 / 5-30-85
Initial/Date

13. Tendon End Caps Re-installed

LN3 / 5-30-85
Initial/Date

14. Tendon Re-greasing:

Date

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

*Per INR400
5-30-85
LN3*
*Data transferred
from procedure
SQ 12.7*

6/4/85

180 °F

NEW

LOT NO. 5-6359

ENTIRE TENDON

DBH / 8/7/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 28 DE
 FIELD (SHOP END) (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: NONE
 Cracks or splits NONE
 Number not
 properly formed: NONE

ANCHOR HEAD

Number GT 066
 Degree of Corrosion A
 Cracks NONE

SEIMS


Degree of Corrosion A & B
 Cracks NONE

BEARING PLATE

Degree of Corrosion A, B & C
 Cracks NONE


ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)
NONE

REMARKS: SOME CORROSION ON
BEARING PLATE FROM RETAINED
PLATE

SKETCH

Date 5-30-85 Signature J. J. Kanner

ANCHORAGE ASSEMBLY INSPECTION
 SEOP END OF TENDON NO. 28 DE



JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2


LEGEND FOR BUTTONHEADS

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with-Split
(Document the Split Size)

SHOP END

TENDON 28 DE

J. J. [Signature] 15-30-85
SIGNATURE DATE



COMMENTS:

05225 0030 TENDON STRESSING CARD

DATE 5-12-77

TENDON LOCATION H 2805 JOB NO 211-505 JOB BARREY UNIT 32

DO NOT EXCEED 80% OF ULT
1602 KIPS 7600 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 1
GAUGE NO. 12
END

JACK NO. 12
GAUGE NO. 12
END

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 2008 PSI 500 PSI 8.75
2. PRIOR TO STRESSING 1500 6.10 1500 7.70
3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION) 3500 8.30 3500 9.10
4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2) 3500 7.70 3500 8.00
5. (NEW LIFT OFF - SAME PSI AS LINE 3) 3500 4.00 3500 4.70
6. (FULL RAM EXTENSION) — — — —
7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5) — — — —
8. (NEW LIFT OFF - SAME PSI AS LINE 6) — — — —
9. OVERSTRESS 1602 KIPS 7600 PSI 7600 9.50 7600 10.30
10. TOTAL MEASURED ELONGATION (4+7+8)
LINE 9 MINUS LINE 2 (9-0+7+8) 6931 8.20 6700 8.40
11. LOCKOFF 1602 KIPS 6646 PSI TO 6700 PSI 6700

REMARKS

SHIMS 11 1/2"

SHIMS 13

BRG. PLATE 46031

BRG. PLATE 46031

FOREMAN Fred Fisher

BRG. PLATE NAME

BRG. PLATE NAME

Q.C. INSPECTOR C. J. Beebe

DATE 5-12-77

TENDON END PROTECTED ok

TENDON END PROTECTED ok

FORM 780.67-40 APRIL 1975 INVENTED BY INLAND STEEL COMPANY

* NOTE: COMPLETE ITEM 10 AS FOLLOWS:

STAGE (4+7+8) 320 STAGE (4+7+8+9)

05224 2085

TENDON BUTTON HEADING CARD

JOB NO.

217

JOB

FARLEY UNIT 2

TENDON LOCATION:

29FD

DATE:

3-21-77

INSPECTION

ACCEPTABLE
(CHECK)

REJECTABLE

GO; NO-GO

(OK) 168

2

SPLITS

(OK) 170

0

ECCENTRICITY

(OK) 170

0

TOTAL UNACCEPTABLE HEADS

2

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK)

✓

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK)

N/A

COMMENTS

LS 013 Two (2) double heads

FOREMAN

Paul Linph

Q.C. INSPECTOR

P. J. Beale

DATE

3-21-77

DATA SHEET 1

TENDON NO. 28 DEFIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTRESS "D" ^{LNS} 5-31-85

2. Last Date Stressed
- 5-12-77

3. Anchor End Number from Stressing Card

Field LS 013Shop LG 031

4. Previous Shim Thickness from Stressing Card

Field 13"Shop 11 1/8"

5. Remove Tendon End Cap

LNS1030^{LNS} 6-1-85

Initials

Time

Date

6. Visual Examination of Bulk Filler Grease
- DARK BROWN with

5m. amt. of BLACK PRESERVATIVE, NO apparent moisture,
100% coverageLNS 16-1-85
Initial/Date

7. Grease Sample Taken

LNS 16-1-85
Initial/Date

8. Bulk Filler Removed (Gal).
- 4 Gal.

LNS 16-1-85
Initial/Date

9. Anchor End Number As Found
- LS 013

LNS 16-1-85
Initial/Date

10. Shim Thickness As Found

12 1/2"LNS 16-1-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

NONE

Misshaped

2

Splits > .12"

NONELNS 16-1-85
Initial/Date

DATA SHEET 1

TENDON NO. 28 DE

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LNS / 6-1-85
Initial/Date

13. Tendon End Caps Re-installed PER INR4LO

LNS / 6-1-85
Initial/Date

14. Tendon Re-greasing:

Date

6-1-85
*Data transferred from
procedure SQ 12.9*

6/4/85

Temperature of Grease in Bulk Container

152 °F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6359

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

DAH / 6/7/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 28 DE
 (FIELD) SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion
 Number missing,
 broken or damaged:

ANONE

Cracks or splits
 Number not
 properly formed:

NONE2

BEARING PLATE

Degree of Corrosion

A, B & C

Cracks

NONE

ANCHORAGE AREA CONCRETE

Cracks (width > 0.01 in.)

NONE

ANCHOR HEAD

Number

LS 013

Degree of Corrosion

A

Cracks

NONE

SEIMS

Degree of Corrosion

A


Cracks

NONE

REMARKS: Some of corrosion
on bearing plate appears
to have been transferred
from the retaining plate


1/2" Gap bet. outside 4'

Shim halves, on top

SKETCH

Date 6-1-85 Signature J. J. Hamilton

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. 28 FE
DE



Date 6-1-85 Signature J. J. Sainmont

LEGEND FOR BUTTONHEADS


JOSEPH M. FARLEY NUCLEAR PLANT UNIT

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON 28 DE

J. J. Shumaker 16-1-85
SIGNATURE DATE



COMMENTS:

2 Double Buttonheads

DATA SHEET 1

TENDON NO. 45 DE

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "E"

2. Last Date Stressed 12-6-76

3. Anchor End Number from Stressing Card

Field HP068

Shop KA 048

4. Previous Shim Thickness from Stressing Card

Field 12 1/2"

Shop 12"

5. Remove Tendon End Cap

LNS / 1630 / 5-30-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease NO APPARENT MOISTURE,

GOOD CONSISTENCY, LIGHT BROWN
100% COVERAGE

LNS / 5-30-85
Initial/Date

7. Grease Sample Taken

LNS / 5-30-85
Initial/Date

8. Bulk Filler Removed (Gal). 5 Gal.

LNS / 5-30-85
Initial/Date

9. Anchor End Number As Found

F0094
Bushing KA 048

LNS / 5-30-85
Initial/Date

10. Shim Thickness As Found

12 3/8"

LNS / 5-30-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

NONE

Misshaped

NONE

Splits > .12"

NONE

LNS / 5-30-85
Initial/Date

DATA SHEET 1

TENDON NO. 45 DE

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LNS / 5-30-85
Initial/Date

13. Tendon End Caps Re-installed

LNS / 5-30-85
Initial/Date

14. Tendon Re-greasing:

Date

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

PER INRYCO

*LNS
5-30-85*

*Data transferred
from procedure
SQ 12.7*

6/4/85

220 °F

NEW

LOT NO. 5-6359

ENTIRE TENDON

DBH / 8/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 45 DE
 FIELD/SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion
 Number missing,
 broken or damaged:

A
None

Cracks or splits
 Number not
 properly formed:

None
None

BEARING PLATE

Degree of Corrosion A, B & C

Cracks None

ANCHORAGE AREA CONCRETE

Cracks (width > 0.01 in.)

None

ANCHOR HEAD

Number

E0094

Degree of Corrosion

A

Cracks

None

SHIMS

Degree of Corrosion


A

Cracks

None


REMARKS: Corrosion on

Bearing plate transferred
from Rebar plate

SKETCH

Date 5-30-85 Signature J. J. Manning

ANCHORAGE ASSEMBLY INSPECTION
 SHOP END OF TENDON NO. 45 DE



Date 5-30-85 Signature T. J. [Signature]

LEGEND FOR BUTTONHEADS


JOSEPH M. FARLEY NUCLEAR PLANT UNIT

● Missing Buttonhead or Wire

Ø Unseated Buttonhead

⊗ Improperly Formed/Misshaped
Buttonhead● Buttonhead with Split
(Document the Split Size)

SHOP END

TENDON 45 DEJ. J. Ramm / 5-30-85
SIGNATURE DATE

COMMENTS:

05225 0053 **TENDON STRESSING CARD**

DATE 12-6-78

TENDON LOCATION H 450E JOB NO 21T-505 JOB SHIRLEY UNIT 42

DO NOT EXCEED 80% OF ULT
1602 KIPS 7600 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 5
GAUGE NO. 24
END C

JACK NO. 1
GAUGE NO. 187
END C

PSI	ELONGATION	PSI	ELONGATION
-----	------------	-----	------------

1. CALCULATED ELONGATION OVER 3000 PSI 500 PSI 8.76
2. PRIOR TO STRESSING 1500 6.40 1500 6.70
3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION) 4000 10.20 4000 10.00
4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2) 3.60
5. (NEW LIFT OFF - SAME PSI AS LINE 3) 4000 4.16 4000 4.30
6. (FULL RAM EXTENSION) - - - -
7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5) - - - -
8. (NEW LIFT OFF - SAME PSI AS LINE 6) - - - -
9. OVERSTRESS 1402 7600 PSI 7600 9.20 7600 9.20
10. TOTAL MEASURED ELONGATION (4+7+8)
(LINE 9 MINUS LINE 2 (9-8+7+6)) 8.70 8.20
11. LOCKOFF 1402 6644 6970 PSI 6850 6900

REMARKS _____

SHIMS 12 1/2"

SHIMS 12"

FLUX HEAD HP068

BUSHING KP008

FOREMAN DW Hall

BRG. PLATE F3

BRG. PLATE 5M26

Q.C. INSPECTOR C. J. Beel

DATE 12-6-78

TENDON END PROTECTED OK

TENDON END PROTECTED OK

05224 2102

SEND ZIT 50

TENDON BUTTON HEADING CARD

Job Farley Unit 2

TENDON LOCATION: 45ED

DATE: 10-19-76

INSPECTION	ACCEPTABLE (CHECK)	REJECTABLE
10% GO; NO-GO	(OK) 17	_____
SPLITS	(OK) 170	_____
ECCENTRICITY	(OK) 170	_____

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) _____

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK) _____

TOTAL UNACCEPTABLE HEADS

-0-

COMMENTS HP 068 (NCR 505-F11) X

FOREMAN D. W. Helms Q.C. INSPECTOR P. K. Smith DATE 10-19-76

DATA SHEET 1

TENDON NO. 45 DE

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "D"

2. Last Date Stressed 12-6-76

3. Anchor End Number from Stressing Card

Field HP068

Shop KAC48

4. Previous Shim Thickness from Stressing Card

Field 12 1/2"

Shop 12"

5. Remove Tendon End Cap

LNS / 1330 / 5-31-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease NO APPARENT MOISTURE,

Good consistency, Light Brown & small amt. of
BLACK preservative - 100% coverage

LNS / 5-31-85
Initial/Date

7. Grease Sample Taken

LNS / 5-31-85
Initial/Date

8. Bulk Filler Removed (Gal). 2 Gal.

LNS / 5-31-85
Initial/Date

9. Anchor End Number As Found HP068

LNS / 5-31-85
Initial/Date

- ✓ 10. Shim Thickness As Found

11 3/8"

LNS / 5-31-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

NONE

Misshaped

1

Splits > .12"

NONE

LNS / 5-31-85
Initial/Date

DATA SHEET 1

TENDON NO. 45 DE

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LNS 1 5-31-85
Initial/Date

13. Tendon End Caps Re-installed

LNS 1 5-31-85
Initial/Date

14. Tendon Re-greasing:

Date

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

*Per INRYCO
5-31-85 LNS
Data transferred
from procedure
SQ 12.7*

6/7/85

190°

NEW

LOT NO. 5-6359

ENTIRE TENDON

DBH 1 8/2/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 45 DE
☒ FIELD ☐ SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing, broken or damaged: NONE
 Cracks or splits Number not properly formed: 1

BEARING PLATE

Degree of Corrosion A, B, & C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE


ANCHOR HEAD

Number HP 06B
 Degree of Corrosion A & B
 Cracks NONE

SHIMS


Degree of Corrosion A & B
 Cracks NONE

REMARKS: MUCH of CORROSION ON
BEARING PLATE APPEARS to
have been transferred from
the Retainer plate

SKETCH

Date 5-31-85 Signature J. J. Shannon

ANCHORAGE ASSEMBLY INSPECTION

FIELD END OF TENDON NO. 45 DEDate 5-31-85 Signature J. J. [Signature]

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT


- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON

45 DE

J. J. Shuman 15-31-85
SIGNATURE DATE



HP068

COMMENTS:

DATA SHEET 1

TENDON NO. 3 EF

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "E"

2. Last Date Stressed 11-15-76

3. Anchor End Number from Stressing Card

Field HP 128

Shop KA021

4. Previous Shim Thickness from Stressing Card

Field 10 1/2"

Shop 11 1/8"

5. Remove Tendon End Cap

MMH
Initials

19:14
Time

15/30/85
Date

6. Visual Examination of Bulk Filler Grease

BROWN (Almost NEW) IN COLOR

GOOD CONSISTENCY WITH SOME FROTHING PRESENT.

MOISTURE IN CAN & ON BOTTOM OF SHIMS. NO H₂O ON ANCHORHEAD. MOISTURE PRESENT IN UNCOLLECTABLE QUANTITIES.

MMH 15/30/85
Initial/Date

7. Grease Sample Taken

MMH 15/30/85
Initial/Date

8. Bulk Filler Removed (Gal).

5 1/2 GALS

MMH 15/30/85
Initial/Date

9. Anchor End Number As Found

(BUSHING) (ANCHOR)
KA021 / GT019

MMH 15/30/85
Initial/Date

10. Shim Thickness As Found

MMH 5/30/85
3 1/4 11 1/2"

MMH 15/30/85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

1

Misshaped

0

Splits > .12"

0

MMH 15/30/85
Initial/Date

DATA SHEET 1

TENDON NO. 3 EF

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

JMH / 5/30/85
Initial/Date

13. Tendon End Caps Re-installed

JMH / 5/30/85
Initial/Date

14. Tendon Re-greasing: PER INRYCO

Date

Data transferred from
procedure SQ 12.7

5/31/85

Temperature of Grease in Bulk Container

210°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-5526

Amount of Grease Replaced (Gal.)

ENTIRE TENDONS

DEH / 8/2/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 3 EF
 FIELD SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion
 Number missing,
 broken or damaged:

A
1

Cracks or splits
 Number not
 properly formed:

0
0

ANCHOR HEAD

Number

KA021/GT019

Degree of Corrosion

A

Cracks

NONE


SHIMS

Degree of Corrosion

A

Cracks

NONE

SKETCH

BEARING PLATE

Degree of Corrosion A & B

Cracks

NONE

ANCHORAGE AREA CONCRETE

Cracks (width > 0.01 in.)

NONE - CONSTRUCTION JOINT

AT ANCHORAGE G. :: O.K

REMARKS: 1/2" SHIM ADJACENT BEARING

PLATE OFF SET 3/4" WAS GROUND

OFF TO ALLOW INSTALLATION OF CAN.

SHOP BUSHING NOT FULLY

ENGAGED (DOWN 7/16")

WATER DRIPPING SLOWLY FROM

GREASE HOLE & SHIM GAP.

SHIM GAP $\leq 1/4$ ON BOTH SIDES.


GASKET RETAINER IS HAS

A TO C CORROSION LEVELS.

Date 5/30/65 Signature Frank M. Hall

ANCHORAGE ASSEMBLY INSPECTION
SEOP END OF TENDON NO. 3 EF

↑ UP



Date 5/30/85 Signature Angel M. Hall

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT


- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

SHOP END

TENDON 3 E F

SIGNATURE

DATE



COMMENTS:

1 BUTTONHEAD MISSING. NO IMPROPERLY FORMED OR UNSEATED
 BUTTONHEADS. NO SPLITS > 0.12"

TENDON STRESSING CARD

DATE 11-15-76

TENDON LOCATION W 200

JOB NO. 251-5/15

JOB

CARRY UNIT #2

DO NOT EXCEED 80% OF ULT
1602 KIPS 7600 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 2
GAUGE NO. 10
END

JACK NO. 3
GAUGE NO. 34
END

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 2000 PSI 500 PSI

1500 2.40

1400 2.00

2. PRIOR TO STRESSING

1500 5.00

1400 5.90

3. 3600 TO 4000 PSI (OR FULL RAM EXTENSION)

4500 9.10

4500 10.40

4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2)

4500 4.20

4500 4.50

5. (NEW LIFT OFF - SAME PSI AS LINE 3)

4500 3.60

4500 3.00

6. (FULL RAM EXTENSION)

- -

- -

7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5)

- -

- -

8. (NEW LIFT OFF - SAME PSI AS LINE 6)

- -

- -

9. OVERSTRESS 1602 KIPS 7600 PSI

7600 8.00

7600 9.30

10. TOTAL MEASURED ELONGATION (4+7+8)
LINE 9 MINUS LINE 2 (9-2+7+8)

8.50

8.80

11. LOCKOFF 1602 KIPS 6970 PSI

6800

6850

REMARKS

SHIMS 10 1/2"

SHIMS 11 1/2"

ELD. HEAD HP128

ELD. HEAD HP128

FOREMAN 2.70 Wilson

BRG. PLATE FB

BRG. PLATE FB

Q.C. INSPECTOR C. J. Bell DATE 11-15-76

TENDON END PROTECTED OK

TENDON END PROTECTED OK

FORM 180-67-40

APRIL 1975

INRYCE an INLAND STEEL company

STAGE 14+7

0 5 2 2 4 2 1 0 0
TENDON BUTTON HEADING CARD

TENDON LOCATION:

3 FE 1

JOB NO.

211 500
Farley Unit 2

DATE:

10-18-76

INSPECTION

ACCEPTABLE
(CHECK)

REJECTABLE

10%
GO; NO-GO

(OK) 17

SPLITS

(OK) 17 (170)

ECCENTRICITY

(OK) 17 (170)

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK)

OK

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK)

N/A

TOTAL UNACCEPTABLE HEADS

0

COMMENTS

HV 128

REVISIONS by C. J. Bess

6-1-77

FOREMAN

Gill Britton

Q.C. INSPECTOR

P. Charles

DATE

10-18-76

DATA SHEET 1

TENDON NO. 3 EF

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "F"

2. Last Date Stressed 11-15-76

3. Anchor End Number from Stressing Card

Field HP 128

Shop KA021

4. Previous Shim Thickness from Stressing Card

Field 10 1/2"

Shop 11 1/8"

5. Remove Tendon End Cap

JMH
Initials

19:15
Time

15-29-85
Date

6. Visual Examination of Bulk Filler Grease TAN COLOR, (LOOKS NEW)

GOOD CONSISTENCY, FULL COVERAGE ON ANCHORAGE

ASSEMBLY — NO MOISTURE FOUND

JMH / 5-29-85
Initial/Date

7. Grease Sample Taken

JMH / 5-29-85
Initial/Date

8. Bulk Filler Removed (Gal). 4 1/2 GAL

JMH / 5-29-85
Initial/Date

9. Anchor End Number As Found HP 128

JMH / 5/29/85
Initial/Date

10. Shim Thickness As Found 10.5"

JMH / 5/29/85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

1

JMH / 5-29-85
Initial/Date

DATA SHEET 1

TENDON NO. 3 EF

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

mmH 15-29-85
Initial/Date

13. Tendon End Caps Re-installed

mmH 15-29-85
Initial/Date

14. Tendon Re-greasing: PER INRY CO

Date

Data transferred from
procedure SQ 12.7

5/29/85

Temperature of Grease in Bulk Container

220 °F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-5526

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

DBH 18/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 3 EF
 FIELD/SHOP END (Circle One)

BUTTONHEAD


Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

ANCHOR HEAD

Number HP128
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

↓ UP

BEARING PLATE

Degree of Corrosion A & B
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE VISIBLE - PAINTED

SURFACE ... NO CRACKING OR

PEELING OF PAINT

REMARKS: ≈ 1/2" SHIM GAP ON TOP

< 1/4" GAP ON BOTTOM OF SHIM STACK

(ADJACENT TO ANCHORHEAD)

1/2" SHIM NEXT TO BEARING PLATE


GOOD OVERALL SHIM STACK APPEARANCE

A & B LEVEL CORROSION ON GASKET

RETAINER PLATE

Date 5/29/88 Signature Joseph M. Hall

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. 3EF



A LEVEL INSIDE 'O' RING
B LEVEL OUTSIDE 'O' RING

Date 5/29/85 Signature Joseph M. Hall

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

FIELD END


TENDON

3 EF

SIGNATURE

DATE

1 SPLIT - 0.125" MAX WIDTH.



COMMENTS:

↓ UP

SHINY NEW APPEARANCE OF ALL BUTTONHEADS.

WELL ROUNDED SHAPE OF BUTTONHEADS. THERE ARE

NUMEROUS SLIPS BUT ALL ARE WITHIN ACCEPTANCE CRITERIA.

DATA SHEET 1

TENDON NO. 17 EF

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
BUTTRESS "E"
2. Last Date Stressed 11-23-76
3. Anchor End Number from Stressing Card
Field HP 050
Shop HW 141
4. Previous Shim Thickness from Stressing Card
Field 12 5/8
Shop 11 5/8
5. Remove Tendon End Cap
LNS / 1130 / 5-30-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease Good consistency,
NO APPARENT FREE MOISTURE, BROWN WITH SOME LNS
SMALL AMT. of BLACK PRESERVATIVE
LNS / 5-30-85
Initial/Date
7. Grease Sample Taken
LNS 5-30-85
LNS / 5-30-85
Initial/Date
8. Bulk Filler Removed (Gal). ~~12~~ 4 Gal.
LNS / 5-30-85
Initial/Date
9. Anchor End Number As Found GL 030
BUSHING HW 141
LNS / 5-30-85
Initial/Date
10. Shim Thickness As Found 11 7/16"
LNS / 5-30-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads: Missing NONE
Misshaped NONE
Splits > .12" NONE

LNS / 5-30-85
Initial/Date

DATA SHEET 1

TENDON NO. 17 EF

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LNS 15-30-85
Initial/Date

13. Tendon End Caps Re-installed

LNS 15-30-85
Initial/Date

14. Tendon Re-greasing:

Date

PER INRYCO
Data transferred from
procedure SQ 12.7

5/31/85

Temperature of Grease in Bulk Container

170°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-5526

Amount of Grease Replaced (Gal.)

ENTIRE Tendon

LNS 15-30-85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 17 EF
 FIELD (SHOP END) (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: NONE

Cracks or splits
 Number not
 properly formed: NONE > 0.12
NONE

ANCHOR HEAD

Number GL030


Degree of Corrosion A

Cracks NONE

SHIMS

Degree of Corrosion A+B

Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A, B & C

Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)


NONE

REMARKS: _____

Some corrosion on bearing
is transferred from retained plate

Date 5-30-85 Signature [Signature]

ANCHORAGE ASSEMBLY INSPECTION
 SHOP END OF TENDON NO. 17EF



Date 5-30-85 Signature J. T. J.

LEGEND FOR BUTTONHEADS

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

JOSEPH M. FARLEY NUCLEAR PLANT UNIT


SHOP END

TENDON 17EFJ. J. H.

SIGNATURE

15-30-05

DATE



COMMENTS:

0522510070 TENDON STRESSING CARD

TENDON LOCATION H 17EE JOE NO. 577-5NE JOB EARLEY TUNEL 32 DATE 8-23-76

DO NOT EXCEED 80% OF ULT

1602 KIPS 7600 PSI

LINES IN PARENTHESIS () FOR STAGE STRESSING ONLY

JACK NO. 2

GAUGE NO. 10

END —

JACK NO. 3

GAUGE NO. 54

END —

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 3000 PSI 500 PSI

2. PRIOR TO STRESSING

3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION)

4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2)

5. (NEW LIFT OFF - SAME PSI AS LINE 3)

6. (FULL RAM EXTENSION)

7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5)

8. (NEW LIFT OFF - SAME PSI AS LINE 6)

9. OVERSTRESS 1602 KIPS 7600 PSI

10. TOTAL MEASURED ELONGATION (4+7+9)
(LINE 9 MINUS LINE 2 (9-2+7+4))

11. LOCKOFF 1402 KIPS 6646 PSI TO 5979 PSI

REMARKS

FOREMAN

G.C. INSPECTOR

OLD HEAD

BRG. PLATE

TENDON END

PROTECTED

SHIMS

BUSHING

BRG. PLATE

TENDON END

PROTECTED

FORM 780.67-60

APRIL 1975

INRYCO an INLAND STEEL company

1. CALCULATED ELONGATION OVER 3000 PSI 500 PSI

2. PRIOR TO STRESSING

3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION)

4. (MEASURED 1ST STAGE ELONGATION)

5. (NEW LIFT OFF - SAME PSI AS LINE 3)

6. (FULL RAM EXTENSION)

7. (MEASURED 2ND STAGE ELONGATION)

8. (NEW LIFT OFF - SAME PSI AS LINE 6)

9. OVERSTRESS 1602 KIPS 7600 PSI

10. TOTAL MEASURED ELONGATION (4+7+9)

11. LOCKOFF 1402 KIPS 6646 PSI TO 5979 PSI

0 5 2 2 4 2 1 1 9

TENDON BUTTON HEADING CARD

TENDON LOCATION:

17FE

JOB NO.

21T 505

DE

Farley Unit 2

DATE:

10-14-76

INSPECTION

ACCEPTABLE

REJECTABLE

10%
GO; NO-GO

(CHECK)
(OK) 17

SPLITS

(OK) 16 (168) + (2)

ECCENTRICITY

(OK) 17 (170)

TOTAL UNACCEPTABLE HEADS

+ (2)

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK)

[Signature]

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK)

N/A

COMMENTS

HV 050

REVISIONS by C. J. Moore
6-1-77

FOREMAN

Gill Bristow

C.C. INSPECTOR

P. Charles

DATE

10-14-76

DATA SHEET 1

TENDON NO. 17 EF

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "F"

2. Last Date Stressed 11-23-76

3. Anchor End Number from Stressing Card

Field HP 050

Shop HW 141

4. Previous Shim Thickness from Stressing Card

Field 12 ⁵/₈"

Shop 11 ⁵/₈"

5. Remove Tendon End Cap

gmH
Initials

11250
Time

15/29/85
Date

6. Visual Examination of Bulk Filler Grease BROWN IN COLOR

GOOD CONSISTENCY, SOME FROTHING PRESENT

NO MOISTURE DETECTED GOOD COVERAGE OVER
ANCHORAGE ASSEMBLY

gmH 15/29/85
Initial/Date

7. Grease Sample Taken

gmH 15/29/85
Initial/Date

8. Bulk Filler Removed (Gal). 2 GAL

gmH 15/29/85
Initial/Date

9. Anchor End Number As Found HP 050

gmH 15/29/85
Initial/Date

10. Shim Thickness As Found 12.3 / 12.55"

gmH 15/29/85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

gmH 15/29/85
Initial/Date

DATA SHEET 1

TENDON NO. 17 EF

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

MMH 1 5/30/85
Initial/Date

13. Tendon End Caps Re-installed

MMH 1 5/29/85
Initial/Date

14. Tendon Re-greasing: PER INRYCO.

Date Data transferred from
procedure SQ 12.7

5/30/85

Temperature of Grease in Bulk Container

185°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-5526

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

DAH 1 5/2/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 1.7 EF
 (FIELD) (SHOP END) (Circle One)

BUTTONHEAD


Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

ANCHOR HEAD

Number HPO50
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A TO C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE VISABLE ... PAINTED

SURFACE ... PAINT NOT

PEELING OR CRACKING.

REMARKS: SHIM STACK WELL

COATED WITH GREASE; SHIM

HEIGHT DIFFERENTIAL OF 0.25"

SHIM GAPS $\approx \frac{1}{4}$ " BOTH SIDES.


GASKET RETAINER PLATE HAS

LEVELS A TO LIGHT C LEVELS

OF CORROSION.

Date 5/29/85 Signature Joseph M. Hall

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. 17 EF



Date 5/29/85 Signature James M. Hall

LEGEND FOR BUTTONHEADS


JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON 17 EF

Joseph M. Hall 15/29/85
SIGNATURE DATE



COMMENTS:

WELL FORMED BUTTONHEADS; SHINY NEW APPEARANCE

DATA SHEET 1

TENDON NO. 31 EF

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "E"

2. Last Date Stressed 12-2-76

3. Anchor End Number from Stressing Card

Field HP 038

Shop HW 031

4. Previous Shim Thickness from Stressing Card

Field 13 1/4"

Shop 12"

5. Remove Tendon End Cap

LN3 / 0830 / 5-31-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease No APPARENT MOISTURE,

Good consistency, light brown,

100% coverage

LN3 / 5-31-85
Initial/Date

7. Grease Sample Taken

LN3 / 5-31-85
Initial/Date

8. Bulk Filler Removed (Gal). 4 Gal.

LN3 / 5-31-85
Initial/Date

9. Anchor End Number As Found

6L 065
BUSHING HW 031

LN3 / 5-31-85
Initial/Date

10. Shim Thickness As Found

11 7/8"

LN3 / 5-31-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

NONE

Misshaped

NONE

Splits > .12"

NONE

LN3 / 5-31-85
Initial/Date

DATA SHEET 1

TENDON NO. 31 EF

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LN5 / 5-31-85
Initial/Date

13. Tendon End Caps Re-installed

LN5 / 5-31-85
Initial/Date

14. Tendon Re-greasing: *PER INRYCO*

Date

*5-31-85
LOT 9*

*Data transferred
from procedure
SQ 12.7*

6/6/85

Temperature of Grease in Bulk Container

220 °F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6359

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

DAN / 6/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 31 EF
 FIELD / SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: NONE
 Cracks or splits
 Number not
 properly formed: NONE

ANCHOR HEAD

Number GL 065
 Degree of Corrosion A & B
 Cracks NONE

SHIMS

Degree of Corrosion A & B
 Cracks NONE


BEARING PLATE

Degree of Corrosion A, B & C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)


NONE

REMARKS: Some of corrosion on
Bearing ^{plate} is transferred from
the retainer plate

SKETCH

Date 5-31-85 Signature J. J. Lanning

ANCHORAGE ASSEMBLY INSPECTION
 SHOP END OF TENDON NO. 31 EF.



Date 5-31-85 Signature [Signature]
 DATA SHEET 4a REV 1

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)


SHOP END

TENDON 31 EFJ. J. Ramm

SIGNATURE

15-31-85

DATE



COMMENTS:

NONE

TENDON LOCATION W 3155 JOB NO 21T-505 JOB SAFETY UNIT 42

DATE 12-2-76

TENDON LOCATION W 3155 JOB NO 21T-505 JOB SAFETY UNIT 42

1502 KIPS 7400 PSI

LINES WITH PARENTHESIS () FOR
 STAGE DRESSING ONLY

JACK NO.

GAUGE NO.

END

JACK NO.

GAUGE NO.

END

PSI

ELONGATION

PSJ

ELONGATION

1. CALCULATED ELONGATION OVER 2000 PSI (500 PSI
2. PRIOR TO STRESSING
3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION)
4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2)
5. (NEW LIFT OFF - SAME PSI AS LINE 3)
6. (FULL RAM EXTENSION)
7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5)
8. (NEW LIFT OFF - SAME PSI AS LINE 6)
9. OVERSTRESS 1602 KIPS 7600 PSI
10. TOTAL MEASURED ELONGATION (4+7+9)
LINE 9 MINUS LINE 2 (5-8+7+4)
11. LOCKOFF 1602 KIPS 6640 PSI TO 6979 PSI

1500	8.75
<u>xxvxxx</u>	<u>7.00</u>
3500	10.00
	<u>3.00</u>
3500	4.10
<u>—</u>	<u>—</u>
<u>—</u>	<u>—</u>
7600	10.10
	<u>9.00</u>
6800	

1500	8.75
XV 2000	7.10
<u>3500</u>	<u>9.80</u>
	<u>2.70</u>
<u>3500</u>	<u>4.90</u>
<u>—</u>	<u>—</u>
<u>—</u>	<u>—</u>
<u>7600</u>	<u>9.80</u>
	<u>8.10</u>
<u>6800</u>	

REMARKS _____

SHIMS 134SHIMS 12

FLD. HEAD HP038

BUSHING HW03

FOREMAN Dwight 3

BRG. PLATE NOTEBRG. PLATE EA

Q.C. INSPECTOR C. J. Zelle DATE 12-27

TENDON END OK
PROTECTED

TENDON END
PROTECTED OK

05224 2133

TENDON BUTTON HEADING CARD

JOB NO. 21T 500

JOB: Farley Unit 2

TENDON LOCATION: 31 FE

DATE: 10-11-76

INSPECTION ACCEPTABLE REJECTABLE

10% 30%

GO; NO-GO

(CHECK)

(OK) 16 (50) 1

SPLITS

(OK) 17 (70) 0

ECCENTRICITY

(OK) 17 (70) 0

TOTAL UNACCEPTABLE HEADS

-1-

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ✓

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK) NA

COMMENTS HPQ38

Revisions by C. F. Hume

6-1-77

FOREMAN

S. Smith

Q.C. INSPECTOR

P. Lischel

DATE

10-11-76



DATA SHEET 1

TENDON NO. 1 EF

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "F"

2. Last Date Stressed 12-2-85

3. Anchor End Number from Stressing Card

Field 42-32

Shop 42-32

4. Previous Shim Thickness from Stressing Card

Field 3.4"

Shop 12"

5. Remove Tendon End Cap

JMS / 1500 / 6-1-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease Dark Red

Good to 1/2" depth. No more at 1/2" depth.
100% to 1/2" depth.

LMS / 6-1-85
Initial/Date

7. Grease Sample Taken

ENS / 6-1-85
Initial/Date

8. Bulk Filler Removed (Gal). 8 gal.

LMS / 6-1-85
Initial/Date

9. Anchor End Number As Found HP-038

JMS / 6-1-85
Initial/Date

10. Shim Thickness As Found 13 1/8"

LMS / 6-1-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

NONE

Misshaped

1

Splits > .12"

NONE

LMS / 6-1-85
Initial/Date

DATA SHEET 1

TENDON NO. 31 EF

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LNS / 6-1-85
Initial/Date

13. Tendon End Caps Re-installed

LNS / 6-1-85
Initial/Date

14. Tendon Re-greasing:

Date

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

*PER INRYCO
6-1-85
LNS*

*Data transferred
from
SQ 12.7*

^{SON}
~~215°F~~ 6/6/85

215°F

NEW

LOT NO. 5-6359

ENTIRE TENDON

LNS / 6/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 31 EF
 (FIELD) SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: NONE

Cracks or splits
 Number not
 properly formed: 1

ANCHOR HEAD

Number HP 030


Degree of Corrosion A

Cracks NONE

SHIMS

Degree of Corrosion A

Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A, B & C

Cracks NONE

ANCHORAGE AREA CONCRETE


Cracks (width > 0.01 in.)

NONE

REMARKS: Much of corrosion
on bearing plate
appears to have been
transferred from the
rebarred plate

Date 6-1-95 Signature J. J. Hummel

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. 31EF



Date 6-1-85 Signature J. J. [Signature]

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

FIELD END


TENDON

31 EF

SIGNATURE

DATE

J. M. Farley, 6-1-85



COMMENTS:

one DOUBLE Buttonhead

DATA SHEET 1

TENDON NO. 13 FDFIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "F"

2. Last Date Stressed 11-22-76

3. Anchor End Number from Stressing Card

Field HV 024Shop KA 090

4. Previous Shim Thickness from Stressing Card

Field 12 1/8"Shop 12 1/4"

5. Remove Tendon End Cap

MMH
Initials11:00
Time5/29/85
Date

6. Visual Examination of Bulk Filler Grease

LIGHT BROWN COLORWITH GOOD CONSISTENCY, SOME FEATHING APPARENT, FULLCOVERAGE ON ANCHORAGE ASSEMBLY - NO MOISTURE PRESENT

7. Grease Sample Taken

MMH 5/29/85
Initial/DateMMH 5/29/85
Initial/Date

8. Bulk Filler Removed (Gal). 2 1/2 GALS

MMH 5/29/85
Initial/Date

9. Anchor End Number As Found

KA090 / FU154MMH 5/29/85
Initial/Date

10. Shim Thickness As Found

12.1"MMH 5/29/85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0MMH 5/29/85
Initial/Date

DATA SHEET 1

TENDON NO. 13 FD

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

JMH 15/29/85
Initial/Date

13. Tendon End Caps Re-installed

JMH 15/29/85
Initial/Date

14. Tendon Re-greasing: PER INRYCO

Date

Data transferred from
procedure SG 12.7

5/30/85

Temperature of Grease in Bulk Container

185°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-5526

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

JMH 12/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 13 FD
 FIELD/SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: 0


Cracks or splits 0
 Number not
 properly formed: 0
1 UNSEATED - PROTRUDES 0.60"

ANCHOR HEAD

Number KAD90/FU154
 Degree of Corrosion A/A
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A + HEAVY B
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE - PAINTED CONCRETE

SURFACE - NO VISABLE CRACKS

PAINT NOT SPLIT OR CRACKING

REMARKS: GOOD TIGHT SHIM

STACK ... BUSHING FULLY

ENGAGED ... BEARING PLATE

NOT PAINTED.

GASKET RETAINER PLATE


HAS A & B LEVELS OF

CORROSION.

SHIM GAPS < 1/4" BOTH SIDE

Date 5/29/85 Signature Jerry M. Hall

ANCHORAGE ASSEMBLY INSPECTION
SHOP END OF TENDON NO. 13 FD.



BEARING PL IS NOT PAINTED

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)


SHOP END

TENDON 13 FD

SIGNATURE

DATE

UP



COMMENTS:

1 UNSEATED BUTTONHEAD PROTRUDE = 0.60"

BUTTONHEADS HAVE FLAT HEADS BUT ARE WELL ROUNDED.

BUTTONHEADS HAVE SHINY NEW APPEARANCE

05225 0113 TENDON STRESSING CARD

DATE 11-22-76

TENDON LOCATION 4 1350 JOB NO 21T-505 JOB 2ADLEY UNIT 82

DO NOT EXCEED 80% OF ULY
1502 KIPS 7600 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 4
GAUGE NO. 114
END

JACK NO. 6
GAUGE NO. 18
END

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 2000 PSI 1500 PSI	1500	9.25	1500	7.95
2. PRIOR TO STRESSING	XX 2000	8.40	XX 2000	5.00
3. 3P. TO 4000 PSI (OR FULL RAM EXTENSION)	3600	11.30	3500	9.70
4. (MEASURED 1ST STAGE ELONGATION) (LINE 3 MINUS LINE 2)		2.90		2.70
5. (NEW LIFT OFF - SAME PSI AS LINE 3)	3600	5.40	3500	3.00
6. (FULL RAM EXTENSION)	-	-	-	-
7. (MEASURED 2ND STAGE ELONGATION) (LINE 6 MINUS LINE 5)		-		-
8. (NEW LIFT OFF - SAME PSI AS LINE 6)	-	-	-	-
9. OVERSTRESS 1502 KIPS 7600 PSI	7600	11.00	7600	9.70
10. TOTAL MEASURED ELONGATION (4+7+9) LINE 9 MINUS LINE 2 (9-8+7+4)		8.50		8.40
11. LOCKOFF 1502 KIPS 4070 PSI TO 6070 PSI	6650		6850	

REMARKS

SHIMS 12 1/8"

SHIMS 12 1/4"

FLD. HEAD H1024

BUSHING KA090

FOREMAN D W Helms

BRG. PLATE EC

BRG. PLATE EA

Q.C. INSPECTOR C J Bell DATE 11-22-76

TENDON END PROTECTED OK

TENDON END PROTECTED OK

0 5 2 2 2 1-6 1

JOB NO.: 217 5

TENDON BUTTON HEADING CARD

JOB: FAIRLEY UNIT 2

TENDON LOCATION: 13FD

DATE: 10-14-76

INSPECTION	ACCEPTABLE (CHECK)	REJECTABLE
10% GO; NO-GO	(OK) 17	
SPLITS	(OK) 170	
ECCENTRICITY	(OK) 170	
TOTAL UNACCEPTABLE HEADS		-0-

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) OK

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK) _____

COMMENTS: HV029

FOREMAN Lewis B. Powell Q.C. INSPECTOR Pharrell

DATE 10-14-76

DATA SHEET 1

TENDON NO. 13 FDFIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
BUTTRESS "D"
2. Last Date Stressed 12-22-76
3. Anchor End Number from Stressing Card Field HV024
Shop KA090
4. Previous Shim Thickness from Stressing Card Field 12 1/8"
Shop 12 1/4"
5. Remove Tendon End Cap MMH 1 15:07 1 5/29/85
Initials Time Date
6. Visual Examination of Bulk Filler Grease CLEAN NEW
'COLD PACK' BY INRYCO - NO GREASE IN
CAN NO MOISTURE PRESENT - GREASE CAN CLEAN
7. Grease Sample Taken → SEE INRYCO DATA
COLD PACKED MMH 1 5/29/85
Initial/Date
8. Bulk Filler Removed (Gal). 0 MMH 1 5/29/85
Initial/Date
9. Anchor End Number As Found HV024 MMH 1 5/29/85
Initial/Date
10. Shim Thickness As Found 12.1 MMH 1 5/29/85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)
- | | | |
|------------------------|---------------|----------|
| Number of Buttonheads: | Missing | <u>0</u> |
| | Misshaped | <u>0</u> |
| | Splits > .12" | <u>0</u> |
- MMH 1 5/29/85
Initial/Date

DATA SHEET 1

TENDON NO. 13 FD

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

MIT 15/29/85
Initial/Date

13. Tendon End Caps Re-installed

MIT 15/29/85
Initial/Date

14. Tendon Re-greasing: PER INRYCO

Date

Data transferred from
procedure SQ 12.7

5/30/85

Temperature of Grease in Bulk Container

160°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-5526

Amount of Grease Replaced (Gal.)

ENTIRE Tendon

DBH 18/2/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 13 FD
 (FIELD/SHOP END (Circle One))

BUTTONHEAD


Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

ANCHOR HEAD

Number HV024
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A
 Cracks NONE

ANCHORAGE AREA CONCRETE

Cracks (width > 0.01 in.)

NO CRACKS VISIBLE...

PAINTED SURFACE WITH NO
CRACKING OR PEELING OBSERVED

REMARKS: GOOD SHIMS STACK


GAP ≈ 1/4 BOTH SIDES ... ANCHOR

HEAD HAS SHINY APPEARANCE (PROBABLY
GLASS BEADED RECENTLY.)

GASKET RETAINER PLATE HAS
LEVEL A CORROSION.

Date 5/29/88 Signature J. M. Hall

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. 13 FD



Date 5/21/13 Signature Joseph M. Hall

LEGEND FOR BUTTONHEADS


JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON 13 FD

Joseph M. Hall 1 5/29/85
 SIGNATURE DATE



COMMENTS:

WELL FORMED BUTTONHEADS ... UNIFORM SIZE AND

SHAPE ... NEW SHINET APPEARANCE NO TS > 0.12

NO MIS-SHAPED HEADS

DATA SHEET 1

TENDON NO. 26 FDFIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "D"

2. Last Date Stressed
- 5-10-77

3. Anchor End Number from Stressing Card

Field HU 035Shop LG 006

4. Previous Shim Thickness from Stressing Card

Field 12"Shop 12 1/4"

5. Remove Tendon End Cap

OBIS LNS / OBIS / 6-1-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease
- DARK BROWN,

GOOD consistency, NO APPARENT moisture
- 100% coverageLNS / 6-1-85
Initial/Date

7. Grease Sample Taken

LNS / 6-1-85
Initial/Date

8. Bulk Filler Removed (Gal).
- 5 GAL.

LNS / 6-1-85
Initial/Date

9. Anchor End Number As Found
- HU 035

LNS / 6-1-85
Initial/Date

10. Shim Thickness As Found
- 11 1/2"

LNS / 6-1-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

2

Misshaped

1

Splits > .12"

NONELNS / 6-1-85
Initial/Date

DATA SHEET 1

TENDON NO. 26 FD

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LNS / 6-1-85
Initial/Date

13. Tendon End Caps Re-installed

LNS / 6-1-85
Initial/Date

14. Tendon Re-greasing: PER INRYCO

Date

LNS
6-1-85

Data transferred
from SQ 12.7
procedure

6/8/85

Temperature of Grease in Bulk Container

220°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6359

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

DBH / 6/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 26 FD
(FIELD) SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
Number missing,
broken or damaged: 2
Cracks or splits
Number not
properly formed: 1


BEARING PLATE

Degree of Corrosion A, B & C
Cracks NONEANCHORAGE AREA CONCRETE
Cracks (width > 0.01 in.)
NONE


ANCHOR HEAD

Number HU 035
Degree of Corrosion A
Cracks NONE

SHIMS

Degree of Corrosion A & B
Cracks NONESKETCHREMARKS: Much of corrosion
on bearing plate appears
to have been transferred
from the retaining plate1/2" gap between halves of
outside 4" shim on bottom
sideDate 6-1-85 Signature J. J. [Signature]

ANCHORAGE ASSEMBLY INSPECTION


FIELD END OF TENDON NO. 26 DFDate 6/1/85 Signature J. T. Dummer

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON 26 DFZ. J. O'Rourke 16-1-85
SIGNATURE DATE

COMMENTS:

2 MISSING WIRES1 DOUBLE BUTTONHEAD

05225 0126
TENDON STRESSING CARD

DATE 5-10-77

TENDON LOCATION 4 2650 JOB NO. 21T-505 JOB EARLY UNIT 42

DO NOT EXCEED 80% OF ULT
1502 KIPS 7500 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 4
GAUGE NO. 51
END

JACK NO. 6
GAUGE NO. 107
END

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 2000 PSI 500 PSI
2. PRIOR TO STRESSING
3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION)
4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2)
5. (NEW LIFT OFF - SAME PSI AS LINE 3)
6. (FULL RAM EXTENSION)
7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 3)
8. (NEW LIFT OFF - SAME PSI AS LINE 6)
9. OVERSTRESS 1502 KIPS 7500 PSI
10. TOTAL MEASURED ELONGATION (4+7+9)
(LINE 9 MINUS LINE 2 (9-8+7+4)) 6931
11. LOCKOFF 1502 KIPS 7500 PSI TO 6700 PSI

1500
XY 2000
3500
3500
—
—
—
—
7600
9.00
6700

1500
XY 2000
3500
3500
—
—
—
—
7600
8.30
6850

REMARKS

SHIMS 12"

SHIMS 12 1/4"

FLD. HEAD H4035

BUSHING H15000

FOREMAN Bud Lingle

BRG. PLATE EP

BRG. PLATE NONE

I.C. INSPECTOR C. Freeze DATE 5-10-77

TENDON END PROTECTED OK

TENDON END PROTECTED OK

U 5 2 2 4 2 1 7 4

TENDON BUTTON HEADING CARD

JOB NO.:

217-5

JOB:

EARLEY UNIT 2

TENDON LOCATION:

26-11

DATE:

4-22-77

INSPECTION

ACCEPTABLE
(CHECK)

REJECTABLE

GO; NO-GO

(OK) 14.9

1

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ☒

SPLITS

(OK) 1.2

0

(OR)

ECCENTRICITY

(OK) 1.10

0

GREASE CANS INSTALLED
BOTH ENDS (CHECK) N/A

TOTAL UNACCEPTABLE HEADS

1

COMMENTS

HY035

FOREMAN

Les Linger

Q.C. INSPECTOR

C. P. Zere

DATE

4-22-77

DATA SHEET 1

TENDON NO. 26 FD

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BUTTRESS "F"

2. Last Date Stressed 5-10-77

3. Anchor End Number from Stressing Card

Field HU 035

Shop LG 006

4. Previous Shim Thickness from Stressing Card

Field 12"

Shop 12 1/4"

5. Remove Tendon End Cap

JMH 115:45 5/31/85
Initials Time Date

6. Visual Examination of Bulk Filler Grease DARK BROWN COLOR

GOOD CONSISTENCY, NO VISABLE MOISTURE; ANCHORAGE

WELL COVERED

7. Grease Sample Taken

JMH 5/31/85
Initial/Date

8. Bulk Filler Removed (Gal). 12

JMH 5/31/85
Initial/Date

9. Anchor End Number As Found

BUSHING ANCHOR
LG006 GL086

JMH 5/31/85
Initial/Date

10. Shim Thickness As Found

12 1/4"

JMH 5/31/85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

JMH 5/31/85
Initial/Date

DATA SHEET 1

TENDON NO. 26 FD

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

mmh 1 5/31/85
Initial/Date

13. Tendon End Caps Re-installed

mmh 1 5/31/85
Initial/Date

14. Tendon Re-greasing: PER INRYCO

Date

Data transferred from
procedure SQ 127

6/5/85

Temperature of Grease in Bulk Container

182°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6359

Amount of Grease Replaced (Gal.)

ENTIRE Tendon

mmh 1 5/31/85
Initial/Date

DBH 8/8/85

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 26 FD
 FIELD SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing, broken or damaged: 0
 Cracks or splits Number not properly formed: 0

BEARING PLATE

Degree of Corrosion A THRU C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE > 0.01 in

ANCHOR HEAD

Number LG006/GL086
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

MEASURABLE
 SURFACE CRACK (NO DEPTH)



REMARKS: GASKET RETAINER

PLATE HAS B & C LEVEL OF
CORROSION. SHIM STACK STRAIGHT
WITH GAPS $\approx 1/4$ ". SHIM BUSHING
IS FULLY ENGAGED. BUSHING
HAS NEW, POLISHED APPEARANCE.
ANCHORAGE ASSEMBLY IS IN
OVERALL GOOD CONDITION.

GASKET RETAINER PLATE APPEARS
TO BE TRANSFERRING CORROSION TO
BEARING PLATE

Date 5/31/85 Signature James M. Hall

ANCHORAGE ASSEMBLY INSPECTION
SEOP END OF TENDON NO. 26 FD



Date 5/31/85 Signature Joseph M. Hall

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2


- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

SHOP END

TENDON 26 FD

SIGNATURE

DATE



COMMENTS:

BURR ON STARTER THREAD.

NO MISSHAPED, MISSING OR UNSEATED BUTTONHEADS

BUTTONHEADS WELL ROUNDED WITH FLAT TOPS. ALL

HAVE SHINY NEW APPEARANCE.

DATA SHEET 1

TENDON NO. 42 FD

(FIELD) SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
BUTTRESS "D"
2. Last Date Stressed 5-18-77
3. Anchor End Number from Stressing Card Field LS 036
Shop LG 024
4. Previous Shim Thickness from Stressing Card Field 11"
Shop 12 1/2"
5. Remove Tendon End Cap LNS / 1530 / 5-31-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease NO APPARENT MOISTURE,
GOOD CONSISTENCY, LIGHT BROWN & SMALL AMT. g
BLACK PRESERVATIVE - 100% COVERAGE
LNS / 5-31-85
Initial/Date
7. Grease Sample Taken LNS / 5-31-85
Initial/Date
8. Bulk Filler Removed (Gal). 5 GAL. LNS / 5-31-85
Initial/Date
9. Anchor End Number As Found LS 036 LNS / 5-31-85
Initial/Date
10. Shim Thickness As Found 10 3/4" LNS / 5-31-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3
or 4 as applicable. (Attach Data Sheets)
- | | | |
|------------------------|---------------|-------------|
| Number of Buttonheads: | Missing | <u>NONE</u> |
| | Misshaped | <u>2</u> |
| | Splits > .12" | <u>NONE</u> |
- LNS / 5-31-85
Initial/Date

DATA SHEET 1

TENDON NO. 42 FD

(FIELD) SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LNS / 5-31-85
Initial/Date

13. Tendon End Caps Re-installed

LNS / 5-31-85
Initial/Date

14. Tendon Re-greasing:

Date

Per INRYCO
203
5-31-85

*Data transferred
from procedure
SQ 12.7*

6/7/85

Temperature of Grease in Bulk Container

190°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6359

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

DAH / 6/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 42 FD
 (FIELD) / SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: NONE
 Cracks or splits
 Number not
 properly formed: 2

BEARING PLATE

Degree of Corrosion A, B & C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)
NONE


ANCHOR HEAD

Number LS 036
 Degree of Corrosion A & B
 Cracks NONE

SHIMS


Degree of Corrosion A & B
 Cracks NONE

REMARKS: Much of BEARING plate
corrosion appears to have
been transferred from
retainer plate

SKETCH

Date 5-31-05 Signature J. Williams

ANCHORAGE ASSEMBLY INSPECTION

FIELD END OF TENDON NO. 42 ^{ED} ~~DE~~ _{0-100%}Date 5-31-85 Signature J. J. R.

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON


42 FD DE 6-12-85

J. J. Dunning

SIGNATURE

15-31-85

DATE



COMMENTS:

2 Double Buttonheads

TENDON STRESSING CARD

DATE 5-18-77

TENDON LOCATION 4 4250 JOB NO 21T-505 JOB EARLEY UNIT #2

DO NOT EXCEED 80% OF ULT
1602 KIPS 7600 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 4
GAUGE NO. 31
END 0

JACK NO. 6
GAUGE NO. 107
END 0

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 2000 PSI 500 PSI	P 75	P 75
2. PRIOR TO STRESSING	1500 XX 2000 <u>6.90</u>	1500 XX 2000 <u>5.70</u>
3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION)	<u>3500</u> <u>9.70</u>	<u>3500</u> <u>8.90</u>
4. (MEASURED 1ST STAGE ELONGATION) (LINE 3 MINUS LINE 2)	<u>2.80</u>	<u>3.20</u>
5. (NEW LIFT OFF - SAME PSI AS LINE 3)	<u>3500</u> <u>4.70</u>	<u>3500</u> <u>3.10</u>
6. (FULL RAM EXTENSION)	<u>—</u>	<u>—</u>
7. (MEASURED 2ND STAGE ELONGATION) (LINE 6 MINUS LINE 5)	<u>—</u>	<u>—</u>
8. (NEW LIFT OFF - SAME PSI AS LINE 6)	<u>—</u>	<u>—</u>
9. OVERSTRESS <u>1602</u> KIPS <u>7600</u> PSI	<u>7600</u> <u>10.40</u>	<u>7600</u> <u>9.30</u>
10. TOTAL MEASURED ELONGATION (4+7+9) (LINE 9 MINUS LINE 2 (9-8+7+4))	<u>6931</u> <u>8.50</u>	<u>6850</u> <u>9.40</u>
11. LOCKOFF <u>1602</u> KIPS <u>6850</u> PSI TO <u>6850</u> PSI	<u>6850</u>	<u>6850</u>

REMARKS _____

SHIMS 11"

SHIMS 12 1/2"

FLD. HEAD LS036

BUSHING LS024

FOREMAN Fred L. Smith

BRG. PLATE NONE

BRG. PLATE GM109

Q.C. INSPECTOR C. J. Beale

DATE 5-18-77

TENDON END
PROTECTED OK

TENDON END
PROTECTED OK

05224 2190

TENDON BUTTON HEADING CARD

JOB NO. 21T 05

JOB: BARLEY UNIT 2

TENDON LOCATION: 42FD DATE: 3-31-77

INSPECTION	ACCEPTABLE (CHECK)	REJECTABLE
GO; NO-GO	(OK) 167	3
SPLITS	(OK) 170	0
ECCENTRICITY	(OK) 170	0
TOTAL UNACCEPTABLE HEADS		3

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ☒

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK) N/A

COMMENTS: L2036 THREE (3) DOUBLE HEADS


FOREMAN: Fred Hingle C.C. INSPECTOR: C. J. Bese DATE: 3-31-77

DATA SHEET 1

TENDON NO. 42 FD

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
BUTTRESS "F"
2. Last Date Stressed 5-18-77
3. Anchor End Number from Stressing Card
Field LS 036
Shop LG 024
4. Previous Shim Thickness from Stressing Card
Field 11"
Shop 12 1/2"
5. Remove Tendon End Cap
LNS 1315 6-1-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease DARK BROWN
NO APPARENT MOISTURE, GOOD CONSISTENCY
- 10% COUPLING
LNS 6-1-85
Initial/Date
7. Grease Sample Taken
LNS 6-1-85
Initial/Date
8. Bulk Filler Removed (Gal). 3 gal.
LNS 6-1-85
Initial/Date
9. Anchor End Number As Found GL 063
BROWN LG 024
LNS 6-1-85
Initial/Date
10. Shim Thickness As Found 12 3/8"
LNS 6-1-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)
Number of Buttonheads: Missing NONE
Misshaped NONE
Splits > .12" NONE
LNS 6-1-85
Initial/Date



DATA SHEET 1

TENDON NO. 42 FD

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LNS / 6-1-85
Initial/Date

13. Tendon End Caps Re-installed

LNS / 6-1-85
Initial/Date

14. Tendon Re-greasing:

Date

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

*PER INRYLO
6-1-85
LNS*
*Data transferred
from procedure
SQ 12.7*

6/6/85

160°F

NEW

LOT NO. 5-6359

ENTIRE TENDON

DBH / 6/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. 42 FD
 FIELD/SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: NONE
 Cracks or splits
 Number not
 properly formed: NONE

BEARING PLATE

Degree of Corrosion A, B & C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE


ANCHOR HEAD

Number GL063
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A & B
 Cracks NONE


REMARKS: Much of corrosion on
the bearing plate appears
to have been transferred from
the retaining plate.

SKETCH

gap between outside 4" shims
halves measures 11/16", top only.
gap between halves of inside
4" shim is 7/16", top only

Date 6-1-85 Signature J. J. Shannon

ANCHORAGE ASSEMBLY INSPECTION
SHOP END OF TENDON NO. 42 FD.



Date 6.1.85 Signature J. J. Shumard
DATA SHEET 4a REV. 1

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)


SHOP END

TENDON 42 FDJ. J. Ramey

SIGNATURE

6-1-85

DATE



COMMENTS:

2 UNSEATED BUTTONHEADS - UNABLE
 TO TURN MORE THAN A HALF ROTATION ETC. WITH
 CHANNEL LOCK PLIERS. LJS
6-1-85

DATA SHEET 1

TENDON NO. D-109

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, (B) or C).
BOTTOM AZ 345° 25' 39"
2. Last Date Stressed 6-13-77
3. Anchor End Number from Stressing Card
Field LS069
Shop KA 115
4. Previous Shim Thickness from Stressing Card
Field 5 3/4"
Shop 6 1/4"
5. Remove Tendon End Cap
SDL 1 09051 6-10-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease BROWN AND BLACK TO
DARK BROWN, ANCHORAGE HAD BEEN COLD PACKED
BY INRYCO AFTER INRYCO INSPECTION, ANCHORAGE
WELL COATED, NO VISIBLE MOISTURE
SDL 16-11-85
Initial/Date
7. Grease Sample Taken
SDL 16-10-85
Initial/Date
8. Bulk Filler Removed (Gal). 1/2 GAL
SDL 16-10-85
Initial/Date
9. Anchor End Number As Found LS 069
SDL 16-10-85
Initial/Date
10. Shim Thickness As Found 5 3/4"
SDL 16-10-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)
Number of Buttonheads: Missing 0
Misshaped 1
Splits > .12" 0
SDL 16-10-85
Initial/Date

DATA SHEET 1

TENDON NO. D-100

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SDL 16-10-85
Initial/Date

13. Tendon End Caps Re-installed

SDL 16-10-85
Initial/Date

14. Tendon Re-greasing:

BY INRYCO
Data transferred from
procedure SQ 12.8

Date

6/13/85

Temperature of Grease in Bulk Container

184°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6359

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

DBH 12/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-109
 (FIELD) SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion
 Number missing,
 broken or damaged:

A

NONE

Cracks or splits
 Number not
 properly formed:

0

1

BEARING PLATE

Degree of Corrosion

A, B & C

Cracks

NONE

ANCHORAGE AREA CONCRETE

Cracks (width > 0.01 in.)

NONE > 0.01"

ANCHOR HEAD

Number

LS 069

Degree of Corrosion

A & B

Cracks

NONE

SHIMS

Degree of Corrosion

A & B

Cracks

NONE

REMARKS: SMALL METAL FILINGS

AROUND BUTTONHEADS, SEEM TO


BE FROM ANCHORHEAD MACHINING,

REMOVED ALL FILINGS POSSIBLE

GOOD SHIM GAPS ON TOP,


APPX 3/8" ON BOTTOM

SKETCH



Date 6-10-85 Signature Steven D. Lowe

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. D109



Date 6-10-85 Signature Steven D. Lowe

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2


- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON

D109

Steve D. Lowe 1 6-10-85
SIGNATURE DATE



COMMENTS:

1 DOUBLE BUTTONHEAD (A-4)

NO SPLITS > 0.12"

DATA SHEET 1

TENDON NO. D-109

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, (B) or C).
BOTTOM AZ 204° 34' 21"
2. Last Date Stressed 6-13-77
3. Anchor End Number from Stressing Card
Field LS 069
Shop KA 115
4. Previous Shim Thickness from Stressing Card
Field 5 3/4"
Shop 6 1/4"
5. Remove Tendon End Cap
SDL , 1546 , 6-10-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease BROWN WITH SOME
BLACK PRESERVATIVE, NO VISIBLE MOISTURE,
GOOD COVERAGE ON ANCHORAGE
SDL 16-10-85
Initial/Date
7. Grease Sample Taken
SDL 16-10-85
Initial/Date
8. Bulk Filler Removed (Gal). 12 GAL
SDL 16-10-85
Initial/Date
9. Anchor End Number As Found LI 051
BUSHING KA 115
SDL 16-10-85
Initial/Date
10. Shim Thickness As Found 6 1/4"
SDL 16-10-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)
Number of Buttonheads: Missing 0
Misshaped 0
Splits > .12" 0
SDL 16-10-85
Initial/Date

DATA SHEET 1

TENDON NO. D-109

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SDL 16-10-85
Initial/Date

13. Tendon End Caps Re-installed

SDL 16-10-85
Initial/Date

14. Tendon Re-greasing: BY INRYCO
Date procedure 12.8

(see field end data)

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

/
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-109
 FIELD/SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits 0
 Number not
 properly formed: 0

BEARING PLATE

Degree of Corrosion A, B & C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE > 0.01"


ANCHOR HEAD

Number KA 115
LT 051
 Degree of Corrosion A
 Cracks NONE

SHIMS


Degree of Corrosion A & B
 Cracks NONE

REMARKS: BUSHING FULLY
ENGAGED, SHIM GAPS $\approx \frac{3}{8}$ "
BEARING PLATE DOES NOT
APPEAR TO HAVE BEEN
PAINTED

SKETCH

Date 6-10-85 Signature Steven A. Fournier

ANCHORAGE ASSEMBLY INSPECTION
 SHOP END OF TENDON NO. D 109.



Date 6-10-85 Signature Steven D. Louie

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)


SHOP END

TENDON

D 109

SIGNATURE

DATE

Ther A Low 1-6-10-85

COMMENTS:

NONE MISSING OR MISSHAPED

NO SLEETS > 0.12"

TENDON STRESSING CARD

DATE 6-13-77

TENDON LOCATION 0 109

JOB NO. 217-505

JOB BARLEY UNIT #2

DO NOT EXCEED 80% OF ULT
1402 KIPS 7600 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 5
GAUGE NO. 107
END

JACK NO. 2
GAUGE NO. 54
END

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 2000 PSI 500 PSI 4.15
2. PRIOR TO STRESSING 1800 4.70 1800 4.10
XX 2000
3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION) — — — —
4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2) — — — —
5. (NEW LIFT OFF - SAME PSI AS LINE 3) — — — —
6. (FULL RAM EXTENSION) — — — —
7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5) — — — —
8. (NEW LIFT OFF - SAME PSI AS LINE 6) — — — —
9. OVERSTRESS 1812 KIPS 7200 PSI 7200 9.30 7200 7.80
10. TOTAL MEASURED ELONGATION (4+7+9)
LINE 9 MINUS LINE 2 (9-4+7+4) 6931 4.60 6650 3.70
1402 544 6070
11. LOCKOFF 1402 KIPS 544 PSI TO 6070 PSI 6800 6650

REMARKS

SHIMS 5 3/4"

SHIMS 6 1/4"

FLD. HEAD LS069

BUSHING KAIN

FOREMAN Fred Lingler

BRG. PLATE 6W66

BRG. PLATE NONE

O.C. INSPECTOR C. J. Bell DATE 6-13-77

TENDON END PROTECTED OK

TENDON END PROTECTED OK

0 5 2 2 4 2 3 3 7

TENDON BUTTON READING CARD

JOB NO.

21T-5

JOB:

FAIRLEY UNIT 2

TENDON LOCATION:

01 04R

DATE:

4-7-77

INSPECTION

ACCEPTABLE
(CHECK)

REJECTABLE

GO; NO-GO

(OK) 169

1

SPLITS

(OK) 170

0

ECCENTRICITY

(OK) 170

0

TOTAL UNACCEPTABLE HEADS

1

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ☒

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK) N/A

COMMENTS

LS069

FOREMAN

Fred Lingher

Q.C. INSPECTOR

C. J. Bell

DATE

4-7-77

FORM 780.65-60

APR 1975



an INLAND STEEL company

DATA SHEET 1

TENDON NO. D-119

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
CENTER AZ 176° 40' 38"
2. Last Date Stressed 6-17-77
3. Anchor End Number from Stressing Card
Field HP 106
Shop HW 032
4. Previous Shim Thickness from Stressing Card
Field 6 1/8"
Shop 6 1/4"
5. Remove Tendon End Cap
MH / 9:40 / 6-10-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease GREASE AROUND ANCHORAGE
IS LIGHT BROWN WITH GOOD CONSISTENCY AND NO APPARENT
MOISTURE. 100% COVERAGE ON ANCHORAGE.
7. Grease Sample Taken
MH / 6-10-85
Initial/Date
8. Bulk Filler Removed (Gal). 19 GAL
MH / 6-10-85
Initial/Date
9. Anchor End Number As Found HW032/L1017
MH / 6-10-85
Initial/Date
10. Shim Thickness As Found 6 1/8"
MH / 6-10-85
Initial Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3
or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

MH / 6-10-85
Initial/Date

DATA SHEET 1

TENDON NO. D-119

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

MH 16-10-85
Initial/Date

13. Tendon End Caps Re-installed

MH 16-10-85
Initial/Date

14. Tendon Re-greasing: PER INRYCO

Date

Data transfered from
procedure SQ 12.8

6/12/85

Temperature of Grease in Bulk Container

210 °F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6357

Amount of Grease Replaced (Gal.)

ENTIRE Tendon

DAH 18/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-119
 FIELD (SHOP END) (Circle One)

BUTTONHEAD


Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

ANCHOR HEAD

Number HW032/41017
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A & B
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NO CRACKS WITH A WIDTH
GREATER THAN 0.01" CONSTRUCTION

JOINT APPARENT.

REMARKS: GASKET RETAINING PLATE

HAS MOSTLY 'B' CORROSION LEVEL

SHIM STALKING GOOD SHAPE. BOTH
GAPS ARE 1/4" OR LESS.

SHOP BUSHING IS FULLY ENGAGED
ON ANCHORHEAD.

REMOVED METAL SHAVINGS OF


UNKNOWN ORIGIN FROM BUTTONHEAD

AREA. SHAVINGS (3) WERE ≈ 1" LONG.

SHINIER AND TIGHTLY CURLED.

Date 6-10-85 Signature [Signature]

ANCHORAGE ASSEMBLY INSPECTION
 SHOP END OF TENDON NO. D-119.C



BEARING PLATE CORROSION APPEARS TO HAVE BEEN
 TRANSFERRED FROM THE GASKET RETAINER PLATE.

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

SHOP END

TENDON D-119-C


SIGNATURE

DATE

Joseph M. Hall

12-10-85

↑ or



COMMENTS:

NO UNSEATED, MISSING OR IMPROPERLY FORMED BUTTONHEADS.

ALL BUTTONHEADS ARE WELL ROUNDED WITH FLAT TOPS, AND

HAVE SHINY NEW APPEARANCE

DATA SHEET 1

TENDON NO. D-119

FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
CENTER AZ 13° 19' 22"
2. Last Date Stressed 6-17-77
3. Anchor End Number from Stressing Card
Field HP 106
Shop HW 032
4. Previous Shim Thickness from Stressing Card
Field 6 1/8"
Shop 6 1/4"
5. Remove Tendon End Cap
LNS 10915 16-8-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease Good consistency,
no apparent moisture, predominantly black
preservative
LNS / 6-8-85
Initial/Date
7. Grease Sample Taken
LNS / 6-8-85
Initial/Date
8. Bulk Filler Removed (Gal). 1 Gal.
LNS / 6-8-85
Initial/Date
9. Anchor End Number As Found HP 106
LNS / 6-8-85
Initial/Date
10. Shim Thickness As Found 6 3/8"
LNS / 6-8-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)
Number of Buttonheads: Missing NONE
Misshaped 1
Splits > .12" 2
LNS / 6-8-85
Initial/Date

DATA SHEET 1

TENDON NO. D-119FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LN3 / 6-8-85
Initial/Date

13. Tendon End Caps Re-installed

LN3 / 6-8-85
Initial/Date

14. Tendon Re-greasing:
- PER INRYCO

Date

LN3
6-8-85 procedure
SQ 12.8(see shop end date)

Temperature of Grease in Bulk Container _____

Type Grease (New/Used) _____

If New Grease, Drum No. _____

Amount of Grease Replaced (Gal.) _____

Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-119
 (FIELD) SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing ,
 broken or damaged: NONE
 Cracks or splits 2 > 0.12"
 Number not
 properly formed: 1

BEARING PLATE

Degree of Corrosion A, B + C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE


ANCHOR HEAD

Number HP 106
 Degree of Corrosion A
 Cracks NONE

SHIMS


Degree of Corrosion A
 Cracks NONE

REMARKS: _____

SKETCH

Date 6.8.95 Signature J. J. [Signature]

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. D119



Date 6-8-85 Signature J. J. [Signature]

LEGEND FOR BUTTONHEADS


JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON D119

G. J. [Signature] 6-8-85
SIGNATURE DATE



COMMENTS:

2 splits approx. 0.15"

1 Double Buttonhead

05225 0299 TENDON STRESSING CARD

DATE 6-17-77

TENDON LOCATION D 112 JOB NO 211-505 JOB EARLY UNIT 42

DO NOT EXCEED 80% OF ULT
1500 KIPS 7500 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 4
GAUGE NO. 10
END

JACK NO. 6
GAUGE NO. 122
END

PSI ELONGATION

PSI ELONGATION

- | | | |
|--|-------------|-------------|
| 1. CALCULATED ELONGATION OVER 2000 PSI 500 PSI | <u>4.70</u> | <u>4.30</u> |
| 2. PRIOR TO STRESSING | <u>5.80</u> | <u>5.40</u> |
| 3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION) | <u>—</u> | <u>—</u> |
| 4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2) | <u>—</u> | <u>—</u> |
| 5. (NEW LIFT OFF - SAME PSI AS LINE 3) | <u>—</u> | <u>—</u> |
| 6. (FULL RAM EXTENSION) | <u>—</u> | <u>—</u> |
| 7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5) | <u>—</u> | <u>—</u> |
| 8. (NEW LIFT OFF - SAME PSI AS LINE 6) | <u>—</u> | <u>—</u> |
| 9. OVERSTRESS <u>1505</u> KIPS <u>7150</u> PSI | <u>7150</u> | <u>7150</u> |
| 10. TOTAL MEASURED ELONGATION (4+7+9)
LINE 9 MINUS LINE 2 (9-8+7+4) | <u>4.70</u> | <u>4.20</u> |
| 11. LOCKOFF <u>1402</u> KIPS <u>6931</u> PSI TO <u>6650</u> PSI | <u>6650</u> | <u>6800</u> |

REMARKS

SHIMS 6 1/8"

SHIMS 6 1/4"

FLD. HEAD HP106

BUSHING HW032

FOREMAN Paul Thompson

BRG. PLATE GN

BRG. PLATE GN60

Q.C. INSPECTOR C. J. Bell DATE 6-17-77

TENDON END
PROTECTED OK

TENDON END
PROTECTED OK

0 5 2 2 4 2 3 4 7

TENDON BUTTON HEADING CARD

JOB NO.:

21T-5

JOB:

FORLEY UNIT 2

TENDON LOCATION:

01 1900

DATE:

4-12-77

INSPECTION

ACCEPTABLE
(CHECK)

REJECTABLE

GO; NO-GO

(OK) 169

1

SPLITS

(OK) 168

2

ECCENTRICITY

(OK) 170

0

TOTAL UNACCEPTABLE HEADS

3

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ☒

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK) N/A

COMMENTS

HP106

FOREMAN

Fred Linple

Q.C. INSPECTOR

C. J. Bess

DATE

4-12-77

FORM 750.65-60

APRIL 1975



an INLAND STEEL company

DATA SHEET 1

TENDON NO. D-117

FIELD (SHOP END) (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

GENTER AZ 182° 13' 27"

2. Last Date Stressed 6-20-77

3. Anchor End Number from Stressing Card

Field HP 091

Shop KA 116

4. Previous Shim Thickness from Stressing Card

Field 5 1/2"

Shop 6 1/4"

5. Remove Tendon End Cap

mh / 845 / 6-10-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease GREASE AROUND ANCHORAGE

IS LIGHT BROWN, GOOD CONSISTENCY WITH NO APPARENT MOISTURE

100% COVERAGE OF ASSEMBLY. GREASE DRAINING FROM

VOID IS DARK BROWN. FLOWS EASILY WITH NO APPARENT MOISTURE
TO BLACK

mh / 6-10-85
Initial/Date

7. Grease Sample Taken

mh / 6-10-85
Initial/Date

8. Bulk Filler Removed (Gal). 36 GALS

mh / 6-10-85
Initial/Date

9. Anchor End Number As Found KA 116 / L1 003

mh / 6-10-85
Initial/Date

10. Shim Thickness As Found

5 5/16"

mh / 6-10-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

mh / 6-10-85
Initial/Date

DATA SHEET 1

TENDON NO. D-117

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

MIT 16-10-85
Initial/Date

13. Tendon End Caps Re-installed

MIT 16-10-85
Initial/Date

14. Tendon Re-greasing: BY INRYCO

Date

Data transfered from
procedure SQ 12.8

6/13/85

Temperature of Grease in Bulk Container

184 °F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6359

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

DAN 18/8/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-117
 FIELD (SHOP END) (Circle One)

BUTTONHEAD


Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

ANCHOR HEAD

Number KA116 / L1003
 Degree of Corrosion A WITH B
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A & B
 Cracks NONE

ANCHORAGE AREA CONCRETE
Cracks (width > 0.01 in.)


NO CRACKS WITH A WIDTH
> 0.01" OBSERVED.

REMARKS: GASKET RETAINER PLATE
HAS LEVEL 'B' CORROSION.
SHIM STACK GAP ON TOP SIDE
IS 5/8". BOTTOM SIDE IS 5/16".
SHOP BUSHING REQUIRES ~ ONE
FULL TURN BEFORE BEING FULLY
ENGAGED. (1/8" BELOW BUSHING FACE)

Date 6-10-85 Signature [Signature]

ANCHORAGE ASSEMBLY INSPECTION
SHOP END OF TENDON NO. D-117-C

↑ UP



CORROSION APPEARS TO BE TRANSFERRED FROM
GASKET RETAINER PLATE.

Date 6-10-85 Signature James M. Hall

DATA SHEET 4a

REV. 1

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)


SHOP END

TENDON D-117-C

SIGNATURE

DATE

Kenneth M. Hall 16-10-85
 SIGNATURE DATE



COMMENTS:

NO MISSING, UNSEATED OR IMPROPERLY FORMED BUTTONHEADS

NO SPLITS > 0.12". BUTTONHEADS HAVE SHINY NEW

APPEARANCE, WELL ROUNDED WITH FLAT HEADS

DATA SHEET 1

TENDON NO. D-117FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
CENTER AZ 07°46'13"
2. Last Date Stressed 6-20-77
3. Anchor End Number from Stressing Card
 Field HP 091
 Shop KA 116
4. Previous Shim Thickness from Stressing Card
 Field 5 1/2"
 Shop 6 1/4"
5. Remove Tendon End Cap
LNS / 1015 / 6-8-85
 Initials Time Date
6. Visual Examination of Bulk Filler Grease DARK BROWN WITH
50% BLACK PRESERVATIVE, GOOD CONSISTENCY,
NO APPARENT MOISTURE
LNS / 6-8-85
 Initial/Date
7. Grease Sample Taken
LNS / 6-8-85
 Initial/Date
8. Bulk Filler Removed (Gal). 3 GAL.
LNS / 6-8-85
 Initial/Date
9. Anchor End Number As Found HP 091
LNS / 6-8-85
 Initial/Date
10. Shim Thickness As Found 6 1/4"
LNS / 6-8-85
 Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)
- | | | |
|------------------------|---------------|-------------|
| Number of Buttonheads: | Missing | <u>1</u> |
| | Misshaped | <u>NONE</u> |
| | Splits > .12" | <u>NONE</u> |
- LNS / 6-8-85
 Initial/Date

DATA SHEET 1

TENDON NO. D-117

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

LN3 / 6-8-85
Initial/Date

13. Tendon End Caps Re-installed

LN3 / 6-8-85
Initial/Date

14. Tendon Re-greasing: Pce INRYCO

Date

6-8-85
LN3 procedure SQ 12.8

(see shop end data)

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

Initial/Date

11
12
13
14
15

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-117
 FIELD/SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: 4885 1

Cracks or splits
 Number not
 properly formed: NONE

ANCHOR HEAD

Number AP091

Degree of Corrosion A

Cracks None

SHIMS

Degree of Corrosion A

Cracks NONE

BEARING PLATE


Degree of Corrosion A, B & C

Cracks None

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)


None

REMARKS:

SKETCH

Date 6-8-85 Signature J. J. [Signature]

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. D117



Date 6-8-85 Signature J. J. [Signature]

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2


- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON

D117

J. J. Pham 16-8-85
SIGNATURE DATE



COMMENTS:

one missing Buttonhead

TENDON STRESSING CARD

DATE 6-20-77

TENDON LOCATION D 117

JOB NO. 217-505

JOB EARLEY UNIT #2

DO NOT EXCEED 80% OF ULT
1402 KIPS 7400 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 4
GAUGE NO. 10
END C

JACK NO. 6
GAUGE NO. 122
END C

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 2000 PSI 500 PSI 4.25
2. PRIOR TO STRESSING 1500 5.70 1500 4.10
3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION) — — — —
4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2) — — — —
5. (NEW LIFT OFF - SAME PSI AS LINE 3) — — — —
6. (FULL RAM EXTENSION) — — — —
7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5) — — — —
8. (NEW LIFT OFF - SAME PSI AS LINE 6) — — — —
9. OVERSTRESS 1-06 KIPS 7150 PSI 7150 9.30 7150 9.10
10. TOTAL MEASURED ELONGATION (4+7+9)
LINE 9 MINUS LINE 2 (9-8+7+4) 6931 3.60 6900 5.00
11. LOCKOFF 1402 KIPS 6800 PSI TO 6800 PSI 6800

REMARKS _____

SHIMS 5 1/2"

SHIMS 6 1/4"

FLD. HEAD HP091

BUSHING KALIL

FOREMAN Fred Linde

BRG. PLATE NONE

BRG. PLATE GN70

O.C. INSPECTOR C. J. Beale DATE 6-20-77

TENDON END PROTECTED OK

TENDON END PROTECTED OK

0 5 2 2 4 2 3 4 5

TENDON BUTTON HEADING CARD

JOB NO. 21T-5

JOB: FAIRLEY UNIT 2

TENDON LOCATION: 01 1700 DATE: 4-12-77

INSPECTION	ACCEPTABLE (CHECK)	REJECTABLE
GO; NO-GO	(OK) <u>170</u>	<u>0</u>
SPLITS	(OK) <u>170</u>	<u>0</u>
ECCENTRICITY	(OK) <u>170</u>	<u>0</u>
TOTAL UNACCEPTABLE HEADS		<u>0</u>

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ✓

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK) NIA

COMMENTS HP 091

FOREMAN Fred Anglin Q.C. INSPECTOR C. J. Rose DATE 4-12-77

DATA SHEET 1

TENDON NO. D-227

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
TOP AZ 213° 45' 11"
2. Last Date Stressed 6-10-77
3. Anchor End Number from Stressing Card
Field HP 150
Shop HW 038
4. Previous Shim Thickness from Stressing Card
Field 5"
Shop 5 1/2"
5. Remove Tendon End Cap
SDL 1 1 6-10-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease BROWN WITH SOME
BLACK PRESERVATIVE PRESENT, GOOD COVERAGE,
SMALL (UNCOLLECTABLE) AMOUNT OF WATER DRIPPED
OUT WHEN BOLT LOOSENEED PROBABLY AROUND
RETAINER PLATE, NO VISIBLE MOISTURE
IN CAN OR ON ANCHORAGE
SDL 6-10-85
Initial/Date
7. Grease Sample Taken
SDL 6-10-85
Initial/Date
8. Bulk Filler Removed (Gal). 4 GAL
SDL 6-10-85
Initial/Date
9. Anchor End Number As Found HP 150
SDL 6-10-85
Initial/Date
10. Shim Thickness As Found 5 1/4"
SDL 6-10-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3
or 4 as applicable. (Attach Data Sheets)
Number of Buttonheads: Missing 0
 Misshaped 0
 Splits > .12" 0
SDL 6-10-85
Initial/Date

DATA SHEET 1

TENDON NO. D-227

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SDL 16-10-85
Initial/Date

13. Tendon End Caps Re-installed

SDL 16-10-85
Initial/Date

14. Tendon Re-greasing:

Date

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

BY INRYCO
Data transferred from
procedure SQ 12.8

6/15/85

190°F

NEW

5-5526

LOT NO. 5-6359

ENTIRE Tendon

DAH 18/10/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-227
 (FIELD/SHOP END (Circle One))

BUTTONHEAD

Degree of Corrosion A
 Number missing ,
 broken or damaged: 0
 Cracks or splits 0
 Number not
 properly formed: 0

BEARING PLATE

Degree of Corrosion A, B & C
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)
NONE > 0.01 "


ANCHOR HEAD

Number HP150
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A & B
 Cracks NONE

REMARKS: ANCHORAGE LOOKS
GOOD, GOOD SHIM GAPS

SKETCH

Date 6-10-85 Signature [Signature]

LEGEND FOR BUTTONHEADS


JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

FIELD END

TENDON D-227

Steven A. Lowe 16-10-85
SIGNATURE DATE



COMMENTS:

NONE MISSING OR MISSHAPEDNO SPlITS > 0.12"

DATA SHEET 1

TENDON NO. D-227

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

BOTTOM AZ 96° 14' 49"

2. Last Date Stressed 6-10-77

3. Anchor End Number from Stressing Card

Field HP 150

Shop HW 038

4. Previous Shim Thickness from Stressing Card

Field 5"

Shop 5 1/2"

5. Remove Tendon End Cap

mmH 11500 1 6-10-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease LIGHT BROWN IN

COLOR, GOOD CONSISTENCY WITH NO APPARENT

MOISTURE, 100 % COVERAGE ON ANCHORAGE ASSEMBLY

7. Grease Sample Taken

mmH 16-10-85
Initial/Date

8. Bulk Filler Removed (Gal). 17 GAL

mmH 16-10-85
Initial/Date

9. Anchor End Number As Found HW 038 / LI 047

mmH 16-10-85
Initial/Date

10. Shim Thickness As Found

4 3/4"

mmH 16-10-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

mmH 16-10-85
Initial/Date

DATA SHEET 1

TENDON NO. D-227

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

JMH / 6-10-85
Initial/Date

13. Tendon End Caps Re-installed

JMH / 6-10-85
Initial/Date

14. Tendon Re-greasing: PER INRYCO
Date procedure SQ 12.8

(see field end data)

Temperature of Grease in Bulk Container _____

Type Grease (New/Used) _____

If New Grease, Drum No. _____

Amount of Grease Replaced (Gal.) _____

/
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-227
 FIELD (SHOP END) (Circle One)

BUTTONHEAD


Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

ANCHOR HEAD

Number HW038/L1047
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A & SOME B
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NO CRACKS WITH A WIDTH > 0.01"

REMARKS: GASKET RETAINER PLATE

HAS 'B' LEVEL CORROSION OVER

40% OF ITS SURFACE REST IS 'A'

CORROSION LEVEL.

SHIM STACK IS STRAIGHT AND

TIGHT. GAPS ARE GOOD $\approx 1/4"$ ON


BOTH SIDES.

Date 6-10-85 Signature [Signature]

ANCHORAGE ASSEMBLY INSPECTION

SEOP END OF TENDON NO. D-227, 6.71cm

UP



Date 6/10/85 Signature [Signature]

LEGEND FOR BUTTONHEADS


JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)

SHOP END

TENDON D-227 BOTTOM

Joseph M. Hall 16-10-88
SIGNATURE DATE

COMMENTS:

NO UNSEATED, IMPROPERLY FORMED OR MISSHAPED BUTTONHEADS.

NO MISSING BUTTONHEADS. NO SPLITS GREATER THAN 0.12"

ANCHORHEAD & BUTTONHEADS HAVE NEW SHINY APPEARANCE. BUTTONHEADS

ARE WELL ROUNDED WITH FLAT HEADS. BUSHING SHOWS SOME WATER

SPOTS (LIGHT RUST) PROBABLY FROM INITIAL INSTALLATION. NO MOISTURE OBSERVED.

05225 0339 **TENDON STRESSING CARD**

DATE 6-10-77

TENDON LOCATION 0 227 JOB NO. 21T-505 JOB EARLY INTT 47

DO NOT EXCEED 80% OF ULT
1502 KIPS 7500 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 4
GAUGE NO. 122
END T

PSI	ELONGATION
-----	------------

JACK NO. 6
GAUGE NO. 24
END 9

PSI	ELONGATION
-----	------------

1. CALCULATED ELONGATION OVER 2000 PSI 1500 PSI 0.00
2. PRIOR TO STRESSING 1500 5.50 1500 3.30
~~XY 2000~~
3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION) — — — —
4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2) — — — —
5. (NEW LIFT OFF - SAME PSI AS LINE 3) — — — —
6. (FULL RAM EXTENSION) — — — —
7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5) — — — —
8. (NEW LIFT OFF - SAME PSI AS LINE 6) — — — —
9. OVERSTRESS 1496 KIPS 7100 PSI 7100 8.80 7100 7.40
10. TOTAL MEASURED ELONGATION (4+7+9)
LINE 9 MINUS LINE 2 (9-2+7+4) 6981 3.30 4.10
11. LOCKOFF 1407 KIPS 5646 PSI TO 6650 6960

REMARKS _____ SHIMS 5" SHIMS 5 1/2"

_____ FLD. HEAD HP150 BUSHING HW638

FOREMAN Paul Linke BRG. PLATE GN BRG. PLATE NONE

Q.C. INSPECTOR C. J. Bell DATE 6-10-77 TENDON END PROTECTED OK TENDON END PROTECTED OK

0 5 2 2 2 3 8 7

TENDON BUTTON HEADING CARD

JOB NO. 21T-5

JOB: FARLEY UNIT 2

TENDON LOCATION: 02 274T

DATE: 4-8-77

INSPECTION	ACCEPTABLE (CHECK)	REJECTABLE
------------	-----------------------	------------

GO; NO-GO	(OK) 170	0
-----------	----------	---

SPLITS	(OK) 170	0
--------	----------	---

ECCENTRICITY	(OR) 170	0
--------------	----------	---

TOTAL UNACCEPTABLE HEADS		0
--------------------------	--	---

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ☒

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK) N/A

COMMENTS: HP 150

FOREMAN: *Ed Simpson* Q.C. INSPECTOR: *C. J. Beale* DATE: 4-8-77

DATA SHEET 1

TENDON NO. D-307

FIELD (SHOP END) (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).

TOP AZ 99°39'55"

2. Last Date Stressed 6-13-77

3. Anchor End Number from Stressing Card

Field LS 010

Shop LG 021

4. Previous Shim Thickness from Stressing Card

Field 4 3/4"

Shop 7"

5. Remove Tendon End Cap

JMH 116:30 16-10-85
Initials Time Date

6. Visual Examination of Bulk Filler Grease LIGHT BROWN

COLOR WITH GOOD CONSISTENCY, NO APPARENT
MOISTURE 90 % COVERAGE OVER ASSEMBLY

7. Grease Sample Taken

JMH 16-10-85
Initial/Date

JMH 16-10-85
Initial/Date

8. Bulk Filler Removed (Gal). 18 GAL

JMH 16-10-85
Initial/Date

9. Anchor End Number As Found LG021 / L1002

JMH 16-10-85
Initial/Date

10. Shim Thickness As Found 7"

JMH 16-10-85
Initial/Date

11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)

Number of Buttonheads:

Missing

0

Misshaped

0

Splits > .12"

0

JMH 16-10-85
Initial/Date

DATA SHEET 1

TENDON NO. D-307

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

MPH 16-10-85
Initial/Date

13. Tendon End Caps Re-installed

MPH 16-10-85
Initial/Date

14. Tendon Re-greasing: PER IN2400

Date

Data transferred from
procedure SQ 12.8

6/13/85

Temperature of Grease in Bulk Container

184°F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6359

Amount of Grease Replaced (Gal.)

ENTIRE Tendon

DBH 12/18/85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-307
 FIELD SHOP END (Circle One)

BUTTONHEAD


Degree of Corrosion A
 Number missing ,
 broken or damaged: 0
 Cracks or splits 0
 Number not
 properly formed: 0

ANCHOR HEAD

Number LG 021 / L1002
 Degree of Corrosion A
 Cracks NONE

SHIMS

Degree of Corrosion A
 Cracks NONE

SKETCH

BEARING PLATE

Degree of Corrosion A WITH B
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)


NO CRACKS WITH A WIDTH
GREATER THAN 0.01"

REMARKS: GASKET RETAINER
PLATE HAS 60% 'B' LEVEL
CORROSION. SHOP BUSHING
IS FULLY ENGAGED.
SHIM STACK GAPS ARE GOOD. (< 1/4")
OVERALL GOOD SHIM STACK SHAPE.

Date 6-10-85 Signature [Signature]

ANCHORAGE ASSEMBLY INSPECTION
 SHOP END OF TENDON NO. D-307

UP



LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)


SHOP END

TENDON D-307 TOP

SIGNATURE

10-10-85
DATE

Joseph M. Hall
UP



COMMENTS:

POLISHED AREA WITH SMALL HARDNESS TEST INDENTATIONS

NO MISSING, UNSEATED OR IMPROPERLY FORMED BUTTONHEADS

NO SPLITS GREATER THAN 0.12" WIDE. BUTTONHEADS WELL

ROUNDED WITH FLAT TOPS. SHINEY NEW APPEARANCE. BUSHING

HAS POLISHED AREA WHERE SMALL INDENTATIONS ARE PRESENT

(PROBABLY FROM HARDNESS TESTING).

DATA SHEET 1

TENDON NO. D-307

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
TOP AZ 330° 20' 05"
2. Last Date Stressed 6-13-77
3. Anchor End Number from Stressing Card
Field LS 010
Shop LG 021
4. Previous Shim Thickness from Stressing Card
Field 4 3/4"
Shop 7"
5. Remove Tendon End Cap
SDL | 1030 | 6-10-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease GOOD COVERAGE.
BROWN, DARK BROWN & BLACK COLOR MIXED, NO
VISIBLE MOISTURE
SDL | 6-10-85
Initial/Date
7. Grease Sample Taken
SDL | 6-10-85
Initial/Date
8. Bulk Filler Removed (Gal). 2 1/2 GAL
SDL | 6-10-85
Initial/Date
9. Anchor End Number As Found LS 010
SDL | 6-10-85
Initial/Date
10. Shim Thickness As Found 4 7/8"
SDL | 6-10-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)
Number of Buttonheads: Missing NONE
Misshaped NONE
Splits > .12" NONE
SDL | 6-10-85
Initial/Date

DATA SHEET 1

TENDON NO. D-307

FIELD SHOP END (Circle One)

12 Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

SDL 6-10-85
Initial/Date

13. Tendon End Caps Re-installed

SDL 6-10-85
Initial/Date

14. Tendon Re-greasing: BY INRYCO
Date procedure 5912.8

(see shop end data)

Temperature of Grease in Bulk Container _____

Type Grease (New/Used) _____

If New Grease, Drum No. _____

Amount of Grease Replaced (Gal.) _____

/
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-307
 (FIELD) SHOP END (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing ,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

BEARING PLATE

Degree of Corrosion A & B
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE > 0.01 "


ANCHOR HEAD

Number LS D10
 Degree of Corrosion A & B
 Cracks NONE

SHIMS

Degree of Corrosion A & B
 Cracks NONE

REMARKS: GOOD SHIM GAP,
SMALL AMOUNT GROUT ON
LOWER RIGHT HAND CORNER OF
BEARING PLATE

SKETCH

Date 6-10-85 Signature John D. Loe

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

● Missing Buttonhead or Wire

Ø Unseated Buttonhead

⊗ Improperly Formed/Misshaped
Buttonhead① Buttonhead with Split
(Document the Split Size)

FIELD END


TENDON

D-307

Steven D. Lowe
SIGNATURE

16-10-85

DATE



COMMENTS:

NONE MISSING, OR MISSHAPED

NO SPlITS > 0.12"

TENDON STRESSING CARD

DATE 6-13-77

TENDON LOCATION 0 307 JOB NO. 21T-505 JOB SAFELY UNIT 42

DO NOT EXCEED 80% OF ULT
1502 KIPS 7400 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 5
GAUGE NO. 107
END +

JACK NO. 3
GAUGE NO. 10
END +

PSI ELONGATION

PSI ELONGATION

- | | PSI | ELONGATION | PSI | ELONGATION |
|--|-------------------------|------------|-------------------------|------------|
| 1. CALCULATED ELONGATION OVER 2000 PSI 500 PSI | 3.75 | | 3.75 | |
| 2. PRIOR TO STRESSING | 1500
2000 | 4.80 | 1500
2000 | 4.80 |
| 3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION) | — | — | — | — |
| 4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2) | — | — | — | — |
| 5. (NEW LIFT OFF - SAME PSI AS LINE 3) | — | — | — | — |
| 6. (FULL RAM EXTENSION) | — | — | — | — |
| 7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5) | — | — | — | — |
| 8. (NEW LIFT OFF - SAME PSI AS LINE 6) | — | — | — | — |
| 9. OVERSTRESS <u>1422</u> KIPS <u>7050</u> PSI | 7050 | 8.20 | 7050 | 9.10 |
| 10. TOTAL MEASURED ELONGATION (4+7+9)
(LINE 9 MINUS LINE 2 (9-8+7+4)) | 6931 | 3.40 | 6900 | 4.30 |
| 11. LOCKOFF <u>1402</u> KIPS <u>6700</u> PSI TO <u>6700</u> PSI | 6700 | | 6900 | |

REMARKS _____

SHIM 3 4 3/4"

SHIMS 7"

FLD. HEAD 65010

BUSHING 66021

FOREMAN Paul Hughes

BRG. PLATE 6N176

BRG. PLATE 6K13

Q.C. INSPECTOR C. J. Beece

DATE 6-13-77

TENDON END
PROTECTED OK

TENDON END
PROTECTED OK

05224 2399

TENDON BUTTON HEADING CARD

JOB NO. 21T 5

JOB: EARLEY UNIT 2

TENDON LOCATION: 03 7TT

DATE: 4-20-77

INSPECTION	ACCEPTABLE (CHECK)	REJECTABLE
------------	-----------------------	------------

GO; NO-GO	(OK) 170	0
-----------	----------	---

SPLITS	(OK) 170	0
--------	----------	---

ECCENTRICITY	(OK) 170	0
--------------	----------	---

TOTAL UNACCEPTABLE HEADS		0
--------------------------	--	---

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ☒

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK) N/A

COMMENTS: L5010

FOREMAN: Fred Simpson Q.C. INSPECTOR: C. J. Beebe DATE: 4-20-77

DATA SHEET 1

TENDON NO. D-319FIELD SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
CENTER AZ 133° 19' 22"
2. Last Date Stressed 6-17-77
3. Anchor End Number from Stressing Card Field HP033
Shop HW159
4. Previous Shim Thickness from Stressing Card Field 6"
Shop 6 1/4"
5. Remove Tendon End Cap JMH 1400 6-10-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease LIGHT BROWN
COLOR WITH GOOD CONSISTENCY, NO APPARENT MOISTURE
100% COVERAGE.
7. Grease Sample Taken JMH 6-10-85
Initial/Date
8. Bulk Filler Removed (Gal). 24 JMH 6-10-85
Initial/Date
9. Anchor End Number As Found HW159 / L1021 JMH 6-10-85
Initial/Date
10. Shim Thickness As Found 6 5/16" JMH 6-10-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)
- | | | |
|------------------------|---------------|----------|
| Number of Buttonheads: | Missing | <u>0</u> |
| | Misshaped | <u>0</u> |
| | Splits > .12" | <u>0</u> |
- JMH 6-10-85
Initial/Date

DATA SHEET 1

TENDON NO. D-319

FIELD SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

DAH 16-10-85
Initial/Date

13. Tendon End Caps Re-installed

DAH 16-10-85
Initial/Date

14. Tendon Re-greasing: PER INEYCO
Date Data transferred from
procedure SQ 12.8

6/14/85

Temperature of Grease in Bulk Container

178 °F

Type Grease (New/Used)

NEW

If New Grease, Drum No.

LOT NO. 5-6359

Amount of Grease Replaced (Gal.)

ENTIRE TENDON

DAH 16-10-85
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-319
 FIELD (SHOP END) (Circle One)

BUTTONHEAD

Degree of Corrosion A
 Number missing,
 broken or damaged: 0
 Cracks or splits
 Number not
 properly formed: 0

BEARING PLATE

Degree of Corrosion A WITH SOME B
 Cracks NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NO CRACKS OBSERVED > 0.01"

NOTE: CONSTRUCTION JOINT THRU

ANCHOR HEAD

Number HW159/LI021
 Degree of Corrosion A
 Cracks NONE


LOWER QUARTER OF ANCHORAGE
IN SOUND CONDITION. COSMETIC
GROUT IN GOOD CONDITION.

SHIMS

Degree of Corrosion A
 Cracks NONE

REMARKS: GASKET RETAINER
PLATE MOSTLY 'B' LEVEL CORROSION.
SHOP BUSHING FULLY ENGAGED
ON ANCHORHEAD.

SKETCH



SHIM STACK GAPS < 1/4"
GOOD UNIFORM STACK, STRAIGHT
& SOUND.

Date 6-10-85 Signature W. M. Hall

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Ø Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- Buttonhead with Split
(Document the Split Size)


SHOP END

TENDON

D-319TOP
↑

SIGNATURE

DATE

Joseph M. Hall 16-10-85

COMMENTS:

NO MISSING, UNSEATED OR IMPROPERLY FORMED BUTTONHEADSNO SPLITS GREATER THAN 0.12" WIDE. BUTTONHEADS AREWELL ROUNDED WITH FLAT TOPS. BUTTONHEADS HAVE A SHINYNEW APPEARANCE

DATA SHEET 1

TENDON NO. D-319

FIELD/SHOP END (Circle One)

1. Location (Buttress, Elevation/Azimuth, and T, B or C).
CENTER AZ 296° 40' 38"
2. Last Date Stressed 6-17-77
3. Anchor End Number from Stressing Card
Field HP 033
Shop HW 159
4. Previous Shim Thickness from Stressing Card
Field 6"
Shop 6 1/4"
5. Remove Tendon End Cap
SDL 1 1306 1 6-10-85
Initials Time Date
6. Visual Examination of Bulk Filler Grease DARK BROWN &
BLACK IN COLOR, NO VISIBLE MOISTURE,
GOOD COVERAGE
7. Grease Sample Taken
SDL 6-10-85
Initial/Date
8. Bulk Filler Removed (Gal). 6 GAL
SDL 6-10-85
Initial/Date
9. Anchor End Number As Found HP 033
SDL 6-10-85
Initial/Date
10. Shim Thickness As Found 6"
SDL 6-10-85
Initial/Date
11. Record Anchorage Assembly Inspection Results on Data Sheets 2 and 3 or 4 as applicable. (Attach Data Sheets)
Number of Buttonheads: Missing 0
Misshaped 0
Splits > .12" 0
SDL 6-10-85
Initial/Date

DATA SHEET 1

TENDON NO. D-319

FIELD/SHOP END (Circle One)

12. Adjacent Tendon Inspection Required

☐ YES ☒ NO

If YES, why? _____

gmH / 6-10-85
Initial/Date

13. Tendon End Caps Re-installed

SDL / 6-10-85
Initial/Date

14. Tendon Re-greasing: BY INRYCO

Date

procedure SQ12.8

(see shop end data)

Temperature of Grease in Bulk Container

Type Grease (New/Used)

If New Grease, Drum No.

Amount of Grease Replaced (Gal.)

/
Initial/Date

ANCHORAGE ASSEMBLY INSPECTION

TENDON NO. D-319
 (FIELD/SHOP END (Circle One))

BUTTONHEAD

Degree of Corrosion
 Number missing,
 broken or damaged:

A
0

Cracks or splits
 Number not
 properly formed:

0
0

BEARING PLATE

Degree of Corrosion

A & B

Cracks

NONE

ANCHORAGE AREA CONCRETE
 Cracks (width > 0.01 in.)

NONE > 0.01"

ANCHOR HEAD

Number

HP033

Degree of Corrosion

A

Cracks

NONE

SHIMS

Degree of Corrosion


A & B

Cracks

NONE


REMARKS: ANCHORAGE LOOKS

GOOD, BEARING PLATE # BS52

SKETCH

Date 6-10-85 Signature Thom A. Dine

ANCHORAGE ASSEMBLY INSPECTION
FIELD END OF TENDON NO. D-319



Date 6-10-85 Signature Steven A. Lowe

LEGEND FOR BUTTONHEADS

JOSEPH M. FARLEY NUCLEAR PLANT UNIT 2

- Missing Buttonhead or Wire
- Unseated Buttonhead
- ⊗ Improperly Formed/Misshaped Buttonhead
- ① Buttonhead with Split
(Document the Split Size)

FIELD END


TENDON

D-319

SIGNATURE

H. D. Low 16-10-85

DATE



COMMENTS:

NONE MISSING OR MISFORMED

NO SPlITS > 0.12"

TENDON STRESSING CARD

DATE 6-17-77

TENDON LOCATION 0 319

JOB NO. 21T-505

JOB EARLEY UNIT 42

DO NOT EXCEED 80% OF ULT
1500 KIPS 7500 PSI

LINES IN PARENTHESIS () FOR
STAGE STRESSING ONLY

JACK NO. 2
GAUGE NO. 54
END

JACK NO. 1
GAUGE NO. 51
END

PSI ELONGATION

PSI ELONGATION

1. CALCULATED ELONGATION OVER 2000 PSI 500 PSI
2. PRIOR TO STRESSING
3. 3500 TO 4000 PSI (OR FULL RAM EXTENSION)
4. (MEASURED 1ST STAGE ELONGATION)
(LINE 3 MINUS LINE 2)
5. (NEW LIFT OFF - SAME PSI AS LINE 3)
6. (FULL RAM EXTENSION)
7. (MEASURED 2ND STAGE ELONGATION)
(LINE 6 MINUS LINE 5)
8. (NEW LIFT OFF - SAME PSI AS LINE 6)
9. OVERSTRESS 1500 KIPS 7150 PSI
10. TOTAL MEASURED ELONGATION (4+7+9)
LINE 9 MINUS LINE 2 (9-8+7+4) 6931
11. LOCKOFF 1500 KIPS 6700 PSI TO 6700 PSI

1500
XX 2000

4.20

4.80

1500
YY 2000

4.20

4.60

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

—

7150

8.80

7150

9.40

4.00

4.80

4.80

4.80

REMARKS

SHIMS 6"

SHIMS 6 1/4"

FLD. HEAD HPA33

BUSHING 414159

FOREMAN Paul Langer

BRG. PLATE FS

BRG. PLATE EP3

Q.C. INSPECTOR C. J. Beel DATE 6-17-77

TENDON END PROTECTED OK

TENDON END PROTECTED OK

05224 2412

TENDON BUTTON HEADING CARD

JOB NO.: 2412-5

JOB: FARLEY UNIT 2

TENDON LOCATION: 03 1900 DATE: 4-7-77

INSPECTION	ACCEPTABLE (CHECK)	REJECTABLE
------------	-----------------------	------------

GO; NO-GO	(OK) 170	0
-----------	----------	---

SPLITS	(OK) 167	3
--------	----------	---

ECCENTRICITY	(OK) 170	0
--------------	----------	---

TOTAL UNACCEPTABLE HEADS		3
--------------------------	--	---

TEMPORARY COVERING APPLIED
TO TENDON ENDS (CHECK) ☒

(OR)

GREASE CANS INSTALLED
BOTH ENDS (CHECK) N/A

COMMENTS: HP033

FOREMAN: And Lingle Q.C. INSPECTOR: C. J. Beal DATE: 4-7-77

APPENDIX A

JOSEPH M. FARLEY NUCLEAR PLANT
UNIT 2
TENDON SURVEILLANCE

TENDON SAMPLE SELECTION PROCEDURE

1.0 Purpose

This procedure provides guidelines to be applied when selecting the containment tendon surveillance test sample and alternate test sample. Its implementation will assure that the test population selection will be determined on a random but representative basis as required.

2.0 References

- 2.1 Nuclear Regulatory Commission (NRC) Regulatory Guide 1.35, Revision 2, "Inservice Inspection of Ungrouted Tendons in Prestressed Concrete Containment Structures".
- 2.2 Technical Specification 3/4.6.1.6.1, "Containment Structural Integrity".
- 2.3 Final Safety Analysis Report, Section 3.8.1.7.3.
- 2.4 Bechtel letter number AP-3029, dated 2-7-78.

3.0 Prerequisites

Prior to the selection of the test sample population, the following reviews should be conducted:

- 3.1 Plant operating status: Determine whether the scheduled tendon surveillance will be performed during plant operation.
- 3.2 ALARA conditions: Determine the radiation levels in the rooms where tendon access is required.
- 3.3 Previous tendon surveillance test reports: Review the previous tendon surveillance test reports for locations of previous test samples and test results.

4.0 Precautions

Compliance with this procedure will assure the following:

- 4.1 Regulatory requirements specify that tendon sample selection must be performed on a random but representative basis.
- 4.2 Some tendons are inaccessible during plant operational modes. Samples from these areas must be tested when conditions permit.
- 4.3 Technical Specification requirements necessitate that the tendons adjacent to each test sample be accessible for testing.

5.0 Instructions for Sample Selection

- 5.1 Review the regulatory requirements referenced in Section 2.0 and determine the required number of tendons to be tested during the next planned surveillance.
- 5.2 Review the precautions listed in Section 4.0 and determine applicability to the next planned surveillance as follows:
 - 5.2.1 If the tendon surveillance is to be conducted concurrently with a plant outage, tendons which are inaccessible during operation (e.g., dome and vertical tendons adjacent to the main steam vents) should be tested during this surveillance, unless a review of previous test sample populations indicates that this portion of the containment has been representatively tested.
 - 5.2.2 Plant operating status may affect the radiation levels in certain areas during operation or during an outage. Determine the expected radiation levels in rooms during the next surveillance and evaluate selection to minimize personnel exposure.
 - 5.2.3 Review the previous tendon surveillance test reports and determine if any abnormal conditions were previously documented. Evaluate corrective action recommended for future surveillances and include these tendons in the test sample as appropriate.
 - 5.2.4 Select tendons which have accessible adjacent tendons. Should a defective tendon be found, the Technical Specification

requires that containment integrity be evaluated based upon the acceptability of adjacent tendons.

- 5.3 Insure that selected tendons, including alternates, are equally spaced geometrically. An equal number of tendons shall be selected, to the extent practical, from each of the three 60° dome tendon groups, from the inner and outer vertical tendon groups and from the three hoop tendon groups. This will derive the most representative sample upon which to evaluate containment integrity.
- 5.4 Select tendons to limit their participation to not more than two surveillances, unless conditions evaluated in Section 5.2.3 require continued surveillance.
- 5.5 Select tendons to be tested, where possible, which had portions of their sheathing removed during installation of the tendon.
- 5.6 Select tendons which have both ends readily accessible. Avoid high radiation zones.

6.0 Documentation

Document the tendon sample population selection in accordance with Section 4.2 of FNP-2-STP-609.0.

APPENDIX B

FARLEY NUCLEAR PLANT
UNIT 2
TENDON SURVEILLANCE

SAFETY AND SERVICING GUIDELINES

1.0 Purpose

This procedure provides safety guidelines to be observed during tendon surveillance. This procedure also provides guidelines and a checklist to be followed for preoperational servicing and inspection of tendon surveillance equipment, load testing the work platform and spider staging, and preparing the equipment for storage after tendon surveillance is completed. Adherence to this procedure will insure that the tendon surveillance equipment is safe to use, and used safely.

2.0 References

- 2.1 U-421018, Spider Staging Operating, Assembly, Service and Inspection Manual.
- 2.2 U-421019, Spider Staging Service and Parts Manual - Model No. ST-18.

3.0 Procedure

- 3.1 During tendon surveillance and all associated activities the safety guidelines given in Attachment #1, "Safety Guidelines", shall be followed.
- 3.2 Prior to beginning tendon surveillance, the equipment will be serviced and inspected in accordance with Attachment #2, "Preoperational Service and Inspection Checklist". This service and inspection will be repeated after six months if tendon surveillance is still in progress.
- 3.3 Prior to using the A-frame, work platform or spider staging, they will be load tested in accordance with Attachment #3, "Load Test Checklist".
- 3.4 Upon completion of tendon surveillance, the equipment will be stored in accordance with Attachment #4, "Guidelines for Storage of Equipment".

4.0 Documentation

As the items on Attachments 2, 3 and 4 are completed, the blank on the checklist by that item should be initialed. When a checklist is completed, the Test Coordinator or his designee will sign and date the checklist to verify that it has been completed.

APPENDIX B

ATTACHMENT 1

FARLEY NUCLEAR PLANT
UNIT 2
TENDON SURVEILLANCE

SAFETY GUIDELINES

1. Wear hard hats and shoes or boots with good soles and leather uppers that afford some reasonable protection against impact or penetration. Tennis or sport shoes are not acceptable.
2. Wear ear protection when working in posted areas.
3. Wear a safety belt tied off to an independent safety line when in the spider staging or transferring between the spider staging and the A-frame or platform.
4. The Davcon ironworker foreman will inspect the hoist cables, and check the emergency cut-off switches and brakes daily.
5. Only one person on a section of ladder at one time.
6. All tools, etc., are to be pulled up by handline or cherry picker. DO NOT climb a ladder without the free use of both hands.
7. Be alert to potential pinch points especially when handling grease cans and drums.
8. Be alert to the potential for burns from drum heater or hot grease.
9. DO NOT lift or lower any load without either voice or visual signals.
10. Only one person to signal at a time.
11. Stay out from under loads being lifted or lowered.
12. No eating, drinking or smoking while in RCA.
13. Wear protective clothing as required while in RCA.
14. No more than 5 people on the platform at one time except in case of emergency.

ATTACHMENT 1
(Continued)

SAFETY GUIDELINES

15. No more than 2 people on the spider staging at one time except in case of emergency.
16. The following apply to the use of Viscosity Industrial #16 solvent:
 - a. Material contains a high concentration of mineral spirits and, therefore, is extremely flammable.
 - b. It must be used only in well ventilated areas.
 - c. The area must be roped off and flammable caution signs and no smoking signs must be posted.
 - d. A fire extinguisher must be readily available to include on the platform.
17. Platform locks shall be down when the platform is stationary.
18. All tools shall be secured when not in use.
19. Housekeeping and the cleanliness of the area are to be maintained throughout the surveillance. Grease spills are to be cleaned up as soon as practical.
20. Pulling winch on A-frame is not to be used for lifting people, only for repositioning the A-frame once it is on top of the Containment Building.
21. IW foreman to check oil level in all winches weekly.

ATTACHMENT 2

FARLEY NUCLEAR PLANT
UNIT 2
TENDON SURVEILLANCE

PREOPERATIONAL SERVICE AND INSPECTION CHECKLIST

A-FRAME

1. Visually inspect welds and structural soundness.
2. Replace plywood decking.
3. Change oil in pulling winch gear box and test operation. Lubricate winch as needed.
4. Change oil in lifting winch gear box and test operation. Lubricate winch as needed.
5. Check electrical contacts and replace as needed.
6. Check all bolts or pins used to support winch cables, platform cables, and spider staging cables for wear and corrosion. Replace as necessary.
7. Inspect brakes and gears for wear on both winches.
8. Inspect winch cables for wear, kinks, broken wires, corrosion and other defects. Grease cables, if dry.
9. Inspect Hillman Rollers for wear, corrosion and proper operation. Replace chains, if needed. Be sure tapered chains are properly positioned to match rail diameter. Apply light coat of oil to chain rollers.

PERFORMED
UNDER INSPECTION
AND REPAIR
PROGRAM
DAN 8/8/85

A-FRAME

#1

#2

ATTACHMENT 2
(Continued)

PREOPERATIONAL SERVICE AND INSPECTION CHECKLIST

WORK PLATFORM	WORK PLATFORM	
	#1	#2
1. Visually inspect for structural soundness.	_____	_____
2. Inspect plywood decking - replace as needed.	_____	_____
3. Check cable locking device for operation.	_____	_____
4. Check all electrical controls and connections for good condition and proper operation.	_____	_____
5. Change oil in winch gear boxes and test operation. Lubricate winch as needed.	_____	_____
6. Inspect brakes and gears on winches for wear.	_____	_____
7. Inspect winch cables for kinks, broken wires, corrosion, wear and other defects. Grease cables, if dry.	_____	_____
SPIDER STAGING	SPIDER STAGING	
	#1	#2
1. Visually inspect for structural soundness.	_____	_____
2. Check cable tension holder for proper operation, repair as needed.	_____	_____
3. Check all electrical controls for good condition and proper operation.	_____	_____
4. Change oil in winch transmission and test operation. Lubricate winch as needed.	_____	_____

ATTACHMENT 2
(Continued)

PREOPERATIONAL SERVICE AND INSPECTION CHECKLIST

	<u>SPIDER STAGING</u>	
	#1	#2
SPIDER STAGING (Continued)		
5. Check wire rope drum and auto-matic brake for wear.	_____	_____
6. Inspect transmission gears and motor brakes for wear.	_____	_____
7. Inspect winch cable for wear, kinks, broken wires, corrosion, and other defects. Grease cables, if dry.	_____	_____
8. Check operation of wire rope level wind system.	_____	_____
OTHER EQUIPMENT		
1. Inspect 3/4" manila lifelines, replace if worn or cut.	_____	_____
2. Inspect safety belts, lanyards and rope grabs.	_____	_____
3. Inspect all slings and replace if worn, kinked or corroded.	_____	_____
4. Inspect counterweight lifting lugs for corrosion or other defects.	_____	_____
5. Check electrical power to top of containment. Check for proper voltage and grounding and for condition and operation of disconnects.	_____	_____

COMMENTS: _____

The above service and inspections have been completed.

SIGNATURE
B-7/DATE
Rev. 2

ATTACHMENT 3
 FARLEY NUCLEAR PLANT
 UNIT 2
 TENDON SURVEILLANCE
 LOAD TEST CHECKLIST

		EQUIPMENT SET	
		#1	#2
1.	A-frame is in place on top of containment.	_____	_____
2.	Counterweights (22,160 lbs.) have been placed on A-frame.	_____	_____
3.	Service and inspection checklist is completed.	_____	_____
4.	All electrical controls have been connected and tested for proper operation.	_____	_____
5.	Electrical power has been connected to platform.	_____	_____
6.	Electrical power has been connected to spider staging.	_____	_____
7.	Cables from platform have been connected to A-frame.	_____	_____
8.	Cable from spider staging has been connected to A-frame.	_____	_____
9.	Test weights totaling approximately 2600 lbs. have been placed on the platform.	_____	_____
10.	Test weights totaling approximately 1000 lbs. have been placed on spider staging.	_____	_____
11.	Test weight of approximately 8000 lbs. has been hung from the lifting winch on A-frame and raised above the work platform.	_____	_____
12.	Raise the platform approximately two feet and hold.	_____	_____

PERFORMED UNDER
 INSPECTION AND
 REPAIR
 PROGRAM
 DON
 8/8/85

ATTACHMENT 3.
(Continued)FARLEY NUCLEAR PLANT
UNIT 2
TENDON SURVEILLANCE
LOAD TEST CHECKLIST

		EQUIPMENT SET	
		#1	#2
13.	Raise the spider staging approximately two feet and hold.	_____	_____
14.	Inspect A-frame for insufficient counterweight or signs of stress.	_____	_____
15.	Lower spider staging and platform and adjust overload shutoffs to trip at approximately 100 lbs. less than test weight.	_____	_____
16.	Remove test weight from A-frame lifting winch.	_____	_____

The above load test of both equipment sets has been successfully completed.

SIGNATURE_____
DATE

ATTACHMENT 4

FARLEY NUCLEAR PLANT
UNIT 2
TENDON SURVEILLANCE

GUIDELINES FOR STORAGE OF EQUIPMENT

1. All partial grease cans consolidated and covered. Do not consolidate grease from different batches. DAH
2. All tools and equipment boxed and returned to storage building. DAH
3. Both platforms and spider stagings returned to storage building. DAH
4. All bolts used to hold platform, spider staging or lifting winch cables removed from A-frame, boxed and placed in storage building. DAH
5. A-frames and counterweights stored. DAH

All tendon surveillance equipment has been properly stored.

David Hartman 12/8/85
SIGNATURE DATE

INRYCO INC. PROCEDURE SQ 12.6
GREASE VERTICAL TENDON-FULL REFILL
APRIL 23, 1985
PAGE 1 OF 12
REVISION 0

FARLEY NUCLEAR PLANT
INRYCO QUALITY CONTROL PROCEDURE
ANCHORHEAD REPLACEMENT PROGRAM

GREASE REPLACEMENT TO COMPLETELY FILL
THE TENDON VOID OF VERTICAL TENDONS.

APPROVED BY: M. W. [Signature] TITLE: Sp. Quality Assurance DATE: 5-2-85
REVIEWED BY: Craig [Signature] TITLE: Sp. Design Engineer DATE: 5-2-85

ALABAMA POWER COMPANY - FNP REVIEW

REVIEWED BY: Robert D. [Signature] TITLE: SP Supt DATE: 5-2-85

PROJECT: _____ UNIT: _____ DATE: _____

TENDON NO.: _____ TENDON END/BUTTRESS NO.: _____

QC
SIGNOFF

(8.4) Concrete Temp: _____ °F. Thermo. No.: _____ Recal Date: _____

(10.1.1) Predraining Waived YES NO Name _____

(10.3) Void Drained YES NO
Method: _____

(12.6.1) Grease Temp. Storage Container _____ °F.

Thermometer No. _____ Recal Date: _____

(13.1) Grease Leaks YES NO _____

Leaks Repaired YES NO _____

(13.1.1) Refill Acceptable: _____

(13.1.2) COMMENTS: _____

(13.1.3) FNP Drum Control No.: _____ Viscosity Batch No. _____

Q.C. REVIEW: _____ LEVEL _____ DATE: _____

TITLE: _____

1. PURPOSE

This procedure will establish the requirements for the Replacement of Grease to fill the Tendon Voids (Ducts) of Vertical Tendons for purposes of establishing the integrity of the corrosion protection compound (Viscosity Oil Co. Visconorust 2090P4) as part of the Anchorhead Replacement Program for the Post-Tensioning System Tendons at Farley Nuclear Generating Station.

2. SCOPE

This procedure shall only apply to Vertical Tendons. This is intended to be the complete filling of the Tendon Void, but not necessarily the complete removal of all the grease that might be in that Void at the time of filling.

2.1 Subsequent inspection will be required outside of the scope of this procedure to assure that the grease cans at the shop anchorhead end of the tendon are appropriately filled with grease.

3. RESPONSIBILITY

As stated in Inryco Procedure QA 4.0.

4. QUALIFICATIONS

As stated in Inryco Procedure QA 4.1.

5. EQUIPMENT

5.1 CONSTRUCTION

5.1.1 Visconorust 2090P4 in 55 gallon drums from FNP controlled inventory or as stored in a large bulk storage grease container.

5.1.2 Drum heaters, electrical connections and power source.

5.1.3 Miscellaneous hand tools, wrenches, sockets, lifting devices, rags, solvent (Viscor #16), teflon thread tape, bushing plugs, etc.

5.1.4 Grease Pumping System, Hoses, Y-Devices, etc.

5.2 QUALITY CONTROL

5.2.1 Data Sheets, thermometer, tapeline or other measuring device.

6. PRECAUTIONS

Review the Safety Comments provided in Inryco Procedure SC 1 for the following items that shall apply both for tendon force control and personnel safety.

6.1 Section 3.1; Tendon Wire Breaking Strength.

6.2 Section 3.2; Stressing Operations: Overstress Force.

INRYCO INC. PROCEDURE SQ 12.6
GREASE VERTICAL TENDON-FULL REFILL
APRIL 23, 1985
PAGE 3 OF 12

6.3 Section 3.2.2; Personnel Safety.

6.4 Section 3.6; Construction Safety: Personnel Safety.

6.5 During Grease Replacement, the grease is usually pumped under pressure with an exit temperature of 120°F. If being pumped from the heated storage tank, the temperature will be in excess of 150°F. It is, therefore, essential to avoid direct contact with the hot grease and to make sure all connections are secure.

6.6 Where drum heaters are used, operating temperatures are usually not as high, but exit temperature is still not less than 120°F. and injury could occur through carelessness.

6.7

CAUTION

DURING GREASING, BE AWARE THAT THE GREASE IS HOT AND BEING PUMPED UNDER PRESSURE.

7. QUALITY CONTROL

All Quality Control Documentation (QCD) points noted in this procedure are Hold Points. The work shall not progress past or through a QCD without a release from the Inspector. The required information or evaluative data shall be documented on Data Sheet 12.6 of this procedure.

8. PREREQUISITES

8.1 All Inspections will be complete.

8.2 The tendon will be in a stressed condition.

8.3 The Grease Can has already been installed.

8.4 QCD - Document the exterior concrete temperature near the tendon.

9. GENERAL

This refilling is intended to completely fill the Tendon Void of a Vertical Tendon, but does not necessarily mean that all the grease presently in that Tendon Void will be removed or displaced by this refilling.

9.1 The grease may be in a large storage container or in 55 gallon drums. The large storage container shall have an automatic thermostat control for temperature, while drum heaters shall be used to heat the grease in drums.

- 9.2 It shall be necessary to maintain specific grease temperatures and to monitor the exit temperature of the grease. It is important to have the grease in a completely liquid state, so that congealing does not occur before the correct quantity is replaced. Provide venting of air while pumping the grease into the grease can.
- 9.3 The original installation temperature of the grease was not less than 120°F. This represents the maximum expansion of the grease under maximum plant operating conditions. As the grease cools, it shrinks back into the tendon void or duct leaving a coating of grease on all steel within the void and grease can. This shrink-back also causes the formation of an air pocket extending from the grease can, a short distance into the trumpet tube. Shrink-back will not occur at the Gallery or Bottom End of a Vertical Tendon. Shrink-back might not occur in Dome Tendons. The coefficient of expansion for this grease will be about 1% for every 20°F. temperature rise from 68°F.

10. PRE-DRAINING OF TENDON VOID

In order to provide a successful refilling of the Tendon Void, it may become necessary to drain the Tendon Void in an effort to provide a relatively clear path for the new grease. It will not be necessary to drain all the grease, but if a complete draining occurs, it will only assist in the refilling of the Void. Have a sufficient quantity of waste containers available to collect the drained grease.

- 10.1 Predraining of the Tendon Void described in Section 10 of this Procedure is optional and may be waived by the direction of the authorized Alabama Power Company personnel provided that the grease can be injected without exceeding a maximum sustained pressure of 350 psig at the pump discharge and a maximum transient pressure of 400 psig at the pump discharge.

10.1.1 QCD - Document the name of the person waiving the predraining.
—when-applicable.—

- 10.2 It is recommended that compressed air be injected at the grease filling hole of the Shop End of the Tendon Grease Can. This will speed up the draining process and perhaps cut a hole through the remaining grease in the Tendon Void, which would permit pumping the grease in from the Gallery Grease Can at lower pressures. It will be acceptable to use Y-Devices and hoses to assist in the draining operation.

10.2.1 Do not inject the compressed air through the Gallery Grease Can.

10.2.2 Do not use compressed air to assist the grease pumping from the Gallery Grease Can. The Grease Pump will probably exert a higher pressure than the compressed air and could force grease into the compressed air lines.

- 10.3 QCD - Document the method of draining the Tendon Void.

11. SET-UP FOR REFILLING THE TENDON DUCT

Two types of hook-ups have been developed for the various types of tendon ducts to be filled and will be explained in the following procedures. Refer to the flow diagram sketches where noted, for a visual view of each system and the-recirculating patterns used, to prevent hose blockages.

- 11.1 Before starting the tendon filling operations, the storage facility, pump, hoses and equipment shall be set up.
- 11.2 A Grease Control Station shall be set up near the tendons to be filled and a communications network established so that the personnel at the furthest end of the tendon to be filled, will be able to communicate with the crew leader or the control station attendant. The general physical make-up of the Grease Control Station will be seen in Sketch 8.0. This configuration may vary from time to time, based on the needs at hand and access to the Tendon Voids.
- 11.3 At the end of each day of filling operations, the pump shall be shut off and the feed-in supply, return and jumper hoses shall be drained. The gate valve on the suction hose shall be closed and that hose drained. It will be acceptable to allow the grease to continue to circulate in the hose lines, providing that responsibility has been assigned for monitoring this recirculation, so that the system can be shut down in the event of system or equipment failure.
- 11.4 Refer to each specific system procedure for the proper selection. Then follow the Tendon Duct Refilling requirements for the actual operation.
- 11.5 The terms casing-filler, grease, corrosion protection compound, tendon void filler are all meant to be another name for the product which is used to fill the Tendon Void. That product is Visconcrust 2090P4 as manufactured by Viscosity Oil Company.

12. SINGLE FILL SYSTEM

This method of Tendon Void filled has the grease pumped through a Y-Device attached to the Gallery Grease Can of a Vertical Tendon. The grease is pumped up from the Gallery, through the Tendon Void and out the filler bushing of the Grease Can at the Dome end of the Vertical Tendon. This system does not require recirculation through the Void, nor is it recommended. Refer to Sketch 8-4 for a pictorial presentation of this system.

- 12.1 Attach a Grease Can Filler Bushing pipe plug to the operating shaft wrench of each Y-Device to be used. Be sure the plug is pulled back far enough into the body, so as to allow an unobstructed flow of casing filler. A sketch of a typical Y-Device will be seen in Sketch 8-1.

- 12.2 Connect the Y-Device to the grease can filler bushing in the Gallery and attach the waste line to the upper end of the tendon. A waste container will be available at the Dome end of the tendon. It will be acceptable to utilize a Y-Device for the Grease Can at the Dome end of the tendon.
- 12.3 Be sure all the grease hoses are clear of blockages before connecting them to the Y-Device.
- 12.4 Before hook-up operations, the 4 port-control valve is set to recirculate the grease flow from the pump to the storage facility, as noted in Sketch 8-2, System A.
- 12.5 Before and after filling operations the feed-line from the 4 port-control valve will be coupled to the return-line completing the recirculating closed loop, and the grease allowed to circulate through the hoses back to the storage facility, as noted in Sketch 8-2, System B.
- 12.6 The grease in the bulk storage container should be in a temperature range of 150°F. to 210°F. Greasing operations should not be performed when the grease temperature is less than 150°F.
 - 12.6.1 QCD - The temperature of the grease in the bulk storage container shall be documented once a day during greasing operations utilizing that container along with the thermometer identification and recalibration data.
- 12.7 The 4 port-control valve will be set for the small loop recirculation pattern as noted in Sketch 8-2, System A.
- 12.8 The pump is operating to circulate the casing filler. The grease temperature during recirculation should not be lower than 140°F. at the thermometer of the Grease Control Station shown in Sketch 8-0.
- 12.9 All connections to the tendon are made. Refer to Sketch 8-4.
- 12.10 The 3 port-outflow valve or waste line is set so that the initial flow of casing filler will be into the waste container. It may not be necessary to incorporate this waste line and the outflow end of the valve shall be plugged.
- 12.11 Open the 4 port-control valve allowing the flow of casing filler into the Tendon Void.
- 12.12 Hot grease shall be pumped into the Tendon Void until it exits at the Vertical Tendon Dome Grease Can. The grease will continue to be pumped out of the can into the waste container until the grease emerging from the waste line is clean and free of air bubbles. It usually takes from 2 to 8 gallons of grease being pumped out until it is clean and clear of dirt or other debris.

- 12.13 When the casing filler appears to be clean, shift the 3 port-outflow valve so the flow is directed through the 4 port-control valve and back to the storage facility.
- 12.14 Before stopping the pumping of grease into the grease can, the grease can filler bushing pipe plug shall be inserted into the grease can filler bushing at the Dome to aid in completely filling the Void. It will be acceptable to apply teflon tape to the pipe plugs to aid in sealing the filler bushing.
- 12.15 Install the grease can filler bushing pipe plug into the Gallery Grease Can and proceed with the valve shifting stated in Section 12.13 above.
- 12.16 QCD - The temperature of the casing filler at the waste line for either system shall not be less than 120°F. when measured with a thermometer. The last portion of the grease exiting from the waste line will be caught in a container and a thermometer dipped into the grease until the temperature stops rising on the thermometer, or 120°F. is reached. If this temperature is not reached, it shall be necessary to recirculate the grease through the tendon duct and the grease hoses in a closed loop until the minimum 120°F. reading is obtained. DO NOT RECIRCULATE THIS GREASE BACK TO THE BULK STORAGE CONTAINER. Also document the thermometer identification and recalibration data.
- 12.17 Remove the waste line, Y-Devices and quick couplers from this tendon and move to the next tendon to be filled.
- 12.18 While moving the hoses after uncoupling, take care not to spill any grease from the hose.
- 12.19 Any grease spilled on concrete or other surfaces shall be removed and solvent-cleaned.
- 12.20 A FINAL WORD OF CAUTION: The casing filler is being pumped under pressure and at temperatures in excess of 120°F., poor connections or the use of the wrong procedures could result in injuries.
13. OTHER CONTROLS
- 13.1 Verify that no grease is leaking. If there is some leakage, the deficiency shall be corrected and cleanup performed.
- 13.1.1 QCD - Document the acceptability of the refilling.
- 13.1.2 QCD - Document any comments of unusual occurrences or references that could assist in evaluating the refill or for future surveillance.
- 13.1.3 QCD - Document the FNP control number for that drum or drums of grease. If that is not visible, document the Viscosity Oil Co. batch numbers.

14. DOCUMENTATION

The items requiring documentation shall be documented on Data Sheet 12.6 shown in this procedure in reduced form.

14.1 The Data Sheet references the applicable section number of the procedure for each QCD point.

14.2 DATA SHEET 12.6

INMYCO INC. PROCEDURE SQ 12.6
GREASE VERTICAL TENDON-FULL REFILL
DATA SHEET 12.6
APRIL 24, 1985, Revision 0
PAGE 1 OF 1

PROJECT: _____ UNIT: _____ DATE: _____

TENDON NO.: _____ TENDON END/BUTTRESS NO.: _____

QC
SIGNOFF

(8.4) Concrete Temp: _____ °F. Thermo. No.: _____ Recal Date: _____

(10.1.1) Predraining Waived YES NO Name _____

(10.3) Void Drained YES NO
Method: _____

(12.6.1) Grease Temp. Storage Container _____ °F.

Thermometer No. _____ Recal Date: _____

(13.1) Grease Leaks YES NO

Leaks Repaired YES NO

(13.1.1) Refill Acceptable: _____


(13.1.2) COMMENTS: _____

(13.1.3) FNP Drum Control No.: _____ Viscosity Batch No. _____

Q.C. REVIEW: _____ LEVEL _____ DATE: _____


TITLE: _____

15.1 Sketch 8-0






15.2 Sketch 8-1


TYPICAL HOOK-UP FOR FILLING TENDON VOIDS




Refer Procedure F9.0 Section 1.4 for operation.

Special Tendon Void Filling Tool	Y-DEVICE	Version 2.0
<p>This drawing has not been published, it is the sole property of INRYCO, INC. It is loaned to the recipient for his confidential use only, and upon the completion and agreement of the recipient, it shall be returned to INRYCO, INC. If the recipient reproduces, distributes, or otherwise provides the drawing or its contents to any third party without the written consent of INRYCO, INC., the recipient shall be liable to INRYCO, INC. for damages.</p>	<p> Inryco an Inland Steel company Post Tensioning Division</p>	<p>Approved by:  7-4-79 Drawn by:  7-2-79 Drawing no: Sketch 8-1</p>

15.3 Sketch 8-2



15.4 Sketch 8-4



PROJECT: FARLEY UNIT: 2 DATE: 5/15/85
TENDON NO.: K-4 TENDON END/BUTTRESS NO.: Step

QC
SIGNOFF

(8.4) Concrete Temp: 55 °F. Thermo. No.: FND TDT 9257 Recal Date: 10/4/85 1585 5/15/85
(10.1.1) Predraining Waived (YES) NO Name JOE HALL 1585 5/15/85
(10.3) Void Drained YES (NO)
Method: N/A 1585 5/15/85

(12.6.1) Grease Temp. Storage Container 171 °F. 1585 5/15/85
Thermometer No. FND TDT 9257 Recal Date: 10/4/85 1585 5/15/85
(13.1) Grease Leaks YES (NO) 1585 5/15/85
Leaks Repaired YES (NO) 1585 5/15/85
(13.1.1) Refill Acceptable: YES 1585 5/15/85
(13.1.2) COMMENTS: Exit Temp 148°F, FND TDT 9257
1585 5/15/85

(13.1.3) FNP Drum Control No.: N/A Viscosity ^{LOT} Batch No. 5-6202 1585 5/15/85

Q.C. REVIEW: [Signature] LEVEL II DATE: 5/16/85
TITLE: S.E. INSPECTOR

INRYCO INC. PROCEDURE SQ 12.6
GREASE VERTICAL TENDON-FULL REFILL
DATA SHEET 12.6
APRIL 24, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FAXLEY UNIT: 2 DATE: 5/15/85
TENDON NO.: V-28 TENDON END/BUTTRESS NO.: 542

QC
SIGNOFF

(8.4) Concrete Temp: 88 °F. Thermo. No.: TOT 935 Recal Date: 10/4/85 1885 5/15/85
(10.1.1) Predraining Waived YES NO Name Joe Hall 885 5/15/85
(10.3) Void Drained YES NO Method: N/A 1885 5/15/85

(12.6.1) Grease Temp. Storage Container 171 °F. 1885 5/15/85
Thermometer No. TOT 935 Recal Date: 10/4/85 1885 5/15/85
(13.1) Grease Leaks YES NO 885 5/15/85
Leaks Repaired YES NO 1885 5/15/85
(13.1.1) Refill Acceptable: YES 1885 5/15/85
(13.1.2) COMMENTS: Exit Temp. 140°F, FNP TOT 935

(13.1.3) FNP Drum Control No.: N/A Viscosity LOT Batch No. 5-6242 1885 5/15/85

Q.C. REVIEW: Joe Hall LEVEL II DATE: 5/16/85
TITLE: Q.E. Inspector

PROJECT: FARLEY UNIT: 2 DATE: 5/15/85
TENDON NO.: V-52 TENDON END/BUTTRESS NO.: SHARP

QC
SIGNOFF

(8.4) Concrete Temp: 88 °F. Thermo. No.: FNP TOT 9357 Recal Date: 11/4/85 1515 5/15/85
(10.1.1) Predraining Waived YES NO Name JOE HALL 1515 5/15/85
(10.3) Void Drained YES NO Method: N/A 1515 5/15/85

(12.6.1) Grease Temp. Storage Container 171 °F. 1515 5/15/85
Thermometer No. FNP TOT 9357 Recal Date: 10/4/85 1515 5/15/85
(13.1) Grease Leaks YES NO 1515 5/15/85
Leaks Repaired YES NO 1515 5/15/85
(13.1.1) Refill Acceptable: YES 1515 5/15/85
(13.1.2) COMMENTS: Exit Temp 142°F FNP TOT 9357

(13.1.3) FNP Drum Control No.: N/A Viscosity LOT Batch No. 5-6202 1515 5/15/85

Q.C. REVIEW: Joe Anthony LEVEL II DATE: 5/16/85
TITLE: O.E. INSPECTOR

PROJECT: FITZGERALD UNIT: 2 DATE: 5/15/85
TENDON NO.: V-79 TENDON END/BUTTRESS NO.: SHEP

QC
SIGNOFF

(8.4) Concrete Temp: 85°F. Thermo. No.: FNP TDT 930 Recal Date: 10/4/85 1585 5/15/85
(10.1.1) Predraining Waived ☒ YES ☐ NO Name JOB HALL 1585 5/15/85
(10.3) Void Drained YES ☒ NO
Method: N/A 1585 5/15/85

(12.6.1) Grease Temp. Storage Container 171°F. 1585 5/15/85
Thermometer No. FNP TDT 930 Recal Date: 10/4/85 1585 5/15/85
(13.1) Grease Leaks YES ☒ NO 1585 5/15/85
Leaks Repaired YES ☒ NO 1585 5/15/85
(13.1.1) Refill Acceptable: YES 1585 5/15/85
(13.1.2) COMMENTS: EXIT Temp 145°F, FNP TDT 930

1585 5/15/85
(13.1.3) FNP Drum Control No.: N/A Viscosity ^{Lot} Batch No. 5-6212 1585 5/15/85

Q.C. REVIEW: Joe Anthony LEVEL II DATE: 5/16/85
TITLE: Q.E. INSPECTOR

INRYCO INC. PROCEDURE SQ 12.6
GREASE VERTICAL TENDON-FULL REFILL
DATA SHEET 12.6
APRIL 24, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FALLS UNIT: 2 DATE: 5/12/85
TENDON NO.: V-100 TENDON END/BUTTRESS NO.: STEP

QC
SIGNOFF

(8.4) Concrete Temp: 110 °F. Thermo. No.: 559 Recal Date: 3/15/86 15RT 5/12/85
(10.1.1) Predraining Waived YES NO Name Joe Hall 15RT 5/12/85
(10.3) Void Drained YES NO Method: N/A 15RT 5/12/85

(12.6.1) Grease Temp. Storage Container 165 °F. 15RT 5/12/85
Thermometer No. FNP TOT 937 Recal Date: 10/4/85 15RT 5/12/85
(13.1) Grease Leaks YES NO 15RT 5/12/85
Leaks Repaired YES NO N/A 15RT 5/12/85
(13.1.1) Refill Acceptable: YES 15RT 5/12/85
(13.1.2) COMMENTS: 15RT 5/12/85
N/A
EXIT TEMP EXCEEDS 120°F, FNP TOT 937 15RT 5/12/85
(13.1.3) FNP Drum Control No.: N/A Viscosity ^{LOT} Batch No. 5-524 15RT 5/12/85

Q.C. REVIEW: Joe Thibault LEVEL II DATE: 5/16/85
TITLE: Q.E. INSPECTOR



INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
May 8, 1985
PAGE 1 OF 18
REVISION 0

FARLEY NUCLEAR PLANT
INRYCO QUALITY CONTROL PROCEDURE
ANCHORHEAD REPLACEMENT PROGRAM

GREASE REPLACEMENT TO FILL THE TENDON
VOID OF HORIZONTAL TENDONS.

APPROVED BY: M. W. [Signature] TITLE: Sup. Quality Assurance DATE: 5-15-85

REVIEWED BY: Craig [Signature] TITLE: Sec. Design Engineer DATE: 5-15-85

ALABAMA POWER COMPANY - FNP REVIEW

REVIEWED BY: Robert [Signature] TITLE: SP Sup DATE: 5-25-85



1. PURPOSE

This procedure will establish the requirements for the Replacement of Grease to fill the Tendon Voids (Ducts) of Horizontal Tendons for purposes of establishing the integrity of the corrosion protection compound (Viscosity Oil Co. Visconorust 2090P4) as part of the Anchorhead Replacement Program for the Post-Tensioning System Tendons at Farley Nuclear Generating Station.

2. SCOPE

This procedure shall only apply to Horizontal Tendons. This is intended to provide a refilling of the Tendon Void, but not necessarily the complete removal of all the grease that might be in that Void at the time of filling.

2.1 As the Tendon Voids are nearly completely full at this time, it is highly unlikely that this quantity of grease could be displaced during the refilling. This procedure will provide reasonable assurance that the Tendon Void will be filled to capacity while fully assuring that the Grease Cans and Trumpet Tubes will be completely full and the Tendon End Anchorage Assembly completely coated with grease.

3. RESPONSIBILITY

As stated in Inryco Procedure QA 4.0.

4. QUALIFICATIONS

As stated in Inryco Procedure QA 4.1.

5. EQUIPMENT

5.1 CONSTRUCTION

5.1.1 Visconorust 2090P4 in 55 gallon drums from FNP controlled inventory and/or as stored in a large bulk storage grease container.

5.1.2 Drum heaters, electrical connections and power source.

5.1.3 Miscellaneous hand tools, wrenches, sockets, lifting devices, rags, solvent (Viscor #16), teflon thread tape, bushing plugs, etc.

5.1.4 Grease Pumping System, Hoses, Y-Device, etc.

5.2 QUALITY CONTROL

5.2.1 Data Sheets, thermometer, tapeline or other measuring device.



6. PRECAUTIONS

Review the Safety Comments provided in Inryco Procedure SC 1 for the following items that shall apply both for tendon force control and personnel safety.

- 6.1 Section 3.1; Tendon Wire Breaking Strength.
- 6.2 Section 3.2; Stressing Operations: Overstress Force.
- 6.3 Section 3.2.2; Personnel Safety.
- 6.4 Section 3.6; Construction Safety: Personnel Safety.
- 6.5 During Grease Replacement, the grease is usually pumped under pressure with an exit temperature of 120°F. If being pumped from the heated storage tank, the temperature will be in excess of 150°F. It is, therefore, essential to avoid direct contact with the hot grease and to make sure all connections are secure.
- 6.6 Where drum heaters are used, operating temperatures are usually not as high, but exit temperature is still not less than 120°F. and injury could occur through carelessness.

6.7

CAUTION

DURING GREASING, BE AWARE THAT THE GREASE IS HOT AND BEING PUMPED UNDER PRESSURE.

7. QUALITY CONTROL

All Quality Control Documentation (QCD) points noted in this procedure are Hold Points. The work shall not progress past or through a QCD without a release from the Inspector. The required information or evaluative data shall be documented on Data Sheet 12.7 of this procedure.

8. PREREQUISITES

- 8.1 All Inspections will be complete.
- 8.2 The tendon will be in a stressed condition.
- 8.3 The Grease Can has already been installed.
- 8.4 QCD - Document the exterior concrete temperature near the tendon.



9. GENERAL

This refilling is intended to provide a fill of the Tendon Void of a Horizontal Tendon, but does not necessarily mean that all the grease presently in that Tendon Void will be removed or displaced by this refilling. There also remains a possibility that there may be some entrapped air in the grease within the Sheathing portion of the Tendon Void.

9.1 The grease may be in a large storage container or in 55 gallon drums. The large storage container shall have an automatic thermostat control for temperature, while drum heaters shall be used to heat the grease in drums.

9.2 It shall be necessary to maintain specific grease temperatures and to monitor the exit temperature of the grease. It is important to have the grease in a completely liquid state so that congealing does not occur before the correct quantity is replaced. Provide venting of air while pumping the grease into the grease can.

9.3 The original installation temperature of the grease was not less than 120°F. This represents the maximum expansion of the grease under maximum plant operating conditions. As the grease cools, it shrinks back into the tendon void or duct leaving a coating of grease on all steel within the void and grease can. This shrink-back also causes the formation of an air pocket extending from the grease can, a short distance into the trumpet tube. Shrink-back will not occur at the Gallery or Bottom End of a Vertical Tendon. Shrink-back might not occur in Dome Tendons. The coefficient of expansion for this grease will be about 1% for every 20°F. temperature rise from 68°F.

10. SET-UP FOR REFILLING THE TENDON DUCT

Several types of hook-ups have been developed for the various types and locations of Tendon Ducts to be filled and will be explained in the following procedures. Refer to the flow diagram sketches where noted, for a visual view of each system and the recirculating patterns used, to prevent hose blockages.

10.1 Before starting the tendon filling operations, the storage facility, drums, heaters, pump, hoses and equipment shall be set up.

10.2 A Grease Control Station shall be set up near the tendons to be filled and a communications network established so that the personnel at the furthest end of the tendon to be filled, will be able to communicate with the crew leader or the control station attendant. The general physical make-up of the Grease Control Station will be seen in Sketch 8.0. This configuration may vary from time to time, based on the needs at hand and access to the Tendon Voids.



- 10.2.1 It may not be possible or reasonable to utilize the bulk filling setup (Grease Control Station and hoses) in Radiologically Controlled Areas. Therefore, instead of using the bulk filling equipment, drums of grease with a high pressure pump will be substituted. Variations in operation will be explained in the following refilling operations.
- 10.3 At the end of each day of filling operations, the pump shall be shut off and the feed-in supply, return and jumper hoses shall be drained. The gate valve on the suction hose shall be closed and that hose drained. It will be acceptable to allow the grease to continue to circulate in the hose lines, providing that responsibility has been assigned for monitoring this recirculation, so that the system can be shut down in the event of system or equipment failure.
- 10.4 Refer to each specific system procedure for the proper selection. Then follow the Tendon Duct Refilling requirements for the actual operation.
- 10.5 The terms casing-filler, grease, corrosion protection compound, tendon void filler are all meant to be another name for the product which is used to fill the Tendon Void. That product is Visconorust 2090P4 as manufactured by Viscosity Oil Company.

11. SINGLE FILL SYSTEM

This method of Tendon Void filled has the grease pumped through a Y-Device attached to the Grease Can of a Horizontal Tendon. The grease is pumped into the Grease Can at one end of the tendon and out through the filler bushing of the Grease Can opposite end of the tendon or out through the Auxiliary filling pipe at the pumping end of the tendon. This system does not require recirculation through the Void, nor is it recommended. Refer to Sketch 12.7.1 for a pictorial presentation of this system. The Grease Can Filler Bushing Pipe Plug has been removed from the Grease Cans at each end of the tendon.

- 11.1 Attach the Grease Can Filler Bushing pipe plug to the operating shaft wrench of each Y-Device to be used. Be sure the plug is pulled back far enough into the body, so as to allow an unobstructed flow of casing filler. A sketch of a typical Y-Device will be seen in Sketch 8-1.
- 11.2 Connect the Y-Device to the grease can filler bushing at one end of the tendon and attach the waste line to the opposite end of the tendon. A waste container should be available at the opposite end of the tendon. It will be acceptable to utilize a Y-Device for the Grease Can at the opposite end of the tendon.



- 11.2.1 The Auxiliary Filler Pipe Plug shall be removed from the Auxiliary Grease Filling Pipe at that end of the tendon where the grease will be pumped in. It would be practical to attach a hose to this pipe so that the waste grease could be directed into a waste container. Refer to Sketch 12.7 for a view of the Tendon End Anchorage Assembly.
- 11.2.2 If there is a Vent Valve attached to the Grease Can, be sure that this Valve is closed, so that the venting can take place through the Grease Can Filler Bushing at the opposite end of the tendon and/or the Auxiliary Grease Filling Piper. Refer to Sketch 12.7.
- 11.3 Be sure all the grease hoses are clear of blockages before connecting them to the Y-Device.
- 11.4 Before hook-up operations, the 4 port-control valve is set to recirculate the grease flow from the pump to the storage facility, as noted in Sketch 8-2, System A.
 - 11.4.1 When the grease is being pumped directly from 55 gallon drums, the grease will not be recirculated. Pumping the grease from 55 gallon drums is a direct filling method with no requirements for a Grease Control Station.
- 11.5 Before and after filling operations the feed-line from the 4 port-control valve will be coupled to the return-line completing the recirculating closed loop, and the grease allowed to circulate through the hoses back to the storage facility, as noted in Sketch 8-2, System B.
- 11.6 The grease in the bulk storage container should be in a temperature range of 150°F. to 210°F. Greasing operations should not be performed when the grease temperature is less than 150°F, when being pumped from bulk storage or directly from 55 gallon drums.
 - 11.6.1 QCD - The temperature of the grease in the bulk storage container shall be documented once a day during greasing operations utilizing that container along with the thermometer identification and recalibration data. The temperature of the grease being pumped from a 55 gallon drum shall be documented for each tendon filled in this manner.
 - 11.6.2 The temperature of the grease in a 55 gallon drum should not exceed 300°F. Temperatures in excess of 300°F. causes frothing of the grease which introduces air bubbles into the grease; it further causes the release of undesirable fumes and brings the grease close to its flash point.



- 11.7 The 4 port-control valve will be set for the small loop recirculation pattern as noted in Sketch 8-2, System A.
- 11.8 The pump is operating to circulate the casing filler. The grease temperature during recirculation should not be lower than 140°F. at the thermometer of the Grease Control Station shown in Sketch 8-0.
- 11.9 All connections to the tendon are made. Refer to Sketch 12.7.1.
- 11.10 The 3 port-outflow valve or waste line is set so that the initial flow of casing filler will be into the waste container. It may not be necessary to incorporate this waste line and the outflow end of the valve shall be plugged.
- 11.11 Open the 4 port-control valve allowing the flow of casing filler into the Tendon Void.
 - 11.11.1 The grease in 55 gallon drums will be pumped directly into the Grease Can.
- 11.12 As the grease is being pumped in, the pumping pressure will cause the grease to exit from the venting hole at the Grease Can Filler Bushing of the opposite end of the tendon and/or the Auxiliary Grease Filling Pipe at the pumping end of the tendon.
 - 11.12.1 If the grease exits the opposite end of the tendon without exiting the Auxiliary, allow about one gallon of grease or more to exit and replace the Grease Can Filler Bushing Pipe Plug.
 - 11.12.2 If the grease exits the opposite end of the tendon and the Auxiliary Grease Filling Pipe at about the same time, allow about one gallon of grease or more to exit either location and then replace the Grease Can Filler Bushing Pipe Plug at the opposite end of the tendon. Take the temperature of the grease exiting the Auxiliary Grease Filling Pipe after about one gallon of grease exits the pipe.
 - 11.12.3 If the grease only exits the Auxiliary Grease Filler Pipe, take the temperature of the grease after about one gallon of grease exits the Filler Pipe. This grease could be caught in a smaller container for purposes of temperature sampling.
 - 11.12.4 QCD - Document the temperature of the grease exiting the Auxiliary Grease Filler Pipe at the pumping end of the tendon. Document thermometer identification and recalibration date.



- 11.13 Continue pumping in hot grease until the temperature of the grease exiting the Auxiliary Grease Filler Pipe is at least 10 degrees higher than the Ambient Grease Temperature documented in Section 11.12.4 above. If the Grease Can Filler Bushing Pipe Plug has not been installed at the opposite end of the tendon, it shall be replaced at this point, while continuing to pump grease.
- 11.13.1 QCD - Document the final exiting temperature of the grease, the thermometer identification and recalibration date.
- 11.14 Once the exiting grease has reached the correct temperature, shift the 3 port-outflow valve so the flow is directed through the 4 port-control valve and back to the storage facility.
- 11.15 Before stopping the pumping of grease into the grease can, the grease can filler bushing pipe plug shall be inserted into the grease can filler bushing at the opposite end of the tendon to aid in completely filling the Void. It will be acceptable to apply teflon tape to the pipe plugs to aid in sealing the filler bushing.
- 11.16 Install the grease can filler bushing pipe plug into the Grease Can where the pumping of grease is taking place and proceed with the valve shifting stated in Section 11.14 above.
- 11.17 Remove the waste line, Y-Devices and quick couplers from the Grease Can at the pumping end of the tendon and move to the next tendon to be greased. The opposite end of the tendon will now be greased following the requirements of Section 12 below.
- 11.18 While moving the hoses after uncoupling, take care not to spill any grease from the hose.
- 11.19 Any grease spilled on concrete or other surfaces shall be removed and solvent-cleaned.
- 11.20 A FINAL WORD OF CAUTION: The casing filler is being pumped under pressure and at temperatures in excess of 120°F., poor connections or the use of the wrong procedures could result in injuries.



12. GREASING THE OPPOSITE END OF THE TENDON - SINGLE FILL

Greasing the opposite end of the tendon just filled may take place at any time after the Grease Can at the pumping end of the tendon has the Grease Can Filler Bushing Pipe Plug installed. This method of Tendon Void filled has the grease pumped through a Y-Device attached to the Grease Can of a Horizontal Tendon. The grease is pumped into the Grease Can at this end of the tendon and out through the Auxiliary filling pipe at this end of the tendon. This system does not require recirculation through the Void, nor is it recommended. Refer to Sketch 12.7.1 for a pictorial presentation of this system. The Grease Can Filler Bushing Pipe Plug has been removed from the Grease Cans only at this end of the tendon.

12.1 Attach the Grease Can Filler Bushing pipe plug to the operating shaft wrench of the Y-Device. Be sure the plug is pulled back far enough into the body, so as to allow an unobstructed flow of casing filler. A sketch of a typical Y-Device will be seen in Sketch 8-1.

12.2 Connect the Y-Device to the grease can filler bushing at this end of the tendon.

12.2.1 The Auxiliary Filler Pipe Plug shall be removed from the Auxiliary Grease Filling Pipe at this end of the tendon, where the grease will be pumped in. It would be practical to attach a hose to this pipe so that the waste grease could be directed into a waste container. Refer to Sketch 12.7 for a view of the Tendon End Anchorage Assembly.

12.2.2 If there is a Vent Valve attached to the Grease Can, be sure that this Valve is closed, so that the venting can take place through the Auxiliary Grease Filling Pipe. Refer to Sketch 12.7.

12.3 Be sure all the grease hoses are clear of blockages before connecting them to the Y-Device.

12.4 Before hook-up operations, the 4 port-control valve is set to recirculate the grease flow from the pump to the storage facility, as noted in Sketch 8-2, System A.

12.4.1 When the grease is being pumped directly from 55 gallon drums, the grease will not be recirculated. Pumping the grease from 55 gallon drums is a direct filling method with no requirements for a Grease Control Station.

- 12.5 Before and after filling operations the feed-line from the 4 port-control valve will be coupled to the return-line completing the recirculating closed loop, and the grease allowed to circulate through the hose back to the storage facility, as noted in Sketch 8-2, System B.
- 12.6 The grease in the bulk storage container should be in a temperature range of 150°F. to 210°F. Greasing operations should not be performed when the grease temperature is less than 150°F, when being pumped from bulk storage or directly from 55 gallon drums.
- 12.6.1 QCD - The temperature of the grease in the bulk storage container shall be documented once a day during greasing operations utilizing that container along with the thermometer identification and recalibration data. The temperature of the grease being pumped from a 55 gallon drum shall be documented for each tendon filled in this manner.
- 12.6.2 The temperature of the grease in a 55 gallon drum should not exceed 300°F. Temperatures in excess of 300°F. causes frothing of the grease which introduces air bubbles into the grease; it further causes the release of undesirable fumes and brings the grease close to its flash point.
- 12.7 The 4 port-control valve will be set for the small loop recirculation pattern as noted in Sketch 8-2, System A.
- 12.8 The pump is operating to circulate the casing filler. The grease temperature during recirculation should not be lower than 140°F. at the thermometer of the Grease Control Station shown in Sketch 8-0.
- 12.9 All connections to the tendon are made. Refer to Sketch 12.7.1.
- 12.10 The 3 port-outflow valve or waste line is set so that the initial flow of casing filler will be into the waste container. It may not be necessary to incorporate this waste line and the outflow end of the valve shall be plugged.
- 12.11 Open the 4 port-control valve allowing the flow of casing filler into the Tendon Void.
- 12.11.1 The grease in 55 gallon drums will be pumped directly into the Grease Can.



- 12.12 As the grease is being pumped in, the pumping pressure will cause the grease to exit from the Auxiliary Grease Filling Pipe at this end of the tendon. Take the temperature of the grease after about one gallon of grease exits the Filler Pipe. This grease could be caught in a smaller container for purposes of temperature and sampling.
- 12.12.1 QCD - Document the temperature of the grease exiting the Auxiliary Grease Filler Pipe at the pumping end of the tendon. Document thermometer identification and recalibration date.
- 12.13 Continue pumping in hot grease until the temperature of the grease exiting the Auxiliary Grease Filler Pipe is at least 10 degrees higher than the Ambient Grease Temperature documented in Section 11.12.4 above. If the Grease Can Filler Bushing Pipe Plug has not been installed at the opposite end of the tendon, it shall be replaced at this point, while continuing to pump grease.
- 12.13.1 QCD - Document the final exiting temperature of the grease, the thermometer identification and recalibration date.
- 12.14 Once the exiting grease has reached the correct temperature, shift the 3 port-outflow valve so the flow is directed through the 4 port-control valve and back to the storage facility.
- 12.15 Install the grease can filler bushing pipe plug into the Grease Can and proceed with the valve shifting stated in Section 12.14 above.
- 12.16 Remove the waste line, Y-Devices and quick couplers from the Grease Can at the pumping end of the tendon and move to the next tendon to be greased.
- 12.17 While moving the hoses after uncoupling, take care not to spill any grease from the hose.
- 12.18 Any grease spilled on concrete or other surfaces shall be removed and solvent-cleaned.
- 12.19 A FINAL WORD OF CAUTION: The casing filler is being pumped under pressure and at temperatures in excess of 120°F., poor connections or the use of the wrong procedures could result in injuries.



13. OTHER CONTROLS

13.1 Verify that no grease is leaking at both ends of the tendon. If there is some leakage, the deficiency shall be corrected and cleanup performed.

13.1.1 QCD - Document the acceptability of the refilling.

13.1.2 QCD - Document any comments of unusual occurrences or references that could assist in evaluating the refill or for future surveillance.

13.1.3 QCD - Document the FNP control number for that drum or drums of grease. If that is not visible, document the Viscosity Oil Co. batch numbers.

14. DOCUMENTATION

The items requiring documentation shall be documented on Data Sheet 12.7 shown in this procedure in reduced form.

14.1 The Data Sheet references the applicable section number of the procedure for each QCD point.



14.2 DATA SHEET 12.7

INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: _____ UNIT: _____ DATE: _____

TENDON NO.: _____ TENDON END/BUTTRESS NO.: _____

QC
SIGNOFF

(8.4) Concrete Temp: _____ °F. Thermo. No.: _____ Recal Data: _____

(11.6.1) Grease Temp. Storage Container _____ °F.

Thermometer No. _____ Recal Data: _____

(11.12.4) Grease Temp. Ambient _____ °F.

Thermometer No. _____ Recal Data: _____

(11.13.1) Grease Temp. Exiting _____ °F.

Thermometer No. _____ Recal Data: _____

(12.6.1) Grease Temp. Storage Container _____ °F.

Thermometer No. _____ Recal Data: _____

(12.12.1) Grease Temp. Ambient _____ °F.

Thermometer No. _____ Recal Data: _____

(12.13.1) Grease Temp. Exiting _____ °F.

Thermometer No. _____ Recal Data: _____

(13.1) Grease Leaks YES NO

Leaks Repaired YES NO

(13.1.1) Refill Acceptable: _____

(13.1.2) COMMENTS: _____

(13.1.3) FNP Drum Control No.: _____ Viscosity Batch No. _____


Q.C. REVIEW: _____ LEVEL _____ DATE: _____

TITLE: _____



INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
May 8, 1985
PAGE 14 OF 18

15.1 Sketch 8-0



GREASE CONTROL STATION

This drawing has not been published. It is the sole property of INRYCO, Inc. It is lent to the recipient for his confidential use only, and upon the conditions and agreements following, in consideration of the loan of this drawing, the recipient promises and agrees to return it upon request, and that it shall not be reproduced, copied, lent or otherwise disposed of directly or indirectly without INRYCO, Inc. written consent, nor be used in any way detrimental to the interests of INRYCO, Inc.



Inryco
an Inland Steel company
Post Tensioning Division


Revised By	Date
Approved By	Date
Drawn By	Date
Drawing No.	SECTION

Sketch 8-0

15.2 Sketch 8-1

TYPICAL HOOK-UP FOR FILLING TENDON VOIDS

- A - Grease Can Body
- B - Pipe
- C - Grease Can Filler Bushing
- D - Y-Device Body
- E - Male Quick Coupler
- F - Operating Shaft & Handle
- G - Square Male Pipe Plug Wrench
- H - Pipe Plug
- I - Casing Filler Hose
- J - Female Quick Coupler
- K - Packing Box
- L - Packing Box Gland
- M - Relief Valve - Optional



Refer Procedure F3.0 Section 1.4 for operation.

Special Tendon Void Filling Tool

This drawing has not been published. It is the sole property of INRYCO, Inc. It is loaned to the recipient for his confidential use only, and upon the conditions and agreements following. In consideration of the loan of this drawing, the recipient promises and agrees to return it upon request, and that it shall not be reproduced, copied, lent or otherwise disposed of directly or indirectly without INRYCO, Inc. written consent, nor be used in any way detrimental to the interests of INRYCO, Inc.

Y-DEVICE



Inryco

an Inland Steel company


Post Tensioning Division

Revised By	Date
Approved By	Date
Drawn By	Date
Drawing No.	

Sketch 8-1


15.3 Sketch 3-2

SYSTEM A




Re-circulation to storage during hook-up operations.

SYSTEM B




Re-circulation through filler hoses before or after filling operations.


All component identification is the same as shown in System A, except where noted.

RECIRCULATION PATTERNS	FLOW DIAGRAM	Revised By Date
<p>This drawing has not been published. It is the sole property of INRYCO, Inc. It is lent to the recipient for his confidential use only, and upon the conditions and agreements following. In consideration of the loan of this drawing, the recipient promises and agrees to return it upon request, and that it shall not be reproduced, copied, lent or otherwise disposed of directly or indirectly without INRYCO, Inc. written consent, nor be used in any way detrimental to the interests of INRYCO, Inc.</p>	 <p>Inryco an Inland Steel company Post Tensioning Division</p>	<p>Approved By Date</p>
		<p>Drawn By Date</p>
		<p>Drawing No. Sketch 3-2</p>




15.4 Sketch 12.7



GREASE REPLACEMENT - HORIZONTAL TENDON	PROCEDURE SQ 12.7	Revised By:  Date: 5-13-85
This drawing has not been published. It is the sole property of INRYCO, Inc. It is loaned to the recipient for his confidential use only, and upon the conditions and agreements following: In consideration of the loan of this drawing, the recipient promises and agrees to return it upon request, and that it shall not be reproduced, copied, or otherwise disposed of directly or indirectly without INRYCO, Inc. written consent, nor be used in any way detrimental to the interests of INRYCO, Inc.	Inryco an Inland Steel company	Approved By: C.H. Date: 5-13-85
	Post Tensioning Division	Drawing No. SKETCH 12.7



15.5 Sketch 12.7.1



SINGLE TENDON REFILL-HORIZONTAL TENDON

This drawing has not been published. It is the sole property of INRYCO, Inc. It is lent to the recipient for his confidential use only, and upon the conditions and agreements following. In consideration of the loan of this drawing, the recipient promises and agrees to return it upon request, and that it shall not be reproduced, copied, lent or otherwise disposed of directly or indirectly without INRYCO, Inc. written consent, nor be used in any way detrimental to the interests of INRYCO, Inc.



Inryco
an Inland Steel company
Post Tensioning Division

Revised By	See
Approved By	Date
Drawn By	Date
Drawing No.	SKETCH 12.7.1

5-14-85
5-13-85

INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: _____ UNIT: _____ DATE: _____

TENDON NO.: _____ TENDON END/BUTTIRESS NO.: _____

QC
SIGNOFF

(8.4) Concrete Temp: _____ °F. Thermo. No.: _____ Recal Date: _____

(11.6.1) Grease Temp. Storage Container _____ °F.

Thermometer No. _____ Recal Date: _____

(11.12.4) Grease Temp. Ambient _____ °F.

Thermometer No. _____ Recal Date: _____

(11.13.1) Grease Temp. Exiting _____ °F.

Thermometer No. _____ Recal Date: _____

(12.6.1) Grease Temp. Storage Container _____ °F.

Thermometer No. _____ Recal Date: _____

(12.12.1) Grease Temp. Ambient _____ °F.

Thermometer No. _____ Recal Date: _____

(12.13.1) Grease Temp. Exiting _____ °F.

Thermometer No. _____ Recal Date: _____

(13.1) Grease Leaks YES NO

Leaks Repaired YES NO

(13.1.1) Refill Acceptable: _____

(13.1.2) COMMENTS: _____

(13.1.3) FNP Drum Control No.: _____ Viscosity Batch No. _____

Q.C. REVIEW: _____ LEVEL _____ DATE: _____

TITLE: _____

INXYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 5-31-85
TENDON NO.: IDE TENDON END/BUTTRESS NO.: E

QC
SIGNOFF

(8.4) Concrete Temp: 78 °F. Thermo. No.: ST-42 Recal Date: 5-22-86 BBB 5-31-85
(11.6.1) Grease Temp. Storage Container °F.
Thermometer No. Recal Date:
(11.12.4) Grease Temp. Ambient °F.
Thermometer No. Recal Date:
(11.13.1) Grease Temp. Exiting °F.
Thermometer No. Recal Date:
(12.6.1) Grease Temp. Storage Container 220 °F. BBB 5-31-85
Thermometer No. PK55 Recal Date: 5-22-86 BBB 5-31-85
(12.12.1) Grease Temp. Ambient 86 °F. BBB 5-31-85
Thermometer No. PK55 Recal Date: 5-22-86 BBB 5-31-85
(12.13.1) Grease Temp. Exiting 108 °F. BBB 5-31-85
Thermometer No. OK55 Recal Date: 5-22-86 BBB 5-31-85
(13.1) Grease Leaks YES ☒ NO BBB 5-31-85
Leaks Repaired YES ☒ NO BBB 5-31-85
(13.1.1) Refill Acceptable: YES BBB 5-31-85
(13.1.2) COMMENTS: NONE

 BBB 5-31-85
(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-5526 BBB 5-31-85

Q.C. REVIEW: John Anthony LEVEL II DATE: 6/1/85
TITLE: W.E. INSPECTOR

INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 5-30-85
TENDON NO.: 01 DE TENDON END/BUTTRESS NO.: D

QC
SIGNOFF

(8.4) Concrete Temp: 86 °F. Thermo. No.: ST-62 Recal Date: 5-22-86 DAWILA 5-30-85
(11.6.1) Grease Temp. Storage Container 180 °F. DAWILA 5-30-85
Thermometer No. PK-54 Recal Date: 5-22-86 DAWILA 5-30-85
(11.12.4) Grease Temp. Ambient 88 °F. DAWILA 5-30-85
Thermometer No. PK-54 Recal Date: 5-22-86 DAWILA 5-30-85
(11.13.1) Grease Temp. Exiting 120 °F. DAWILA 5-30-85
Thermometer No. PK-54 Recal Date: 5-22-86 DAWILA 5-30-85
(12.6.1) Grease Temp. Storage Container _____ °F. _____
Thermometer No. _____ Recal Date: _____
(12.12.1) Grease Temp. Ambient N °F. N/A
Thermometer No. _____ Recal Date: A
(12.13.1) Grease Temp. Exiting _____ °F. _____
Thermometer No. _____ Recal Date: _____
(13.1) Grease Leaks YES ☒ NO DAWILA 5-30-85
Leaks Repaired YES ☒ NO DAWILA 5-30-85
(13.1.1) Refill Acceptable: YES DAWILA 5-30-85
(13.1.2) COMMENTS: NONE

DAWILA 5-30-85
(13.1.3) FWP Drum Control No.: N/A Viscosity ^{LOT} Batch No. 5-5526 DAWILA 5-30-85

Q.C. REVIEW: Joe Phibbs LEVEL II DATE: 5/31/85
TITLE: Q.E. INSPECTOR

INXYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 6-3-85
TENDON NO.: 21DE TENDON END/BUTTRESS NO.: E

QC
SIGNOFF

(8.4) Concrete Temp: 95 °F. Thermo. No.: ST-60 Recal Date: 5-22-86 JAD 6/3/85
(11.6.1) Grease Temp. Storage Container _____ °F.
Thermometer No. _____ Recal Date: _____
(11.12.4) Grease Temp. Ambient _____ °F.
Thermometer No. _____ Recal Date: _____ N/A
(11.13.1) Grease Temp. Exiting _____ °F.
Thermometer No. _____ Recal Date: _____
(12.6.1) Grease Temp. Storage Container 193 °F. JAD 6/3/85
Thermometer No. PK55 Recal Date: 5-22-86 JAD 6/3/85
(12.12.1) Grease Temp. Ambient 93 °F. JAD 6/3/85
Thermometer No. PK53 Recal Date: 5-22-86 JAD 6/3/85
(12.13.1) Grease Temp. Exiting 130 °F. JAD 6/3/85
Thermometer No. PK53 Recal Date: 5-22-86 JAD 6/3/85
(13.1) Grease Leaks YES ☒ NO ☒ JAD 6/2/85
Leaks Repaired YES NO N/A JAD 6/3/85
(13.1.1) Refill Acceptable: Yes JAD 6/3/85
(13.1.2) COMMENTS: Report for 'E' Buttress only.

(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-5556 JAD 6/3/85

Q.C. REVIEW: VCW Joe Thompson LEVEL II DATE: 6/4/85
TITLE: R/E. INSPECTOR

INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 5-30-85
TENDON NO.: 21 DE TENDON END/BUTTRESS NO.: D

QC
SIGNOFF

(8.4) Concrete Temp: 108 °F. Thermo. No.: ST-62 Recal Date: 5-22-86 Dalva 5-30-85

(11.6.1) Grease Temp. Storage Container 190 °F. Dalva 5-30-85

Thermometer No. PK-54 Recal Date: 5-22-86 Dalva 5-30-85

(11.12.4) Grease Temp. Ambient 96 °F. Dalva 5-30-85

Thermometer No. PK-54 Recal Date: 5-22-86 Dalva 5-30-85

(11.13.1) Grease Temp. Exiting 120 °F. Dalva 5-30-85

Thermometer No. PK-54 Recal Date: 5-22-86 Dalva 5-30-85

~~(12.6.1) Grease Temp. Storage Container _____ °F.~~

~~Thermometer No. _____ Recal Date: _____~~

~~(12.12.1) Grease Temp. Ambient _____ °F.~~ N A

~~Thermometer No. N Recal Date: A~~

~~(12.13.1) Grease Temp. Exiting _____ °F.~~

~~Thermometer No. _____ Recal Date: _____~~

(13.1) Grease Leaks YES ☒ NO Dalva 5-30-85

Leaks Repaired YES ☒ NO Dalva 5-30-85

(13.1.1) Refill Acceptable: YES Dalva 5-30-85

(13.1.2) COMMENTS: NONE

(13.1.3) FWP Drum Control No.: N/A Viscosity ^{LOT} Batch No. 5-5526 Dalva 5-30-85

Q.C. REVIEW: Jed Parker LEVEL II DATE: 5/31/85

TITLE: U.E. INSPECTOR

PROJECT: Farley UNIT: 2 DATE: 6/4/85
TENDON NO.: 28 DE TENDON END/BUTTERESS NO.: E

QC
SIGNOFF

(8.4) Concrete Temp: 96 °F. Thermo. No.: ST62 Recal Date: 5/22/86 JHD 6/4/85

(11.6.1) Grease Temp. Storage Container 180 °F. JHD 6/4/85

Thermometer No. PK-53 Recal Date: 5/22/86 JHD 6/4/85

(11.12.4) Grease Temp. Ambient 100 °F. JHD 6/4/85

Thermometer No. PK-53 Recal Date: 5/22/86 JHD 6/4/85

(11.13.1) Grease Temp. Exiting 122 °F. JHD 6/4/85

Thermometer No. PK-53 Recal Date: 5/22/86 JHD 6/4/85

(12.6.1) Grease Temp. Storage Container 0 °F.

Thermometer No. Recal Date:

(12.12.1) Grease Temp. Ambient N/A °F. N/A

Thermometer No. Recal Date:

(12.13.1) Grease Temp. Exiting °F.

Thermometer No. Recal Date:

(13.1) Grease Leaks YES ☒ NO ☐ JHD 6/4/85

Leaks Repaired YES ☐ NO ☒ N/A JHD 6/4/85

(13.1.1) Refill Acceptable: Yes JHD 6/4/85

(13.1.2) COMMENTS: Report for E. Buttrick only.

(13.1.3) FWP Drum Control No.: N/A Viscosity Batch No. 5-6259 JHD 6/4/85

Q.C. REVIEW: UCW J. J. Haring LEVEL II DATE: 6/5/85

TITLE: 28 INSPECTOR

PROJECT: FARLEY UNIT: 2 DATE: 6-4-85
TENDON NO.: 280E TENDON END/BUTTRISS NO.: D

QC
SIGNOFF

(8.4) Concrete Temp: 96 °F. Thermo. No.: ST-60 Recal Date: 5-22-86 554-4-85
(11.6.1) Grease Temp. Storage Container _____ °F.
Thermometer No. _____ Recal Date: _____
(11.12.4) Grease Temp. Ambient N/A °F.
Thermometer No. _____ Recal Date: _____ N/A
(11.13.1) Grease Temp. Exiting _____ °F.
Thermometer No. _____ Recal Date: _____
(12.6.1) Grease Temp. Storage Container 152 °F. 513 6-4-85
Thermometer No. PK55 Recal Date: 5-22-86 553 6-4-85
(12.12.1) Grease Temp. Ambient 92 °F. 554-4-85
Thermometer No. PK55 Recal Date: 5-22-86 554-4-85
(12.13.1) Grease Temp. Exiting 124 °F. 554-4-85
Thermometer No. PK55 Recal Date: 5-22-86 554-4-85
(13.1) Grease Leaks YES NO 554-4-85
Leaks Repaired YES NO 554-4-85
(13.1.1) Refill Acceptable: YES 554-4-85
(13.1.2) COMMENTS: NONE

(13.1.3) FYP Drum Control No.: N/A Viscosity Batch No. 5-6359 554-4-85

Q.C. REVIEW: John Anthony LEVEL A DATE: 6/5/85
TITLE: Q.E. INSPECTION

PROJECT: Farley UNIT: 2 DATE: 6/4/85
TENDON NO.: 45 DE TENDON END/BUTRESS NO.: 'E'

QC
SIGNOFF

(8.4) Concrete Temp: 102°F Thermo. No.: ST 62 Recal Date: 5/22/86 JAD 6/4/85

(11.6.1) Grease Temp. Storage Container 220 °F. JAD 6/4/85

Thermometer No. PK-53 Recal Date: 5/22/86 JAD 6/4/85

(11.12.4) Grease Temp. Ambient 110 °F. JAD 6/4/85

Thermometer No. PK-53 Recal Date: 5/22/86 JAD 6/4/85

(11.13.1) Grease Temp. Exiting 160 °F. JAD 6/4/85

Thermometer No. PK 53 Recal Date: 5/22/86 JAD 6/4/85

(12.6.1) Grease Temp. Storage Container °F.

Thermometer No. Recal Date:

(12.12.1) Grease Temp. Ambient °F. N/A

Thermometer No. Recal Date:

(12.13.1) Grease Temp. Exiting °F.

Thermometer No. Recal Date:

(13.1) Grease Leaks YES NO JAD 6/4/85

Leaks Repaired YES NO N/A JAD 6/4/85

(13.1.1) Refill Acceptable: Yes JAD 6/4/85

(13.1.2) COMMENTS: Report for 'E' Butties only

(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-4359 JAD 6/4/85

Q.C. REVIEW: JAD Thibault LEVEL II DATE: 6/5/85

TITLE: P.E. INSPECTOR

PROJECT: FARLEY UNIT: 2 DATE: 6-7-85
TENDON NO.: 45 DE TENDON END/BUTTRESS NO.: D

QC
SIGNOFF

(8.4) Concrete Temp: 102 °F. Thermo. No.: ST-56 Recal Date: 3-15-86 BB 6-7-85
(11.6.1) Grease Temp. Storage Container _____ °F.
Thermometer No. _____ Recal Date: _____
(11.12.4) Grease Temp. Ambient _____ °F.
Thermometer No. _____ Recal Date: _____ N/A
(11.13.1) Grease Temp. Exiting _____ °F.
Thermometer No. _____ Recal Date: _____
(12.6.1) Grease Temp. Storage Container 190 °F. BB 6-7-85
Thermometer No. PK55 Recal Date: 5-22-86 BB 6-7-85
(12.12.1) Grease Temp. Ambient 100 °F. BB 6-7-85
Thermometer No. PK55 Recal Date: 5-22-86 BB 6-7-85
(12.13.1) Grease Temp. Exiting 150 °F. BB 6-7-85
Thermometer No. PK55 Recal Date: 5-22-86 BB 6-7-85
(13.1) Grease Leaks YES ☒ NO BB 6-7-85
Leaks Repaired YES ☒ NO BB 6-7-85
(13.1.1) Refill Acceptable: YES BB 6-7-85
(13.1.2) COMMENTS: NONE
BB 6-7-85
BB 6-7-85
(13.1.3) FYP Drum Control No.: N/A Viscosity ^{AST} Batch No. 3-6359 BB 6-7-85

Q.C. REVIEW: W. D. W. Jell LEVEL II DATE: 6-20-85
TITLE: QC Inspector

INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 5-31-85
TENDON NO.: 3EF TENDON END/BUTTRESS NO.: E

QC
SIGNOFF

(8.4) Concrete Temp: 78 °F. Thermo. No.: 5F-62 Recal Date: 5-22-86 Davilla 5-31-85
(11.6.1) Grease Temp. Storage Container N/A °F.
Thermometer No. N/A Recal Date: N/A
(11.12.4) Grease Temp. Ambient N/A °F.
Thermometer No. N/A Recal Date: N/A
(11.13.1) Grease Temp. Exiting N/A °F.
Thermometer No. N/A Recal Date: N/A
(12.6.1) Grease Temp. Storage Container 210 °F. Davilla 5-31-85
Thermometer No. PK-54 Recal Date: 5-22-86 Davilla 5-31-85
(12.12.1) Grease Temp. Ambient 84 °F. Davilla 5-31-85
Thermometer No. PK-54 Recal Date: 5-22-86 Davilla 5-31-85
(12.13.1) Grease Temp. Exiting 120 °F. Davilla 5-31-85
Thermometer No. PK-54 Recal Date: 5-22-86 Davilla 5-31-85
(13.1) Grease Leaks YES ☒ NO Davilla 5-31-85
Leaks Repaired YES ☒ NO Davilla 5-31-85
(13.1.1) Refill Acceptable: YES Davilla 5-31-85
(13.1.2) COMMENTS: NONE
Davilla 5-31-85
Davilla 5-31-85
(13.1.3) FNP Drum Control No.: N/A Viscosity ^{LOT} Batch No. 5-5526 Davilla 5-31-85

Q.C. REVIEW: Joe Anthony LEVEL II DATE: 6/1/85

INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 5-29-85
TENDON NO.: 3EF TENDON END/BUTTRESS NO.: F

QC
SIGNOFF

(8.4) Concrete Temp: 94 °F. Thermo. No.: ST-59 Recal Date: 3-15-86 DAWILL 5-29-85

(11.6.1) Grease Temp. Storage Container 7220 °F. DAWILL 5-29-85

Thermometer No. PK-52 Recal Date: 5-22-86 DAWILL 5-22-85

(11.12.4) Grease Temp. Ambient 94 °F. DAWILL 5-29-85

Thermometer No. PK-54 Recal Date: 5-22-86 DAWILL 5-22-85

(11.13.1) Grease Temp. Exiting 120 °F. DAWILL 5-29-85

Thermometer No. PK-54 Recal Date: 5-22-86 DAWILL 5-29-85

(12.6.1) Grease Temp. Storage Container _____ °F. _____

Thermometer No. _____ Recal Date: _____

(12.12.1) Grease Temp. Ambient _____ °F. _____

Thermometer No. _____ Recal Date: _____

(12.13.1) Grease Temp. Exiting _____ °F. _____

Thermometer No. _____ Recal Date: _____

(13.1) Grease Leaks YES ☒ NO DAWILL 5-29-85

Leaks Repaired YES ☒ NO DAWILL 5-29-85

(13.1.1) Refill Acceptable: YES DAWILL 5-29-85

(13.1.2) COMMENTS: NONE

(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-5526 DAWILL 5-29-85

Q.C. REVIEW: [Signature] LEVEL II DATE: 5/30/85

INEXCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 5-31-85
TENDON NO.: 17EF TENDON END/BUTTRESS NO.: E

QC
SIGNOFF

(8.4) Concrete Temp: 102 °F. Thermo. No.: 5462 Recal Date: 5-22-86 Dalvella 5-31-85
(11.6.1) Grease Temp. Storage Container N/A °F.
Thermometer No. N/A Recal Date: N/A
(11.12.4) Grease Temp. Ambient N/A °F.
Thermometer No. N/A Recal Date: N/A N/A
(11.13.1) Grease Temp. Exiting N/A °F.
Thermometer No. N/A Recal Date: N/A
(12.6.1) Grease Temp. Storage Container 170 °F. Dalvella 5-31-85
Thermometer No. PK 54 Recal Date: 5-22-86 Dalvella 5-31-85
(12.12.1) Grease Temp. Ambient 90 °F. Dalvella 5-31-85
Thermometer No. PK 54 Recal Date: 5-22-86 Dalvella 5-31-85
(12.13.1) Grease Temp. Exiting 120 °F. Dalvella 5-31-85
Thermometer No. PK 54 Recal Date: 5-22-86 Dalvella 5-31-85
(13.1) Grease Leaks YES NO Dalvella 5-31-85
Leaks Repaired YES NO Dalvella 5-31-85
(13.1.1) Refill Acceptable: YES Dalvella 5-31-85
(13.1.2) COMMENTS: NONE
Dalvella 5-31-85
Dalvella 5-31-85
(13.1.3) FHP Drum Control No.: N/A Viscosity Batch No. 5-5526 Dalvella 5-31-85

Q.C. REVIEW: Joe Thibault LEVEL II DATE: 6/1/85

INXYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: Farley UNIT: 2 DATE: 5/30/85
TENDON NO.: 17 EF TENDON END/BUTTRESS NO.: F

QC
SIGNOFF

(8.4) Concrete Temp: 95 °F. Thermo. No.: ST 56 Recal Date: 3/15/86 JAD 5/30/85

(11.6.1) Grease Temp. Storage Container 185 °F. JAD 5/30/85

Thermometer No. PK 53 Recal Date: 5/22/85 JAD 5/30/85

(11.12.4) Grease Temp. Ambient 95 °F. * JAD 5/30/85

Thermometer No. PK 53 Recal Date: 5/22/85 JAD 5/30/85

(11.13.1) Grease Temp. Exiting 150 °F. JAD 5/30/85

Thermometer No. PK 53 Recal Date: 5/22/85 JAD 5/30/85

(12.6.1) Grease Temp. Storage Container _____ °F. _____

Thermometer No. _____ Recal Date: _____

(12.12.1) Grease Temp. Ambient N/A °F. _____

Thermometer No. _____ Recal Date: _____

(12.13.1) Grease Temp. Exiting _____ °F. _____

Thermometer No. _____ Recal Date: _____

(13.1) Grease Leaks YES NO JAD 5/30/85

Leaks Repaired YES NO N/A JAD 5/30/85

(13.1.1) Refill Acceptable: Yes JAD 5/30/85

(13.1.2) COMMENTS: Report for 'F' Buttress only.

* No grease available in drum or vent for Ambient

Temperature shown is air-temperature in can. JAD 5/30/85

(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-5526 JAD 5/30/85

Q.C. REVIEW: UCW Joe Thabery LEVEL II DATE: 5/31/85

INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 6-6-85
TENDON NO.: 31EF TENDON END/BUTTRESS NO.: E

QC
SIGNOFF

(8.4) Concrete Temp: 106 °F. Thermo. No.: ST-56 Recal Date: 3-15-86 BB 6-6-85
(11.6.1) Grease Temp. Storage Container 220 °F. BB 6-6-85
Thermometer No. PK55 Recal Date: 5-22-86 BB 6-6-85
(11.12.4) Grease Temp. Ambient 106 °F. BB 6-6-85
Thermometer No. PK55 Recal Date: 5-22-86 BB 6-6-85
(11.13.1) Grease Temp. Exiting 134 °F. BB 6-6-85
Thermometer No. PK55 Recal Date: 5-22-86 BB 6-6-85
(12.6.1) Grease Temp. Storage Container _____ °F. _____
Thermometer No. _____ Recal Date: _____
(12.12.1) Grease Temp. Ambient _____ °F. _____
Thermometer No. _____ Recal Date: _____
(12.13.1) Grease Temp. Exiting _____ °F. _____
Thermometer No. _____ Recal Date: _____
(13.1) Grease Leaks YES NO BB 6-6-85
Leaks Repaired YES NO BB 6-6-85
(13.1.1) Refill Acceptable: YES BB 6-6-85
(13.1.2) COMMENTS: NONE

(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-6359 BB 6-6-85

Q.C. REVIEW: UCWandel LEVEL II DATE: 6-20-85

INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: Farley UNIT: 2 DATE: 6/6/85
TENDON NO.: 31 EF TENDON END/BUTTRESS NO.: 'F'

QC
SIGNOFF

(8.4) Concrete Temp: 110 °F. Thermo. No.: 5762 Recal Date: 5/22/86

STAD 6/6/85

(11.6.1) Grease Temp. Storage Container _____ °F.

Thermometer No. _____ Recal Date: _____

(11.12.4) Grease Temp. Ambient _____ °F.

Thermometer No. _____ Recal Date: _____

(11.13.1) Grease Temp. Exiting _____ °F.

Thermometer No. _____ Recal Date: _____

(12.6.1) Grease Temp. Storage Container 215 °F.

STAD 6/6/85

Thermometer No. PK 53 Recal Date: 5/22/86

STAD 6/6/85

(12.12.1) Grease Temp. Ambient 102 °F.

STAD 6/6/85

Thermometer No. PK 53 Recal Date: 5/22/86

STAD 6/6/85

(12.13.1) Grease Temp. Exiting 142 °F.

STAD 6/6/85

Thermometer No. PK 53 Recal Date: 5/22/86

STAD 6/6/85

(13.1) Grease Leaks YES ☒ NO

STAD 6/6/85

Leaks Repaired YES ☒ NO N/A

STAD 6/6/85

(13.1.1) Refill Acceptable: Yes

STAD 6/6/85

(13.1.2) COMMENTS: Report for F Buttress only

(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-6302

STAD 6/6/85

O.C. REVIEW: W. Daniel

LEVEL II DATE: 6-20-85

INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 5-30-85
TENDON NO.: 13 FD TENDON END/BUTTRESS NO.: F

QC
SIGNOFF

(8.4) Concrete Temp: 92 °F. Thermo. No.: ST-56 Recal Date: 3-15-86 JAD 5/30/85
(11.6.1) Grease Temp. Storage Container 185 °F. JAD 5/30/85
Thermometer No. PK53 Recal Date: 5-22-86 JAD 5/30/85
(11.12.4) Grease Temp. Ambient 94* °F. JAD 5/30/85
Thermometer No. PK53 Recal Date: 5-22-86 JAD 5/30/85
(11.13.1) Grease Temp. Exiting 150 °F. JAD 5/30/85
Thermometer No. PK53 Recal Date: 5-22-86 JAD 5/30/85
(12.6.1) Grease Temp. Storage Container _____ °F. _____
Thermometer No. _____ Recal Date: _____
(12.12.1) Grease Temp. Ambient _____ °F. _____
Thermometer No. N A Recal Date: _____
(12.13.1) Grease Temp. Exiting _____ °F. _____
Thermometer No. _____ Recal Date: _____
(13.1) Grease Leaks YES ☒ NO ☒ JAD 5/30/85
Leaks Repaired YES ☒ NO ☒ JAD 5/30/85
(13.1.1) Refill Acceptable: YES JAD 5/30/85
(13.1.2) COMMENTS: *NO VISIBLE GREASE, AIR TEMPERATURE ONLY
Report for F Buttress only
JAD 5/30/85
(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-5526 JAD 5/30/85

Q.C. REVIEW: JAD LEVEL II DATE: 5/31/85

INRYCO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 5-30-85
TENDON NO.: 13FD TENDON END/BUTTRESS NO.: D

QC
SIGNOFF

(8.4) Concrete Temp: 98 °F. Thermo. No.: ST-56 Recal Date: 3-15-86

Davila 5-30-85

(11.6.1) Grease Temp. Storage Container _____ °F.

Thermometer No. _____ Recal Date: _____

(11.12.4) Grease Temp. Ambient _____ °F.

Thermometer No. N A Recal Date: _____

(11.13.1) Grease Temp. Exiting _____ °F.

Thermometer No. _____ Recal Date: _____

(12.6.1) Grease Temp. Storage Container 160 °F.

Davila 5-30-85

Thermometer No. PK-54 Recal Date: 5-22-86

Davila 5-30-85

(12.12.1) Grease Temp. Ambient 92 °F.

Davila 5-30-85

Thermometer No. PK-54 Recal Date: 5-22-86

Davila 5-30-85

(12.13.1) Grease Temp. Exiting 120 °F.

Davila 5-30-85

Thermometer No. PK-54 Recal Date: 5-22-86

Davila 5-30-85

(13.1) Grease Leaks YES ☒ NO

Davila 5-30-85

Leaks Repaired YES ☒ NO

Davila 5-30-85

(13.1.1) Refill Acceptable: YES

Davila 5-30-85

(13.1.2) COMMENTS: NONE

Davila 5-30-85

(13.1.3) FNP Drum Control No.: N/A Viscosity ^{LOT} Batch No. 5-5526 Davila 5-30-85

Q.C. REVIEW: Joe Thompson LEVEL II DATE: 5/31/85

LNEYCO INC. PROCEDURE SQ 12.7
 GREASE HORIZONTAL TENDON-FINAL REFILL
 DATA SHEET 12.7
 MAY 8, 1985, Revision 0
 PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 6-8-85
TENDON NO.: 26FD TENDON END/BUTRESS NO.: D

QC
SIGNOFF

(8.4) Concrete Temp: 110 °F. Thermo. No.: ST-56 Recal Date: 3-15-86

BSP 6.8.85

(11.6.1) Grease Temp. Storage Container 1 °F.

Thermometer No. _____ Race/Date: _____

(11.12.4) Grease Temp. Ambient °F.

Thermometer No. _____ Recal Date: _____

(11.13.1) Grease Temp. Exiting Ct.

Thermometer No. Recal Data:

(12.6.1) Grease Temp. Storage Container 220 °F.

BB 6-885

Thermometer No. PK55 Recal Date: 5-22-86

BB6-8-85

(12.12.1) Grease Temp. Ambient 98 09.

BB6-P-85

Thermometer No. PK55 Recal Date: 5-22-86

26.8.85

(12.13.1) Grease Temp. Exiting 146 °F.

BB6-855

Thermometer No. PK55 Recal Data: 5-22-86

BB 6.8-85

(13.1) Grease Leaks YES NO

BB 6-8-85

Leaky repaired YES NO

BB 6-8-85

(13.1.1) Refill Acceptable: YES

356.885

(13.1.2) COMMENTS: NONE

(11.1.3) FYP Drum Control No.: NA Viscosity Batch No. 5.659

BB 6.8-95

10000 SOUTH. Wash. - Ind

DATE: 6-70-81

INTECO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: Forley UNIT: 2 DATE: 6/5/85
TENDON NO.: 26 FD TENDON END/BUTTRESS NO.: F

QC
SIGNOFF

(8.4) Concrete Temp: 104°F. Thermo. No.: ST 62 Recal Date: 5/22/86 JAD 6/5/85

(11.6.1) Grease Temp. Storage Container 182 °F. JAD 6/5/85

Thermometer No. PK 53 Recal Date: 5/22/86 JAD 6/5/85

(11.12.4) Grease Temp. Ambient 98 °F. JAD 6/5/85

Thermometer No. PK 53 Recal Date: 5/22/86 JAD 6/5/85

(11.13.1) Grease Temp. Exiting 140 °F. JAD 6/5/85

Thermometer No. PK 53 Recal Date: 5/22/86 JAD 6/5/86

(12.6.1) Grease Temp. Storage Container _____ °F. _____

Thermometer No. _____ Recal Date: _____

(12.12.1) Grease Temp. Ambient N/A °F. N/A

Thermometer No. _____ Recal Date: _____

(12.13.1) Grease Temp. Exiting _____ °F. _____

Thermometer No. _____ Recal Date: _____

(13.1) Grease Leaks YES NO JAD 6/5/86

Leaks Repaired YES NO N/A JAD 6/5/86

(13.1.1) Refill Acceptable: Yes JAD 6/5/86

(13.1.2) COMMENTS: Signal for F Buttress only

(13.1.3) FWP Drum Control No.: NA Viscosity Batch No. 5-4357 JAD 6/5/86

Q.C. REVIEW: UCW LEVEL II DATE: 6-20-85

INTECO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: FARLEY UNIT: 2 DATE: 6-7-85
TENDON NO.: 42FD TENDON END/BUTTERESS NO.: D

QC
SIGNOFF

(8.4) Concrete Temp: 100°F. Thermo. No.: ST-56 Recal Date: 3-15-86 BBB 6-7-85
(11.6.1) Grease Temp. Storage Container _____ °F.
Thermometer No. _____ Recal Date: _____
(11.12.4) Grease Temp. Ambient _____ °F. N/A
Thermometer No. _____ Recal Date: _____
(11.13.1) Grease Temp. Exiting _____ °F.
Thermometer No. _____ Recal Date: _____
(12.6.1) Grease Temp. Storage Container 190 °F. BBB 6-7-85
Thermometer No. PK55 Recal Date: 5-22-86 BBB 6-7-85
(12.12.1) Grease Temp. Ambient 101 °F. BBB 6-7-85
Thermometer No. PK55 Recal Date: 5-22-86 BBB 6-7-85
(12.13.1) Grease Temp. Exiting 136 °F. BBB 6-7-85
Thermometer No. PK55 Recal Date: 5-22-86 BBB 6-7-85
(13.1) Grease Leaks YES ☒ NO BBB 6-7-85
Leaks Repaired YES ☒ NO BBB 6-7-85
(13.1.1) Refill Acceptable: YES BBB 6-7-85
(13.1.2) COMMENTS: NONE

(13.1.1) FNP Drum Control No.: N/A Viscosity Lot Batch No. 5 6359 BBB 6-7-85

Q.C. REVIEW: CCW LEVEL II DATE: 6-20-85

INTECO INC. PROCEDURE SQ 12.7
GREASE HORIZONTAL TENDON-FINAL REFILL
DATA SHEET 12.7
MAY 8, 1985, Revision 0
PAGE 1 OF 1

PROJECT: Fawley UNIT: 2 DATE: 6/6/85
TENDON NO.: 42 FD TENDON END/BUTTERESS NO.: 'F'

QC
SIGNOFF

(8.4) Concrete Temp: 88 °F. Thermo. No.: ST-62 Recal Date: 5/22/86 JAD 6/6/85

(11.6.1) Grease Temp. Storage Container 160 °F. JAD 6/6/85

Thermometer No. BK 53 Recal Date: 5/22/86 JAD 6/6/85

(11.12.4) Grease Temp. Ambient 94 °F. JAD 6/6/85

Thermometer No. PK 53 Recal Date: 5/22/86 JAD 6/6/85

(11.13.1) Grease Temp. Exiting 132 °F. JAD 6/6/85

Thermometer No. PK 53 Recal Date: 5/22/86 JAD 6/6/85

(12.6.1) Grease Temp. Storage Container °F.

Thermometer No. Recal Date:

(12.12.1) Grease Temp. Ambient °F. N/A

Thermometer No. Recal Date:

(12.13.1) Grease Temp. Exiting °F.

Thermometer No. Recal Date:

(13.1) Grease Leaks YES NO JAD 6/6/85

Leaks Repaired YES NO N/A JAD 6/6/85

(13.1.1) Refill Acceptable: Yes JAD 6/6/85

(13.1.2) COMMENTS: Report for 'F' Butters only

(13.1.3) PYP Drum Control No.: N/A Viscosity Batch No. 5-6359 JAD 6/6/85

Q.C. REVIEW: Oscar Del LEVEL II DATE: 6-20-85

FARLEY NUCLEAR PLANT
INRYCO QUALITY CONTROL PROCEDURE
ANCHORHEAD REPLACEMENT PROGRAM

GREASE REPLACEMENT TO FILL THE TENDON
VOID OF DOME TENDONS.

△ APPROVED BY: *D. W. Winters* TITLE: *Superintendent* DATE: *6/12/85*
△ REVIEWED BY: *Craig M. Kent* TITLE: *SEDAW ENGINEER* DATE: *6/12/85*

ALABAMA POWER COMPANY - FNP REVIEW

REVIEWED BY: *Robert D. Benge* TITLE: *SP Supt* DATE: *6-18-85*
0252N

May 23, 1985

 PAGE 2 OF 15

1. PURPOSE

This procedure will establish the requirements for the Replacement of Grease to fill the Tendon Voids (Ducts) of Dome Tendons for purposes of establishing the integrity of the corrosion protection compound (Viscosity Oil Co. Visconorust 2090P4) as part of the Anchorhead Replacement Program for the Post-Tensioning System Tendons at Farley Nuclear Generating Station.

2. SCOPE

This procedure shall only apply to Dome Tendons. This is intended to provide a refilling of the Tendon Void, but not necessarily the complete removal of all the grease that might be in that Void at the time of filling.

2.1 As the Tendon Voids are nearly completely full at this time, it is highly unlikely that this quantity of grease could be displaced during the refilling. This procedure will provide reasonable assurance that the Tendon Void will be filled to capacity while fully assuring that the Grease Cans and Trumpet Tubes will be completely full and the Tendon End Anchorage Assembly completely coated with grease.

3. RESPONSIBILITY

As stated in Inryco Procedure QA 4.0.

4. QUALIFICATIONS

As stated in Inryco Procedure QA 4.1.

5. EQUIPMENT

5.1 CONSTRUCTION

5.1.1 Visconorust 2090P4 in 55 gallon drums from FNP controlled inventory and/or as stored in a large bulk storage grease container.

5.1.2 Drum heaters, electrical connections and power source.

5.1.3 Miscellaneous hand tools, wrenches, sockets, lifting devices, rags, solvent (Viscor #16), teflon thread tape, bushing plugs, etc.

5.1.4 Grease Pumping System, Hoses, Y-Device, etc.

5.2 QUALITY CONTROL

5.2.1 Data Sheets, thermometer, tapeline or other measuring device.

6. PRECAUTIONS

Review the Safety Comments provided in Inryco Procedure SC 1 for the following items that shall apply both for tendon force control and personnel safety.

- 6.1 Section 3.1; Tendon Wire Breaking Strength.
- 6.2 Section 3.2; Stressing Operations: Overstress Force.
- 6.3 Section 3.2.2; Personnel Safety.
- 6.4 Section 3.6; Construction Safety: Personnel Safety.
- 6.5 During Grease Replacement, the grease is usually pumped under pressure with an exit temperature of 120°F. If being pumped from the heated storage tank, the temperature will be in excess of 150°F. It is, therefore, essential to avoid direct contact with the hot grease and to make sure all connections are secure.
- 6.6 Where drum heaters are used, operating temperatures are usually not as high, but exit temperature is still not less than 120°F. and injury could occur through carelessness.

6.7

CAUTION

DURING GREASING, BE AWARE THAT THE GREASE IS HOT AND BEING PUMPED UNDER PRESSURE.

7. QUALITY CONTROL

All Quality Control Documentation (QCD) points noted in this procedure are Hold Points. The work shall not progress past or through a QCD without a release from the Inspector. The required information or evaluative data shall be documented on Data Sheet 12.8 of this procedure for each end of a tendon that has been greased.

8. PREREQUISITES

- 8.1 All Inspections will be complete.
- 8.2 The tendon will be in a stressed condition.
- 8.3 The Grease Can has already been installed.
- 8.4 QCD - Document the exterior concrete temperature near the tendon.

9. GENERAL

This refilling is intended to provide a fill of the Tendon Void of a Dome Tendon, but does not necessarily mean that all the grease presently in that Tendon Void will be removed or displaced by this refilling. There also remains a possibility that there may be some entrapped air in the grease within the Sheathing portion of the Tendon Void.

- 9.1 The grease may be in a large storage container or in 55 gallon drums. The large storage container shall have an automatic thermostat control for temperature, while drum heaters shall be used to heat the grease in drums.
- 9.2 It shall be necessary to maintain specific grease temperatures and to monitor the exit temperature of the grease. It is important to have the grease in a completely liquid state so that congealing does not occur before the correct quantity is replaced. Provide venting of air while pumping the grease into the grease can.
- 9.3 The original installation temperature of the grease was not less than 120 F. This represents the maximum expansion of the grease under maximum plant operating conditions. As the grease cools, it shrinks back into the tendon void or duct leaving a coating of grease on all steel within the void and grease can. This shrink-back also causes the formation of an air pocket extending from the grease can, a short distance into the trumpet tube. Shrink-back will not occur at the Gallery or Bottom End of a Vertical Tendon. Shrink-back might not occur in Dome Tendons. The coefficient of expansion for this grease will be about 1% for every 20°F. temperature rise from 68°F.

10. SET-UP FOR REFILLING THE TENDON DUCT

several types of hook-ups have been developed for the various types and locations of Tendon Ducts to be filled and will be explained in the following procedures. Refer to the flow diagram sketches where noted, for a visual view of each system and the recirculating patterns used, to prevent hose blockages.

- 10.1 Before starting the tendon filling operations, the storage facility, drums, heaters, pump, hoses and equipment shall be set up.
- 10.2 A Grease Control Station shall be set up near the tendons to be filled and a communications network established so that the personnel at the furthest end of the tendon to be filled, will be able to communicate with the crew leader or the control station attendant. The general physical make-up of the Grease Control Station will be seen in Sketch 8.0. This configuration may vary from time to time, based on the needs at hand and access to the Tendon Voids.



Inryco
an Inland Steel company

INRYCO INC. PROCEDURE SQ 12.8
GREASE DOME TENDON-FINAL REFILL
May 23, 1985

△ PAGE 5 OF 15

- 10.3 At the end of each day of filling operations, the pump shall be shut off and the feed-in supply, return and jumper hoses shall be drained. The gate valve on the suction hose shall be closed and that hose drained. It will be acceptable to allow the grease to continue to circulate in the hose lines, providing that responsibility has been assigned for monitoring this recirculation, so that the system can be shut down in the event of system or equipment failure.
- 10.4 Refer to each specific system procedure for the proper selection. Then follow the Tendon Duct Refilling requirements for the actual operation.
- 10.5 The terms casing-filler, grease, corrosion protection compound, tendon void filler are all meant to be another name for the product which is used to fill the Tendon Void. That product is Visconorust 2090P4 as manufactured by Viscosity Oil Company.

11. SINGLE FILL SYSTEM

This method of Tendon Void filled has the grease pumped through a Y-Device attached to the Grease Can of a Dome Tendon. The grease is pumped into the Grease Can at one end of the tendon and out through the filler bushing of the Grease Can opposite end of the tendon or out through the Auxiliary filling pipe at the pumping end of the tendon. This system does not require recirculation through the Void, nor is it recommended. Refer to Sketch 12.8.1 for a pictorial presentation of this system. The Grease Can Filler Bushing Pipe Plug has been removed from the Grease Cans at each end of the tendon.

- 11.1 Attach the Grease Can Filler Bushing pipe plug to the operating shaft wrench of each Y-Device to be used. Be sure the plug is pulled back far enough into the body, so as to allow an unobstructed flow of casing filler. A sketch of a typical Y-Device will be seen in Sketch 3-1.
- 11.2 Connect the Y-Device to the grease can filler bushing at one end of the tendon and attach the waste line to the opposite end of the tendon. A waste container should be available at the opposite end of the tendon. It will be acceptable to utilize a Y-Device for the Grease Can at the opposite end of the tendon.


- △ 11.2.1 If there is a Vent Valve attached to the Grease Can, be sure that this Valve is closed, so that the venting can take place through the Grease Can Filler Bushing at the opposite end of the tendon and/or the Auxiliary Grease Filling Pipe. Refer to Sketch 12.8.


△ Delete





- 11.3 Be sure all the grease hoses are clear of blockages before connecting them to the Y-Device.
- 11.4 Before hook-up operations, the 4 port-control valve is set to recirculate the grease flow from the pump to the storage facility, as noted in Sketch 8-2, System A.
- 11.5 Before and after filling operations the feed-line from the 4 port-control valve will be coupled to the return-line completing the recirculating closed loop, and the grease allowed to circulate through the hoses back to the storage facility, as noted in Sketch 8-2, System B.
- 11.6 The grease in the bulk storage container should be in a temperature range of 150°F. to 210°F. Greasing operations should not be performed when the grease temperature is less than 150°F. when being pumped from bulk storage or directly from 55 gallon drums.
 - 11.6.1 QCD - The temperature of the grease in the bulk storage container shall be documented once a day during greasing operations utilizing that container along with the thermometer identification and recalibration data. The temperature of the grease being pumped from a 55 gallon drum shall be documented for each tendon filled in this manner.
- 11.7 The 4 port-control valve will be set for the small loop recirculation pattern as noted in Sketch 8-2, System A.
- 11.8 The pump is operating to circulate the casing filler. The grease temperature during recirculation should not be lower than 140°F. at the thermometer of the Grease Control Station shown in Sketch 8-0.
- 11.9 All connections to the tendon are made. Refer to Sketch 12.8.1.
- 11.10 The 3 port-outflow valve or waste line is set so that the initial flow of casing filler will be into the waste container. It may not be necessary to incorporate this waste line and the outflow end of the valve shall be plugged.
- 11.11 Open the 4 port-control valve allowing the flow of casing filler into the Tendon Void.





 11.12 As the grease is being pumped in, the pumping pressure should cause the grease to exit from the filling port of the Grease Can Filler Bushing of the opposite end of the tendon and/or the Auxiliary Grease Filling Pipe at the pumping end of the tendon.

 11.12.1 Monitor the outflow at the opposite end of the tendon. It should not be necessary to allow more than about twenty gallons of grease or more to exit from this end of the tendon.

 11.12.2 QCD - Document the temperature of the grease exiting from the opposite end of the tendon. This reading will establish the Ambient Temperature of the Grease. Document the identification of the thermometer and the recalibration date.

 Delete


 11.13 Continue pumping in hot grease until the temperature of the grease exiting from the opposite end of the tendon is at least 10 degrees higher than the Ambient Grease Temperature documented in Section 11.12.2 above. Install the Grease Filler Bushing Pipe Plug while continuing to pump grease.

 11.13.1 QCD - Document the final exiting temperature of the grease, the thermometer identification and recalibration date. Document the pumping pressure prior to installing the Pipe Plug in the Auxiliary Grease Filling Pipe.

11.14 If the grease quantity exiting the opposite end of the tendon has not reached about 20 gallons, continue pumping grease until this approximate quantity has been reached. Once about 20 gallons has exited the Filler Bushing, the Filler Bushing Pipe Plug shall be installed in the Bushing. Observe the pumping pressure of the grease just prior to installing the Pipe Plug, while continuing to pump grease.

11.14.1 QCD - Document the pumping pressure prior to installing the Pipe Plug to the Grease Can Filler Bushing.


11.14.2 Continue to pump grease until the pumping pressure is about 50 psi higher than the pressure recorded in Section 11.14.1 above or the Pump Safety Limit engages.

- 11.14.3 QCD - Document the pressure noted at the time the pump was disengaged or the grease line recirculated.
- 11.14.4 In the event that no grease exits the Grease Can at the opposite end of the tendon, the Pipe Plug shall be installed in the Grease Can once the pumping pressure is about 50 psi higher than the pressure documented in Section 11.13.1 above (installation of Pipe Plug to Auxiliary Grease Filling Pipe) or the Pump Safety Limit engages. This pressure shall be documented in the area designated (11.14.3) of DS 12.8.
- 11.15 Once the exiting grease has reached the correct temperature, shift the 3 port-outflow valve so the flow is directed through the 4 port-control valve and back to the storage facility.
- 11.16 Before stopping the pumping of grease into the grease can, the grease can filler bushing pipe plug shall be inserted into the grease can filler bushing at the opposite end of the tendon to aid in completely filling the Void. It will be acceptable to apply teflon tape to the pipe plugs to aid in sealing the filler bushing.
- 11.17 Install the grease can filler bushing pipe plug into the Grease Can where the pumping of grease is taking place and proceed with the valve shifting stated in Section 11.15 above.
-  11.18 Remove the waste line, Y-Devices and quick couplers from the Grease Can at the pumping end of the tendon and move to the next tendon to be greased. The opposite end of the tendon will not require greasing unless the grease has not exited at the end of the tendon.
- 11.19 While moving the hoses after uncoupling, take care not to spill any grease from the hose.
- 11.20 Any grease spilled on concrete or other surfaces shall be removed and solvent-cleaned.
- 11.21 A FINAL WORD OF CAUTION: The casing filler is being pumped under pressure and at temperatures in excess of 120°F., poor connections or the use of the wrong procedures could result in injuries.



△ 12. GREASING THE OPPOSITE END OF THE TENDON - SINGLE FILL

In the event that little or no grease has exited the opposite end of the tendon it will be necessary to pump grease into that (opposite end of the tendon). This should be performed sometime after the grease in the pumped end of the tendon has had a chance to cool or solidify somewhat. Once cooled, the opposite end of the tendon will be filled in the same manner as the pumped end of the tendon as cited in Sections 11 through 11.2.1. The documentation will take place on a new Data Sheet 12.8 for this end of the tendon.



Delete

13. OTHER CONTROLS

13.1 Verify that no grease is leaking at both ends of the tendon. If there is some leakage, the deficiency shall be corrected and cleanup performed.

13.1.1 QCD - Document the acceptability of the refilling.

13.1.2 QCD - Document any comments of unusual occurrences or references that could assist in evaluating the refill or for future surveillance.

13.1.3 QCD - Document the FNP control number for that drum or drums of grease. If that is not visible, document the Viscosity Oil Co. batch numbers.


14. DOCUMENTATION

The items requiring documentation shall be documented on Data Sheet 12.7 shown in this procedure in reduced form.

14.1 The Data Sheet references the applicable section number of the procedure for each QCD point.



14.2 DATA SHEET 12.8



INRYCO INC. PROCEDURE SQ 12.8
GREASE DOME TENDON-FINAL REFILL
DATA SHEET 12.8
MAY 23, 1985, Revision 0
⚠ JUNE 11, 1985, Revision 1
PAGE 1 OF 1

PROJECT: _____ UNIT: _____ DATE: _____
TENDON NO.: _____ TENDON END/BUTTRESS NO.: _____

QC
SIGNOFF

(8.4) Concrete Temp: _____ °F. Thermo. No.: _____ Recal Date: _____

(11.6.1) Grease Temp. Storage Container _____ °F.
Thermometer No. _____ Recal Date: _____

(11.12.4) Grease Temp. Ambient _____ °F.
Thermometer No. _____ Recal Date: _____

(11.13.1) Grease Temp. Exiting _____ °F.
Thermometer No. _____ Recal Date: _____
Pump Pressure Before Pipe Plug Installed to Filler Pipe _____ psi

(11.14.1) Pump Pressure Before Pipe Plug Installed in Grease Can _____ psi

(11.14.3) Pump Pressure When Pumping Stopped _____ psi

⚠ Deleted

(13.1) Grease Leaks YES NO
Leaks Repaired YES NO

(13.1.1) Refill Acceptable: _____

(13.1.2) COMMENTS: _____

(13.1.3) FNP Drum Control No.: _____ Viscosity Batch No. _____


Q.C. REVIEW: _____ LEVEL _____ DATE: _____

TITLE: _____

May 23, 1985

▲ PAGE 11 OF 15

15.1 Sketch 8-0



GREASE CONTROL STATION

This drawing has not been sustained. It is the sole property of INRYCO, Inc. It is loaned to the recipient for his confidential use only, and upon the conditions and agreements following. In consideration of the loan of this drawing, the recipient promises and agrees to return it upon request and that it shall not be reproduced, copied, or in any way disseminated or directly or indirectly without INRYCO, Inc. written consent, nor be used in any way detrimental to the interests of INRYCO, Inc.




Inryco
an Inland Steel company
Post Tensioning Division

Revised By	Date
Approved By	Date
Drawn By	Date
DW/W	7-15-77
Drawing No.	7-15-77
Sketch 8-0	

15.2 Sketch 8-1

TYPICAL HOOK-UP FOR FILLING TENDON VOIDS

- A - Grease Can Body
- B - Pipe
- C - Grease Can Filler Bushing
- D - Y-Device Body
- E - Male Quick Coupler
- F - Operating Shaft & Handle
- G - Square Male Pipe Plug Wrench
- H - Pipe Plug
- I - Casing Filler Hose
- J - Female Quick Coupler
- K - Packing Box
- L - Packing Box Gland
- M - Relief Valve - Optional



Refer Procedure F8.0 Section 1.4 for operation.

Special Tendon Void Filling Tool

This drawing has not been published. It is the sole property of INRYCO, Inc. It is loaned to the recipient for his confidential use only. It is to be returned to the originator upon request. In consideration of the loan of this drawing, the recipient promises and agrees to return it upon request, and that it shall not be reproduced, copied, or otherwise disposed of directly or indirectly without INRYCO, Inc. written consent. Nor be used in any way detrimental to the interests of INRYCO, Inc.



Y-DEVICE

Inryco
an Inland Steel company

Post Tensioning Division


Revised By	Date
Approved By	Date
Drawn By	Date
Drawing No.	Sketch 8-1

May 23, 1985

△ PAGE 13 OF 15


15.3 Sketch 8-2

SYSTEM A



Re-circulation to storage during hook-up operations.

SYSTEM B



All component identification is the same as shown in System A, except where noted.

Re-circulation through filler hoses before or after filling operations.

RECIRCULATION PATTERNS

FLOW DIAGRAM

This drawing has not been evaluated, it is the sole property of INRYCO, INC. It is loaned to the recipient for his confidential use only, and under the conditions and agreements following. A consideration of the loan of this drawing, the recipient promises and agrees to return it upon request, and that it shall not be reproduced, copied, lent or otherwise divulged or directly or indirectly to anyone without INRYCO, INC. written consent, nor be used in any way detrimental to the interests of INRYCO, INC.




Inryco

an Inland Steel company

Post Tensioning Division

Revised by	Date
Approved by	Date
Drawn by	Date
Drawing No.	Sketch 8-2

15.4 Sketch 12.8



GREASE REPLACEMENT - DOME TENDON

PROCEDURE SQ 12.3

Revised By: *CVI* Date: *5.23.85*

This drawing has not been published. It is the sole property of INRYCO, Inc. It is loaned to the recipient for his confidential use only, and upon the conditions and agreements following. In consideration of the loan of this drawing, the recipient promises and agrees to return it upon request, and that it shall not be reproduced, copied, lent or otherwise disposed of directly or indirectly without INRYCO, Inc. written consent, nor be used in any way detrimental to the interests of INRYCO, Inc.



Inryco
an Inland Steel company

Post Tensioning Division

Approved By: *CVI* Date: *5.23.85*
Drawn By: *DWW* Date: *5.23.85*

Drawing No. SKETCH 12.3




Inryco
an Inland Steel company

INRYCO INC. PROCEDURE SQ 12.3
GREASE DOME TENDON-FINAL REFILL

May 23, 1985
PAGE 15 OF 15



15.5 Sketch 12.8.1



GREASE REPLACEMENT - DOME TENDON

PROCEDURE SQ 12.3

Revised By	DATE
Approved By	DATE
Drawn By	DATE
Sketching No.	SKETCH 12.3.1



Inryco
an Inland Steel company
Post Tensioning Division

This drawing has not been submitted. It is the sole property of INRYCO, Inc. It is loaned to the recipient for his confidential use only, and upon the conditions and agreements following. In consideration of the loan of this drawing, the recipient promises and agrees to return it upon request, and that it shall not be reproduced, copied, lent or otherwise disposed of directly or indirectly without INRYCO, Inc. written consent, nor be used in any way detrimental to the interests of INRYCO, Inc.

0252Y

⚠ 6-11-85 Page # Only

PROJECT: _____ UNIT: _____ DATE: _____

TENDON NO.: _____ TENDON END/BUTTRESS NO.: _____

QC
SIGNOFF

(8.4) Concrete Temp: _____ °F. Thermo. No.: _____ Recal Date: _____

(11.6.1) Grease Temp. Storage Container _____ °F.
Thermometer No. _____ Recal Date: _____

(11.12.4) Grease Temp. Ambient _____ °F.
Thermometer No. _____ Recal Date: _____

(11.13.1) Grease Temp. Exiting _____ °F.
Thermometer No. _____ Recal Date: _____
Pump Pressure Before Pipe Plug Installed to Filler Pipe _____ psi

(11.14.1) Pump Pressure Before Pipe Plug Installed in Grease Can _____ psi

(11.14.3) Pump Pressure When Pumping Stopped _____ psi

(13.1) Grease Leaks YES NO
Leaks Repaired YES NO

(13.1.1) Refill Acceptable: _____

(13.1.2) COMMENTS: _____

(13.1.3) FNP Drum Control No.: _____ Viscosity Batch No. _____

Q.C. REVIEW: _____ LEVEL _____ DATE: _____

TITLE: _____
0252N



INRYCO INC. PROCEDURE EQ 12.8
GREASE DOME TENDON-FINAL REFILL
DATA SHEET 12.8
MAY 23, 1985, Revision 0
JUNE 11, 1985, Revision 1
PAGE 1 OF 1

PROJECT: Farley UNIT: 2 DATE: 6/13/85
TENDON NO.: D109 TENDON END/BUTTRESS NO.: 204° 36' 29"
D189

QC
SIGNOFF

(8.4) Concrete Temp: 78°F. Thermo. No.: 5761 Recal Date: 5/22/86 JAD 6/13/85

(11.6.1) Grease Temp. Storage Container 184°F.
Thermometer No. PK 55 Recal Date: 5/22/86 JAD 6/13/85

(11.12.4) Grease Temp. Ambient 90°F.
Thermometer No. 'B' Recal Date: 12/8/85 JAD 6/13/85

(11.13.1) Grease Temp. Exiting 140°F.
Thermometer No. 'B' Recal Date: 12/8/85
Pump Pressure Before Pipe Plug Installed to Filler Pipe N/A psi JAD 6/13/85

(11.14.1) Pump Pressure Before Pipe Plug Installed in Grease Can 45 psi BSD 6-13-85

(11.14.3) Pump Pressure When Pumping Stopped 95 psi BSD 6-13-85

(13.1) Grease Leaks YES NO
Leaks Repaired YES NO N/A BSD/JAD 6/13/85

(13.1.1) Refill Acceptable: Yes BSD/JAD 6/13/85

(13.1.2) COMMENTS: N/A

(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-6359 JAD 6/13/85

QC REVIEW: G. C. Inspecta LEVEL II DATE: 6-20-85

TITLE: QC Inspecta

INRYCO INC. PROCEDURE SQ 12.8
GREASE DOME TENDON-FINAL REFILL
DATA SHEET 12.8
MAY 23, 1985, Revision 0
JUNE 11, 1985, Revision 1
PAGE 1 OF 1

 **Inryco**
an Inland Steel company

PROJECT: Farker UNIT: 2 DATE: 6/12/85
TENDON NO.: D 119 TENDON END/BUTTRESS NO.: Fill end Azimuth 176° 40' - 38"
DIC 19
view 6-13-85

QC
SIGNOFF

(8.4) Concrete Temp: 88 °F. Thermo. No.: ST62 Recal Date: 5/22/86 JAD 6/12/85

(11.6.1) Grease Temp. Storage Container 210 °F.
Thermometer No. PK 55 Recal Date: 5/22/85 JAD 6/12/85

(11.12.4) Grease Temp. Ambient 98 °F.
Thermometer No. B' Recal Date: 12/8/85 JAD 6/14/85

(11.13.1) Grease Temp. Exiting 152 °F.
Thermometer No. B' Recal Date: 12/8/85
Pump Pressure Before Pipe Plug Installed to Filler Pipe N/A psi JAD 6/12/85

(11.14.1) Pump Pressure Before Pipe Plug Installed in Grease Can 70 psi 8836-12-85

(11.14.3) Pump Pressure When Pumping Stopped 120 psi 8836-12-85

(13.1) Grease Leaks YES NO
Leaks Repaired YES NO N/A 8836-12-85/ JAD 6/12/85

(13.1.1) Refill Acceptable: Yes 8836-12-85/ JAD 6/12/85

(13.1.2) COMMENTS: NA

(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-6359 JAD 6/12/85

Q.C. REVIEW: W. C. Ouel LEVEL II DATE: 6-20-85

TITLE: QC Inspector



INRYCO INC. PROCEDURE SQ 12.8
GREASE DOME TENDON-FINAL REFILL
DATA SHEET 12.8
MAY 23, 1985, Revision 0
JUNE 11, 1985, Revision 1
PAGE 1 OF 1

PROJECT: Farley UNIT: 2 DATE: 6/13/85
TENDON NO.: D117 TENDON END/BUTTRESS NO.: 182° 13' 27"
D1C17

QC
SIGNOFF

(8.4) Concrete Temp: 73 °F. Thermo. No.: ST-62 Recal Date: 5/22/86 JAD 6/13/85

(11.6.1) Grease Temp. Storage Container 184 °F.
Thermometer No. PK 55 Recal Date: 5/22/86 JAD 6/13/85

(11.12.4) Grease Temp. Ambient 82 °F.
Thermometer No. B' Recal Date: 12/8/85 JAD 6/13/85

(11.13.1) Grease Temp. Exiting 130 °F.
Thermometer No. B' Recal Date: 12/8/85
Pump Pressure Before Pipe Plug Installed to Filler Pipe N/A psi JAD 6/13/85

(11.14.1) Pump Pressure Before Pipe Plug Installed in Grease Can 50 psi JAD 6/13/85

(11.14.3) Pump Pressure When Pumping Stopped 100 psi JAD 6/13/85

(13.1) Grease Leaks YES (NO)
Leaks Repaired YES (N/A) NO (N/A) JAD 6/13/85

(13.1.1) Refill Acceptable: Yes JAD 6/13/85

(13.1.2) COMMENTS: N/A

(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-6359 JAD 6/13/85

Q.C. REVIEW: ccw LEVEL II DATE: 6-20-85

TITLE: QC Inspector

PROJECT: Farley UNIT: 2 DATE: 6/15/85
TENDON NO.: D 227 TENDON END/BUTTRESS NO.: 96° 14' 43"

QC
SIGNOFF

(8.4) Concrete Temp: 74°F. Thermo. No.: ST62 Recal Date: 5/22/86

JAD 6/15/85

(11.6.1) Grease Temp. Storage Container 190°F.
Thermometer No. PK 55 Recal Date: 5/22/86

JAD 6/15/85

(11.12.4) Grease Temp. Ambient
Thermometer No. B' 90°F. Recal Date: 12/8/85

JAD 6/15/85

(11.13.1) Grease Temp. Exiting, B' 112°F.
Thermometer No. B' Recal Date: 12/8/85
Pump Pressure Before Pipe Plug Installed to Filler Pipe N/A psi

JAD 6/15/85

(11.14.1) Pump Pressure Before Pipe Plug Installed in Grease Can 150 psi

B5B 6-15-85

(11.14.3) Pump Pressure When Pumping Stopped 200 psi

B5B 6-15-85

(13.1) Grease Leaks YES ☒ NO ☐
Leaks Repaired YES ☐ NO ☒ N/A

B5B 6/15/85

B5B 6/15/85

(13.1.1) Refill Acceptable: Yes

B5B 6/15/85

(13.1.2) COMMENTS: _____

(13.1.3) FNP Drum Control No.: N/A Viscosity Batch No. 5-552645-6357
5-6357

Q.C. REVIEW: OC Wardell LEVEL II DATE: 6-20-85

TITLE: GC Inspector
0252N

PROJECT: Farley UNIT: 2 DATE: 6/13/85
TENDON NO.: D 307 TENDON END/BUTTRESS NO.: 99° 39 55 F. 11 End
DIT 1

QC
SIGNOFF

(8.4) Concrete Temp: 81 °F. Thermo. No.: 5762 Recal Date: 5/22/86 JAD 6/13/85

(11.6.1) Grease Temp. Storage Container 184 °F.
Thermometer No. PK 55 Recal Date: 5/22/86 JAD 6/13/85

(11.12.4) Grease Temp. Ambient 90 °F.
Thermometer No. B Recal Date: 12/8/85 JAD 6/13/85

(11.13.1) Grease Temp. Exiting 142 °F.
Thermometer No. B Recal Date: 12/8/85
Pump Pressure Before Pipe Plug Installed to Filler Pipe N/A psi JAD 6/13/85

(11.14.1) Pump Pressure Before Pipe Plug Installed in Grease Can 60 psi JAD 6/13/85

(11.14.3) Pump Pressure When Pumping Stopped 115 psi JAD 6/13/85

(13.1) Grease Leaks YES NO
Leaks Repaired YES NO N/A JAD 6/13/85

(13.1.1) Refill Acceptable: YES JAD 6/13/85

(13.1.2) COMMENTS: N/A

13.1.3) FNP Drum Control No.: N/A Lot No. 5-6359 Viscosity Batch No. JAD 6/13/85

QC REVIEW: UCW LEVEL H DATE: 6-20-85

TITLE: QC Inspector

PROJECT: Farley UNIT: 2 DATE: 6/14/85
TENDON NO.: D 319 TENDON END/BUTTRESS NO.: 133° 40' 22"
D 3 C 19

QC
SIGNOFF

(8.4) Concrete Temp: 73 °F. Thermo. No.: ST62 Recal Date: 5/22/86 JAD 6/14/85

(11.6.1) Grease Temp. Storage Container 178 °F.
Thermometer No. PK 55 Recal Date: 5/22/86 JAD 6/14/85

(11.12.4) Grease Temp. Ambient 92 °F.
Thermometer No. B Recal Date: 12/8/85 JAD 6/14/85

(11.13.1) Grease Temp. Exiting 124 °F.
Thermometer No. B' Recal Date: 12/8/85
Pump Pressure Before Pipe Plug Installed to Filler Pipe NA psi JAD 6/14/85

(11.14.1) Pump Pressure Before Pipe Plug Installed in Grease Can 75 psi BBB 6/14/85

(11.14.3) Pump Pressure When Pumping Stopped 125 psi BBB 6/14/85

(13.1) Grease Leaks YES NO
Leaks Repaired YES NO N/A BBB / JAD 6/14/85
BBB / JAD 6/14/85

(13.1.1) Refill Acceptable: Yes BBB / JAD 6/14/85

(13.1.2) COMMENTS: N/A

(13.1.3) FYP Drum Control No.: N/A Viscosity Batch No. 5-6359 JAD 6/14/85

Q.C. REVIEW: Wendell LEVEL II DATE: 6-20-85

TITLE: QC Inspector

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842473 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description V4, Gallery, Field End, Anchor Face
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm) *1
Water Soluble Nitrate (NO₃) (ppm) *1
Water Soluble Sulfides (S) (ppm) *1
Water (Toluene Distillation) 0.5%

Neutralization Number:

Strong Base Number 45.8

* None found if present less than


Methods:

Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,
LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1938
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842476

Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description V 28 Gallery, Field End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	1.2%

Neutralization Number:

Strong Base Number 56.4

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1988
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842474 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description V 79, Gallery, Field End, Grease Can
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm) *1
Water Soluble Nitrate (NO₃) (ppm) *1
Water Soluble Sulfides (S) (ppm) *1
Water (Toluene Distillation) 0.5%

Neutralization Number:

Strong Base Number 60.8

* None found if present less than

Methods:

Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

By Robert E. Laffer

Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842475 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description V 100, Gall, Field End
Tendon Grease, P. O. 4081

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 48.5

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number

842477

Sample of

Received

6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description

1 DE, Shop
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.3%

Neutralization Number:

Strong Base Number 44.1

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842480 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description 1 DE, Field End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm) *1
Water Soluble Nitrate (NO₃) (ppm) *1
Water Soluble Sulfides (S) (ppm) *1
Water (Toluene Distillation) 0.5%

Neutralization Number:

Strong Base Number 44.6

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number

842484

Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description

21 ^{DE} DG, Shop
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 45.8

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1998
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842485 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description 21 DE, Field
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.1%

Neutralization Number:

Strong Base Number 48.5

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842479 Sample of

Received 6/18/85

For
Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description 28 DE, Shop End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 46.9

* None found if present less than


Methods:

Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,
LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number

842483

Sample of

Received

6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description

28 DE, Field
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 56.4

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1858
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA GA 7/25/85

Number 842482 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description 45 DE, Shop End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.3%

Neutralization Number:

Strong Base Number 54.7

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1988

ATLANTA, GA. 30301

Chemical Report

763
Number 842481 Sample of

ATLANTA, GA. 7/25/85

Received 6/18/85

For
Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description 45 DE, Field End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.4%

Neutralization Number:

Strong Base Number 48.5

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763
Number 842491 Sample of
For Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

ATLANTA, GA. 7/25/85

Received 6/18/85

Marks

Description ³ EF, Shop
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	1.3%

Neutralization Number:

Strong Base Number 46.9

* None found if present less than


Methods:

Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

By 

Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

ATLANTA, GA. 7/25/85

763

Number 842493 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description 3 EF, Field
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 49.7

* None found if present less than


Methods:

Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,
LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763
Number 842492 Sample of
For Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

ATLANTA, GA. 7/25/85

Received 6/18/85

Marks

Description 17 EF, Shop
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.5

Neutralization Number:

Strong Base Number 48.0

* None found if present less than


Methods:

Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,
LAW & COMPANY

BY



Inv. to Birmingham, AL
J 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1936
ATLANTA, GA. 30301

Chemical Report

763
Number 842496 Sample of
For Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

ATLANTA, GA. 7/25/85

Received 6/18/85

Marks

Description 17 EF, Field
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.3%

Neutralization Number:

Strong Base Number 54.7

* None found if present less than

Methods:

Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY

Robert E. Jeff

Inv. to Birmingham, AL
J 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763
Number 842495 Sample of
For Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

ATLANTA, GA. 7/25/85
Received 6/18/85

Marks

Description 31 EF, Shop
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.3%

Neutralization Number:

Strong Base Number 51.3

* None found if present less than


Methods:

Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,
LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500ay

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1862
ATLANTA, GA. 30301

Chemical Report

763
Number 842494 Sample of
For Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

ATLANTA, GA. 7/25/85

Received 6/18/85

Marks

Description 31 EF, Field
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.3%

Neutralization Number:

Strong Base Number 48.5

* None found if present less than

Methods:

Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,
LAW & COMPANY

BY 

Inv. to Birmingham, AL
J 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1555
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842490 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description 13 FD, Shop
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 43.5

* None found if present less than


Methods:

Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,
LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763
Number 842486 Sample of
For Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

ATLANTA, GA. 7/25/85

Received 6/18/85

Marks

Description 13 FD, Field
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.4%

Neutralization Number:

Strong Base Number 44.6

* None found if present less than


Methods:

Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,
LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1559
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842489 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description 26 FD, Shop
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.3%

Neutralization Number:

Strong Base Number 42.4

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1886
ATLANTA, GA. 30301

Chemical Report

ATLANTA, GA. 7/25/85

763

Number 842487 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description 26 DF, Field End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.4%

Neutralization Number:

Strong Base Number 61.4

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
J 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1938
ATLANTA, GA. 30301

Chemical Report

ATLANTA, GA. 7/25/85

763

Number 842488 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description 42 FD, Shop
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.4%

Neutralization Number:

Strong Base Number 58.6

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number

842478

Sample of

Received

6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description

42 DF, Field
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 67.0

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
3 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763
Number 842471 Sample of

43 ATLANTA, GA. 7/25/85

Received 6/18/85

For
Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description D 109, Field
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 45.1

* None found if present less than

Methods:

Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,
LAW & COMPANY

BY 

Inv. to Birmingham, AL
J 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

ATLANTA, GA. 7/25/85

763

Number 842468

Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description D 109, Sharp End,
Tendon Grease, P.O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.1%

Neutralization Number:

Strong Base Number 62.5

* None found if present less than

Methods:

Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY: 

Inv. to Birmingham, AL
10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

Number

842466

Sample of

ATLANTA, GA. 7/25/85

Received

6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description D 119, Field End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm) *1
Water Soluble Nitrate (NO₃) (ppm) *1
Water Soluble Sulfides (S) (ppm) *1
Water (Toluene Distillation) 0.5%

Neutralization Number:

Strong Base Number 22.3

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888

ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number

842464

Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description

D 119, Shop End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 60.8

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
; 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1000
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number

842463

Sample of

Received

6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description Tendon Grease, P. O. 40811
D 117, Field End

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 59.7

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
J 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842467 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description D 117, Shop End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 59.2

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
J 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1988
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 8 42 469 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description D-227, Field End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.1%

Neutralization Number:

Strong Base Number 63.6

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1598
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842461 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description D-227, Shop End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.1%

Neutralization Number:

Strong Base Number 55.2

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY:



Inv. to Birmingham, AL
10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1858
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842470 Sample of

Received 6/18/85

For
Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description D 307, Field
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm) *1
Water Soluble Nitrate (NO₃) (ppm) *1
Water Soluble Sulfides (S) (ppm) *1
Water (Toluene Distillation) 0.7

Neutralization Number:

Strong Base Number 65.3

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
5 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842472 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description

3
D-207, Shop End
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.1%

Neutralization Number:

Strong Base Number 69.8

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water extract. Nitrates, ASTM D-992, Brucine on water extract. Sulfide, APHA 427 15th Ed, Methylene Blue on water extract. Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
; 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1988
ATLANTA, GA. 30301

Chemical Report

763

63 ATLANTA, GA. 7/25/85

Number

842465

Sample of

Received

6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description

D-319, Field
Tendon Grease, P. O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.1%

Neutralization Number:

Strong Base Number 59.2

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
S 10500av

LAW & COMPANY

CONSULTING AND ANALYTICAL CHEMISTS

P. O. BOX 1888
ATLANTA, GA. 30301

Chemical Report

763

ATLANTA, GA. 7/25/85

Number 842462 Sample of

Received 6/18/85

For

Alabama Power Company
P. O. Drawer #470
Ashford, AL 36312

Marks

Description D319, Shop End
Tendon Grease, P.O. 40811

Water Soluble Chloride (Cl) (ppm)	*1
Water Soluble Nitrate (NO ₃) (ppm)	*1
Water Soluble Sulfides (S) (ppm)	*1
Water (Toluene Distillation)	0.2%

Neutralization Number:

Strong Base Number 58.0

* None found if present less than

Methods:


Chloride, ASTM D-512, Mercurimetric titration on water
extract. Nitrates, ASTM D-992, Brucine on water extract.
Sulfide, APHA 427 15th Ed, Methylene Blue on water extract.
Water, ASTM D-95, Neutralization number ASTM D-974 modified.

The above analysis were performed in conformance with Alabama
Power Co., Purchase Order #40811.

Respectfully submitted,

LAW & COMPANY

BY



Inv. to Birmingham, AL
J 10500av



VISCOSITY OIL CO.
3200 S. WESTERN AVENUE
CHICAGO, IL 60608 U.S.A.

TELEPHONE:
(312) 847-0224
TWX 910-221-0245

PETROLIA, PA

Yours-PO# QP0016
Ours-NYR-03420

Job Order No.

Lot No.

5-5526

QUALITY CONTROL SPECIFICATION SHEET
VISCONORUST 2090P-4 CASING FILLER
NUCLEAR GRADE

PHYSICAL PROPERTIES

TEST RESULTS

REQUIRED

Pound per gallon @ 60°F (15.5°C)		7.5	7.3-7.8
Specific Gravity @ 60°F (15.5°C)	ASTM D-287	0.90	0.88-0.94
Congearing Point, °F(°C)	ASTM D-938	142	135-145(57-63)
Flash Point, °F(°C)	ASTM D-92	460	420 (215) min.
Viscosity SUS @ 210°F (98.9°C)	ASTM D-88	153	150-300
ASTM Consistency (cone penetration @ 77°F (25°C)	ASTM D-937	192	190-220
Total Base No. Modified	ASTM D-974	48.7	35 min.
Water Content (% by Wt.)	ASTM D-95	0.6	0.4

CHEMICAL PROPERTIES

Water Soluble Chlorides	ASTM D-512	1	2 ppm max.
Water Soluble Nitrates	ASTM D-992	2	4 ppm max.
Water Soluble Sulfides	APHA No. 427 (15th Ed.) Methylene Blue	1	2 ppm max.

This certifies compliance with the Specifications or requirements covered by Customer's Purchase Order.

BY

Thomas D. Hindman
CONTROL CHEMIST

DATE

March 4, 1985



VISCOSITY OIL CO.

3200 S. WESTERN AVENUE
CHICAGO, IL 60608 U.S.A.

TELEPHONE:
(312) 847-0224
TWX 910-221-0245

PETROLIA, PA

Job Order No. QP-0016

Lot No. 5-5928

QUALITY CONTROL SPECIFICATION SHEET
VISCONDURST 2090P-4 CASING FILLER
NUCLEAR GRADE

PHYSICAL PROPERTIES

TEST RESULTS

REQUIRED

Pound per gallon
@ 60°F (15.5°C)

7.5

7.3-7.8

Specific Gravity
@ 60°F (15.5°C)

ASTM D-287

0.9

0.88-0.94

Congealing Point, °F(°C)

ASTM D-938

140

135-145(57-63)

Flash Point, °F(°C)

ASTM D-92

425

420 (215) min.

Viscosity SUS
@ 210°F (98.9°C)

ASTM D-88

164

150-300

ASTM Consistency (cone penetration
@ 77°F (25°C)

ASTM D-937

194

190-220

Total Base No. Modified

ASTM D-974

52

35 min.

Water Content (% by Wt.)

ASTM D-95

0.1

0.4 %

CHEMICAL PROPERTIES

Water Soluble Chlorides

ASTM D-512

1

2 ppm max.

Water Soluble Nitrates

ASTM D-992

2

4 ppm max.

Water Soluble Sulfides

APHA No. 427 (15th Ed.)

Methylene Blue

1

2 ppm max.

This certifies compliance with the Specifications or requirements covered
by Customer's Purchase Order.

BY

Thomas D. Hildner
CONTROL CHEMIST

DATE

April 11, 1985



VISCOSITY OIL CO.
3200 S. WESTERN AVENUE
CHICAGO, IL 60608 U.S.A.

TELEPHONE
(312) 847-0224
TWX 910-221-0245

PETROLIA, PA

Job Order No. 35053

Lot No. 5-6202

QUALITY CONTROL SPECIFICATION SHEET
VISCONORUST 2090P-4 CASING FILLER
NUCLEAR GRADE

PHYSICAL PROPERTIES

		<u>TEST RESULTS</u>	<u>REQUIRED</u>
Pound per gallon @ 60°F (15.5°C)		7.5	7.3-7.8
Specific Gravity @ 60°F (15.5°C)	ASTM D-287	0.9	0.88-0.94
Congealing Point, °F(°C)	ASTM D-938	145	135-145(57-63)
Flash Point, °F(°C)	ASTM D-92	475	420 (215) min.
Viscosity SUS @ 210°F (98.9°C)	ASTM D-88	169	150-300
ASTM Consistency (cone penetration @ 77°F (25°C)	ASTM D-937	215	190-220
Total Base No. Modified	ASTM D-974	51	35 min.
Water Content (% by Wt.)	ASTM D-95	0.2	0.4

CHEMICAL PROPERTIES

Water Soluble Chlorides	ASTM D-512	1	2 ppm max.
Water Soluble Nitrates	ASTM D-992	2	4 ppm max.
Water Soluble Sulfides	APHA No. 427 (15th Ed.) Methylene Blue	1	2 ppm max.

This certifies compliance with the Specifications or requirements covered
by Customer's Purchase Order.

BY

D. Hildman
CONTROL CHEMIST

DATE May 13, 1985

40 40 40#

9182022

80:91 18/90

7162 '85/05/31 13160

VISCOITY OIL CO.3200 S. WESTERN AVENUE
CHICAGO, IL 60608 U.S.A.TELEPHONE
(312) 347-01
TWA 910-2211PETROLIA, PAJob Order No. QP-C016Lot No. 5-6359QUALITY CONTROL SPECIFICATION SHEET
VISCONORUST 2000P-4 CASTING FILLER
NUCLEAR GRADEPHYSICAL PROPERTIESTEST RESULTSREQUIREDPound per gallon
@ 60°F (15.5°C)7.57.3-7.8Specific Gravity
@ 60°F (15.5°C)ASTM D-2870.920.88-0.94

Congealing Point, °F (°C)

ASTM D-938144135-145 (57-6)

Flash Point, °F (°C)

ASTM D-92420420 (215) minViscosity SUS
@ 210°F (98.9°C)ASTM D-88180150-300ASTM Consistency (cone penetration
@ 77°F (25°C)ASTM D-937199190-220

Total Base No. Modified

ASTM D-97449.835 min.

Water Content (% by wt.)

ASTM D-950.20.4CHEMICAL PROPERTIES

Water Soluble Chlorides

ASTM D-51212 ppm max.

Water Soluble Nitrates

ASTM D-99224 ppm max.

Water Soluble Sulfides

APHA No. 427 (15th Ed.)Methylene Blue12 ppm max.This certifies compliance with the Specifications or requirements covered
by Customer's Purchase Order.

BY

Thomas D. Anderson
CONTROL CH. MIST

DATE

May 30, 1985

170736