

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Wolf Creek Generating Station	DOCKET NUMBER (2) 0 5 0 0 0 4 8 1 2	PAGE (3) 1 OF 0 1 3
--	--	------------------------

TITLE (4)

ESF Actuation - Reactor Trip, Auxiliary Feed Actuation, Feedwater Isolation

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)													
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)											
0	7	0	9	8	5	8	5	0	4	9	0	0	0	8	6	8	5	0	5	0	0	0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)											
OPERATING MODE (9)		1		20.402(b)		20.405(c)		<input checked="" type="checkbox"/> 50.73(a)(2)(iv)		73.71(b)	
POWER LEVEL (10)		0 4 7		20.405(a)(1)(i)		50.36(c)(1)		<input type="checkbox"/> 50.73(a)(2)(v)		73.71(c)	
				20.405(a)(1)(ii)		50.36(c)(2)		<input type="checkbox"/> 50.73(a)(2)(vii)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)	
				20.405(a)(1)(iii)		50.73(a)(2)(i)		<input type="checkbox"/> 50.73(a)(2)(viii)(A)			
				20.405(a)(1)(iv)		50.73(a)(2)(ii)		<input type="checkbox"/> 50.73(a)(2)(viii)(B)			
				20.405(a)(1)(v)		50.73(a)(2)(iii)		<input type="checkbox"/> 50.73(a)(2)(ix)			

LICENSEE CONTACT FOR THIS LER (12)

NAME Merlin G. Williams - Superintendent of Regulatory, Quality and Administrative Services	TELEPHONE NUMBER AREA CODE 3 1 1 6 3 1 6 4 1 - 1 8 1 8 1 3 1 1
--	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On July 9, 1985, at approximately 1115 CDT, a Reactor Trip, Main Turbine Trip, Feedwater Isolation, Auxiliary Feedwater Actuation, and Steam Generator Blowdown and Sample Isolation occurred due to low-low water level in Steam Generator "C". A Turbine-driven Auxiliary Feedwater Actuation occurred when water level in Steam Generator "A" also reached the low-low level setpoint.

Prior to this event, the plant was in Mode 1, Power Operation, at a Reactor power level of approximately forty-seven percent. During Power Ascension Testing, feedwater flow to the Steam Generators began decreasing rapidly, resulting in the steam generator water levels reaching the low-low level setpoint for Engineered Safety Features Actuation.

Subsequent investigations determined that the loss of feedwater flow was the result of installation and removal of test equipment in the feedwater control circuit cabinets. All required Engineered Safety Features and Reactor Protection System equipment performed their intended safety function, and the actuated systems were restored to normal at approximately 1230 CDT.

To prevent future occurrences of this type, personnel have been cautioned about the effects of installing and removing testing equipment.

There was no damage to plant equipment or release of radioactivity as a result of this event, and at no time did conditions develop that may have posed a threat to the health and safety of the public.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Wolf Creek Generating Station	0 5 0 0 0 4 8 2	8 5	— 0 4 9	— 0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 368A's) (17)

On July 9, 1985, at approximately 1115 CDT, an Engineered Safety Features Actuation and a Reactor Trip occurred due to low-low water level in Steam Generator (S/G)[AB-SG]"C".

Prior to this event, the plant was in Mode 1, Power Operation. Power Ascension Testing was in progress in accordance with SU7-008.2, "Power Coefficient Determination", which involves ramping the Main Turbine [TA-TRB] load down forty megawatts, allowing conditions to stabilize, and then ramping the Main Turbine load back up forty megawatts at five percent per minute. The ramp down was completed successfully, and the plant was stable at forty-seven percent reactor power, with the S/G's being maintained at a level of approximately fifty percent by the Main Feedwater Control Valves [SJ-FCV], which were in automatic control.

As the ramp back up was attempted, feedwater flow fluctuations occurred on all four Steam Generators. The operators took manual control of the Main Feedwater Control Valves for steam generators "A", "B", and "C", but the levels continued to decrease. Level in S/G "C" reached the low-low level setpoint for Engineered Safety Features Actuation first, resulting in a Reactor Trip, Main Turbine Trip, motor-driven Auxiliary Feedwater Actuation, Steam Generator Blowdown and Sample Isolation, and a Feedwater Isolation. Shortly thereafter, S/G "A" water level reached the low-low level setpoint, initiating a Turbine-driven Auxiliary Feedwater Actuation.

All required Engineered Safety Features and Reactor Protection System equipment responded properly with the exception of Intermediate Range Nuclear Instrumentation [IG] channel SE-NI-35B, which would not allow Permissive P-6 to energize the Source Range Nuclear Instruments following the trip. The Source Range Nuclear Instruments had to be manually energized.

During this event, pressurizer [AB-PZR] level decreased to approximately sixteen percent, and the Reactor Coolant System [AB] average temperature reached a minimum of 538 degrees Fahrenheit. Levels in all four Steam Generators reached the low-low level setpoint during this event. The actuated systems were restored to normal configuration per plant procedures, and normal feedwater flow was restored at approximately 1230 CDT.

An investigation into this event determined that the initial feedwater flow fluctuations in all S/G's were the result of a personnel activity in installing and removing test recorders in the feedwater control circuits. The test leads being utilized created a "short", resulting in a loss of program level signal to the controller for Main Feedwater Control Valves which caused a loss of feedwater to the S/G's. This scenario has been reenacted with an identical loss of program level signals, although no ESF actuations occurred due to plant conditions at the time. Circuit cards which were exposed to the test signals have been replaced.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Wolf Creek Generating Station	DOCKET NUMBER (2) 0 5 0 0 0 4 8 2 8 5 - 0 4 9 - 0 0 0 3	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The problems experienced with the intermediate range nuclear instrumentation channel SE-NI-35B were investigated by Instrumentation and Control (I&C) personnel and found to be the result of dirty connectors. These connectors were cleaned, and SE-NI-35B was returned to operable status.

This event is considered to be a unique situation, caused by the installation and removal of test equipment. The importance of being aware of the consequences of installing and removing test equipment was stressed to I&C personnel, and further emphasis will be placed on this event by incorporation of this report into I&C Required Reading.

There was no damage to plant equipment or release of radioactivity as a result of this event, and at no time did conditions develop that may have posed a threat to the health or safety of the public.



KANSAS GAS AND ELECTRIC COMPANY

GLENN L. KOESTER
VICE PRESIDENT - NUCLEAR

August 6, 1985

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Mr. R.P. Denise, Director
Wolf Creek Task Force
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011


KMLNRC 85-190
Re: Docket No. STN 50-482
Subj: Licensee Event Report 85-049-00

Dear Gentlemen:

The enclosed Licensee Event Report is submitted pursuant to 10 CFR 50.73(a) (2) (iv) concerning an Engineered Safety Feature actuation.

If you have any questions concerning this matter, please contact me or Mr. Otto Maynard of my staff.

Yours very truly,

for 
Glenn L. Koester
Vice President - Nuclear

CLK:dab

Enclosure

xc: PO'Connor (2), w/a
JCummins, w/a

LE22
1/1