



An EDISON INTERNATIONAL Company

R. W. Krieger  
Vice President  
Nuclear Generation

January 20, 1997

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555

Subject: Docket Nos. 50-206, 50-361 and 50-362  
14-Day Report  
Licensee Event Report No. 97-001  
San Onofre Nuclear Generating Station, Units 1, 2 and 3

This submittal provides a written follow-up 14-day report required by Unit 2/3 License Condition 2.G using the Licensee Event Report (LER) format as required by Unit 1 License Condition 2.D. The reported condition, missed testing/inspection of security systems, affected neither the health nor the safety of plant personnel or the public.

Sincerely,

A handwritten signature in cursive script, appearing to read "RWKrieger".

Enclosure: LER No. 97-001

cc: L. J. Callan, Regional Administrator, NRC Region IV  
T. P. Gwynn, Director, Division of Reactor Safety, NRC  
Region IV  
K. E. Perkins, Jr., Director, Walnut Creek Field Office, NRC  
Region IV  
J. A. Sloan, NRC Senior Resident Inspector, San Onofre Units  
2 & 3  
L. C. Carson, NRC Project Manager, San Onofre Unit 1  
M. B. Fields, NRC Project Manager, San Onofre Units 2 and 3  
Institute of Nuclear Power Operations (INPO)

9701280102 970120  
PDR ADOCK 05000206  
S PDR

P. O. Box 128  
San Clemente, CA 92674  
714-368-6255  
Fax 714-368-6183

JE22%

LICENSEE EVENT REPORT (LER)																			
Facility Name (1)										Docket Number (2)				Page (3)					
SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 1										0   5   0   0   0   2   0   6   1				1 of 0   1					
Title (4) Missed Security Test/Inspection																			
EVENT DATE (5)				LER NUMBER (6)				REPORT DATE (7)				OTHER FACILITIES INVOLVED (8)							
Month	Day	Year	Year	/// ///	Sequential Number	/// ///	Revision Number	Month	Day	Year	Facility Names			Docket Number(s)					
0	1	0	7	9	7	9	7	0	1	2	0	9	7	SONGS, UNIT 2			0   5   0   0   0   3   6   1		
												SONGS, UNIT 3			0   5   0   0   0   3   6   2				
OPERATING MODE (9)				0				THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)											
POWER LEVEL (10) 0   0   0				20.402(b)				20.405(c)				50.73(a)(2)(iv)				73.71(b)			
				20.405(a)(1)(i)				50.36(c)(1)				50.73(a)(2)(v)				73.71(c)			
				20.405(a)(1)(ii)				50.36(c)(2)				50.73(a)(2)(vii)				xx Other (Specify in			
				20.405(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(viii)(A)				Abstract below and			
				20.405(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)				in text)			
				20.405(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(x)				Unit 1, License 2.0 Units 2&3, License 2.0			
LICENSEE CONTACT FOR THIS LER (12)																			
Name										TELEPHONE NUMBER									
R. W. Krieger, Vice President, Nuclear Generation										AREA CODE		7   1   4   3   6   8   -   6   2   5   5							
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																			
CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	/////	CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	/////								
					/////						/////								
					/////						/////								
					/////						/////								
SUPPLEMENTAL REPORT EXPECTED (14)												Expected Submission Date (15)		Month	Day	Year			
Yes (If yes, complete EXPECTED SUBMISSION DATE)												xx NO							

These occurrences were caused by cognitive personnel error. The individual responsible for security system tests/inspections failed to ensure they were completed as required.

LER 1-96-002 reported a missed inspection of security tamper switches. That event was caused by inadequate communication when capturing inspection requirements for a newly installed security system, a cause not present for the events reported herein.