



Entergy Operations, Inc.
River Bend Station
5485 U. S. Highway 61
P.O. Box 220
St. Francisville, LA 70775
Tel 504 336 6225
Fax 504 635 5068

Rick J. King
Director
Nuclear Safety & Regulatory Affairs

October 18, 1996

U.S. Nuclear Regulatory Commission
Document Control Desk
Mail Stop P1-37
Washington, D.C. 20555

Subject: River Bend Station - Unit 1
Docket No. 50-458
License No. NPF-47
Licensee Event Report 50-458/96-007-01
File Nos. G9.5, G9.25.1.3

RBG- 43324
RBF1-96-0390

Gentlemen:

Licensee Event Report 96-007-00 was submitted on March 14, 1996, reporting a condition with the River Bend Station Containment Airlocks. During subsequent corrective actions which included, in part, accelerated performance testing, an additional condition was identified. This supplement provides additional information concerning this condition. The text of the original report has not been modified. In accordance with 10CFR50.73, enclosed is the subject report.

Sincerely,

RJK/RMM/kvm
enclosure

IE221

9610280175 961018
PDR ADOCK 05000458
S PDR

·Licensee Event Report 50-458/96-007-01

October 18, 1996

RBG-

RBF1-96-0390

Page 2 of 2

cc: U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

NRC Sr. Resident Inspector
P. O. Box 1051
St. Francisville, LA 70775

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-3064

Mr. C. R. Oberg
Public Utility Commission of Texas
7800 Shoal Creek Blvd., Suite 400 North
Austin, TX 78757

Louisiana Department of Environmental Quality
Radiation Protection Division
P.O. Box 82135
Baton Rouge, LA 70884-2135
ATTN: Administrator

NRC FORM 366 (5-92)		U.S. NUCLEAR REGULATORY COMMISSION				APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95				
<h2 style="margin: 0;">LICENSEE EVENT REPORT (LER)</h2>						ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503				
FACILITY NAME (1) River Bend Station						DOCKET NUMBER (2) 05000-458		PAGE (3) 1 of 4		
TITLE (4) Containment Airlock Pneumatic System Ball Valve Failure Due to Debris Internal to the System										
EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
02	14	96	96	007	01	10	18	96	N/A	05000
									FACILITY NAME	DOCKET NUMBER
									N/A	05000
OPERATING MODE (9)		1		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more (11))						
POWER LEVEL (10)		46.5%		20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)
				20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)
				20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		OTHER
				20.405(a)(1)(iii)		50.73(a)(2)(i)		50.73(a)(2)(viii)(A)		(Specify in abstract below and in text, NRC Form 365A)
				20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)		
				20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)		
LICENSEE CONTACT FOR THIS LER (12)										
NAME David N. Lorfing, Supervisor - Nuclear Licensing						TELEPHONE NUMBER (Include Area Code) 504-381-4157				
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
SUPPLEMENTAL REPORT EXPECTED (14)						EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)		x		NO						
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)										
<p>On February 14, 1996, with the plant in operational Mode 1, River Bend engineering determined a single condition contributed to the failure of Surveillance Test Procedure (STP) 057-7203, "Containment Personnel Airlock Door Seal Air System Leak Rate Test" for each of the four inflatable seal pneumatic systems of the 171 foot reactor building personnel airlock (*AL*). On March 24, 1996, as part of corrective actions for the previous condition, STP-057-7203 was re-performed, identifying additional failures. This report is being submitted pursuant 10CFR50.73(a)(2)(vii).</p> <p>The single condition for the prior condition was determined to be entrained debris internal to the pneumatic system. The debris was most likely introduced into the system from modifications performed during refuel outage (RF) 5. This debris adhering to lubricant applied to the ball valve and check valve seating surfaces resulted in leakage beyond an acceptable limit. The leaking valves were reworked and Preventative Maintenance (PM) tasks will be developed to replace the seating surfaces on a regular basis. Additionally, the surveillance test will be performed on a more frequent basis. The corrective action will be extended to the 113 foot containment airlock due to similarities of usage and maintenance history. The primary cause of the March 24, 1996, condition was premature failure of the air lock ball valve seats. This resulted from less than adequate inspection criteria for the ball valve components which caused subsequent seat failure. Corrective actions included, in part, replacement of the parts.</p> <p>These conditions are not safety significant. Engineering analysis concluded the pneumatic system was capable of supplying sufficient seal pressure, for both conditions, to maintain containment integrity for 30 days post design basis accident (DBA).</p>										

NRC FORM 366A (5-82)	U.S. NUCLEAR REGULATORY COMMISSION	APPROVED BY OMB NO. 3150-0104 EXPIRES 6/31/95		
<p align="center">LICENSEE EVENT REPORT (LER) TEXT CONTINUATION</p>		<p>ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503</p>		
		FACILITY NAME (1) River Bend Station	DOCKET NUMBER (2) 05000-458	LER NUMBER (6) 96-007-00

Reported Condition:

On February 14, 1996, with the plant in Mode 1, River Bend engineering determined that a single condition caused the failure of Surveillance Test Procedure (STP) 057-7203, "Containment Personnel Airlock Door Seal Air System Leak Rate Test" for each of the four inflatable seal pneumatic systems on the reactor building containment personnel airlock. Engineering investigation found that debris in the system adhered to excess lubricant on the ball valve and check valve seating surfaces, eventually causing air leakage beyond the specified limits. This condition was reported as a single condition that caused two independent trains to become inoperable in a single system designed to control the release of radioactive material pursuant to 10CFR50.73(a)(2)(vii). Corrective actions initiated subsequent to the identification of this condition, in part, included accelerated performance of STP-057-7203. On March 24, 1996, during this accelerated testing, an additional condition was identified.

Investigation:

The primary containment at River Bend Station is equipped with two double door airlocks that provide personnel access to the primary containment. The airlocks are designed to limit the release of radioactive material to the environment during normal operation and through a range of transients and accidents up to and including postulated design basis accidents (DBA's). Each airlock door has two inflatable seals maintained at pressure by a separate pneumatic system. The purpose of the pneumatic system is to ensure an adequate supply of air is available to the containment airlock door seals for a period of 30 days following a DBA. Only one seal pneumatic system per airlock is needed to accomplish this requirement.

Surveillance Test Procedure (STP) 057-7203, "Containment Personnel Airlock Door Seal Air System Leak Rate Test" was being performed between December 7, 1995, and December 13, 1995, to confirm the Technical Specification operability of the personnel airlock pneumatic system.

On December 7, 1995, both airlock seal pneumatic systems on the 171 foot containment airlock inner door failed their surveillance tests. The pressure drop exceeded the Technical Specification allowable value for leakage. Investigation found the upper and lower accumulator ball valves were leaking. The seats were replaced and during retest the upper air accumulator check valve was found leaking. The check valve elastomers were replaced and the surveillance tests were re-performed successfully. On December 11, 1995, both airlock seal pneumatic systems on the 171 foot containment airlock outer door failed their surveillance tests. The pressure drop exceeded the Technical Specification allowable value for leakage. Investigation found the upper and lower ball valves and upper air accumulator check valve leaking. The ball valve seats and check valve's elastomers were replaced and during retest the lower air accumulator check valve was found leaking. The elastomers were replaced on this valve also and the surveillance tests were re-performed successfully.

NRC FORM 366A (5-82)	U.S. NUCLEAR REGULATORY COMMISSION	APPROVED BY OMB NO. 3150-0104 EXPIRES 6/31/95		
LICENSEE EVENT REPORT (LER) TEXT CONTINUATION		ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.		

Engineering performed an investigation in order to determine the root cause or causes of the failures. Inspection of the failed parts found minor scratches on the seating surfaces and particles adhering to the lubricant residue on all seating surfaces of the valves. The particles were analyzed to determine size and general composition. It was concluded that the debris adhering to the lubricant had been entrained by air movement within the system's pneumatic piping, then captured by residual lubricant on the ball and check valve seating surfaces. This debris caused scratches to the ball valve's seats and accumulated on the check valve's seats allowing the valves to leak beyond an acceptable limit.

On March 24, 1996, during accelerated performance of STP-057-7203 an additional test failure occurred. Subsequent investigation identified that the condition was due to premature failure of the air lock ball valve seats. This resulted from less than adequate inspection criteria for the ball valve components. During previous rework of the air lock ball valves, minor scratches were identified on the ball. At that time, the seats were replaced and the balls were reinstalled without rework. Subsequently, the as-left test was successfully completed. The investigation determined that the scratches remaining on the ball accelerated valve seat and ball wear resulting in premature failure.

Root Cause:

Based on physical evidences the single condition is determined to be entrained debris internal to the pneumatic system which adhered to valve's seating surfaces resulting in an unacceptable leakage rate. Engineering evaluated the potential sources of the debris. The potential sources included the pneumatic system accumulators, fragments internal to the seal left from the manufacturing process, and debris introduced during system maintenance or modifications. It was concluded that the debris was most likely introduced into the pneumatic system as a result of system modifications performed in refuel outage (RF) 5.

Subsequent to the identification of the March 24, 1996 test failure, an engineering investigation determined that the condition was due to premature failure of the air lock ball valve seats. This resulted from less than adequate inspection criteria for the ball valve components.

Corrective Action:

The failed valves soft parts were replaced. The surveillance tests (STP) 057-7203 were re-performed satisfactorily for all seal pneumatic systems allowing the airlock doors to be returned to an operable status. Subsequently, concurrence was obtained from the vendor to cease lubricating the valve's soft parts and the site's lubrication manual was changed accordingly. The ball valve and check valve soft parts that have been in service through cycle 6 and passed the most recent leakage test have been scheduled to be replaced. Additionally, each air accumulator will be examined for signs of contaminants. The surveillance test frequency was modified so the test is performed more often until operating experience proves reliable operation of the system. A maintenance task will be developed to replace the check and ball valve's soft parts on a regular basis. The existing cleanliness requirements delineated in Station Operating Procedure,

NRC FORM 366A (5-92)	U.S. NUCLEAR REGULATORY COMMISSION	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95		
<p align="center">LICENSEE EVENT REPORT (LER) TEXT CONTINUATION</p>		<small>ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503</small>		
		FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)
River Bend Station		05000-458	96-007-00	4 OF 4

ADM-0081 (Cleanliness Control) for air systems were reviewed by engineering and determined to be adequate to provide an effective barrier to future incidents of entrained debris. However; the importance of foreign material exclusion on the air system was stressed with Mechanical Maintenance repairmen. The PM task being developed to replace the ball and check valve soft parts will include a reference to the requirements specified in ADM-0081.

For the recent condition, key corrective actions are as follows:

- The non-conforming air lock ball valve discs not previously replaced were replaced.
- The applicable preventive maintenance task procedures were revised to include the appropriate inspection criteria including part replacement, if necessary.

Safety Assessment:

The design basis requires at least one of four containment seals per airlock remain pressurized to a minimum pressure sufficient to maintain containment integrity for 30 days post DBA. The design minimum pressure required to inflate the seals to assure a leak-tight boundary is known. The actual leakage rates determined from surveillance test performances was used to calculate seal pressure after 30 days. The engineering analyses determined adequate margin was available for the identified conditions to ensure containment integrity for 30 days post DBA.

Note: Energy Industry Identification Codes are indicated in the text as (*XX*)