




ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

July 27, 1985



ØCANØ78514


Mr. Richard P. Denise, Director  
Division of Reactor Safety and Projects  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011

SUBJECT: Arkansas Nuclear One - Units 1 & 2  
Docket Nos. 50-313 and 50-368  
License Nos. DPR-51 and NPF-6  
Response to Inspection Reports  
50-313/85-13 and 50-368/85-13

Gentlemen:

The subject inspection report has been reviewed. A response to the Notice of Violation is attached.

Very truly yours,

  
J. Ted Enos  
Manager, Licensing

JTE:RJS:ds

Attachment

cc: Mr. Richard C. DeYoung  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Norman M. Haller, Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

LC-106/85  
8508280314 850815  
PDR ADOCK 05000368  
Q PDR

## NOTICE OF VIOLATION

Based on the results of an NRC inspection conducted during the period of May 1-31, 1985, and in accordance with the NRC Enforcement Policy (10CFR Part 2, Appendix C), 49 FR 8582, dated March 8, 1984, the following violations were identified:

### 1. Fire Doors Left Open

Technical Specification 3.7.11 states, "All penetration fire barriers protecting safety related areas shall be functional."

Contrary to the above, on May 28, 1985, the NRC inspector found Fire Door 213 to be ajar at 3:30 p.m. and at 3:35 p.m. and Fire Door 235 to be ajar at 2:30 p.m. and at 3:00 p.m.

This is a Severity Level IV Violation (Supplement I.D.) (368/8513-01)

#### Response

As a result of the NRC Inspectors finding relating to open fire doors, Managers were instructed to inform their departments that each individual is responsible for ensuring that a fire door closes when he/she passes through it.

An engineering evaluation of the closure mechanisms installed on these and other selected doors was conducted. This resulted in modifications which replaced the closure mechanisms on Doors 213 and 235. These efforts resulted in compliance on July 8, 1985.

### 2. Inadequate Emergency and Abnormal Procedure Reviews by Licensed Operators

Appendix A of 10CFR Part 55, requires that each licensed operator and senior operator review the contents of all abnormal and emergency procedures on a regularly scheduled basis.

Training Administration Procedure 1063.08, "Operations Training Program," has been established to implement the requirements of 10CFR Part 55, Appendix A.

Procedure 1063.08 requires licensed operators to review the abnormal and emergency operating procedures not less than twice each year.

Contrary to the above, three abnormal and emergency procedures have not been reviewed twice each year by the Unit 2 licensed operators since the procedures were issued.

This is a Severity Level IV Violation. (Supplement I.D.) (368/8513-03)

### Response

The cause of the operators' failure to review the procedures as required was that these specific procedures were not included on the procedure review sheets issued by the Training Department. The review sheets were immediately revised to include the these procedures. The review sheets were subsequently removed from the general training file and placed under the control of the Operator Licensing Clerk. In addition, the Operator Training Supervisors have been instructed to verify that the review sheets are current prior to issuance.

Although these three procedures were not on the procedure review sheet, the Unit 2 operators have reviewed or received training on the procedures in the past. The training cycle which includes these procedure reviews will be completed by the end of September such that full compliance will be achieved.