

February 11, 1997

Ms. Irene M. Johnson, Acting Manager  
Nuclear Regulatory Services  
Commonwealth Edison Company  
Executive Towers West III  
1400 Opus Place, Suite 500  
Downers Grove, IL 60515

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION REGARDING THE REVISED STEAM  
GENERATOR TUBE RUPTURE ANALYSIS - BYRON STATION AND BRAIDWOOD  
STATION (TAC NOS. M97315, M97316, M97317 AND M97318)

Dear Ms. Johnson:

On November 13, 1996, Commonwealth Edison Company (ComEd) submitted its revised steam generator tube rupture analysis for Byron, Units 1 and 2, and Braidwood, Units 1 and 2. During the course of our review, we have identified the need for further information as discussed in the enclosed request for additional information (RAI). Please provide your response to the request so that we may maintain our schedule for review of your submittal.

Sincerely,

/s/

George F. Dick, Jr., Project Manager  
Project Directorate III-2  
Division of Reactor Projects III/IV  
Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455,  
STN 50-456, STN 50-457

Enclosure: RAI

cc w/encl: see next page

130042

9702130238 970211  
PDR ADOCK 05000454  
P PDR

**NRC FILE CENTER COPY**

4/1  
PFOI

<b>DISTRIBUTION:</b>	Docket File	PUBLIC	PDIII-2 r/f	J. Roe, JWR
R. Capra	C. Moore	G. Dick	OGC, 015B18	ACRS, T2E26
S. Bailey	C. Jackson, CPJ	R. Assa	J. Lyons	R. Lanksbury, RDL
C. Thomas	J. Arildsen, JAA	G. West, GXW	E. Adensam, EGA1	

Document Name: G:\CMNTJR\BRAID-BY\BB97315.RAI

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

OFF	PM:PDIII-2	LA:PDIII-2	HHFB	SRXB	D:PDIII-2
NAME	GDICK	CMOORE	ETHOMAS	JLYONS	RCAPRA
DATE	02/06/97	02/11/97	02/11/97	02/11/97	02/11/97

OFFICIAL RECORD COPY

I. Johnson  
Commonwealth Edison Company

cc:

Mr. William P. Poirier, Director  
Westinghouse Electric Corporation  
Energy Systems Business Unit  
Post Office Box 355, Bay 236 West  
Pittsburgh, Pennsylvania 15230

Joseph Gallo  
Gallo & Ross  
1250 Eye St., N.W.  
Suite 302  
Washington, DC 20005

Michael I. Miller, Esquire  
Sidley and Austin  
One First National Plaza  
Chicago, Illinois 60603

Howard A. Learner  
Environmental law and Policy  
Center of the Midwest  
203 North LaSalle Street  
Suite 1390  
Chicago, Illinois 60601

U.S. Nuclear Regulatory Commission  
Byron Resident Inspectors Office  
4448 North German Church Road  
Byron, Illinois 61010-9750

Regional Administrator, Region III  
U.S. Nuclear Regulatory Commission  
801 Warrenville Road  
Lisle, Illinois 60532-4351

Ms. Lorraine Creek  
Rt. 1, Box 182  
Manteno, Illinois 60950

Chairman, Ogle County Board  
Post Office Box 357  
Oregon, Illinois 61061

Mrs. Phillip B. Johnson  
1907 Stratford Lane  
Rockford, Illinois 61107

Byron/Braidwood Power Stations

George L. Edgar  
Morgan, Lewis and Bochiuss  
1800 M Street, N.W.  
Washington, DC 20036

Attorney General  
500 South Second Street  
Springfield, Illinois 62701

EIS Review Coordinator  
U.S. Environmental Protection Agency  
77 W. Jackson Blvd.  
Chicago, Illinois 60604-3590

Illinois Department of  
Nuclear Safety  
Office of Nuclear Facility Safety  
1035 Outer Park Drive  
Springfield, Illinois 62704

Commonwealth Edison Company  
Byron Station Manager  
4450 North German Church Road  
Byron, Illinois 61010

Kenneth Graesser, Site Vice President  
Byron Station  
Commonwealth Edison Station  
4450 N. German Church Road  
Byron, Illinois 61010

U.S. Nuclear Regulatory Commission  
Braidwood Resident Inspectors Office  
Rural Route #1, Box 79  
Braceville, Illinois 60407

Mr. Ron Stephens  
Illinois Emergency Services  
and Disaster Agency  
110 East Adams Street  
Springfield, Illinois 62706

Chairman  
Will County Board of Supervisors  
Will County Board Courthouse  
Joliet, Illinois 60434

Commonwealth Edison Company  
Braidwood Station Manager  
Rt. 1, Box 84  
Braceville, Illinois 60407

Ms. Bridget Little Rorem  
Appleseed Coordinator  
117 North Linden Street  
Essex, Illinois 60935

Document Control Desk-Licensing  
Commonwealth Edison Company  
1400 Opus Place, Suite 400  
Downers Grove, Illinois 60515

Mr. H. G. Stanley  
Site Vice President  
Braidwood Station  
Commonwealth Edison Company  
RR 1, Box 84  
Braceville, IL 60407

REQUEST FOR ADDITIONAL INFORMATION

REVISED STEAM GENERATOR TUBE RUPTURE ANALYSIS

COMMONWEALTH EDISON COMPANY

BYRON STATION, UNITS 1 AND 2; BRAIDWOOD STATION, UNITS 1 AND 2

DOCKET NOS. STN 50-454, STN 50-455, STN 50-456, AND STN 50-457

A. Questions Regarding Margin to Overfill Calculations

1. The submittal states that as part of the T-HOT reduction program Byron and Braidwood have been analyzed for a  $T_{avg}$  window of 569.1 degrees Fahrenheit to 588.4 degrees Fahrenheit. The analysis submitted assumes 567.1 degrees Fahrenheit, 2 degrees Fahrenheit lower than the low end of the  $T_{avg}$  window. The Updated Final Safety Analysis Report states (pg. 15.0-9) that the average reactor coolant system temperature uncertainty is  $\pm 4.7$  degrees Fahrenheit. Please explain why the choice of 567 degrees Fahrenheit bounds the operational range with instrument uncertainty included.
2. The analysis concluded that the limiting margin to overfill is 60 cubic feet. Given that this is probably less than a half a foot of water level, less than 30 seconds of auxiliary feedwater flow, less than a few seconds of main feedwater flow and less than two percent of the total steam generator volume, please provide greater justification that this very small margin gives reasonable assurance that the steam generators will not fill. An evaluation of the sensitivity of key parameters to the margin available or an estimation of the calculational uncertainty may be helpful in determining if the margin is adequate.
3. The original staff approved analysis was performed using RETRAN-02 MOD 3. The current analysis uses RETRAN-02 MOD 5.1. Please provide a reference for both the generic and site specific staff approval of MOD 5.1 for the application of steam generator tube rupture analysis.
4. Provide additional discussion of why the amount of turbine runback is now assumed to be 70 percent rather than 60 percent in the previous analysis. Describe the effect of a turbine runback on the results of the analysis. Additionally, why is an immediate manual reactor trip not assumed if this provides more conservative results?
5. Provide greater detail explaining why the assumption of 102 percent initial reactor power before the steam generator tube rupture (SGTR) is more conservative than the previously assumed value of 100 percent power.

ENCLOSURE

B. Questions Regarding Operator Actions

1. As noted in Question A.2, the margin to overfill is small. What assurance will the licensee provide to the staff that demonstration runs on the overfill scenario discussed in the submittal dated November 13, 1996, will be completed for 100 percent of Byron and Braidwood operators?
2. The licensee committed to evaluate a minimum of 80 percent of the Byron and Braidwood licensed operator crews in the design basis SGTR overfill scenario, and in fact evaluated all 12 similar crews at each site. Please discuss the rationale for selecting the two licensed reactor operator crews from Byron and Braidwood for the revised SGTR overfill scenario.
3. Provide the results of a sensitivity study that would evaluate the significance of observed average response times that exceed the revised analysis response times discussed in Tables 3 and 4 of the November 13, 1996, submittal.
4. Provide the actual times for the Byron and Braidwood licensed operator crews that participated in demonstration runs for the overfill scenario discussed in the November 13, 1996, submittal.
5. Provide information regarding the time anticipated to obtain steam generator sample results. Include discussion of the effect on performance of subsequent EOP steps and any resultant effect regarding the SGTR event.